

COLLATERAL
REPORT

VOL. III OF III

DEFENDANT'S
EXHIBIT
D 300
III of III

VOLUME IIITAB

Mission Directive.71
AFTO Forms 781 - for Mission Originating at Travis AFB on 1 April 1975 until accident.72
Extract of 22AF Operations Center Controller's Log.73
DOD International Flight Plan.74
Weight and Balance Clearance Form F.75
Flight Weather Briefing.76
Route of Flight.77
Impact and Wreckage Map.78
Wreckage Diagram79
Crash Scene Pictures80
C-5A 218 CDPIR Audio Transcript.81
Certificate of Aircraft Damage82
Statement of Private Property Damage83
MAC/DOV Letter dated 12 June 1975.84
Press Release Re Medals for Heroism.85
Drawings of Aircraft.86
Laboratory Reports and Other Materials Concerning Explosive Damage87
22LGM Letter - MADAR Tape Analysis88
AFTO Forms 781A for period 31 March 1975 to 4 April 197589
AFTO Form 781A re Tie Rod Assemblies90
AFTO Form 781A re Rig Check.91
AFTO Form 781A re Rig Check.92

22LGM Letter dated 24 July 1975.93
Metallurgical Laboratory Analysis Reports.94
SAALC/MM Letter dated 14 July 197595
Engineering Analysis96
Summary Report of C-5A Accident Investigation Board.	97
Press Release - New York Times98
Summary of Pleadings in Lawsuits filed Against Lockheed Aircraft Corporation99

MISSION DIRECTIVE

Doc

1

PTTUZYUW RUCIMAA5706/0901518-UUUU--RUMMEFA;

ZNR UUUUU

P R 311455Z MAR 75

FM MAC SCOTT AFB IL/DOOMS

TO AIG 8332

INFO RUCIAFB/CDR ARMCOM ROCK ISLAND IL/AMSAR-TMA-C ✓

RHNSMVA/USDAO SAIGON RVN VIETNAM/AOSAR-MA

RUEGBEA/CDR AMC ALEX VA/AMCSU-BT/AMCIL ✓

RUEADHD/DA WASH DC/DALO-TRM-S ✓

RUEKJCS/JCS WASH DC ✓

RUCLNNA/ANNISTON ARMY DEPOT ANNISTON AL/TO ✓

RUEFHQA/CSAF WASH DC/LGTTB ✓

RUMMRGA/COMUSSAG NKP APRT THAI ✓

RUMMRGA/7AF NKP APRT THAI ✓

BT

UNCLAS

THIS IS A MAC DIRECTIVE TO OPERATE APRIL SAAM 3578 (TACT A463 (AFR 76-11 APPLIES); CHARGE OF 12237374 IS NOW FIXED); THIS IS A CLOSE WATCH MISSION.

ITEM 1: 22 AF WILL OPERATE MAC MISSION 3578/01 WARNER ROBINS AFB/TAN SON NHUT; PRIORITY 2A(1) ASSIGNED.

ITEM 2: AVAILABLE 010100Z APR 75. PICKUP AND DELIVER ASAP.

PAGE 2 RUCIMAA5706 UNCLAS

ITEM 3: AIRLIFT 91,900 POUNDS CARGO, 21,900 CUBE;

SEVENTY (70) RECOILLESS RIFLES (M1841); SEVENTEEN M101A1 HOWITZERS;

FIVE (5) ROCKET LAUNCHERS, (M202A1)

311 4,780 POUNDS, 835 CUBE, 238 X 87 X 70;

ITEM 4: CONTACTS:

ORIGIN: ANNISTON ARMY DEPOT, MR. LAMAR NOLAN, AV 694 6212/7738;

DESTINATION: USDAO SGN.

ITEM 5: REMARKS:

MAC AFS AND OR OPERATING UNIT WILL CONFIRM SPECIFIED TIME FOR LOAD AVAILABILITY AND PROPER LOADING EQUIPMENT WITH USER BY TELEPHONE PRIOR TO POSITIONING AIRCRAFT.

5706

220

NNN

A
22DOOMS


037

I
60000M

WCRF

31 MAR 1975

52



PTTEZYUW RUWMEFA0007 0910150-EEEE-~~RUWMEFA~~.
ZNY EEEEE

P R 010050Z APR 75

FM 60MAW TRAVIS AFB CA

TO RUCPAAA/MAC CP SCOTT AFB ILL

RUWJARA/22AF CP TRAVIS AFB CA

RUVRAAA/00PS ROBINS AFB GA

RHNSMVA/USDAO SAIGON RVN/AOSAR-MA/AOSOP/OR

INFO RUWMEFA/60MAWG TRAVIS AFB CA/DOO

~~RUWVAAD/HICKAM OPS CTR HICKAM AFB HAW~~

RUHWRA/6051AS CP ANDERSEN AFB GUAM

RHMDWLA/4050PS CTR CLARK AB P I

RUEDFEA/21AF CP MCGUIRE AFB N J

RUCIMAA/MAC SCOTT AFB ILL/DOOMS

~~RUWMEFA/22AF TRAVIS AFB CA/DOOMS~~

ZEN/60MAW CP TRAVIS AFB CA

RUCIAFB/CDR ARMCOM ROCK ISLAND ILL/AMSAR TMA-6

RUCBBEA/CDRAMC ALEX VA/MCSU-BT/AMCIL

RUHMRGA/7AF NKP APRT THAI

RUHMRGA/COMUSSAG NKP ART THAI

RUFFHQA/CSAF WASH DC/LGTTB

RUCLNNC/ANNISTON ARMY DEPOT ANNISTON AL/TO

PAGE 2 RUWMEFA0007 UNCLAS E F T O

RUUKJCS/JCS WASH DC

RUADWD/DA WASH DC/DHLO-TRM-S

BT

UNCLAS E F T O 60000/DOCP

AM-4 THIS IS 60MAWG MSN SETUP NO 01 TO SAAM 3578

CLD 4 APR 75 60MAWG WILL OPR PRIORITY 2A1 MSN

ONLOAD ROBINS AFB GA OFFLOAD TSN AB RVN

PLANNED PAX 0 CARGO 45.9 TONS TOT ELAPSED TIME 88.7 FLYING TIME 49.0

PAN/3578/01/091/C5/060/B/A

ITINERARY ALL TIMES GMT

STATION	ICAO	ARRIVE	DEPART	REMARKS
TRAVIS	KSUU	00/0000/0	01/0700/P	PYM3578/01/091
ROBINS	KWRB	01/1110/P	01/1425/0	PAN3578/01/091
TRAVIS	KSUU	01/1930/C	02/0350/C	
HICKAM	PHNL	02/0920/R	02/1735/C	
ANDERSEN	PGUA	03/0200/R	03/1015/R	
CLARK	RPHK	03/1350/R	03/2030/C	
SAIGON	VVVS	03/2330/U	04/0545/0	PZM3578/01/091
CLARK	RPHK	04/0845/R	AS DIRECTED	

REMARKS PART 3 CONTACTS ONLOAD MR LAMAR NOLAN AV694-6212/773



91

#0007

NNNN

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

55

AFTO FORMS 781

AEROSPACE VEHICLE FLIGHT DATA DOCUMENTS

C-5A 68218

FOR

MISSION ORIGINATING AT TRAVIS AFB

ON 1 APRIL 1975 UNTIL ACCIDENT

1. DATE			2. MDS			3. SERIAL NUMBER			4. DUP CODE		5. ASGT. CODE		6. ORGANIZATION		7. LOCATION		8. SHEET NO.		9. FLIGHT TIME		10. MISSION SYMBOL								
YR	MO	DAY	M	D	S																								
75	04	01	C	5	A	68	218			IF		60 MAW (NAC)	TRAVIS AFB CA			1	09.7			M-6									
2-3			4-6			8-9			10-11			12			13-15			16			17-18			19-21			22-24		
LOCAL USE	ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER	LAST NAME	DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS				APPR-DACHES				LOCAL USE	CREDIT					
						DAY VFR	DAY INST	NIGHT VFR	NIGHT INST	SIMUL INST	TYPE	NJ	TYPE	NO.	SIM	WEA	PRE	N-P	SORTIES										
A	B	C(1)	C(2)	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V							
25-26	27-30	31	32-40	41-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80								
	0022			Schryer *	FP	01.5	.	01.5	.	00.5	LN	01	LL	01				2	2										
				"	CP	01.8	.	01.4	.	.																			
				"	AC	03.2																			
				Byers	FP	02.0	.	01.2	.	.									2										
				"	CP	01.9	.	01.4	.	.																			
				"	AC	03.2																			
				DALLARI	FP	02.0	.	01.2	.	.									2										
					CP	01.8	.	01.7	.	.																			
					AC	03.3																			
				PARKER	N	05.5	.	04.2	.	.									2										
				BASS	IS	09.7									2										
				HERRICK	FE	09.7									2										
				CRAWFORD	FE	09.7									2										
				DUTCHER	LM	09.7									2										

11. FLIGHT DATA BY SORTIE						12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS		
PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	FULL STOP	TOUCH GO	TOTAL	PILOT	MAINT	OPS	
AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CB	CC	
1	6	TRAVIS AFB CA	Robins AFB GA	I	1058	0647	04:2	1	0	1	DRS		df	
2	0103, 197	Robins AFB GA	TRAVIS AFB CA	I	2242	1710	05:5	1	0	1	DRS			
3	A CERTIFIED TRUE COPY;													
4														
5														
6	BERNARD A. WAXSTEIN, JR., Colonel, USAF													

14. TOTAL	
-----------	--

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PEM 3578/01/091 Travis-Robins

TRIP No. PAM 3578/01/091 Robins-Travis

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN	-.0 HR
3 THRU 8 MIN	-.1 HR
9 THRU 14 MIN	-.2 HR
15 THRU 20 MIN	-.3 HR
21 THRU 26 MIN	-.4 HR
27 THRU 33 MIN	-.5 HR
34 THRU 39 MIN	-.6 HR
40 THRU 45 MIN	-.7 HR
46 THRU 51 MIN	-.8 HR
52 THRU 57 MIN	-.9 HR
58 THRU 60 MIN	NEXT WHOLE HOUR

AFTO FORM 781
JUN 73

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PZM 3578/01/091 Travis-Robins
 TRIP No. PAM 3578/01/091 Robins-Travis

HOURS AND MINS TO
 HOUR AND TENTH
 CONVERSION TABLE

1 OR 2 MIN-.0 HR
 3 THRU 5 MIN-.1 HR
 6 THRU 14 MIN-.2 HR
 15 THRU 20 MIN-.3 HR
 21 THRU 26 MIN-.4 HR
 27 THRU 33 MIN-.5 HR
 34 THRU 39 MIN-.6 HR
 40 THRU 45 MIN-.7 HR
 46 THRU 51 MIN-.8 HR
 52 THRU 57 MIN-.9 HR
 58 THRU 60 MIN-NEXT
 WHOLE HOUR

1. DATE			2. NDS			3. SERIAL NUMBER		4. DUP CODE		5. ASGT. CODE		6. ORGANIZATION		7. LOCATION		8. SHEET NO.		9. FLIGHT TIME		10. MISSION SYMBOL										
YR	MO	DAY	M	D	S																									
75	04	02	C	5	A	68 218						60 MALLY (MAC)		TRAVIS AFB CA				5.3		M-1										
2-3			4-5			6-8			9-11			12			13-15			16			17-18			19-21			22-24			
LOCAL USE	ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER			LAST NAME		DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS				APPR-OACHES				SORTIES		LOCAL USE		CREDIT
A	B	C(1)	C(2)			D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U							
25-26	27-30	31	32-40			41-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80							
	0075					Adams	FP	.	.	1.0	0.8	.	LN	1																
	"		"			"	CP	.	.	1.0	0.8	.																		
	"		"			"	AC	1.7																		
	"					ESTRUMSE	FP	.	.	1.0	0.8	.																		
	"		"			"	CP	.	.	1.0	0.7	.																		
	"		"			"	AC	1.8																		
	"					Floring	FP	.	.	1.0	0.7	.																		
	"		"			"	CP	.	.	1.0	0.8	.																		
	"		"			"	AC	1.8																		
	"					HOFFMAN	AN	.	.	5.3	.	.																		
	"					MORRISON	NN	.	.	5.3	.	.	LC	01																
	"					Dacy	FE	5.3																		
	"					BLACKARD	IS	5.3																		
	"					Wilson	FE	5.3																		

11. FLIGHT DATA BY SORTIE							12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS		
FLIGHTS	PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	LANDINGS			PILOT	MAINT	OPS	
	AA	AB	AC	AD	AE				FULL STOP	TOUCH GO	TOTAL				
						BA	BB	BC	BD	BE	BF	CA	CB	CC	
1	05		TRAVIS	Hickam	I	10:20	05:05	5:3	1	0	1			ND	
2								:							
3			A CERTIFIED TRUE COPY:					:							
4								:							
5								:							
6								:							
14. TOTAL															

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

PAM 378

LGC-1

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN	-.0 HR
3 THRU 8 MIN	-.1 HR
9 THRU 14 MIN	-.2 HR
15 THRU 20 MIN	-.3 HR
21 THRU 26 MIN	-.4 HR
27 THRU 33 MIN	-.5 HR
34 THRU 39 MIN	-.6 HR
40 THRU 45 MIN	-.7 HR
46 THRU 51 MIN	-.8 HR
52 THRU 57 MIN	-.9 HR
58 THRU 60 MIN	NEXT WHOLE HOUR

AFTO FORM 781
JUN 73

1. DATE			2. MDS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT. CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
YR	MO	DAY	M	D	S																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
75	04	02	C	5	A	68	218		1F	60 MAW (MAC)	TRAVIS AFB CA	1	7.8	M-6																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
25-26			27-30			31			32-40			41-45			46-47			48-50			51-53			54-56			57-59			60-61			62-63			64-65			66-67			68-69			70			71			72			73			74			75-79			80																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
LOCAL USE		ORGANIZATION		GOVT AGENCY		SOCIAL SECURITY ACCOUNT NUMBER		LAST NAME		DUTY CODE		DAY VFR		DAY INST		NIGHT VFR		NIGHT INST		SIMUL INST		LANDINGS		PENE-TRATIONS		APPR-OACHES		SORTIES		LOCAL USE		CREDIT																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
A	B	C (1)	C (2)	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AL	AM	AN	AO	AP	AQ	AR	AS	AT	AU	AV	AW	AX	AY	AZ	BA	BB	BC	BD	BE	BF	BG	BH	BI	BJ	BK	BL	BM	BN	BO	BP	BQ	BR	BS	BT	BU	BV	BW	BX	BY	BZ	CA	CB	CC	CD	CE	CF	CG	CH	CI	CJ	CK	CL	CM	CN	CO	CP	CQ	CR	CS	CT	CU	CV	CW	CX	CY	CZ	DA	DB	DC	DD	DE	DF	DG	DH	DI	DJ	DK	DL	DM	DN	DO	DP	DQ	DR	DS	DT	DU	DV	DW	DX	DY	DZ	EA	EB	EC	ED	EE	EF	EG	EH	EI	EJ	EK	EL	EM	EN	EO	EP	EQ	ER	ES	ET	EU	EV	EW	EX	EY	EZ	FA	FB	FC	FD	FE	FF	FG	FH	FI	FJ	FK	FL	FM	FN	FO	FP	FQ	FR	FS	FT	FU	FV	FW	FX	FY	FZ	GA	GB	GC	GD	GE	GF	GG	GH	GI	GJ	GK	GL	GM	GN	GO	GP	GQ	GR	GS	GT	GU	GV	GW	GX	GY	GZ	HA	HB	HC	HD	HE	HF	HG	HH	HI	HJ	HK	HL	HM	HN	HO	HP	HQ	HR	HS	HT	HU	HV	HW	HX	HY	HZ	IA	IB	IC	ID	IE	IF	IG	IH	II	IJ	IK	IL	IM	IN	IO	IP	IQ	IR	IS	IT	IU	IV	IW	IX	IY	IZ	JA	JB	JC	JD	JE	JF	JG	JH	JI	IJ	JK	KL	LM	LN	LO	LP	LQ	LR	LS	LT	LU	LV	LW	LX	LY	LZ	MA	MB	MC	MD	ME	MF	MG	MH	MI	MI	MJ	MK	ML	MM	MN	MO	MP	MQ	MR	MS	MT	MU	MV	MW	MX	MY	MZ	NA	NB	NC	ND	NE	NF	NG	NH	NI	NJ	NK	NL	NM	NO	NP	NQ	NR	NS	NT	NU	NV	NW	NX	NY	NZ	OA	OB	OC	OD	OE	OF	OG	OH	OI	OJ	OK	OL	OM	ON	OO	OP	OQ	OR	OS	OT	OU	OV	OW	OX	OY	OZ	PA	PB	PC	PD	PE	PF	PG	PH	PI	PJ	PK	PL	PM	PN	PO	PP	PQ	PR	PS	PT	PU	PV	PW	PX	PY	PZ	QA	QB	QC	QD	QE	QF	QG	QH	QI	QJ	QK	QL	QM	QN	QO	QP	QQ	QR	QS	QT	QU	QV	QW	QX	QY	QZ	RA	RB	RC	RD	RE	RF	RG	RH	RI	RJ	RK	RL	RM	RO	RP	RQ	RR	RS	RT	RU	RV	RW	RX	RY	RZ	SA	SB	SC	SD	SE	SF	SG	SH	SI	SJ	SK	SL	SM	SN	SO	SP	SQ	SR	SS	ST	SU	SV	SW	SX	SY	SZ	TA	TB	TC	TD	TE	TF	TG	TH	TI	TJ	TK	TL	TM	TN	TO	TP	TQ	TR	TS	TT	TU	TV	TW	TX	TY	TZ	UA	UB	UC	UD	UE	UF	UG	UH	UI	UJ	UK	UL	UM	UN	UO	UP	UQ	UR	US	UT	UU	UV	UW	UX	UY	UZ	VA	VB	VC	VD	VE	VF	VG	VH	VI	VJ	VK	VL	VM	VO	VP	VQ	VR	VS	VT	VU	VV	VW	VX	VY	VZ	WA	WB	WC	WD	WE	WF	WG	WH	WI	WJ	WK	WL	WM	WN	WO	WP	WQ	WR	WS	WT	WU	WV	WW	WX	WY	WZ	XA	XB	XC	XD	XE	XF	YG	YH	YI	YJ	YK	YL	YM	YN	YO	YP	YQ	YR	YS	YT	YU	YV	YW	YX	YY	YZ	ZA	ZB	ZC	ZD	ZE	ZF	ZG	ZH	ZI	ZJ	ZK	ZL	ZM	ZN	ZO	ZP	ZQ	ZR	ZS	ZT	ZU	ZV	ZW	ZX	ZY	ZZ

11. FLIGHT DATA BY SORTIE										12. FLIGHT TIME AND LANDING DATA BY SORTIE										13. TRANSCRIBING CHECK INITIALS					
PAX		CARGO WEIGHT		FROM		TO		ATC SERVICES		LANDING		TAKE-OFF		FLIGHT TIME		LANDINGS		PILOT		MAINT		OPS			
AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CB	CC	CD	CE	CF	CG	CH	CI	CJ	CK	CL			
1	Q2		Hickam	ANDERSON	I	2315	1524	07:8	1	0	1	T													
2																									
3																									
4																									
5																									
6																									
TOTAL																									

A CERTIFIED TRUE COPY:

Bernard A. Waxstein, Jr.

BERNARD A. WAXSTEIN, JR., Colonel, USAF

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No: PAM 3578/61/491

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN	-.0 HR
3 THRU 8 MIN	-.1 HR
9 THRU 14 MIN	-.2 HR
15 THRU 20 MIN	-.3 HR
21 THRU 26 MIN	-.4 HR
27 THRU 33 MIN	-.5 HR
34 THRU 39 MIN	-.6 HR
40 THRU 45 MIN	-.7 HR
46 THRU 51 MIN	-.8 HR
52 THRU 57 MIN	-.9 HR
58 THRU 60 MIN	-NEXT WHOLE HOUR

1. DATE			2. MDS			3. SERIAL NUMBER			4. DUP CODE		5. ASGT CODE		6. ORGANIZATION		7. LOCATION		8. SHEET NO.		9. FLIGHT TIME		10. MISSION SYMBOL								
YR	MO	DAY	M	D	S																								
75	04	03	C	5	A	68	218			IF	60 MACU(MAC)	TRAVIS AFB CA			1	04.0	M-6												
2-3			4-5			6-8			9-11			12			13-15			16			17-18			19-21			22-24		
LOCAL USE	ORGANIZATION	SOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER	LAST NAME	DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PNE-TRATIONS				APPR-OACHES				LOCAL USE	CREDIT					
						DAY VFR	DAY INST	NIGHT VFR	NIGHT INST	SIMUL INST	TYPE	NJ	TYPE	NO.	SIM	WEA	PRE	N-P	S	T	U								
A	B	C(1)	C(2)	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U								
25-26	27-30	31	32-40	41-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80								
	0022			TRAYNOR	* FP	0.9	00.5	.	.	.	LL	1							1										
			"	"	CP	01.3																			
			"	"	AC	01.3																			
				HARP	FP	01.3	00.5	.	.	.							1	1											
			"	"	CP	0.9																			
			"	"	AC	01.3																			
				MELTON	FP	01.3									1										
			"	"	CP	01.3																			
			"	"	AC	01.4																			
				MALONE	AC	04.0									1										
				WALLACE	NN	00.0									1										
			"	"	AN	04.0																			
				LANGFORD	NN	04.0	XC	1							1										
			"	"	AN	00.0																			

11. FLIGHT DATA BY SORTIE						12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS		
PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	FULL STOP	TOUCH GO	TOTAL	PILOT	MAINT	OPS	
AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CB	CC	
1	QR	GUAM	CLARK	I	06:37	02:39	4:0	1	0	1	T		JS	
2														
3	A CERTIFIED TRUE COPY:													
4														
5	BERNARD A. WAXSTEIN, JR., Colonel, USAF													
6														
14. TOTAL														

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN--0 HR
3 THRU 8 MIN--.1 HR
9 THRU 14 MIN--.2 HR
15 THRU 20 MIN--.3 HR
21 THRU 26 MIN--.4 HR
27 THRU 33 MIN--.5 HR
34 THRU 39 MIN--.6 HR
40 THRU 45 MIN--.7 HR
46 THRU 51 MIN--.8 HR
52 THRU 57 MIN--.9 HR
58 THRU 60 MIN--NEXT WHOLE HOUR

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN - .0 HR
3 THRU 8 MIN - .1 HR
9 THRU 14 MIN - .2 HR
15 THRU 20 MIN - .3 HR
21 THRU 26 MIN - .4 HR
27 THRU 33 MIN - .5 HR
34 THRU 39 MIN - .6 HR
40 THRU 45 MIN - .7 HR
46 THRU 51 MIN - .8 HR
52 THRU 57 MIN - .9 HR
58 THRU 60 MIN - NEXT WHOLE HOUR

1. DATE			2. MOS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT. CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL											
YR	MO	DAY	M	D	S																				
75	04	04	C	5	A	68	218	1F	60 MAW(MAC)	TRAVIS AFB CA	1	1.3	M-6												
2-3		4-5		6-8		9-11		12		13-15		16		17-18		19-21		22-24							
LOCAL USE		ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER		LAST NAME		DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS		APPR. OACHES		SORTIES		LOCAL USE	CREDIT
A		B	C(1)	C(2)		D		E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	
25-26		27-30	31	32-40		42-45		46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80	
	0022					TRAYNOR *	FP	0.5												
						"	CP	0.4												
						"	AC	0.4												
						HARP	FP	0.4												
						"	CP	0.5												
						"	AC	0.4												
						MELTON	FP	0.4												
						"	CP	0.4												
						"	AC	0.5												
						MAZONE	AC	1.3												
						WALLACE	NN	1.3												
						"	AN	0.0												
						LANGFORD	NN	0.0												
						"	AN	1.3												

11. FLIGHT DATA BY SORTIE						12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS		
PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	FULL STOP	TOUCH GO	TOTAL	PILOT	MAINT	OPS	
AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CB	CC	
1	02	Clark	SAIGON FIR	I	0328	0213	1:3	0	0	0	T		lt	
2							:							
3	A CERTIFIED TRUE COPY:													
4														
5														
6	BERNARD A. WAXSTEIN, JR., Colonel, USAF													
14. TOTAL														

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN—	.0 HR
3 THRU 6 MIN—	.1 HR
9 THRU 14 MIN—	.2 HR
15 THRU 20 MIN—	.3 HR
21 THRU 26 MIN—	.4 HR
27 THRU 33 MIN—	.5 HR
34 THRU 39 MIN—	.6 HR
40 THRU 45 MIN—	.7 HR
46 THRU 51 MIN—	.8 HR
52 THRU 57 MIN—	.9 HR
58 THRU 60 MIN—	NEXT WHOLE HOUR

1. DATE			2. MDS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL							
YR	MO	DAY	M	D	S																
75	04	04	C	5	A	68	218		IF	60 MAW(MAC)	TRAVIS AFB CA	2	1.3	M-6							
2-3		4-5		6-8		9-11		12	13-15		16	17-18		19-21	22-24						
LOCAL USE	ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER	LAST NAME	DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS		APPR-OACHES		SORTIES	LOCAL USE	CREDIT
						DAY VFR	DAY INST	NIGHT VFR	NIGHT INST	SIMUL INST	TYPE	NO.	TYPE	NO.	SIM	WEA	PRE	N-P			
A	B	C(1)	C(2)	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
25-26	27-30	31	32-40	41-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80
	0022			McAtee	FE	1.3											
				Engels	FE	1.3											
				Dionne	FE	1.3											
				Perkins	LM	1.3											
				Bradley	LM	1.3											
				Aguillon	LM	1.3											
				Doughty	LM	1.3											
				Payne	IS	1.3											
				Parker	LM	1.3											
				Snedegae	IS	1.3											
	0065			Wirtz	FN	1.3											
				Gmreck	MT	1.3											
	0010			Wise	MT	1.3											
	0010			Hune	FN	1.3											
				Hadley	MT	1.3											
11. FLIGHT DATA BY SORTIE											12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS				
FLIGHTS	PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	FULL STOP	TOUCH GO	TOTAL	PILOT	MAINT	OPS							
	AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CE	CC							
1	02		CLARK	SAIGON FIR	I	0328	0213	1:3	0	0	0	T									
2								:													
3								:													
4								:													
5								:													
6								:													
14. TOTAL																					

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN	-.0 HR
3 THRU 8 MIN	-.1 HR
9 THRU 14 MIN	-.2 HR
15 THRU 20 MIN	-.3 HR
21 THRU 26 MIN	-.4 HR
27 THRU 33 MIN	-.5 HR
34 THRU 39 MIN	-.6 HR
40 THRU 45 MIN	-.7 HR
46 THRU 51 MIN	-.8 HR
52 THRU 57 MIN	-.9 HR
58 THRU 60 MIN	NEXT WHOLE HOUR

1. DATE			2. MOS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT. CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL													
YR	MO	DAY	M	D	S																						
75	04	04	C	5	A	68	218		1F	60 th MAW(MAC)	TRAVIS AFB CA	01		M-6A													
2-3		4-5		6-8		9-11		12		13-15		16		17-18													
17-18		19-21		22-24																							
LOCAL USE	ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER	LAST NAME	DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS		APPR-OACHES		SORTIES	LOCAL USE	CREDIT						
						DAY VFR	DAY INST	NIGHT VFR	NIGHT INST	SIMUL INST	TYPE	NO.	TYPE	NO.	SIM	WEA	PRE	N-P									
A	B	C(1)	C(2)	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U						
25-26	27-30	31	32-40	41-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80						
	0022			TRAYNOR	FP	0.3	LL	1						1	1								
				"	CP	0.5																	
				"	AC	0.4																	
				HARP	FP	0.5									1								
				"	CP	0.4																	
				"	AC	0.5																	
				MELTON	FP	0.4									1								
				"	CP	0.5																	
				"	AC	0.5																	
				MALONE	AC	1.4									1								
				WALLACE	NN	1.4									1								
				"	AN	0.0																	
				LANEFORD	NN	0.0									1								
				"	AN	1.4																	
11. FLIGHT DATA BY SORTIE											12. FLIGHT TIME AND LANDING DATA BY SORTIE					13. TRANSCRIBING CHECK INITIALS											
PAX		CARGO WEIGHT		FROM		TO		ATC SERVICES		LANDING		TAKE-OFF		FLIGHT TIME		LANDINGS			PILOT		MAINT		OPS				
AA		AR		AC		AD		AE		BA		BB		BC		BD		BE		BF		CA		CB		CC	
1		02		SAIGON FIR		TAN SON NHUT		I		0451		0328		1:4		1		0		1		T				JG	
2																											
3																											
4																											
5																											
6																											
FLIGHTS																											
14.		TOTAL																									

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

15. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN	-.0 HR
3 THRU 8 MIN	-.1 HR
9 THRU 14 MIN	-.2 HR
15 THRU 20 MIN	-.3 HR
21 THRU 26 MIN	-.4 HR
27 THRU 33 MIN	-.5 HR
34 THRU 39 MIN	-.6 HR
40 THRU 45 MIN	-.7 HR
46 THRU 51 MIN	-.8 HR
52 THRU 57 MIN	-.9 HR
58 THRU 60 MIN	NEXT WHOLE HOUR

1. DATE			2. MDS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL											
YR	MO	DAY	M	D	S																				
75	04	04	C	5	A	68	218		1F	60 MAW(MAC)	TRAVIS AFB CA	2	1.4	M-6A											
2-3			4-8			9-11			12	13-15		16	17-18												
LOCAL USE		ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER		LAST NAME		DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS		APPR. DACHES		SORTIES		LOCAL USE	CREDIT
A	B	C(1)	C(2)		D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V		
25-26	27-30	31	32-40		41-43	44-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80			
	0022				McAtee	FE	1.4														
					Engels	FE	1.4														
					Dionne	FE	1.4														
					Perkins	LM	1.4														
					BRADLEY	LM	1.4														
					Aquillon	LM	1.4														
					Doughty	LM	1.4														
					Payne	IS	1.4														
					PARKER	LM	1.4														
					SNEDEGAR	IS	1.4														
	0065				WIRTZ	EN	1.4														
					SMRECK	MT	1.4														
					Wise	MT	1.4														
	0010				Wise	EN	1.4														
	0010				HADLEY	MT	1.4														
11. FLIGHT DATA BY SORTIE															12. FLIGHT TIME AND LANDING DATA BY SORTIE							13. TRANSCRIBING CHECK INITIALS			
FLIGHTS	PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	LANDINGS			PILOT			MAINT		OPS								
	AA	AB	AC	AD	AE	BA	BB	BC	FULL STOP	TOUCH GO	TOTAL	CA	CP	CC											
	1	02		SAIGON FIR	Tan Son Nhut	I	0451	0328	1:4	1	0	1	T												
	2								:																
	3								:																
	4								:																
	5								:																
6								:																	
14. TOTAL																									

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

1. DATE			2. MDS			3. SERIAL NUMBER			4. DUP CODE		5. ASGT. CODE		6. ORGANIZATION		7. LOCATION		8. SHEET NO.		9. FLIGHT TIME		10. MISSION SYMBOL				
YR	MO	DAY	M	D	S																				
25-28	29-31	32-34	35-37	38-40	41-43	44-46	47-49	50-52	53-55	56-58	59-61	62-64	65-67	68-70	71-73	74-76	77-79	80-82	83-85	86-88	89-91	92-94			
75	04	04	0	5	A	68	218			1F	60 MAW(MAC)	TRAVIS AFB CA			1		0.5				M.6A				
LOCAL USE		ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER		LAST NAME		DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PNE-TRATIONS		APPR. DACHES		SORTIES		LOCAL USE	CREDIT
A		B	C(1)	C(2)		D		E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	
25-28		29-31	32-34	35-37		38-40		41-43	44-46	47-49	50-52	53-55	56-58	59-61	62-64	65-67	68-70	71-73	74-76	77-79	80-82	83-85	86-88	89-91	92-94
0022						TRAYNOR *		FP	0.3	0.2	LL	1						1	1		
						"		CP	0.0											
						"		AC	0.0											
						HARR		FP	0.0								1			
						"		CP	0.5											
						"		AC	0.0											
						MELTON		FP	0.0								1			
						"		CP	0.0											
						"		AC	0.5											
						MALONE		AC	0.5								1			
						WALLACE		NN	0.0								1			
						"		AN	0.5											
						LANGFORD		NN	0.5								1			
						"		AN	0.0											

11. FLIGHT DATA BY SORTIE						12. FLIGHT TIME AND LANDING DATA BY SORTIE						13. TRANSCRIBING CHECK INITIALS		
PAX	CARGO WEIGHT	FROM	TO	ATC SERVICES	LANDING	TAKE-OFF	FLIGHT TIME	FULL STOP	TOUCH GO	TOTAL	PILOT	MAINT	OPS	
AA	AB	AC	AD	AE	BA	BB	BC	BD	BE	BF	CA	CB	CC	
1	02	Tan Son Nhut	Tan Son Nhut	P	0830	0803	0:5	1	0	1	T			
2							:							
3							:							
4							:							
5							:							
6							:							
14. TOTAL														

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

13. REMARKS OTHER THAN FLIGHT DISCREPANCIES

TRIP No. PAM 3578/01/091

HOURS AND MINS TO
HOUR AND TENTH
CONVERSION TABLE

1 OR 2 MIN—	.0 HR
3 THRU 6 MIN—	.1 HR
9 THRU 14 MIN—	.2 HR
15 THRU 20 MIN—	.3 HR
21 THRU 26 MIN—	.4 HR
27 THRU 33 MIN—	.5 HR
34 THRU 39 MIN—	.6 HR
40 THRU 45 MIN—	.7 HR
46 THRU 51 MIN—	.8 HR
52 THRU 57 MIN—	.9 HR
58 THRU 60 MIN—	NEXT WHOLE HOUR

1. DATE			2. MDS			3. SERIAL NUMBER		4. DUP CODE	5. ASGT CODE	6. ORGANIZATION	7. LOCATION	8. SHEET NO.	9. FLIGHT TIME	10. MISSION SYMBOL													
YR	MO	DAY	M	D	S																						
75	04	04	C	5	A	68	218		1F	60 MAW(MAC)	TRAVIS AFB CA	2	0.5	M-6A													
2-3			4-5			6-8		9-11		12		13-15		16													
17-18			19-21			22-24																					
LOCAL USE	ORGANIZATION	GOVT AGENCY	SOCIAL SECURITY ACCOUNT NUMBER			LAST NAME	DUTY CODE	FLIGHT CONDITIONS					LANDINGS				PENE-TRATIONS		APPR-OACHES		SORTIES	LOCAL USE	CREDIT				
A	B	C(1)	C(2)			D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U				
25-28	27-30	31	32-40			42-45	46-47	48-50	51-53	54-56	57-59	60-61	62-63	64-65	66-67	68-69	70	71	72	73	74	75-79	80				
	0022					McAtee	FE	0.5									/						
						Engels	FE	0.5									/						
						Dionne	FE	0.5									/						
						Perkins	FE	0.5									/						
						Beauley	LM	0.5									/						
						Aguillon	LM	0.5									/						
						Doughty	LM	0.5									/						
						Payne	IS	0.5									/						
						Parker	LM	0.5									/						
						Snedegar	IS	0.5									/						
						Wirtz	FN	0.5									/						
						Gorecki	MT	0.5									/						
						Wise	MT	0.5									/						
						Hilde	FN	0.5									/						
						Hodley	MT	0.5									/						
11. FLIGHT DATA BY SORTIE																											
PAX		CARGO WEIGHT		FROM		TO		ATC SERVICES		LANDING		TAKE-OFF		FLIGHT TIME		LANDINGS		TOTAL		PILOT		MAINT		OPS			
AA		AB		AC		AD		AE		BA		BB		BC		BD		BE		BF		CA		CB		CC	
1		02		Tan Son Nhut		Tan Son Nhut		P		0830		0803		0.5		1		0		1		T					
2																											
3																											
4																											
5																											
6																											
TOTAL																											

SEE REVERSE SIDE FOR REMARKS OTHER THAN FLIGHT DISCREPANCIES AND CONVERSION TABLE

EXTRACT

OF

22AF OPERATIONS CENTER

CONTROLLER'S LOG

FOR


3 APRIL 1975

EVENTS LOG

DATE 3 Apr 75 TIME	TOUR OF DUTY (Time)		NAME OF CONTROLLER Maj. Spinney, Lewis, Shobert
	FROM 03/1500Z	TO 03/2200Z	
RECORD OF EVENTS			

2000 Per Maj. Geron/MOC: COMAC has approved C-5 80218 to pick up any orphans available and processed to depart Saigon and move them to Clark. Put necessary medical supplies and nurses aboard at Clark. Col. Rash, (passed to Gen Gange) Col. Hoover; 4c Tonex; pmicoc/Capt. Johnson.

CERTIFIED AS A REPRODUCED COPY OF AN EXTRACT FROM 22 AIR FORCE OPERATIONS CENTER CONTROLLER'S LOG FOR 3 APRIL 1975.


BERNARD A. WAXSTEIN, JR., COLONEL, USAF

DOD INTERNATIONAL FLIGHT PLAN

FOR

FLIGHT FROM SAIGON TO CLARK

4 APRIL 1975

DOD INTERNATIONAL FLIGHT PLAN

PRECEDENCE: **FF** ADDRESS: **INDICATOR: (5)** **(FILED 0100 4METS)**

FLIGHT DATE/TIME: **APR 08 1975 1204/135** ORIGINATOR: **INDICATOR**

SPECIFIC IDENTIFICATION OF ADDRESSEE(S) AND/OR ORIGINATOR

ORIGINATOR: **FPL** — **M80218** — **I**

NO. AND TYPE ACFT: **C-5** — **R** / **R** / **J**

POINT OF DEPARTURE AND TIME: **VVVV 0330** → **RPMM 0439**

POINT OF DEPARTURE AND TIME: **0458 F330** → **RVOC TRACK 4 CASONG PE-9 R-68 LB**

POINT OF DEPARTURE AND TIME: **T-23 CRK**

POINT OF DEPARTURE AND TIME: **RPmk 0552** → **RPMB**

POINT OF DEPARTURE AND TIME: **NOT FOR TRANSMISSION**

POINT OF DEPARTURE AND TIME: **FUEL/0315** → **POB/16+PAX** → **RDO/** 1245 → 243 → 500 → 954

POINT OF DEPARTURE AND TIME: **POLAR** → **DESERT** → **MARITIME** → **JUNGLE** → **GLOBAL** → **JACKETS** → **LIGHT** → **FLUORESCIN**

POINT OF DEPARTURE AND TIME: **DINGHIES** → **COVER** **YELLOW 4/100** → **RMK/** **CDPIR & FLARES**

REMARKS: **REG. RADAR MONT. DEPARTURE**

AIRCRAFT SERIAL NUMBERS AND TYPE OF AIRCRAFT IN FLIGHT: **AF 68-218**

CREW LIST: ☒ ATTACHED ☐ LOCATED AT: **PAC**

AIRCRAFT HOME STATION OR ORGANIZATION: **60 MAW/SUU** NAME OF PILOT IN COMMAND: **TRAYNOR** SIGNATURE OF PILOT IN COMMAND OR DESIGNATED REPRESENTATIVE: **[Signature]**

PILOT'S PREFLIGHT CHECK		BASE OPERATIONS USE		APPROVAL	
<input checked="" type="checkbox"/>	NOTAMS	<input type="checkbox"/>	CURRENT P/FCIC CARD	F P L	REQUEST CLEARANCE AFTER (3)
<input checked="" type="checkbox"/>	AIR SPACE RESTRICTIONS	<input type="checkbox"/>	SPECIAL BRIEFINGS		
<input checked="" type="checkbox"/>	AIRCRAFT/DEST NAV AIDS	<input type="checkbox"/>	DIP CLNC/US CODE /PPR		
<input checked="" type="checkbox"/>	WEATHER AND WINDS	<input type="checkbox"/>	BZ FLT/GAT/OAT	T A W R	MISSION/CONTROL AUTHORITY
<input checked="" type="checkbox"/>	SIDS, FLIPS AND CHARTS	<input type="checkbox"/>	VIP CODE/BLOCK TIME		
<input checked="" type="checkbox"/>	FLIGHT PLAN LOG	<input type="checkbox"/>	PAX MANIFEST		
<input checked="" type="checkbox"/>	POPPY SEED REPORTS	<input type="checkbox"/>	CUSTOMS FORM		SIGNATURE OF APPROVING AUTHORITY
<input checked="" type="checkbox"/>	FOREIGN CLNC GUIDE	<input type="checkbox"/>	FLT ORDERS OR CREW LIST		
<input checked="" type="checkbox"/>	COMMAND LOCAL DIRECTIVES	<input type="checkbox"/>	FUEL REQUIREMENTS		

WEIGHT AND BALANCE CLEARANCE FORM F

DD FORM 365F

FOR

FLIGHT FROM SAIGON TO CLARK AB

4 APRIL 1975

(USE REVERSE FOR TACTICAL MISSIONS)

FOR USE IN
T. O. 1-1B-40
AN 01-1B-40

DATE 4 APR 75		AIRCRAFT TYPE C-5A		FROM SARAGON		HOME STATION TRAVIS						
MISSION/TRIP/FLIGHT/NO. PCA 3578		SERIAL NO. 6F-218		TO CLARK		PILOT CAPT TRAVIS						
LIMITATIONS				REF	ITEM	WEIGHT	INDEX OR MOM/100M					
CONDITION	TAKEOFF	LANDING	LIMITING WING FUEL									
1 ALLOWABLE GROSS WEIGHT	712 500	635 850	498 000	1	BASIC AIRCRAFT (From Chart C)	33 935 0	47 64					
TOTAL AIRCRAFT WEIGHT (Ref. 11)	441 341			2	OIL (F11 Gal.)	205	3					
OPERATING WEIGHT PLUS ESTIMATED LANDING FUEL WEIGHT		373 141		3	CREW (No. V6 (2076-20))	3 200	24					
OPERATING WEIGHT (Ref. 8)			345 141	4	CREW'S BAGGAGE TP 1	800	4					
ALLOWABLE LOAD (Ref. 18) (use SMALLEST figure)	271 159	262 709	152 859	5	STEWARD'S EQUIPMENT	584	4					
PERMISSIBLE C. G. TAKEOFF	FROM 19 7 TO (% M.A.C. 41)			6	EMERGENCY EQUIPMENT	532	9					
PERMISSIBLE C. G. LANDING	FROM 14 9 TO (% M.A.C. 41)			7	EXTRA EQUIPMENT	970	8					
LANDING FUEL WEIGHT	28 000	12		8	OPERATING WEIGHT	345 141	48 14					
REMARKS Ramp Fuel 99M AIT Fuel 502	DISTRIBUTION OF ALLOWABLE LOAD (PAYLOAD)			9	TAKEOFF FUEL (Gal.)	9 620 0	14 18					
	UPPER COMPARTMENTS			10	WATER INJ. FLUID (Gal.)							
	PASSENGERS			11	TOTAL AIRCRAFT WEIGHT	441 341	62 32					
	NO. WEIGHT			LOWER COMPARTMENTS								
	A			PASSENGERS								
	B			NO. WEIGHT CARGO								
	C			E		150 4350	17 6					
	D			F								
	E			G								
	F			H		690 12000	12 000					
TOTAL FREIGHT	L/A											
TOTAL MAIL	L/A											
COMPUTER PLATE NUMBER (If used)	L/A											
1 Enter constant used. 2 Enter values from current applicable T. O. 3 Applicable to gross weight (Ref. 13). 4 Applicable to gross weight (Ref. 20). 5 Ref. 9 minus Ref. 17.				13	TAKEOFF CONDITION (Uncorrected)	23250	22.74					
CORRECTIONS (Ref. 14)				14	CORRECTIONS (If required)	464591	6506					
COMPT	ITEM	CHANGES (+ or -)	WEIGHT	INDEX OR MOM/100M	15	TAKEOFF CONDITION (Corrected)						
					16	TAKEOFF C. G. IN % M. A. C. OR IN.	39 9.					
					17	LESS FUEL	68200	1015				
					18	LESS AIR SUPPLY LOAD DROPPED						
					19	MISC. VARIABLES						
					20	ESTIMATED LANDING CONDITION	396391	5491				
					21	ESTIMATED LANDING C. G. IN % M. A. C. OR IN.	35 9.					
					COMPUTED BY				WEIGHT AND BALANCE AUTHORITY			
					TOTAL WEIGHT REMOVED				TOTAL WEIGHT ADDED			
					NET DIFFERENCE (Ref. 14)				SIGNATURE			

NOTE.--THIS TRANSPORT CLEARANCE FORM HAS RESULTED FROM TRIPARTITE AGREEMENT AND NO FURTHER CHANGES MAY BE MADE TO IT WITHOUT PRIOR CONSIDERATION BY TRIPARTITE AUTHORITIES.

FLIGHT WEATHER BRIEFING

DD FORM 175-1


FLIGHT FROM CLARK

TO SAIGON AND RETURN


FLIGHT WEATHER BRIEFING

I. MISSION							
DEP/ETA 2300 ⁰²⁰⁰ Z	DEST/ETA 0130 Z	ALTN/ETA 0216 Z	BRIEFING NO.	DATE 03 Apr 75	ACFT NUMBER C5/80218		
II. TAKEOFF DATA							
RUNWAY TEMP 25 °C	DEWPOINT _____ °C	SFC WIND VR003	TEMP DEV +15 °C	PRESSURE ALT +410 FT	DENSITY ALT _____ FT	RCR _____	
CLIMB WINDS 17017			LOCAL WEA WARNING OR MET WATCH ADVISORY _____				
REMARKS/TAKEOFF ALTN FCST _____							
III. ENROUTE DATA							
FLT LEVEL 310		FLT LEVEL WINDS/TEMP CFP					
CLOUDS AT FLT LEVEL <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> IN AND OUT		MINIMUM VISIBILITY AT FLT LEVEL OUTSIDE CLOUDS _____ MILES, DUE TO <input type="checkbox"/> SMOKE <input type="checkbox"/> DUST <input type="checkbox"/> HAZE <input type="checkbox"/> FOG <input type="checkbox"/> PRECIPITATION <input type="checkbox"/> NO OBSTRUCTION					
MINIMUM CEILING FT AGL		LOCATION	MAXIMUM CLOUDS TOPS FT MSL		LOCATION	MINIMUM FREEZING LEVEL FT MSL	
THUNDERSTORMS (within fifty miles of route)		TURBULENCE (within ten miles of route not associated with TSTMS)		ICING (within ten miles of route not associated with TSTMS)		PRECIPITATION (within ten miles of route not associated with TSTMS)	
MWWA NO.		CAT ADVISORY		Z NONE		NONE	
<input type="checkbox"/> NONE	<input type="checkbox"/> AREA	<input type="checkbox"/> LINE	<input type="checkbox"/> NONE	<input type="checkbox"/> IN CLEAR	<input type="checkbox"/> IN CLOUD	<input type="checkbox"/> RIME	<input type="checkbox"/> MIXED
ISOLATED 1-2%		LIGHT		TRACE		LIGHT	
FEW 3-10%		MOD		LIGHT		MOD	
SCATTERED 16-45%		SVR		MOD		HEAVY	
NUMEROUS-MORE THAN 45%		EXTREME		SVR		SHWS	
HAIL, SVR TURB, SEVERE ICING, AND PRECIPITATION EXPECTED IN AND NEAR TSTMS		LEVELS		LEVELS		PRECIP	
LOCATION		LOCATION		LOCATION		LOCATION	
IV. TERMINAL FORECASTS							
DESTINATION	CLOUD LAYERS		VIS/WFA	SFC WIND	ALTIMETER	VALID TIME	
VVVS	(CIG) 2SC040 3AC130 5CS280		7	34008	2979 INS	0030 Z TO 02300 Z	
✓							
ALTERNATE	(CIG)						
VTDU	2SC020 5AC100 6CS280		7	VR005	2982 INS	0116 Z TO 0316 Z	
INTMED STOP					INS	Z TO Z	
INTMED STOP					INS	Z TO Z	
V. COMMENTS/REMARKS							
T 28 C PA + 160'							
<i>This is a certified true copy</i> <i>J. Fambill</i> ltc							
VI. BRIEFING RECORD							
BRIEFED ON LATST RCR FOR DEST AND ALTN <input checked="" type="checkbox"/> YES <input type="checkbox"/> NOT AVAILABLE				VOID TIME			
REQUEST PIREP AT <input checked="" type="checkbox"/>				EXTENDED TO			
SEE FLIMSY NO	WEA BRIEFED	FORECASTER'S SIGNATURE		WEA REBRIEFED AT			
041-3C	2101	STEPHEN DIEDA, Sgt		FORECASTER'S INITIALS <i>SD</i>			
WEA FCSTY	TAPE NO.	START	STOP	PHONE CHARGE	NAME OF PERSON RECEIVING BRIEFING		

ROUTE OF FLIGHT



IMPACT AND WRECKAGE MAP




ROUTE OF FLIGHT

WRECKAGE DIAGRAM


WRECKAGE DIAGRAM

C-5A SN 68-218 4 APRIL 1975




CRASH SCENE PICTURES


1. *Overview of crash scene showing touchdown point, Saigon River and primary wreckage*
2. *Major wreck area showing empennage, troop compartment, flight deck and wing section with Saigon River in foreground.*
3. *Overhead view of troop compartment, flight deck and burned wing section.*
4. *Major wreck area showing empennage, troop compartment, flight deck and wing section*
5. *Overhead view of empennage*
6. *Closeup of empennage*
7. *Closeup of troop compartment*
8. *Closeup of flight deck*
9. *Closeup of wing section*



Overview of crash scene showing touchdown point (lower left),
Saigon River and primary wreckage (upper center)




Major wreck area showing empennage, troop compartment, flight deck and wing section with Saigon River in foreground.




Overhead view of troop compartment (upper right center), flight deck (lower right center) and burned wing section (left center). The brown areas around the troop compartment and the flight deck do not represent areas of burn. Only the wing section subsequently burned.




Major wreck area showing empennage, troop compartment, flight deck and wing section.




Major wreck area showing empennage, troop compartment, flight deck and wing section.



OVERHEAD VIEW OF EMPENNAGE




Closeup of empennage



Closeup of troop compartment



Closeup of flight deck



Closeup of wing section

C-5A 218

CDPIR

AUDIO TRANSCRIPT

Well, the way all these people are milling around, it would be to our advantage to get these doors closed -- then we would not have to wait for 'em later.

OK. Let me get - well -- John, can you - you're the only one at your panel -- find a couple of loadmasters and tell 'em we want the doors closed.

You want the rear doors closed, is that right?

Right.

OK.

Jump position - we're gonna close the doors - ah - engineer load, can I.

Go ahead - this is the engineer.

Yeah, give 'em No. 1 hydraulic system - we're ready to close these doors.

OK -- they were saying something about loading some chains and stuff yet.

We just finished now.

Finished. OK, you got No. 1?

OK.

Scanners in position?

Scanners in position -- get 'em closed.

Copilot - engineer

Stab's gonna be .05 39%.

How much weight did we figure on all these -- about 33,000?

Ah - that we put on?

Yeah.

About 31 and it's a hell of a lot less than that.

Just wondering - ah Nav can we make 37 'cause I was talking to a 141 crew and they came in at 35 and they were right in the stuff too before coming in

Let me check.

And said they were really in a lot of turbulence

What kind of a temp deviation were they running? 15?

I didn't think to ask them.

I'd - I'd figure a plus 15 engineer without even looking at it.

Yeah, it's pretty hot out there.

We might be ahead if we could get 37 and stay above all that weather.

I don't think we can get up that high, Sir, but I'll check it.

According to my chart - ah - we can make - ah - 37 right on the button. At ah the weight we're at, 15 plus 15, and we're gonna be a lot less 'cause we figure a hundred pounds apiece for each of those kids and it's gonna take about 10 of them kids to make a hundred pounds.

Yeah, but then you got the problems of ah - Jesus, we're up at 370 and we have a rapid decompression, ah we're gonna lose someone.

How are we doing on the ramp?

What's gonna happen at 35? It's gonna be the same thing, isn't it?

About 33, I'm just thinking there.

Eng, let me cut in here, you're ok loadmaster.

Keep it going.

Yeah according to the chart if we're at 460 some odd thousand pounds per the engineer we can make 37.

OK.

I guess maybe 33 would really be the best bet. If we really get bounced around in the weather, we'll ask for 37 and --- worry about the rapid decompression if it happens but we'll have definitely have to get down from 37 'cause they don't have oxygen masks in the cargo compartment -- those babies they ain't gonna get 'em all out in time.

They ain't got anything downstairs for all those people in the cargo compartment anyway and there's not enough upstairs for those people either so -

Yeah

Loadmaster Do Not Stop The Operation - Do Not

I'm gonna go down there and see if I can help - their having some problems down there.

What kind?

I'm not sure.

Troop Compartment Copilot

Loadmaster, turn around and tell them to open that crew troop door again please. We got a man that needs in.

OK, I got you.

(Tower)

He's one of the news men. They just gave him a walk through, I think.

Good.

FOR OFFICIAL USE ONLY
(THIS IS A PRIVILEGED DOCUMENT
NOT RELEASEABLE IN WHOLE OR IN PART TO
PERSONS OR AGENCY OUTSIDE THE AIR FORCE
WITHOUT THE EXPRESS APPROVAL OF THE

Are they trying to get them off now?

Good.

Never heard of them.

Wonder how they're doing on the Colonel's passport?

It's not the Colonel's -- it's some of the people on board. I guess there's some Vietnamese hangups.

Yeah, there's some Vietnamese Army here -- they're trying to take some of them off -- I don't think they're having any luck though.

Well, I'll check again on the clearance when you're done.

Good.

Ground MAC 218.

Saigon.

Have you heard anything on the clearance on 218.

Pilot - troop, ready to copy now?

Stand by troop.

Right, 218 is ready to copy.

OK loadmaster your doors are locked. Roger.

80218 (tower)

Engineer your left APU is clear.

Flight plan route climb maintain FL 330 departure 134.1/363.8 squawk 0400 (tower)

Can you safe the ait door please?

Disarm the doors please.

Understand. MAC 80218 is cleared to the Clark Airport (engineer-scanner) via track 4 flight plan route, climb and maintain flight level 330. Departure 134.1/363.8. Squawk 0400.

Readback is correct. (tower)

Hey, you got a fire bottle by that thing?

That's affirm.

OK, we'll be starting in about 10 minutes.

OK, we got our clearance - as filed.

Nav copied the clearance.

Pilot-Troop - Go ahead troop this is copilot. Pilot's getting hooked in.

OK, Sir, we're ready back here as best we can be.

OK, is it halfway comfortable back there for 'em?

Yes, sir, it's pretty good air back there.

OK.

OK, I got 'em on speed right now.

OK, you're looking good out here -- there's a little smoke but it seems stable

OK, keep an eye on it for me.

Roger

Nav-Pilot

Go.

How's the ball?

It's on the way. I'd say you got about 8 minutes.

OK.

Before Starting Engines Check.

Forms 781 and 365F - checked and signed.

Oxygen - checked and on - copilot -- checked and on - pilot

Radios, radar altimeters, and IFF - on and standby - copilot - on and stand by - pilot

Primary radio Victor Two Guard on Uniform Two

Roger

Flight augmentation - off

Thrust reverser limiter - set

Throttles - start

OK, Sir, the Colonel's got his passport. He's coming on board.

OK

Brake switch - Emergency

Anti skid switch - off

Parking brake - set

Gear pins, chocks, and stabilizer struts - removing and stowing

Cockpit windows - closed and locked copilot - closed and locked pilot.

Navigation and Anti-collision lights - steady and all

Inboard Elevator left system 3 and right system 2 hydraulic power switches - off

Windshield heat - normal

Crew start report - Nav ready - engineer ready - troop ready (God only knows how many people and crew)

Rog -

Aft flight deck?

I don't think there is anybody up back there yet

I'll get someone in a minute.

Scanners ready

OK scanner - ah

Before starting engines check completed.

Would you ask somebody out there to act as a wing marshaller for my left wing please? Maybe you can get that Colonel out there to do it for us.

OK, Sir, just a minute, I'll see if I can get him.

Saigon ground MAC 8021 - 218 starting engines

0218 clear to start altimeter 2978 (tower)

Understand 2978 altimeter - 218

Sounds like he said denied

Yeah

Starting engines check

Clear to start engines

Engines clear to start

Starting No. 1

OK, the Colonel's ...be on interphone.

I didn't even tell them they were there.

No I don't think there was any problem at all.

I don't either - I like what they saw down there - that was very orderly and nice sitting on, -

Starting No. 2

Needless to say we're not getting a brake check?

Right. I hadn't planned on one.

No - let's just a periodical scan and check the area scanner

This is the second stop - I don't think anything happened.

Aft flight deck on, how do you read.

Say again

Loud and clear (this is Sgt Perkins)

OK, starting No. 3

About how much gas do we have engineer, do you remember?

We had 98.4 a while ago - I guess we probably have about 98.5 now, 95 rather

OK

Aft flight deck copilot - if you would make sure the rest of the crew is onboard.

Roger, sir.

Have the rest of the stations checked in engineer?

Ah - we're - we're gonna go through all these before we taxi to make sure - Tell you what - why don't we get a roll call by the people on the inter-phone?

OK - let's see here

Pilot-Load -
Cargo Compartment-Load

Switchin power, Nav.

Continuous ignition - on

Engineers report - in progress

OK, we're gonna go through and Traynor's here, Harp's here, Melton's here - is he around - does anyone see him

Check Melton

He's on

Good, ok, Wallace - I saw him downstairs

Langford. Here

McAtee - does somebody see him?

Yes, Sir, he's on the cord.

OK, Engels - he's on the panel. Dionne - someone see him?

I have him with me

OK, Perkins

Here

Bradley

Downstairs ready at the door

OK, ah, Aguillon

Yes, Sir, I'm on the aft section of the airplane

OK, Doughty?

Troop compartment.

OK Payne - Wendell Payne - where's he?

He's down here in

How about Parker?

Troop compartment

OK, where's Payne?

Payne's downstairs, here.

OK, make sure someone has seen him. OK, that's everybody.

Still holding on engineers report

Check completed

Starting engines, check completed.

OK, before taxi check

Kneeling system checked unknelt, flight augmentation - on

Ground Clearance -

All clear

Clear to board -

Boarding airplane

Nose gear pin removed, boarding airplane

OK - I'll buy that.

ADS panel - Safe

Seat belt light - On

IDNE mode status - Inertial

Hams check -

Checks OK - let's go

Completed

Door open lights

Hell, our damn troop or crew door just started screwing up.

And it's on film, too.

I know that's what worries me.

Pilot - Cargo Compartment

Go ahead

I'm going to give a very, very short briefing if it won't interfere with you.

No, go right ahead.

Door open lights off

Brake switch - normal

Crew taxi report - Nav ready, engineer ready

Troop compartment?

Go

Rog, we're running a crew taxi report

Troop compartment ready

Scanners ready

Cargo compartment ready and aft flt deck ready.

Thank you

Before taxi check completed.

Tell them. We're ready for taxi?

Saigon Ground MAC 80218 ready for taxi

Saigon Ground Runway 07R altimeter 2978 Contact Saigon tower for taxi, over.

218, Altimeter 2978 going to tower frequency

Saigon tower, MAC 80128 ready to taxi for takeoff

Saigon tower, 218 Roger

Anybody copy that?

Saigon tower, 218 say again please.

Did you make your (paused) 218, Saigon, do you have you started engines?

218 We have started engines and we have called ready for taxi for takeoff over.

Roger, 218, Saigon, you taxi now to runway 07 and make 180 for departure.

OK. 218, understand we are cleared to taxi down runway 7R, 218

Roger, clear Left, clear Right

Now let's see, you can come a little bit right

He says you're clear left

Clear to the right

Taxi just a tad bit further to the right, OK?

He says come right.

You're clear

Straight ahead he said on the left

Rear wheel well clear

Taxi check

Brakes-checked

Flight instruments - checked copilot checked pilot

taxi check completed

Before takeoff check

Flaps and Slats 40 percent extend - copilot 40 percent extend - pilot

Seat belts and shoulder harnesses? Adjusted

Crew briefing crew attention to takeoff briefing: CP, N, Eng

OK this will be a reduced rolling takeoff 4.47 Vgo and rotate 112. Minimum flap retract 147. Cmd marker 112 Radar Altimeter is set 200 feet. Climb planning to use tactical departure direct to Vung Tau will be climbing at 200 knots after a 180 down here we will be cleared for takeoff and after we are airborne I would like each compartment to check in and give us status of people on board. Emergency return will be a left VFR pattern with plans to land on this runway. The terrain remains as briefed when we came in. Minimum altitude is 3500 feet within 25 nautical miles. Are there any questions?

Pilot - engineer

Go ahead

This is going to be a TRT rolling, right?

OK - I'm going to TRT right after we break ground so that your 112 is good.

Copilot checked it also 2.87 is good.

4.87 is good - OK - I'll make the TRT.

Crew briefing completed

Radios, radar, radar altimeters and IFF checked and set - copilot
Checked and set - pilot with the exception of the radar - we'll get it later. Ram air turbine switch auto.

Altimeters 2978 reading 70 ft - copilot, 2978 - pilot, 2978 - Nav

Let's have the readings please real quick, 80 ft - Pilot, 20 ft - Nav

Flight controls? Checked

Caster

Trim - checked and set

Spoilers - closed

Rudder Lim Switch - Auto

Warning light -- Center - Checked

Crew takeoff report - Nav ready, Engineer ready Troop Compartment?
Troop compartment ready.

MAC ah 218 (tower)

He's calling us

Tower 218, go ahead

Line up check

Departure 134.1 363.8 squawk 0400 (tower)

Understand MAC 80218 is cleared for takeoff. Runway 7R. Right turn on course. Departure 134.1, Good Day!

Winds are 110/10. Clear for takeoff.

218 clear for takeoff.

Crew takeoff report

Nav-ready, Engineer-ready, Troop compartment ready, Cargo Compartment-ready, Aft flight deck-ready, Scanners-ready.

Before takeoff check completed

Line up check

IFF-set

AFCS master power pushbutton on light - Off

Trim settings-checked

Flaps and slats - 40 percent, extend

What's our stab setting engineer?

0.05 down?

Pitot heat and Angle of attack de-ice - On

Anti skid switch - On

Caster control-center

Landing gear cross wind positioning - set zero degrees. Lineup check completed

Clear for takeoff and let me check departure.

OK

Saigon departure MAC 80218 ground radio check, 80218 Loud and clear, over.

218, we'll call you when airborne.

Primary radio Victor two guard on uniform - Two. Clear for takeoff

Advancing throttles now. How about switching that back from PA to interphone for me? OK!

4.87

15 - 20 - Time

Go

Gear up?

Gear up.

Gear is up.

Roger

Help us clear jump seat

OK

Nav you got Vung Tau on the computer, right?

Roger that. Track steer to Vung Tau. If you want it give you destination steer.

Now you got your air speed clear right?

Destination steer Vung Tau.

Flaps and slats up and retracted

Accelerating to 200 knots

Saigon departure, MAC 80218 is airborne

MAC 80218, Saigon radar contact on departure, Squawk low. Report reaching FL 80 over?

218 will call reaching FL 080

We want to try and be smooth.

Probably would be a good idea

OK passing

Transition 29.92 set-Copilot, 2992-Pilot, 2992-Nav it's a good heading to Vung Tau. OK. Do you see anything out there? No. and I talked to the 141 crew and they said that at 350 they were right in the stuff so -

We can get higher

Well the Nav says, Engineer says we can make 37 but I was thinking about the oxygen masks for the

For the what?

For the cargo compartment, they don't have anything.

FOR OFFICIAL USE ONLY
(THIS IS A PRIVILEGED DOCUMENT
NOT RELEASEABLE IN WHOLE OR IN PART TO
PERSONS OR AGENCY OUTSIDE THE AIR FORCE
WITHOUT THE EXPRESS APPROVAL OF THE
SECRETARY OF THE AIR FORCE)

We'll just go down.

Yeah

Well I was thinking that if we're at 37, we are gonna have to get down awful fast.

Yeah

Probably valid

Same way with the babies up there - they got the masks but they ain't got enough masks.

Do we have a 25,000 restriction on this? .

No

There's no oxygen masks.

Yeah, we know. There's no life rafts either.

I was thinking about a 25,000 ft restriction.

Saigon, 80218 passing flight level 080

MAC 80218, thank you, continue climbing (tower)

218, Wilco

Go to 330, Huh.

Rog

OK, how's my time - let's go to MRT.

OK, you're 4 minutes now MRT.

OK

You're riding MRT right now 500.

OK

N1 in a minute.

10,000 ft

Rog

Visual on Vung Tau.

How's the air in the troop compartment?

It's just right.

Babies still squalling or have they quieted down with all the noise?

They're sleeping.

It's just as well.

FOR OFFICIAL USE ONLY
(THIS IS A PRIVILEGED DOCUMENT
NOT RELEASEABLE IN WHOLE OR IN PART TO
PERSONS OR AGENCY OUTSIDE THE AIR FORCE
WITHOUT THE EXPRESS APPROVAL OF THE
SECRETARY OF THE AIR FORCE)

In the cargo compartment they're all puking.

Are they?

Right, hey, do we have any bags or anything on board?

Yeah, we do - I had 'em give out as many as they had and there's not many.

Better keep it cool enough down there too, Engineer.

OK

OK passing 12,000.

Passing 120 for 330

That checks. Destination - ah, track steer.

I'm gonna give you a (garbled) back on Vung Tau.

OK

Track steer

N1 will be 95.2

OK 95.2?

Roger-that

That doesn't compute.

You're MRT is now 509 for that fan setting

OK

MAC 08218 squawk 1,000 say passing altitude

218 is passing flight level 140

I'd just like to thank everyone that's on the interphone right now. I think we did an outstanding job, everybody, especially the Loads.

MAC 80218 contact Saigon center 125.9 or 124.5.

125.9, Good Day

Saigon control, MAC 80218 is leaving flight level 150 for 330

MAC 218 report reaching 330

218 Wilco

What's the heading out of Vung Tau?

136 on the Mag

FOR OFFICIAL USE ONLY
(THIS IS A PRIVILEGED DOCUMENT
NOT RELEASEABLE IN WHOLE OR IN PART TO
PERSONS OR AGENCY OUTSIDE THE AIR FORCE
WITHOUT THE EXPRESS APPROVAL OF THE
SECRETARY OF THE AIR FORCE)

OK and Keith would you call in a message to Clark?

What was that, Call in a message to Clark?

Do you want to do that or just wait till we get in close?

They said they wanted a maintenance call in and everything and our off time so I guess we ought to do that now.

Let's wait until we are established away from land 'cause (garbled) gonna be some landing and everything. We don't need to hurry.

OK

Pilot Cargo

Go ahead

Yes, sir, I'm going to move my interphone cord up the middle if it's all right with you. I'm gonna be off for about a minute.

OK. Do you need any more help, or do you need anything else down there?

No, sir. We're pretty good.

OK

How's the temperature down there troop?

I guess someone would be complaining if the temperature were bad.

Yeah. Don't want it to get too cold for 'em down there, though.

You're doing fine right now, sir..

Nav, CP, you might put the radar on weather.

Think we're gonna be out of most of the stuff for a while.

Have to go through it sooner or later though, I'm afraid.

What MACH you flying now, sir?

I'm flying 250, .53

I think we're at the appropriate place. Let's make it climb power and after takeoff climb check.

OK. We're at Vung Tau

OK

And what's our climb power, Engineer?

504 putting it on the bar.

Is that NRT?

NRT 504

Rudder lim switch - auto.

Flaps and slats-up and retracted.

FOR OFFICIAL USE ONLY
(THIS IS A PRIVILEGED DOCUMENT)
NOT RELEASABLE IN WHOLE OR IN PART TO
PERSONS OR AGENCY OUTSIDE THE AIR FORCE
WITHOUT THE EXPRESS APPROVAL OF THE
SECRETARY OF THE AIR FORCE)

LDCS - Set

Seat Belt and No Smoking light - Off.

Engineer's report - in progress, 96.4 new fan speed.

Thank you, and I'm gonna slowly pick up 270.

Did anybody happen to notice what time we started what time we were rolling?

We started engines at approximately 1555 and we rolled or, excuse me, 1545 and we rolled at 05.

(a loud noise is heard at this point) (source unknown but not related to RD)

Is something wrong? (statement made by copilot concerning unrelated subject)

Engineer's check completed - May we have EMAC auto, please?

You got it.

After takeoff climb check completed.

Sgt Snedegar was asking what altitude we could go to with no oxygen Shall we tell him 13? I hope he's kidding. There is, its 13,000.

Yes, and that's not for very long - it's something like 2 hours.

3 hours

3 hours?

We have some weather on both sides of the nose and about a 20 but I think we're climbing up through it.

Right

THIS IS WHERE THE TAPE SEEMS TO REPLAY ITSELF

Do we have a loadmaster on a headset (and starts talking about the way the people are milling around outside)

CERTIFICATE


OF

AIRCRAFT DAMAGE

CERTIFICATE OF AIRCRAFT DAMAGE

The aircraft was totally destroyed beyond any capability to repair. Total cost to replace airframe with associated equipment and systems is (Reference T.O. 00-25-30, Table I and III, dated 30 June 1974):

Basic Airframe (Table I)	\$29,879,000
Installed Engines (Table I)	6,636,000
Specific R & D Costs (Table III)	12,037,000
Specific Class V Mod Costs (Table III)	419,299
OTHER (Table I)	<u>43,000</u>
TOTAL	\$49,014,299



TED N. CLAY, Colonel, USAF
Accident Board Maintenance Officer

STATEMENT

OF

PRIVATE PROPERTY DAMAGE

STATEMENT OF PRIVATE PROPERTY DAMAGE

1. C-5A SN 68-218 was returning to Tan Son Nhut AB for an emergency landing. The pilot was unable to maintain aircraft control and the aircraft crash landed in a rice paddy/marsh area approximately 2 NM Northeast of Tan Son Nhut Air Base. Coordinates of initial impact are 11°99'20"N 106°42'40"E. Aircraft continued to travel for 1 1/4 miles on a 280-degree heading shedding debris until it came to rest at coordinates 11°99'20"N 106°40'30"E.

2. Aircraft landing gear gouged out an area approximately 300 feet long and 20 feet wide at the point of initial impact. Aircraft became airborne for approximately 750 yards, crossed the Saigon river and impacted on the other side. Wreckage strewn on the west side of the river encompassed an area approximately 1,000 yards long and 500 yards wide. Final wreckage came to rest in a Vietnamese cemetery and broke several gravestones/grave markers.

3. All baggage and personal belongings aboard the aircraft were either destroyed by the impact or pilfered by local populace prior to recovery.

4. Estimated costs:

Repair land damage	\$ 1,000
Crop loss	1,000
Grave Markers/Stones damage	5,000
Loss of Crew Baggage, 29 @ \$250	7,250
Loss of Pax Baggage, 54 @ \$600	<u>32,400</u>
TOTAL	\$46,650

NOTE: Due to location of crash site and RVN political situation at present time, claims regarding land damage, crop loss, and grave marker/stones repair are not expected.

STATEMENT BY

Charles E. Bopp

CHARLES E. BOPP

Major, USAF

Investigating Officer

MAC/DOV LETTER

DATED

12 JUNE 1975

12 June 1975

SUBJ: Collateral Board Investigation -- C-5 80218

TO: Collateral Investigation Officer
(Col Bernard A Waxstein)

1. The history of flight for C-5 80218 and the Collateral Board statement of witnesses were reviewed per the Collateral Board Investigation Officer's request. The following statements were reviewed:

Maj Anthony F Diferdinando
Capt Dennis W Traynor
Capt Tilford W Harp
Capt Keith D Malone
Maj William G Wallace
Capt John T Langford
TSgt Allen R Engels
SMSgt Howard C Perkins
TSgt Percy D Bradley
TSgt Peter P Doughty
SMSgt Raymond F Smedegar
MSgt Lynn F McAtee

2. The analysis made by Maj Diferdinando is generally concurred in.

3. Technical order guidance does not address an emergency of this magnitude. The crew was faced with multiple system failures resulting in a catastrophic situation. Loss of pitch and yaw control resulted in an essentially uncontrollable vehicle. Actions taken by the crew exhibited good judgment, timely analysis, innovativeness, and pilotage skills which enhanced the potential for survival. The aircraft commander was required to develop alternate control techniques. These techniques reflect astute analysis and prudent judgment. Actions taken by other crew members were correct and enhanced the survival potential of those aboard.



LOUIE O. McFERON, Colonel, USAF
Dep Director, Aircrew Stan/Eval
DCS/Operations

1 Atch
Statements

PRESS RELEASE

RE

MEDALS FOR HEROISM

AWARDED

CREW MEMBERS



Members of the crew joined in reviewing troops at an awards ceremony at Travis AFB Monday in which 37 medals for heroism were presented for their actions in saving many passengers on an orphan-laden C-5 Galaxy which crashed near Saigon April 4. As crew members stand at the left, Capt. Dennis W. Traynor III, who was

commander of the aircraft, salutes. To his right are Lt. Gen. Paul K. Carlton, Military Airlift Command commander; Maj. Gen. John F. Gonge, who commanded the 22nd Air Force at Travis at the time of the crash, and Col. Donald W. Bennett, 60th Military Airlift Wing commander. —Times-Herald Photo.

Airmen Receive Heroism Medals

By WAYNE RATLIFF
Times-Herald Staff Writer

TRAVIS AFB — Thirty-seven medals for heroism, including two Air Force Crosses, the nation's second highest military award, were presented here Monday to survivors and the next-of-kin of casualties of the crash of a C-5 Galaxy loaded with orphans April 4 near Saigon.

Aircraft commander Capt. Dennis W. Traynor III and a co-pilot, Capt. Tilford W. Harp, received the Air Force Cross for extraordinary heroism in handling the aircraft during the emergency, and aiding survivors of the crash afterwards.

Distinguished Flying Crosses for

heroism or extraordinary achievement were awarded co-pilot Capt. Keith D. Malone, navigator Capt. John T. Langford, loadmasters SM. Sgt. Howard Perkins and SM. Sgt. Raymond F. Snedegar Jr., and flight engineers M. Sgt. Lynn F. Mc Atee and T. Sgt. Allen R. Engels.

Airman's Medals were awarded all members of the medical and air crews on the flight. Eleven of the airman's medals were approved for posthumous presentation to the next-of-kin of crew members who died in the crash.

Military Airlift Command commander Gen. Paul K. Carlton, accompanied by MAC vice-commander Maj. Gen. John G. Gonge, who was commander of the 22nd Air Force at Travis at the time of the crash made the presentations in a formal military ceremony on the Travis AFB flightline.

After the presentations, the crew members were invited to review the troops and to attend a reception in a lounge at the flight terminal. Traynor and Harp answered questions about the crash in a brief press conference following the presentations.

The plane, laden with 247 or more Vietnamese orphans, 29 air crew members and 54 civilians, experienced an explosive decompression caused by loss of a large rear door shortly after takeoff. The door severed control cables governing the rear portion of the plane when it blew off.

Flight crew members formed themselves into two teams, one directing efforts to controlling the aircraft and the other going to the aid of passengers, calming them and ensuring that each was receiving oxygen. When it became apparent the plane would crash, quick



Two recipients of high Air Force medals shook hands with Lt. Gen. Paul K. Carlton, MAC commander, Monday at a reception after an awards ceremony honoring their deeds along with those of other crew members following the crash of a C-130 Galaxy in Saigon last April. At right is leadmaster SMSgt. Howard Perkins, who received the Distinguished Flying Cross, and Capt. Dennis W. Traynor, the aircraft commander, who was awarded the Air Force Cross.—Times-Herald Photo.

MORE ON HEROISM

Airmen Get Awards For Rescue Efforts

From PAGE ONE

preparations were made for impact, possibly saving some lives.

Traynor and others trying to control the aircraft were credited with saving some lives by using available control, engine power with which he could raise the nose of the aircraft slightly, to set the craft down in a rice paddy.

After the crash, crew members disregarded their own injuries to carry children and other injured survivors to the rescue craft, wading through water and mud which were waist deep in some areas. Some medical crew members were reported to have con-


tinued administering to the injured even after they reached the Vietnamese hospital.

Much of the broken portion of the aircraft, where crew members worked to evacuate survivors, was saturated with highly flammable fuel and hydraulic fluids which could have caused a severe fire if they were exposed to a spark, according to survivors' reports.


Approximately 155 persons died in the crash. The number of orphans aboard the plane could not be absolutely confirmed, according to the Air Force's central identification laboratory in Thailand.

DRAWINGS
OF
AIRCRAFT


1. *Ramp and Pressure Door General Arrangement*
2. *Aft Cargo Openings*
3. *Empennage*
4. *Aft Troop Compartment Area*
5. *Flight Deck Area*
6. *Entire Fuselage*




RAMP AND PRESSURE DOOR GENERAL ARRANGEMENT




AFT CARGO OPENINGS






C-5A AFT TROOP COMPARTMENT AREA



C-5A FLIGHT DECK AREA



LABORATORY REPORTS AND OTHER MATERIALS

CONCERNING EXPLOSIVE DAMAGE

1. EXPLOSIVE ORDNANCE DISPOSAL REPORT
2. 3 SPGP/LES LTR, 18 APR 75
3. USAF SCHOOL OF APPLIED AEROSPACE SCIENCES/TSPD
LTR, 22 APR 75
4. USAF SCHOOL OF APPLIED AEROSPACE SCIENCES/TSPD
LTR, 2 MAY 75
5. FBI REPORT

EXPLOSIVE ORDNANCE DISPOSAL REPORT				REPORTS CONTROL SYMBOL LC RM (A) 7118	
FROM: 3d Am Maint Sq/NAME APO San Francisco 96274			TO: Det 63, HQ, Ogden AFB/NAME NAVECD:AC, Indian Head MD 20640		
1. INCIDENT					2. MANHOURS EXPENDED 158
A. REPORTED BY (Grade, Last Name, Initials)		DATE	TIME		
3d Trn Command Center		4 Apr 75	1930		
B. JOB STARTED		5 Apr 75	0200		
C. JOB COMPLETED		6 Apr 75	2300		
3. NAME, GRADE OF PERSONNEL PARTICIPATING					
MSgt Sloan, J. MSgt Johnson, G. MSgt Lent, E. MSgt Shahan, J.					
4. ITEM(S)			5. FUZING		
QUANTITY	NATIONALITY	NOMENCLATURE	NOSE	TAIL	OTHER
		None			
6. COMPLETE NARRATIVE OF INCIDENT (Continue on reverse if needed)					
<p>Four personnel responded to a request for investigation of a C-54 crash site. The purpose of the investigation was to help determine exactly what had caused the accident. No personnel found no ordnance, explosive/or evidence of an explosion in the aircraft residue.</p>					
7. LOCAL CONTROL NO.	8. ATTACHMENTS	9. DATE	10. SIGNATURE OF ORIGINATOR		
75-JANK-011	None	14 Apr 75	GARY D. JOHNSON, MSgt, EOD Tech.		
11. SIGNATURE OF EOD SUPERVISOR			12. SIGNATURE MAJCOM STAFF		
BILLY L. GILBERT, 1 Lt., USAF, OIC					

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS 3D SECURITY POLICE GROUP (PACAF)
APO SAN FRANCISCO 96274



REPLY TO
ATTN OF: 3dLES/Sgt Ruiz/45221

18 Apr 75

SUBJECT: Statement on Aircraft Explosives Search

TO: Accident Investigation Board

1. On 7 Apr 75, I, Sgt Jose M. Ruiz, FR [REDACTED] Explosive Detector Dog Handler, 3dLES/Clark AB, Philippines along with Explosive Detector Dog "Rastus" VO17 conducted a search for explosives in the wreckage of a C-5A aircraft, located in a rice paddie outside of Saigon. The following areas were searched:

- (a) T-Tail Section
- (b) Fuselage section adjacent to the wings
- (c) Pieces of wreckage identified as the Ramp
- (d) Miscellaneous pieces of wreckage scattered about the area.


2. The search was extremely difficult due to the terrain at crash site. The dog was experiencing difficulty in searching due to amount of water the dog was working in. There were also numerous people located within the search areas which also added to the distraction. Search met with negative result.

3. On 11 Apr 75, Sgt Jose M. Ruiz and Explosive Detector Dog "Rastus" conducted a search of pieces of the wreckage of the C-5A at the 31 ARMS Hanger. The following pieces were searched:

- (a) Three pieces of the section called the Ramp
- (b) Twenty miscellaneous pieces

Search met with negative result. Search of these pieces was extremely difficult due to the fact, the pieces searched had been washed prior to the search.

4. Military Working Dog/Explosive Detector Dog "Rastus" brand #VO17, age: 4 years was certified as an Explosive Detector Dog at PACAF Military Training Dog Center, Kadena AB, Okinawa on 22 Aug '74. "Rastus" has been trained to detect/alert on the odors of the following explosives: Smokeless Powder, Composition C-4, TNT and Dynamite.


JOSE M. RUIZ, Sgt, USAF
FR 082-44-1313, 3d Law Enforcement
Squadron/Military Working Dog Section

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS USAF SCHOOL OF APPLIED AEROSPACE SCIENCES (ATC)
LACKLAND AIR FORCE BASE, TEXAS 78236



REPLY TO
ATTN OF: TSPD

22 April 1975


SUBJECT: Explosive Detector Dog Exercise

TO: Accident Investigation Board C-5A (218)


1. On 21 April 1975 the Military Dog Studies Branch received a telephone call from the MME-5 Branch, Kelly AFB, requesting a search by explosive detector dog teams. The search was to be inside door 11, building 155, at Kelly AFB. Permission to conduct the search was received.
2. The following personnel and dogs responded to Kelly AFB to conduct the search.
 - a. Major Dan J. Craig, Chief, Animal Behavior Science Section, Department of Security Police Training.
 - b. SFC Edwardo W. Eckert, Chief, Explosive Detector Dog Course, Military Dog Studies Branch.
 - c. Michael K. Regan, TSgt, Instructor, Explosive Detector Dog Course and detector dog Rex 7K84.
 - d. Dennis M. Burke, TSgt, Instructor, Explosive Detector Dog Course and detector dog Margo Y004
3. The search entailed checking several parts and pieces of an aircraft for residual explosives odors. During the search of these parts there were four positive responses by both dogs on the following.
 - a. Cargo floor attachment to aft ramp.
 - b. Right hand pedal door.
 - c. Two small pieces of cargo floor.

"PREPARE THE MAN"


d. Right upper hinge (pressure door).




DAN J. CRAIG, Major, USAF VC
Chief, Animal Behavior Science Section



EDUARDO W. ECKERT, SFC, USA
Chief, Explosive Detector Dog Course



MICHAEL K. REGAN, TSgt, USAF
Instructor, Explosive Detector Dog Course



DENNIS M. BURKE, TSgt, USAF
Instructor, Explosive Detector Dog Course

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS USAF SCHOOL OF APPLIED AEROSPACE SCIENCES (ATC)
LACKLAND AIR FORCE BASE, TEXAS 78236



2 May 1975

REPLY TO
ATTN OF:

TSPD

SUBJECT:

Explosive Detector Dog Exercise

TO: Accident Investigation Board C-5A (218)

1. On May 1, 1975 the Military Dog Studies Branch received a telephone call from the MME-J Branch, Kelly AFB, requesting a search by explosive detector dog teams. Permission to conduct the search was received. The search was conducted inside door 11, Building 155 and an adjacent Building at Kelly AFB.

2. The following personnel and dogs responded to Kelly AFB to conduct the search.

a. SFC Edwardo W. Eckert, Chief, Explosive Detector Dog Course, Military Dog Studies Branch.


b. Michael K. Regan, TSgt, Instructor, Explosive Detector Dog Course and detector dog Rex 7K84.

c. Dennis M. Burke, TSgt, Instructor, Explosive Detector Dog Course and detector dog Margo Y004.

The search entailed checking the aft ramp and the pressure door of an

"PREPARE THE MAN"

aircraft for residual explosives odors. During the search there were no positive responses.



EDUARDO W. ECKERT, SFC USA

Chief, Explosive Detector Dog Course



MICHAEL K. REGAN, TSgt, USAF

Instructor, Explosive Detector Dog Course



DENNIS M. BURKE, TSgt, USAF

Instructor, Explosive Detector Dog Course

DATE FROM	TO	CREW CHIEF	ORGN	LOCATION	MDS	SERIAL NO.
DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE
24/03/5	F	084	0512	P	/ /	/ /
DISCREPANCY				CORRECTIVE ACTION		
RIG CK DUE ON AFT RAMP RT SIDE				Rig Checked Ramp		
DUE TO INST. OF RAMP TIE RODS				Tie Rods 1AW 1C-SA-2-12		
BETWEEN 2+3, 3+4 LOCKS				O.C. OK.		
DN				CORRECTED BY		DATE CORRECTED
DISCOVERED BY				C721		29/03/5
K. Hill SGT				Montgomery		
DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE
25/03/5	F	084	0511	P	/ /	/ /
DISCREPANCY				CORRECTIVE ACTION		
REMOVED LINE FROM LT SIDE RAMP				INSTALLED LINE 1AW		
ACT. BECAUSE OF LEAK				1C-SA-2-12		
				(SEE Pg 19 ITEM 1 FOR PASS CK)		
DN				CORRECTED BY		DATE CORRECTED
DISCOVERED BY				5625		25/03/5
K. Hill SGT				G. DAVISON AIC		
DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE
25/03/5	F	083	0541	P	/ /	/ /
DISCREPANCY				CORRECTIVE ACTION		
ANTI SKID WILL NOT PASS BITE CK				REMOVED AND REPLACED -		
(3C 44A VALVES BAD)				3C 44A KEN VALVES 1AW		
				TOIC-SA-2-10		
DN				CORRECTED BY		DATE CORRECTED
DISCOVERED BY				0151		28/03/5
G24HS50830461				M. J. Dandy AMN		
DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE
25/03/5	F	085	0247	P	/ /	/ /
DISCREPANCY				CORRECTIVE ACTION		
DUCT FROM LT APU ISO VALVE TO				Installed APU ISO DUCT		
BULKHEAD CRACKED. 100 / 100				FROM VALVE TO BULKHEAD		
DUCT REMOVED TO MA SHOP BY				1AW 1C-SA-2-13		
SGT IRIZARRI 5697.				(see Pg 21 F 4)		
(INCLUDE ISO VALVE OPS 4LK CK UPON RE-INSTALLATION OF DUCT. PREV. MAINT 074-023)				DATE CORRECTED		
DN				CORRECTED BY		26/03/5
DISCOVERED BY				085		
K. Hill SGT				M. J. Dandy SGT		

AFTO FORM 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT

PREVIOUS EDITION IS OBSOLETE

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS TWENTY-SECOND AIR FORCE (MAC)
TRAVIS AIR FORCE BASE, CALIFORNIA 94535



REPLY TO
ATTN OF: 22LGM

24 JUL 1975

SUBJECT: Review of Witness Statements for Collateral Investigation of C-5
S/N 68-218

TO: 22JA


As requested by Colonel Bernard A. Waxstein, Jr., C-5A Collateral Investigating Officer, I have reviewed the witness statements of TSgt Noah E. Fields, FR 566-44-7386, Sgt Larry G. Van Dyne, FR 007-52-7219, Mr. Glen Critchfield, WL-10, SSAN 547-28-7261 and Mr. William E. Hell, L-10, SSAN 470-07-9640. My review included the statements made by above named individuals and also the technical order guidance provided for the tasks involved, i. e., cannibalization of aft ramp lock subsystem tie rods from C-5 S/N 68-213 and installation of the tie rods on C-5A S/N 68-218. My conclusions are as follows:

a. Mr. Hell and Sgt Van Dyne removed two tie rods from aircraft -213 and installed them on aircraft -218 from which the rods had been previously removed. No specific instructions covering removal and installation of these rods are included in TO 1C-5A-2-12. Paragraph 3-81a, TO 1C-5A-2-12, "Aft Ramp Lock Subsystem Installation", states "install components of the aft ramp lock in the reverse order of removal". Mr. Hell and Sgt Van Dyne statements indicate that they did follow this simple instruction. After the rods were installed, the final rigging, adjustment and operational checks could not be accomplished since hydraulic power could not be applied to the aircraft due to other maintenance problems. Mr. Hell and Sgt Van Dyne made AFTO 781A form entries indicating that final adjustments and operational checks were still required. The procedures followed by these technicians was considered adequate and proper.

b. The actions of Mr. Glen Critchfield were only involved in observing an operational check of the doors and in signing off the AFTO 781A entries after final adjustment/rigging checks were accomplished by TSgt Fields. Since the requirement for final rigging and operational checks were entered as a red x, corrective actions required two signatures for proper clearance. Mr. Critchfield's actions were considered proper.

c. The actions of TSgt Noah E. Fields involved final rigging, adjustment and operationally checking tie rod installations previously accomplished by Mr. Hell and Sgt Van Dyne and clearing of the AFTO 781A entries. No specific rigging, adjusting or operational checking instructions for tie rod installations are given in TO 1C-5A-2-12. Paragraph 3-81b of Aft Ramp Lock Subsystem Installation instructions states "Rig aft ramp locks in accordance with rigging instructions provided in Figure 3-44". Paragraph 3-168, Aft Ramp Rigging Instructions includes Figure 3-44. Paragraph 3-168d states "Instructions are sequenced for complete ramp rigging. If a particular maintenance effort requires performance of only a portion of the rigging procedure, use the following tabulation to isolate the applicable steps". This following tabulation does not contain steps for checking, rigging, and/or adjusting the tie rods replaced by Mr. Hell and Sgt Van Dyne. Only Step 53 of Figure 3-44 could be considered as providing any tie rod rigging information pertinent to the rods that had just been installed. Considering the lack of specific tie rod rigging/adjustment information in TO 1C-5A-2-12, the actions taken by TSgt Field became a matter of personal judgement and experience. Sgt Fields decided to use Paragraph 3-173, Aft Ramp Mechanical Rigging Verification guidance to verify the proper rigging and adjustment of the tie rods. Since no specific guidance was provided elsewhere in TO 1C-5A-2-12, his decision is not considered improper for the task that was required.

d. The following is in reply to a question posed by the Collateral Investigating Officer. Question: Would the procedures that Sgt Fields stated that he used actually verify that the aft ramp locks were properly rigged? Answer: Sgt Fields indicated that he used paragraph 3-173, TO 1C-5A-2-12, Aft Ramp Mechanical Rigging Verification to verify if the tie rods were properly adjusted. The title of paragraph 3-173 is misleading and might indicate that accomplishing the instructions of para 3-173c would verify that the ramp locking system is properly rigged. Accomplishment of para 3-173c does not verify that all adjustments, measurements, pull forces, and over center positions are correct as required in the total ramp rigging procedures contained in para 3-168, Aft Ramp Rigging Instructions. This is a deficiency in the technical instructions. This deficiency has been brought to light by this accident. Corrective actions resulting from this accident should correct this deficiency.


KARL F. POLANSHEK
GS-12, DAFC, 22LGMW
Aircraft Equipment Specialist

MINCE

30 April 1975

Task #1128 CSA Accident Investigation (S/N 68-0218)

ME-5/Capt Gregory/Capt Scheiding

The listed 24 Attachments were submitted to the Metallurgical Laboratory for metallurgical analysis, by the Accident Investigation Team. The analysis performed on the various items were those specifically requested by the Accident Investigation Team. Also included are additional analyses which the metallurgists felt would be helpful in answering questions concerning failure of the items.

SIGNED

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA

24 Attachments
Task 1128, Attachments
1 thru 24.

**REPORT
of the**



**FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535**

To: Major General Werner E. Newby
Accident Board President
Twenty-Second Air Force/Safety
Travis Air Force Base, California 94533

May , 1975

ATTN: IN

FBI FILE NO. 65-2886-93

LAB. NO. PC-A7638 OF 17

YOUR NO.

Re: CRASH OF AIR FORCE C-54, SERIAL
NUMBER 62-218, NEAR SAIGON
RVN ON 4/4/75

Lieutenant General
Donald G. Nunn
Department of the
Air Force

A handwritten signature in cursive script, reading "Clarence M. Kelley".

Clarence M. Kelley
Director

Examination requested by: Headquarters United States
Air Force, Washington, D.C.
Reference: Letter 4/23/75

Examination requested: Explosives - Metallurgy

Specimens personally delivered by Lieutenant Hugh C. Briggs
on 4/23/75:

- Q1 Cargo floor section
- Q2 Cargo floor aft edge
- Q3 Pressure door hinge backup structure

Result of examination:

Microscopic examination of the fractured metal
surfaces and the damage areas exhibited by specimens Q1
through Q3 revealed no indication that the fractures or
metal damage was directly caused by exposure of the specimens
to detonation of a high explosive.

1 - Lieutenant General Donald G. Nunn
The Inspector General
Department of the Air Force
Headquarters United States Air Force
Washington, D.C. 20330

No residues which could be associated with an explosive composition were found on specimens Q1 through Q4.

Specimens Q1 through Q4 are being maintained in the Laboratory until called for by a representative of your department.

22AF/LGM LETTER

MADAR TAPE ANALYSIS

16 JULY 1975

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS TWENTY-SECOND AIR FORCE (MAC)
TRAVIS AIR FORCE BASE, CALIFORNIA 94535



REPLY TO
ATTN OF: 22LGM

16 JUL 1975

SUBJECT: MADAR Tape Analysis, C-5A S/N 68-218

TO: 22JA

1. At the request of the collateral Investigating Officer, Colonel Bernard A. Waxstein, Jr., the following information concerning the MADAR maintenance data recorder tape is submitted. Analysis was made of the Ground Processing System (GPS) Program 67220, Flight Segment Parameter Listing (FSPL) reflecting the mission from Travis AFB, CA, to the crash landing at Saigon during the period 30 Mar - 4 Apr 75.

2. Description of MADARS: MADARS is the malfunction detection, analysis and recording system. It is installed in the aircraft to assist flight and maintenance crews in checking airplane line replaceable units and airplane systems for degradation or failure. The system monitors critical flight and aircraft system parameters and announces to the operator excessive system degradation. The system also records this data on a maintenance data recorder (MDR) magnetic tape. This data is transmitted to and stored in a central data bank at Oklahoma City ALC and can be extracted by the ground processing system. The data can be used to determine operational trends, aircraft performance and structural integrity.

3. The MADAR MDR tapes were recovered from the crashed C-5 S/N 68-218 and the data was transmitted to the central data bank at the Oklahoma City Air Logistics Center. A GPS Program No. 67220 Flight Segment Parameter Listing was then extracted for use in verifying operational conditions of C-5 S/N 68-218 on the flights prior to the crash. The GPS machine run Program 67220 is stored with other aircraft maintenance records in the collateral investigation case file.

4. The GPS Program 67220 FSPL analysis reveals the following:

a. The aircraft had been operating normally since it had left Travis AFB on 30 Mar 75. No unusual maintenance malfunctions that could be related to a rapid decompression or aft ramp/door

system failures were recorded. Critical engine, flight control, airframe and aircraft system parameters were indicating normal operations.

b. The flight from Clark to Saigon was normal with no malfunction indications that could be related to problems that could cause a rapid decompression or failure of aft ramp/cargo door systems.

c. Take off from Saigon was at 05:01Z.

d. Climb out was normal with all engines operating within limits.


e. At 05:13+ aircraft was in climb power, all engine parameters within limits, at an airspeed of .610 mach, at 23,424 ft altitude. At this time, the reported rapid decompression occurred and hydraulic pressure to the pitch and yaw augmentation systems was lost.

f. At 05:14+, hydraulic pressure to the lateral augmentation system was lost, aircraft began descending and engine throttles were retarded.

g. From 05:14 to 05:28, aircraft was erratically descending and extremely erratic throttle usage was recorded. Also, airspeed was continuously increasing and decreasing in direct relationship to throttle manipulation and rate of altitude changes. This verifies the reports of the flight crew that descent of the aircraft was being controlled through use of engine power.

h. CDPIR voice tape (transcript included elsewhere in this report) indicates that the aircraft was on a heading of 136 degrees at 05:08 and passing Vung Tau at 05:10+.

i. At 05:28+, the MADAR tape indicated loss of power to the recorder and no subsequent recordings. Aircraft at this time was at 537 ft pressure altitude which was the same altitude recorded at take-off.


KARL F. POLANSHEK
GS-12 DAFC, 22LGMW
Aircraft Equipment Specialist

AFTO FORMS 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT

FOR PERIOD 31 MARCH 1975 TO 4 APRIL 1975

31 MAR 75 TO 4 APR 75

PAGE 1 OF 1 PAGES

DATE FROM 31/03/75	TO 1/1	CREW CHIEF Bright Tsgt	DRGN LO MAW	LOCATION Thru's GFB	MDS C-54	SERIAL NO. 68-218			
SYM 19/12/74	DATE DISCD F	WDC 0851064	JCN 580313	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Pilots Radar Alt. INDP					CORRECTIVE ACTION				
recorded 22/03/75 GIL WOOD ⁴²⁰⁸									
ETR RT					DATE CORRECTED / /				
DN 646RR5081	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
SYM 08/08/74	DATE DISCD D	WDC 2510989	JCN	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY HET Main G/C Bus #1 Light stays on (Bad IND)					CORRECTIVE ACTION				
					DATE CORRECTED / /				
DN 625EL5074-046	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
SYM 06/09/74	DATE DISCD F	WDC 2390506	JCN 372929	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY NAV'S #2 BDHI 180° Dut					CORRECTIVE ACTION				
(Shop reorder reordered by GIL WOOD ⁴²⁰⁸)									
					DATE CORRECTED / /				
DN 646RR4239	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
SYM 08/01/75	DATE DISCD F	WDC 0080505	JCN	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Pilots #1 Eng. N ² has off flag in view sym G/C by Lt. CHANN 60 SMS IND ETR CFLT Eng's Ind Put in Pilots Pos					CORRECTIVE ACTION				
					DATE CORRECTED / /				
DN 625IN5090065	DISCOVERED BY			CORRECTED BY			INSPECTED BY		

AFPD FORM 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT

PREVIOUS EDITION
IS OBSOLETE

DATE FROM 31/03/51	TO / /	CREW CHIEF	ORGN	LOCATION	MDS C-5A	SERIAL NO. 68-218
SYM 506/02/5	DATE DISCD 06/02/5	WDC Q	JCN 0389703	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY SAR 18 auto 4200014-1276				CORRECTIVE ACTION INSTALLED SAR		
Location aft elect Equip rack				JAWIC-5A-2-6		
				DATE CORRECTED 01/04/5		
DN 646CP50381028	DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM 506/02/5	DATE DISCD 06/02/5	WDC Q	JCN 0269711	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY T2C Temp v-ducer (556PR)				CORRECTIVE ACTION		
Comp inlet #2 Eng 519						
FixL MAC						
				DATE CORRECTED / /		
DN 643J550450320	DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM 506/02/5	DATE DISCD 06/02/5	WDC Q	JCN 0269712	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY T2C Temp v-ducer (556PR)				CORRECTIVE ACTION		
Comp inlet #3 Eng 516						
FixL MAX						
				DATE CORRECTED / /		
DN 643J550450319	DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM 506/02/5	DATE DISCD 06/02/5	WDC M	JCN 0376972	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY #3 Eng oil Qty ind.				CORRECTIVE ACTION		
Test Knob broken FTR'D						
				DATE CORRECTED / /		
DN 645IN 50371027	DISCOVERED BY			CORRECTED BY		INSPECTED BY

DATE FROM 3/103/5	TO 1/1	CREW CHIEF	ORGN	LOCATION	MDS C5A	SERIAL NO. 68-218	
SYM /	DATE DISCD 02/02/5	WDC M	JCN 0376870	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY Duct Assy behind troop lav (in Cargo air Supply) damaged (removed)				CORRECTIVE ACTION			
DN 624ML50381045				DISCOVERED BY	CORRECTED BY	INSPECTED BY	DATE CORRECTED / /
SYM /	DATE DISCD 14/02/5	WDC F	JCN 0450549	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY Bracket broken in NLG w/w for rt. aft insep Lamp				CORRECTIVE ACTION			
DN 240FL50450362				DISCOVERED BY	CORRECTED BY	INSPECTED BY	DATE CORRECTED / /
SYM /	DATE DISCD 18/02/5	WDC J	JCN 0497809	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY SQ Plate & screen missing from #3 Hinge Panel Lt aft Cargo door				CORRECTIVE ACTION			
DN 240FL50480280				DISCOVERED BY	CORRECTED BY	INSPECTED BY	DATE CORRECTED / /
SYM /	DATE DISCD 01/02/5	WDC D	JCN 0540960	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY #2 Eng fuel temp inop reads off scale (Bad Temp bulb)				CORRECTIVE ACTION			
DN 625IN50540218				DISCOVERED BY	CORRECTED BY	INSPECTED BY	DATE CORRECTED / /

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN	LOCATION	MDS C-5A	SERIAL NO. 08-218
SYM /	DATE DISCD 18/02/5	WDC F	JCN 0490539	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY Shims Loose x-head #3 MLC Sym 9/6 by Major Staples 60 Dms 24/02/5					CORRECTIVE ACTION	
DN					DATE CORRECTED / /	
DISCOVERED BY		CORRECTED BY		INSPECTED BY		
SYM /	DATE DISCD 25/02/5	WDC B	JCN 0560512	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY fwd Ramp extension toes do not lock up in truck bed.					CORRECTIVE ACTION	
DN					DATE CORRECTED / /	
DISCOVERED BY		CORRECTED BY		INSPECTED BY		
SYM /	DATE DISCD 25/02/5	WDC J	JCN 0560397	TAG NO. 580198	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY Corner of Catwalk aft of 7 Lt. door broken					CORRECTIVE ACTION	
DN					DATE CORRECTED / /	
DISCOVERED BY		CORRECTED BY		INSPECTED BY		
SYM /	DATE DISCD 10/03/5	WDC F	JCN 0710902	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /
DISCREPANCY RT. Side OB Removable rail (PP32) Lock is broken and wont Lock into position					CORRECTIVE ACTION Repaired Movable Rail Lock	
DN					DATE CORRECTED 31/03/5	
DISCOVERED BY		CORRECTED BY		INSPECTED BY		

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN	LOCATION	MDS CSA	SERIAL NO. 68-218			
SYM /	DATE DISCD 10/03/5	WDC D	JCN 0710966	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Crew door has large air Lk. at upper Rh Corner and all across lower bottom seal at 8.2 PSI					CORRECTIVE ACTION				
DN CFHS EXCESSIVE MAINT.					DISCOVERED BY		CORRECTED BY		INSPECTED BY
SYM /	DATE DISCD 11/03/5	WDC D	JCN 0710973	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Rail attachment device for fwd ramp IB rail assy w/ lock to ramp extension					CORRECTIVE ACTION Removed & Replaced Omni Roller Conveyor				
DN					DISCOVERED BY		CORRECTED BY / 559		INSPECTED BY
SYM /	DATE DISCD 11/03/5	WDC D	JCN 0710974	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Rail allinger Panel missing from fwd Ramp IB rail assy					CORRECTIVE ACTION Installed allinger Panel				
DN					DISCOVERED BY		CORRECTED BY / 559		INSPECTED BY
SYM /	DATE DISCD 11/03/5	WDC D	JCN 0710979	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY PP 34 OB Roller Conveyor damaged aft rollers at conveyor w/ turn					CORRECTIVE ACTION Removed & Replaced Roller Conveyor				
DN					DISCOVERED BY		CORRECTED BY / 559		INSPECTED BY

DATE FROM 31/07/5		TO / /		CREW CHIEF		ORGN		LOCATION		MDS C-5A		SERIAL NO. 18-218	
SYM 7		DATE DISCD 11/03/5		WDC D		JCN 0710975		TAG NO.		CF TO 781A DATED P 1 / /		TRANSFERRED TO 781K DATE / /	
DISCREPANCY O/B Rail bridge missing from fwd ramp										CORRECTIVE ACTION Installed O/B Rail Bridge			
										DATE CORRECTED 31/03/5			
DN				DISCOVERED BY				CORRECTED BY J. J. J.				INSPECTED BY	
SYM 7		DATE DISCD 11/03/5		WDC D		JCN 0710980		TAG NO.		CF TO 781A DATED P 1 / /		TRANSFERRED TO 781K DATE / /	
DISCREPANCY PP5 F/B roller conveyor is bad										CORRECTIVE ACTION Removed & replaced roller conveyor			
										DATE CORRECTED 31/03/5			
DN				DISCOVERED BY				CORRECTED BY J. J. J.				INSPECTED BY	
SYM 7		DATE DISCD 12/03/5		WDC D		JCN 0710984		TAG NO.		CF TO 781A DATED P 1 / /		TRANSFERRED TO 781K DATE / /	
DISCREPANCY 2 nd from Lt. O/B OMNI roller on fwd ramp sticks in channel due to bushing coming out										CORRECTIVE ACTION Removed & replaced OMNI conveyor			
										DATE CORRECTED 31/03/5			
DN				DISCOVERED BY				CORRECTED BY J. J. J.				INSPECTED BY	
SYM 7		DATE DISCD 08/03/5		WDC D		JCN 0710953		TAG NO.		CF TO 781A DATED P 1 / /		TRANSFERRED TO 781K DATE / /	
DISCREPANCY Pallet pos 36 O/B rail will not lock in cargo floor										CORRECTIVE ACTION Repaired O/B Rail lock at Pallet pos 36			
										DATE CORRECTED 31/03/5			
DN				DISCOVERED BY				CORRECTED BY J. J. J.				INSPECTED BY	

DATE FROM 31/03/5	TO 1/1	CREW CHIEF	QSON LOMAN	LOCATION TANVIA	MDS CSA	SERIAL NO. 68-218	
SYM A	DATE DISCD 12/03/5	WDC F	JCN 0830446	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY A/Ct requires an in-flight press test & Eval. This A/Ct lowers press test level from OTE test Plan 5-30-74				CORRECTIVE ACTION C/W IN FLIGHT PRESS TEST & EVAL. SEE WRITEUP ON PAGE 11 ITEM 4 - FAILED TEST.			
DN				DISCOVERED BY	CORRECTED BY R. H. H. H.	INSPECTED BY	
SYM /	DATE DISCD 12/03/5	WDC F	JCN 0830535	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY POLL Lamp missing				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
SYM /	DATE DISCD 14/03/5	WDC F	JCN 0730507	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY Canned aft press door bottom seal restraint strips (rod ends on A/Ct)				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
SYM /	DATE DISCD 20/03/5	WDC F	JCN 0800536	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY Bent Loop by Lt KPH ISO Valve				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN 60MAN	LOCATION	MDS C-5A	SERIAL NO. 68-248	
SYM /	DATE DISCD 27/03/5	WDC 3	JCN 0867125	TAG NO. 581052	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Lower fuselage Light Missing (Lens, bulb, & Seal)					CORRECTIVE ACTION		
					DATE CORRECTED / /		
DN 2402L5088-0013		DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM /	DATE DISCD 26/03/5	WDC 3	JCN 0877134	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY #3 Eng drain line dented 6 o'clock position Comp Case					CORRECTIVE ACTION		
					DATE CORRECTED / /		
DN 64350870448		DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM /	DATE DISCD 29/03/5	WDC J	JCN 0888310	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Both troop latrines drain "T" handles w/N retract					CORRECTIVE ACTION		
					DATE CORRECTED / /		
DN		DISCOVERED BY			CORRECTED BY		INSPECTED BY
SYM /	DATE DISCD 29/03/5	WDC J	JCN 0888291	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Book 247 missing from "6" file					CORRECTIVE ACTION		
					DATE CORRECTED / /		
DN		DISCOVERED BY			CORRECTED BY		INSPECTED BY

DATE FROM 31/03/5	TO 1	CREW CHIEF	ORGN GUMAN	LOCATION TRAVIS AFB, TX	MDS CSA	SERIAL NO. 68-21P	
SYM W	DATE DISCD 31/03/5	WDC J	JCN 0908431	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY #2 Eng w/n Overheat test.				CORRECTIVE ACTION Removed & Replaced FLD PyLon Loop - System ops ck OK. IAW IC-5A-2-7			
				DATE CORRECTED 31/03/5			
DN		DISCOVERED BY		CORRECTED BY P. M. M. 5567 41389		INSPECTED BY H. W. M. 5567	
SYM /	DATE DISCD 31/03/5	WDC J	JCN 0908448	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY winch beam mount pins missing.				CORRECTIVE ACTION			
				DATE CORRECTED / /			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY	
SYM /	DATE DISCD 31/03/5	WDC J	JCN 0908439	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY #2 #4 MLC wheelwell Lights switch broken (Lights w/n shut off)				CORRECTIVE ACTION			
				DATE CORRECTED / /			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY	
SYM /	DATE DISCD 31/03/5	WDC J	JCN 0908436	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Panel cracked & rivets popped just above aft rt. corner of fwd ramp				CORRECTIVE ACTION			
FA7				DATE CORRECTED / /			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY	

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN LCMAW	LOCATION JMWV'S AREA 12	MDS C-5A	SERIAL NO. 68-218	
SYM #1	DATE DISCD 31/03/5	WDC J	JCN 0908491	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Test PR FLT 1C5A-6W-C-151 C/W 1100 LOC'D NO Power ON for FLT Control Check Card B-22 Transcribe to New 781A				CORRECTIVE ACTION			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 31/03/5	WDC F	JCN 0900085	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY fwd galley flood 110 Socket shorted out				CORRECTIVE ACTION			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 31/03/5	WDC F	JCN 0801588	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY IFR Opens Check due to replacement of IFR actuator FAI				CORRECTIVE ACTION IFR Sys ops OK'd. GOOD IAW T.O. 1C-5A.2-5			
DN		DISCOVERED BY		CORRECTED BY <i>[Signature]</i>		INSPECTED BY <i>[Signature]</i>	
DATE CORRECTED 01/04/5							
SYM #1	DATE DISCD 31/03/5	WDC F	JCN 090008	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Navigators Pre Flight Completed 1845Z All Systems OK good. requested BDHT for Nav. Position				CORRECTIVE ACTION Noted			
DN		DISCOVERED BY		CORRECTED BY		INSPECTED BY <i>[Signature]</i>	
DATE CORRECTED 31/03/5							

DATE FROM		TO		CREW CHIEF		ORGN		LOCATION		MDS		PAGE 11 OF 68 - 218			
31/03/5		1				RE MAN		TANIS AP, CO		CSA					
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY					
N 01	31/03/5	F	0900008			P 1 / /		/ /							
DISCREPANCY						CORRECTIVE ACTION									
Air crew Pre. Pre flight						NOTED									
Complete 19:30 31 Mar. 75															
						DATE CORRECTED 31/03/5									
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY			
												Donald R. Hyer			
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY					
/	31/03/5	B	0900545			P 1 / /		/ /							
DISCREPANCY						CORRECTIVE ACTION									
RE APU GEN FREQ															
FLUX															
1 volts Reg.															
						DATE CORRECTED / /									
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY			
16/3555091				W-10											
31/03/5				F				TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
31/03/5				F						P 1 / /		/ /			
DISCREPANCY						CORRECTIVE ACTION									
781 H and 781 J															
ACFT TIMES DO NOT															
agree															
						DATE CORRECTED / /									
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY			
31/03/5				F				TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
31/03/5				F						P 1 / /		/ /			
DISCREPANCY						CORRECTIVE ACTION									
UNABLE TO MAINTAIN 8.0 PSID															
EITHER LT OR RT PACK															
WITH ONE PACK PLUS FLOOR															
HEAT CABIN WENT TO 2500 AND															
WAS STILL CLIMBING WHEN TEST															
WAS TERMINATED. SEE PG 13 Item 2.															
						DATE CORRECTED / /									
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY			
31/03/5				F				TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
31/03/5				F						P 1 / /		/ /			
DISCREPANCY						CORRECTIVE ACTION									
UNABLE TO MAINTAIN 8.0 PSID															
EITHER LT OR RT PACK															
WITH ONE PACK PLUS FLOOR															
HEAT CABIN WENT TO 2500 AND															
WAS STILL CLIMBING WHEN TEST															
WAS TERMINATED. SEE PG 13 Item 2.															
						DATE CORRECTED / /									
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY			
31/03/5				F				TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
31/03/5				F						P 1 / /		/ /			
DISCREPANCY						CORRECTIVE ACTION									
UNABLE TO MAINTAIN 8.0 PSID															
EITHER LT OR RT PACK															
WITH ONE PACK PLUS FLOOR															
HEAT CABIN WENT TO 2500 AND															
WAS STILL CLIMBING WHEN TEST															
WAS TERMINATED. SEE PG 13 Item 2.															
						DATE CORRECTED / /									

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN 60MAN	LOCATION TRAVIS AFB	MDS C-5A	SERIAL NO. 68-218	
SYM /	DATE DISCD 01/04/5	WDC	JCN	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY NO CROSS HAIRS IN BOTH RADARS, X AND KU.				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 01/04/5	WDC	JCN	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY NAVIGATORS SEAT CHEST STRAPS WILL NOT RELEASE.				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							
SYM X	DATE DISCD 01/04/5	WDC	JCN	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY IMU HAS EXCESSIVE MILEAGE ERROR. 4.2 HR FLT 17.2 ERROR, IN INERT/DOFF				CORRECTIVE ACTION CHECKED IMU INERT 5.5 HRS ERROR OK. DOPPLER MOVING EXCESSIVE ERROR DO NOT OPERATE IN I/D.			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED 01/04/5							
SYM X	DATE DISCD 01/04/5	WDC D	JCN 091579	TAG NO.	CF TO 781A DATED P / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY EXTERNAL POWER WILL NOT STAY ON THE LINE WHEN LOAD IS APPLIED. AT TIMES WORKS GOOD, (IT MAY KICK OFF AT ANY TIME.)				CORRECTIVE ACTION RTR Bus Protection PANEL SYSTEM OK (GOOD) TAW (C-5A 2-7)			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							

DATE FROM 31/03/5		TO 1/1		CREW CHIEF		ORON 60 MAN		LOCATION TANH MA. CA. CSA		MDS 68-218		SERIAL NO.	
SYM		DATE DISCD 01/04/5		WDC JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
DISCREPANCY SEVERAL EXT POWER UNITS USED. THAT WERE KNOWN TO BE SERVICEABLE. APPEARS TO BE SHORT CIRCUIT IN EXT POWER CONNECTOR.								CORRECTIVE ACTION					
DN								DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED 01/04/5													
SYM		DATE DISCD 01/04/5		WDC JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
DISCREPANCY PRESSURE LEAK AT # 2 ESCAPE HATCH.								CORRECTIVE ACTION RESET SEAL					
DN								DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED 01/04/5													
SYM		DATE DISCD 01/04/5		WDC JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
DISCREPANCY ENGS # 2 N-1 THERM READS APPROX 60 TO LOW								CORRECTIVE ACTION					
DN								DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED													
SYM		DATE DISCD 12/04/5		WDC JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
DISCREPANCY TRAILING EDGE FLAPS HAD A TE. FING BRAKE UN LITE ON AND TE ASSYM LITE UN. AND FING WOULD NOT MOVE. USED PROCEDURES IN 15-5A-1 TO RESET. ^{1 OCCURRED AGAIN LATER} IN RT								CORRECTIVE ACTION R/R RA WING TRANSDUCERS SYSTEM O.C. GOOD IAW ICSA-2-9					
DN								DISCOVERED BY		CORRECTED BY		INSPECTED BY	
DATE CORRECTED 01/04/5													

DATE FROM		TO		CREW CHIEF		ORGN		LOCATION		MDS		SERIAL NO.	
31/08/9		/ /				LOMAN		TRAVIS A7A, CA		C-5A		48-218	
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY			
/	01/04/5	D	0710589	419304		P / /		/ /		XDOT			
DISCREPANCY						CORRECTIVE ACTION							
# 2 UHF WILL XMIT						REMOVED AND REPLACED							
BUT WILL NOT RECEIVE.						# 2 UHF XMITER							
ETR # 2 UHF RT UNIT						SYSTEM OPS CK							
						GOOD IAW TO IC-CJA-							
						2-8							
						DATE CORRECTED 01/04/5							
DN		DISCOVERED BY				CORRECTED BY		INSPECTED BY					
X6460509A 0886						J. S. H. J. S. G.							
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY			
/	01/04/5	D				P / /		/ /					
DISCREPANCY						CORRECTIVE ACTION							
TERRAIN CAN MISSING													
IN CREW KATRINE													
						DATE CORRECTED / /							
DN		DISCOVERED BY				CORRECTED BY		INSPECTED BY					
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY			
/	01/04/5	D				P / /		/ /					
DISCREPANCY						CORRECTIVE ACTION							
SAATCHI BLOC CABLE													
GUIDE MISSING ON RT													
SIDE STA 600													
						DATE CORRECTED / /							
DN		DISCOVERED BY				CORRECTED BY		INSPECTED BY					
SYM	DATE DISCD	WDC	JCN	TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY			
/	01/04/5	D				P / /		/ /					
DISCREPANCY						CORRECTIVE ACTION							
LOADING LIFE ON LH													
FWO RAMP BURNED OUT.													
(CB Will Not Reset)													
						DATE CORRECTED / /							
DN		DISCOVERED BY				CORRECTED BY		INSPECTED BY					

DATE FROM 31/03/5	TO 1/1	CREW CHIEF	ORGN 60 MAW	LOCATION TRAVIS AFB, CA.	MDS C5A	SERIAL NO. 68-218			
SYM /	DATE DISCD 01/04/5	WDC D	JCN	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY LITE'S INOP. STROOP COMP SEAT ROW 11 & 16 L.H. SIDE					CORRECTIVE ACTION				
DN					DISCOVERED BY		CORRECTED BY		INSPECTED BY
SYM /	DATE DISCD 01/04/5	WDC D	JCN	TAG NO. 0710588	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY #2 HF Radio with NO T. CHANNELIZE.					CORRECTIVE ACTION XDAT				
ETR #2 HF COUPLIFIER ME					REMOVED, REPAIRED & REINSTALLED COUPLIFIER, OP CX OK 12W TO IC-SA-2-8				
DN X646R050910JAN					DISCOVERED BY X6		CORRECTED BY 11111 TSGT 0092		INSPECTED BY
SYM /	DATE DISCD 01/04/5	WDC D	JCN	TAG NO. 0910592	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY Doppler SOC INOP					CORRECTIVE ACTION XDAT				
ME					GROUND CKS OK IAW IC-SA-2-8				
DN					DISCOVERED BY		CORRECTED BY Pamela St		INSPECTED BY
SYM P	DATE DISCD 01/04/5	WDC F	JCN	TAG NO. 0910123	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K / /	DATE / /	TRANSFERRED BY
DISCREPANCY NO SPARE MAC FORM 278-B BOARD R/C.					CORRECTIVE ACTION XDAT				
278-B BOARD R/C.					INSTALLED SPARE 278B O/B				
DN					DISCOVERED BY		CORRECTED BY 2579 EK Panastrosio		INSPECTED BY
DATE CORRECTED 01/04/5					DATE CORRECTED 01/04/5				

DATE FROM 31/03/5	TO 1/1	CREW CHIEF	ORGN COMAN	LOCATION TRAVIS AFB TX	MDS C-5A	SERIAL NO. 68-218	
SYM 01/04/5	DATE DISCD 01/04/5	WDC F	JCN	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY SEAT CAMEL FOR ENG ^S SEAT MISSING.				CORRECTIVE ACTION			
DN				DISCOVERED BY Donald R. Schuyler	CORRECTED BY		INSPECTED BY
DATE CORRECTED 1/1/1							
SYM 01/04/5	DATE DISCD 01/04/5	WDC F	JCN	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY LATRINE SMELLS BAD.				CORRECTIVE ACTION Service Latrine			
DN				DISCOVERED BY Donald R. Schuyler	CORRECTED BY M. J. Schuyler		INSPECTED BY
DATE CORRECTED 01/04/5							
SYM 01/04/5	DATE DISCD 01/04/5	WDC F	JCN 0910581	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY PITCH TRIM W/IN TRAVEL FULL UP.				CORRECTIVE ACTION O.C. PITCH TRIM SYSTEM AND FOUND OK I-A-W TO-IC-SA-2-9.			
DN				DISCOVERED BY Edmund K. W. 10	CORRECTED BY Edmund K. W. 10		INSPECTED BY
DATE CORRECTED 01/04/5							
SYM 01/04/5	DATE DISCD 01/04/5	WDC F	JCN 0910580	TAG NO.	CF TO 781A DATED P 1/1/1	TRANSFERRED TO 781K DATE 1/1/1	TRANSFERRED BY
DISCREPANCY PITCH TRIM Noisy.				CORRECTIVE ACTION O.C. PITCH TRIM SYSTEM AND FOUND OK I-A-W TO-IC-SA-2-9.			
DN				DISCOVERED BY Edmund K. W. 10	CORRECTED BY Edmund K. W. 10		INSPECTED BY
DATE CORRECTED 01/04/5							

DATE FROM 31/03/5		TO / /		CREW CHIEF		ORGN 10MAN		LOCATION TAMU/15 AFH, CA		MDS CSA		SERIAL NO. 68-218		
SYN #		DATE DISCD 01/04/5		WDC F		JCN 0910123		TAG NO.		CF TO 781A DATED P / /		TRANSFERRED TO 781K DATE / /		
DISCREPANCY IFR PRE FLIGHT N/C/W									CORRECTIVE ACTION IFR PREFLIGHT C/W IAW T.O. 1C-5A-2-5					
DN									DISCOVERED BY D. L. L. S. S. S.		CORRECTED BY D. L. L. S. S. S.		INSPECTED BY 31/04/5	
SYN #		DATE DISCD 01/04/5		WDC F		JCN 0910123		TAG NO.		CF TO 781A DATED P / /		TRANSFERRED TO 781K DATE / /		
DISCREPANCY #1 ENG FAN STOPPER INSTALLED									CORRECTIVE ACTION FAN STOPPER REMOVED					
DN									DISCOVERED BY R. Embury L-10		CORRECTED BY D. S. 13		INSPECTED BY R. Embury L-10	
SYN #		DATE DISCD 01/04/5		WDC F		JCN 0910123		TAG NO.		CF TO 781A DATED P / /		TRANSFERRED TO 781K DATE / /		
DISCREPANCY #2 ENG FAN STOPPER MISTAKEN									CORRECTIVE ACTION FAN STOPPER REMOVED					
DN									DISCOVERED BY R. Embury L-10		CORRECTED BY D. S. 13		INSPECTED BY R. Embury L-10	
SYN #		DATE DISCD 01/04/5		WDC F		JCN 0910123		TAG NO.		CF TO 781A DATED P / /		TRANSFERRED TO 781K DATE / /		
DISCREPANCY #3 ENG FAN STOPPER INSTALLED									CORRECTIVE ACTION FAN STOPPER REMOVED					
DN									DISCOVERED BY R. Embury L-10		CORRECTED BY D. S. 13		INSPECTED BY R. Embury L-10	
SYN #		DATE DISCD 01/04/5		WDC F		JCN 0910123		TAG NO.		CF TO 781A DATED P / /		TRANSFERRED TO 781K DATE / /		
DISCREPANCY									CORRECTIVE ACTION					
DATE CORRECTED 01/04/5														

DATE FROM		TO	CREW CHIEF	ORGN	LOCATION	MDS	SERIAL NO.	PAGE 18 OF	PAGES
31/03/5		/	/	WUMAN	7AF15 CH	C-577	68-319		
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K	DATE	TRANSFERRED BY
X	01/04/5	F	0910123		P	/ /	/ /	/ /	
DISCREPANCY					CORRECTIVE ACTION				
#4 ENG FAN STOPPER INSTALLED					XDAT				
					FAN STOPPER RE-MOVED				
					DATE CORRECTED				
					01/04/5				
DN	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
	R Emery L-10			W Palen W-10			R Emery L-10		
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K	DATE	TRANSFERRED BY
X	01/04/5	F	0910123		P	/ /	/ /	/ /	
DISCREPANCY					CORRECTIVE ACTION				
Panel 4233-4 RT. wing					XDAT				
opened F.O.M.					PANEL #4233-4				
					INSTALLED				
					DATE CORRECTED				
					01/04/5				
DN	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
	A. Johnson W-10			W Palen W-10			R Emery L-10		
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K	DATE	TRANSFERRED BY
X	01/04/5	F	0910123		P	/ /	/ /	/ /	
DISCREPANCY					CORRECTIVE ACTION				
RT. APU door open					XDAT				
F.O.M.					RT APU DOOR CLOSED				
					DATE CORRECTED				
					01/04/5				
DN	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
DB	A. Johnson W-10			W Palen W-10			R Emery L-10		
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K	DATE	TRANSFERRED BY
	02/04/5				P	/ /	/ /	/ /	
DISCREPANCY					CORRECTIVE ACTION				
Flight #1 TRAVEL - NICKAR									
					DATE CORRECTED				
					/ /				
DN	DISCOVERED BY			CORRECTED BY			INSPECTED BY		
				1					

DATE FROM 21/07/5		TO / /		CREW CHIEF		ORGN 601AN		LOCATION TATM		MDS C-57A		SERIAL NO. 65			
SYM /		DATE DISCD 02/04/5		WDC /		JCN /		TAG NO.		CF TO 781A P 1		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY Left AF Rail Catwalk Missing										CORRECTIVE ACTION					
DN										DISCOVERED BY P. Smith RGT		CORRECTED BY		INSPECTED BY	
SYM /		DATE DISCD 02/04/5		WDC /		JCN /		TAG NO.		CF TO 781A P 1		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY R-T/D Rail Venticle Restraint Flange Hold down Plate Missing										CORRECTIVE ACTION					
DN CM										DISCOVERED BY P. Smith RGT		CORRECTED BY		INSPECTED BY	
SYM /		DATE DISCD 02/04/5		WDC /		JCN /		TAG NO.		CF TO 781A P 1		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY Burn - Aft Stair deck 2 seat Cushions Right side										CORRECTIVE ACTION					
DN CM										DISCOVERED BY P. Smith RGT		CORRECTED BY		INSPECTED BY	
SYM /		DATE DISCD 02/04/5		WDC /		JCN /		TAG NO.		CF TO 781A P 1		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY Belief Green Comp. PT. Floor Needs repainting										CORRECTIVE ACTION					
DN										DISCOVERED BY		CORRECTED BY		INSPECTED BY	
SYM /		DATE DISCD 02/04/5		WDC D		JCN /		TAG NO.		CF TO 781A P 1		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY										CORRECTIVE ACTION					
DATE CORRECTED / /															
DN										DISCOVERED BY		CORRECTED BY		INSPECTED BY	

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN COMAW	LOCATION TAFB, CA	MDS C-5A	SERIAL NO. 68-218	
SYM /	DATE DISCD 02/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P I / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY PILOTS INST. LT. RHIOSTAT (OH PANEL) EXTREMELY LOOSE.				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 02/04/5	WDC D	JCN 0934/16	TAG NO.	CF TO 781A DATED P I / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY COPILOTS YOKER. INTERCOM BUTTON STICKS. <u>WMC</u>				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 02/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P I / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY FLT ENG INTERCOM LONG CORR INDP IN XMIT, OK RECIEVE.				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							
SYM /	DATE DISCD 02/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P I / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY PILOTS RUDDOR PEDS HARD TO ADJUST.				CORRECTIVE ACTION			
DN				DISCOVERED BY	CORRECTED BY	INSPECTED BY	
DATE CORRECTED / /							

DATE FROM 31/03/5	TO 1/1	CREW CHIEF	ORGN HUMAN	LOCATION TAFM 18	MDS C-5A	SERIAL NO. 69-218		
SYM A	DATE DISCD 02/04/5	WDC D	JCN	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY PILOTS HSI HARD TO SET COURSE.				CORRECTIVE ACTION OPS OK PILOTS HSI BOTH REMOTES & NORMAL MODE S43CK GOOD IAW IC 5A-2-6				
DN				DISCOVERED BY		CORRECTED BY J. Dunn MSgt		INSPECTED BY
SYM A	DATE DISCD 02/04/5	WDC D	JCN 0934117	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY PILOTS HSI COMPASS CARD STICKS.				CORRECTIVE ACTION OPS CK #1 HSI INDICATING SYS. SYS CK GOOD IAW KSA-2-6 AND IC 5A-2-8				
DN				DISCOVERED BY		CORRECTED BY J. Dunn MSgt		INSPECTED BY
SYM A	DATE DISCD 02/04/5	WDC D	JCN 0934118	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY ROLL/YAW/PACS AUTOPILOT COMPUTER FAILED (LRU 5005)-(5048)(5775)(5777)-ALL IN FLT TROUBLE SHOOTING PROCEDURES FOR ABOVE LRU FAILURES SHOW COMPUTER FAILURE.				CORRECTIVE ACTION DULK REMOVED & REPLACED ROLL YAW PACS COMPUTER. SYS OPS CK OK IAW IC-5A-2-9				
DN				DISCOVERED BY		CORRECTED BY J. Dunn MSgt		INSPECTED BY
SYM A	DATE DISCD 02/04/5	WDC D	JCN	TAG NO.	CF TO 781A P 1	DATED / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY Loran Tape Cartridge TORN (MC)				CORRECTIVE ACTION Replaced TAPE and Programmed system. OPS CHK OK (DULK)				
DN				DISCOVERED BY		CORRECTED BY J. Dunn MSgt		INSPECTED BY

DATE FROM 31/03/5		TO / /		CREW CHIEF		ORGN 60 MAW		LOCATION TAFO CA		MDS C-5A		SERIAL NO. 68-218			
SYM /		DATE DISCD 02/04/5		WDC D		JCN		TAG NO.		CF TO 781A P I		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY PRES. SEAL LEAKING, PRESSURE DOOR RT. SIDE UPPER HINGE POINT, C/E SFF WGE 5 T/FAL 1										CORRECTIVE ACTION					
DN										DISCOVERED BY		CORRECTED BY		INSPECTED BY	
SYM X		DATE DISCD 02/04/5		WDC D		JCN		TAG NO.		CF TO 781A P I		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY #2 HYD SUCTION BOOST PUMP FAILING. WITH BOTH PUMPS ON QUANTITY FLUXATES + PUMP VIBRATION CAN BE FELT IN RESERVOIR WITH BOTH HYD										CORRECTIVE ACTION REMOVED + REPLACED #2 SYS. RESERVOIR HYD SUCT. LAST PUMP PRESS FOR CK. GOOD TUN KSA-2-3					
DN										DISCOVERED BY		CORRECTED BY		INSPECTED BY	
SYM /		DATE DISCD / /		WDC /		JCN		TAG NO.		CF TO 781A P I		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY PUMPS DEPRESSD + 1/2 PTU ON QUANTITY FLUX CREASES, BUT VIBRATION CAN STILL BE FELT IN RESERVOIR ME										CORRECTIVE ACTION					
DN										DISCOVERED BY		CORRECTED BY DGUA		INSPECTED BY Thomas T2599 Harilla SGT	
SYM X		DATE DISCD 03/04/5		WDC		JCN		TAG NO.		CF TO 781A P I		DATED / /			
										TRANSFERRED TO 781K		DATE / /			
DISCREPANCY #1 HF X-MIT & REC OFF FREQ MC										CORRECTIVE ACTION REPAIRED TRAX CONN. AT RE TIGHTENED ALL RF CONN. SYSTEM OF CI GOOD TUN 70. 10-3A-2-3 (DGUA)					
DN										DISCOVERED BY		CORRECTED BY Powers Sgt 2139		INSPECTED BY	
														DATE CORRECTED C3/04/5	

DATE FROM 31/03/5	TO / /	CREW CHIEF	ORGN	LOCATION	MDS C-5A	SERIAL NO. 68-218	
SYM X	DATE DISCD 03/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY #2 HF WILL NOT X-MIT OR CHANNELIZE				CORRECTIVE ACTION TIGHTENED RECEIVER EXCITER IN MOUNT AND RF CONNECTORS. SYSTEM OP CH GOOD JAW T.O.			
DN				DISCOVERED BY <i>[Signature]</i>	CORRECTED BY <i>[Signature]</i>	INSPECTED BY	DATE CORRECTED 03/04/5
SYM X	DATE DISCD 03/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY #4 top pump excessive case drain flow				CORRECTIVE ACTION PRESS. TOP CK. OF #4 TOP HYD PUMP GOOD IC-5A-2-3 (PGUA)			
DN				DISCOVERED BY PGUA	CORRECTED BY <i>[Signature]</i>	INSPECTED BY	DATE CORRECTED 03/04/5
SYM X	DATE DISCD 03/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY LT APU GEN fact cycles out of limits				CORRECTIVE ACTION LT APU GEN cycles WITHIN LIMITS INK TO IC-5A-2-4CL-1			
DN				DISCOVERED BY PGUA	CORRECTED BY DULC	INSPECTED BY	DATE CORRECTED 03/04/5
SYM X	DATE DISCD 03/04/5	WDC D	JCN	TAG NO.	CF TO 781A DATED P 1 / /	TRANSFERRED TO 781K DATE / /	TRANSFERRED BY
DISCREPANCY RT APU GEN Low FREQ				CORRECTIVE ACTION APU Gen Sys. Ops checked On Freq. 1000 Hz			
DN				DISCOVERED BY <i>[Signature]</i>	CORRECTED BY T. H. H. O.	INSPECTED BY <i>[Signature]</i>	DATE CORRECTED 03/04/5

DATE FROM	TO	CREW CHIEF	ORGN	LOCATION	MDS	SERIAL NO.	
/ /	/ /				C-5A	68-218	
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
NPD	03/04/5	F			P / /	/ /	
DISCREPANCY				CORRECTIVE ACTION			
DRUG Insp DUE				DRUG Insp CW			
							DATE CORRECTED
							03/04/5
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
	7625 Doughan 159T			7625 Doughan 159T			
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	F			P / /	/ /	
DISCREPANCY				CORRECTIVE ACTION			
ALL ENGINES DUE FOD				ENG INLET Insp CW			
Insp PRIOR TO ENGINE				NO FOD NOTE			
START							
							DATE CORRECTED
							03/04/5
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
	7625 Doughan 159T			7625 Doughan 159T			
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	B	0734420		P / /	/ /	
DISCREPANCY				CORRECTIVE ACTION			
Shut DOWN #2 ENG AT 0400							
Z, (FRAME 2070) FAN DOMINANT 3/4							
SCALE DIVISIONS VIB. (FRAME 2072)							
TROUBLE SHOOTING ROUTINE. ABNORMAL							
CORE VIBRATIONS, MORE THAN 3, BUT							
LESS THAN 5							DATE CORRECTED
							/ /
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
	7625 Doughan 159T			7625 Doughan 159T			
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
↓	↓ /	↓	↓	↓	P / /	/ /	
DISCREPANCY				CORRECTIVE ACTION			
SCALE DIVISIONS. (FRAME 2073)							
3.0 SCALE DIV. VIBRATION.							
(FRAME 2075) ROUTINE-3/4							
SCALE DIV VIB, FAILURE. EXCESS-							
IVE FAN VIBRATION. #2 ENG							DATE CORRECTED
							/ /
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
	C/F SEC PROC 37 ITPM 4						

DATE FROM	TO	CREW CHIEF	ORGN	LOCATION	MDS	SERIAL NO.	
1/1	1/1				C-5A	68-218	
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
03/04/5	D				P 1	1/1	
DISCREPANCY				CORRECTIVE ACTION			
Eng's Seat will not swivel							
				DATE CORRECTED			
				1/1			
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
03/04/5	D		0934121		P 1	1/1	
DISCREPANCY				CORRECTIVE ACTION			
On Decent #2 Eng CSD Fail				CSD FAIL LT CAME ON			
Light came on. CSD disconnected.				BECAUSE ENG WAS SHUT			
				DOWN. RECONNECTED CSD			
				DATE CORRECTED			
				DULK 13/04/5			
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
				W. Kelly 559540			
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
03/04/5	D				P 1	1/1	
DISCREPANCY				CORRECTIVE ACTION			
No 4 Throttle will not							
maintain settings with throttle							
friction applied.							
				DATE CORRECTED			
				1/1			
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
03/04/5	D		0934122		P 1	1/1	
DISCREPANCY				CORRECTIVE ACTION			
X BAND MMR cursors did							
NOT WORK UPON 3 ATTEMPTS.							
MONITORING APPROACH							
May A-D 0 BAL							
C/F #1261							
				DATE CORRECTED			
				1/1			
DN	DISCOVERED BY			CORRECTED BY		INSPECTED BY	
J. T. O'Connell							

DATE FROM	TO	CREW CHIEF	ORGN	LOCATION	MDS	SERIAL NO.	
03/04/5	D	0934123			C-5A	65-218	
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	D	0934123		P I / /	/ /	
DISCREPANCY #1 HF xmits garbled & off frequency (Repeat) me					CORRECTIVE ACTION SWAPPED REC. EXT. FROM #2HF SYS OIC/G IAW TO IC-SA-2-8		
					(DVLK)		
DN	DISCOVERED BY				CORRECTED BY	INSPECTED BY	DATE CORRECTED
					G. H. T. SGT		03/04/5
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	D	0934124		P I / /	/ /	
DISCREPANCY #2 HF channelizes each x-mit however no airborne answer					CORRECTIVE ACTION		
UAC @ BAL CF COMPLIFIER 0101662 REGENER EXCITER 0101663 (DVLK)							
DN	DISCOVERED BY				CORRECTED BY	INSPECTED BY	DATE CORRECTED
							/ /
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	F	0934311		P I / /	/ /	
DISCREPANCY ALL FOUR ENG FAN STOPPERS INSTALLED					CORRECTIVE ACTION All Low Tail stops removed		
					(DVLK)		
DN	DISCOVERED BY				CORRECTED BY	INSPECTED BY	DATE CORRECTED
	M. Pelletier SSGT				M. O'Kernore	O. C. Williams	03/04/5
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY
X	03/04/5	F			P I / /	/ /	
DISCREPANCY #2 ENG VIB PICKUPS OR MADDER BAD INSPECTED ALL FILTERS, FAN, ENGINE SOAP SAMPLES + FILTERS GOOD C/F HOME STA SEE PAGE 25					CORRECTIVE ACTION		
ITEM 3							
DN	DISCOVERED BY				CORRECTED BY	INSPECTED BY	DATE CORRECTED
	W. Muller SS 9540						/ /

DATE FROM		TO		CREW CHIEF		ORGN		LOCATION		MDS		SERIAL NO.	
01/04/5		F		0934115				CF TO 781A DATED		TRANSFERRED TO 781K DATE		TRANSFERRED BY	
DISCREPANCY						CORRECTIVE ACTION							
ALL ELECTRICAL LEADS						CONNECTED LEADS							
TO CO-PILOTS						IAW 10-5A-2-11							
WINDSHIELD													
DISCONNECTED TO													
E.O.M.						DATE CORRECTED 04/04/5							
DN		DISCOVERED BY		M. R. [Signature]		CORRECTED BY		L. [Signature]		INSPECTED BY		W. [Signature]	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
04/04/5		F		093-						P 1			
DISCREPANCY						CORRECTIVE ACTION							
SMALL CRACKED ON INNER													
SURFACE OF CO-PILOTS													
FRONT WINDSHIELD. CRACKED													
AT UPPER RT CORNER (WITHIN													
LIMIT IAW 10-5A-2-3) DULK						DATE CORRECTED							
DN		DISCOVERED BY		[Signature]		CORRECTED BY				INSPECTED BY			
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
04/04/5		F		1						P 1			
DISCREPANCY						CORRECTIVE ACTION							
Both #2 Eng Vib													
Transducers Bad													
[Signature]													
DN		DISCOVERED BY		CF H.S. DULK		CORRECTED BY		[Signature]		INSPECTED BY			
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
04/04/5		F								P 1			
DISCREPANCY						CORRECTIVE ACTION							
FLT ENG LOW INTERPHONE													
CORD WILL NOT XMIT. REV.													
DN.													
DN		DISCOVERED BY				CORRECTED BY				INSPECTED BY		DATE CORRECTED	

DATE FROM		TO		CREW CHIEF		ORGN		LOCATION		MDS		SERIAL NO.	
/ /		/ /								C-5A		68-218	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
/ /		07/04/5								P I / /		/ /	
DISCREPANCY										CORRECTIVE ACTION			
AFT FLIGHT DECK GALLEY Will Not													
Recieve Portable Water from													
Water Truck. When Truck Is Connected													
To Ground Connection, Water Over													
Flows In Watrin										DATE CORRECTED / /			
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
/ /		/ /								P I / /		/ /	
DISCREPANCY										CORRECTIVE ACTION			
										DATE CORRECTED / /			
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
/ /		/ /								P I / /		/ /	
DISCREPANCY										CORRECTIVE ACTION			
										DATE CORRECTED / /			
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
/ /		/ /								P I / /		/ /	
DISCREPANCY										CORRECTIVE ACTION			
										DATE CORRECTED / /			
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY	
SYM		DATE DISCD		WDC		JCN		TAG NO.		CF TO 781A DATED		TRANSFERRED TO 781K DATE	
/ /		/ /								P I / /		/ /	
DISCREPANCY										CORRECTIVE ACTION			
										DATE CORRECTED / /			
DN				DISCOVERED BY				CORRECTED BY				INSPECTED BY	

AFTO FORM 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT
(PAGE 58 OF 70 PAGES)

REFLECTING REMOVAL OF TIE ROD ASSEMBLIES

ON 16 MARCH 1975 AND REINSTALLATION ON 24 MARCH 1975

AFTO FORM 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT
(PAGE 67 OF 70 PAGES)

REFLECTING RIG CHECK DUE AS RESULT OF

INSTALLATION OF TIE ROD ASSEMBLIES DATED 24 MARCH 1975

DATE FROM		TO		CREW CHIEF		LOCATION		MDS	SERIAL NO.
07/03/5		27/03/5						C-5A	68-218
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY	
	24/03/5	F	0830008		P	/ /	/ /		
DISCREPANCY					CORRECTIVE ACTION				
EACK gen Dm - a card					press a t o r good				
LEAK check Due To change					In Am - SA - 2				
					DATE CORRECTED 21/03/5				
ON					DISCOVERED BY <i>[Signature]</i>		CORRECTED BY <i>[Signature]</i>		INSPECTED BY
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY	
X	24/03/5	F	0840512		P	26/03/5	/ /	<i>[Signature]</i>	
DISCREPANCY					CORRECTIVE ACTION				
RIG CHECK DUE IN APT									
RAMP RIG AT SIDE Dm ZI									
INSTALLATION OF Pump TUG RODS									
BETWEEN 2 & 3 AND 3 & 4 LUGS									
RIGID PACE 58 BLOCK 1 & 2									
					DATE CORRECTED / /				
ON					DISCOVERED BY <i>[Signature]</i>		CORRECTED BY		INSPECTED BY
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY	
X	24/03/5	F	0830008		P	/ /	/ /		
DISCREPANCY					CORRECTIVE ACTION				
At Bolt hole Striped					Repaired striped hole				
ON Crew Refrigerator									
					DATE CORRECTED 25/03/5				
ON					DISCOVERED BY <i>[Signature]</i>		CORRECTED BY <i>[Signature]</i>		INSPECTED BY
SYM	DATE DISCD	WDC	JCN	TAG NO.	CF TO 781A	DATED	TRANSFERRED TO 781K DATE	TRANSFERRED BY	
X	25/03/5	F	1839541		P	/ /	/ /		
DISCREPANCY					CORRECTIVE ACTION				
Anti skid will not					installed IC-3C				
Pass Bite ok					press switch				
IC-3C press switch					IN W IC-5A-2-10				
hand					usec pg 68 b/k 1				
					DATE CORRECTED 25/03/5				
ON					DISCOVERED BY <i>[Signature]</i>		CORRECTED BY <i>[Signature]</i>		INSPECTED BY

AF10 FORM 781A

MAINTENANCE DISCREPANCY AND WORK DOCUMENT
(PAGE 18 OF 55 PAGES)

REFLECTING RIG CHECK DUE NOTED ON 24 MARCH 1975

AND THE ACCOMPLISHMENT OF RIG CHECK ON 29 MARCH 1975

22AF/LGM

LTR

24 JULY 1975

35 METALLURGICAL ANALYSIS REPORTS

PREPARED BY

METALLURGICAL LABORATORY

SAN ANTONIO AIR LOGISTICS CENTER

KELLY AIR FORCE BASE, TEXAS

A-1
26 April 1975

MME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

6 Left Side Bellcrank & Pushrod

23 Apr 75

Task # 1128 Attachment # 1

#142

Metallurgical Analysis

1. Two failed pieces of Bellcrank identified as No 6 left side bellcrank and pushrod were submitted for analysis as per attachment #1 of basic MME Task 1128.
2. Photographs of the exhibits as received are identified as Photo 1 and Photo 2, and also shows where metallurgical specimen was taken, along with the TEM (Transmission Electron Microscope) fractographs.
3. Spectrographic analysis identified the material of the two failed pieces as 7075 aluminum alloy, with a Rockwell hardness of R_p 92, this indicates the material is in a T6 heat treated condition. The bellcrank arm that failed showed that there was some evidence of shot peening on the inside where no paint was present, about 50% coverage.
4. Visual and microscopic examination of the thin rib section fracture surfaces showed that area where metallurgical sample was taken (See photo 3) there was considerable corrosion on the fracture surface which indicates it could have been open for sometime, other fractured surfaces did not show this condition (See photos 4 & 5). Also this area (Photo 3) revealed a "Chevron" pattern on the surface which points to the origin of failure, and sometimes is associated with fatigue. Most of the fractures on other areas was caused by excessive overload from the steel stud on the rear of bellcrank, which tore through the complete thickness of the bellcrank with some sliding to the side.
5. Metallurgical & TEM analysis revealed the fracture on the arm portion of the bellcrank showed stress-corrosion cracking on the surface at the area indicated in photo 2 (Met specimen). In stress-corrosion cracking the initiation and growth of cracks, or the extension of cracks, result from the combined action of a corrosive and applied or residual stresses. Fractures in high-strength aluminum alloys such as this, are distinctly intergranular when fracture occurs by stress-corrosion cracking, and the continuous grain-boundary path in the short transverse direction of wrought products makes this direction least resistance to stress-corrosion cracking. TEM fractographs (See photos 9 & 10) shows stress-corrosion facets along with some dimpling, (A dimple is half of a microvoid through which fracture has occurred) and corrosion debris on the flat intergranular surface.
6. Conclusion: The failure of the bellcrank was initiated by stress-corrosion which was found present (See photos 9 & 10). Other fractures on the assembly were found to be of the overload (impact) type failures.

JOHN PARKER, Metallurgist

1 Atch

Photos 1 thru 10

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section

MA

29 April 1975

MME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

#6 Left Side Bellcrank & Pushrod

23 Apr 75

Task #1128, Attachment #1

#142

Metallurgical Analysis

1. The following additional information was requested after report was typed. Additional fractographs were made on fracture surfaces of areas designated as "A" and "B" on photo 2.
2. These fractographs furnished additional confirmation of stress corrosion as shown in photos 11 thru 14.

SIGNED

JOHN PARKER, Metallurgist

1 Atch
Photos -11 thru 14

SIGNED

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA




Photo 1

No 6 Left side Bellcrank & Pushrod - Showing the exhibit as received here in the Metallurgical Laboratory.




Photo 2

No 6 Left side Bellcrank & Pushrod - Showing the areas where metallurgical specimen & TEM fractograph were taken, notice the corrosive product (blackened areas) where Met specimen was taken.




Photo 3

No 6 Left side Bellcrank & Pushrod - Showing the fractured surface where metallurgical specimen were taken, notice the "Chevron" pattern (pointing to the right) leading to the origin of fracture. This thin rib section is where there was corrosion on the surface.




Photo 4

No 6 Left side Bellcrank & Pushrod - Showing the fractured surface on another area, no corrosion was noted on this surface. The woody appearance is typical for this type of material because of excessive overload that created it.




Photo 5

No 6 Left side Bellcrank & Pushrod - Showing the fractured surface with the same condition as reported in photo 4.




Photo 6

No 6 Left side Bellcrank & Pushrod - Showing the fractured surface that fits around the large steel stud & sleeve, this where Transmission Electron Microscopic (TEM) specimen was taken, no corrosion appears on the surface.



Photo 7 200X

No 6 Left Side Bellcrank & Pushrod - Showing a polished & etched metallographic specimen of 7075-T6 aluminum alloy with the fracture surface in profile at the top, notice the "leaves" on top fracture surface, these "leaves" indicate stress-corrosion was attacking the grains at the grain boundary and intergranularly.




Photo 8 500X

No 6 Left Side Bellcrank & Pushrod - Showing a polished & etched metallographic specimen of 7075-T6 aluminum alloy with fracture surface in profile at the top, notice the grains are very elongated, which facilitated propagation of both the primary fracture and the secondary crack shown under the fracture surface.




Photo 9 4000X

No 6 Left Side Bellcrank & Pushrod - Showing a TEM fractograph of the fractured surface mentioned in photo 2 (TEM Specimen). The facet shows stress-corrosion covers nearly all of the surface of the fracture.



Photo 10 4000X

No 6 Left Side Bellcrank & Pushrod - Showing a TEM fractograph of the fractured surface with stress-corrosion and dimpling, there is some debris on the flat intergranular surface.




Photo 11 5600X



Photo 12 5600X




Photo 13 5600X




Photo 14 5600X

MME-3/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

Left Side No 6 Saddle Fitting

23 Apr 75

Attachment 2, Task 1128

#142

Metallurgical Analysis

1. A failed number 6 saddle fitting from the left side was submitted for analysis as specified in attachment 2 of basic MME task 1128.
2. Spectrographic analysis showed that subject fitting was made of material conforming to type 7075 aluminum alloy.
3. The failure involved a crack in the web area of the fitting. Also, three battered areas associated with the failure were noted (see photos #1 and #2). Photograph #3 shows paint flakes and stains on one of the damaged areas. The color of the paint was similar to the paint on the fitting itself.
4. Fractographic analysis of the fractured surface revealed small and flat dimples characteristic of a shear overload failure (reference photo #4).
5. Conclusion: it was determined that the failure (crack) was caused by an impact load that caused the web to crack in a shear fracture mode. The damage observed was also caused by foreign object impact.

MARCOS R. SOLIS
Metallurgist

1 Atch
Photos 1 thru 4

O. H. DOUGLASS, JR
Chief, Metallurgical Laboratory Section
MA




Photo 1. Saddle fitting as received. Arrows point to crack and damaged areas.




Photo 2. Close up view of crack and associated damaged area.



Photo 7 200X

No 6 Left Side Bellcrank & Pushrod - Showing a polished & etched metallographic specimen of 7075-T6 aluminum alloy with the fracture surface in profile at the top, notice the "leaves" on top fracture surface, these "leaves" indicate stress-corrosion was attacking the grains at the grain boundary and intergranularly.





Photo 8 500X

No 6 Left Side Bellcrank & Pushrod - Showing a polished & etched metallographic specimen of 7075-T6 aluminum alloy with fracture surface in profile at the top, notice the grains are very elongated, which facilitated propagation of both the primary fracture and the secondary crack shown under the fracture surface.



Photo 3. Battered surface revealed paint stains and paint flakes similar in color to the fitting paint.



5600X

Photo 4. Shear dimples typical of a shear overload failure as revealed in fractographic analysis.

C-1
28 April 1975

NME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

Left Side - No 7 Hook Bellcrank Assembly

23 Apr 75

Task #1128, Attachment 3

#142

Metallurgical Analysis

1. One CSA left side No 7 hook bellcrank assembly was submitted to the Metallurgical Laboratory to determine if any cracks were present, and to evaluate possible impact damage to the 55K capacity hook as requested on Task 1128. Photo #1.

2. NDI Inspection was requested to determine if any additional cracks were present. (See attached report).

3. Visual and microscopic examinations revealed the following:

a. Photo #2 & #2A taken at two different angles illustrate that the 34K capacity cargo ramp lock had suffered impact damage in two directions.

b. Photos #3 & #3A taken of the assembled and disassembled bolt assembly indicator mechanism cargo ramp lock illustrate points of impact. Also seen in photo #3A is the direction of bending after impact.

c. Photos #4 & #4A as requested in attachment 3 illustrate damage to the left side of the hook (Black arrow).

d. Photos #5 & #6 taken along the 34K capacity cargo ramp lock fracture surfaces, revealed possible signs of corrosion.

e. TEM (Transmission Electron Microscope) fractograph taken along the fracture faces (Photos #5 & #6), confirms the presence of stress-corrosion. Photo #7.

4. Conclusion: Failure to the bellcrank was brought about by stress-corrosion which was confirmed in Photo #7. Other fractures on the bellcrank assembly were found to be of the overload type.

DAVID BARRERA, Metallurgist

2 Atch
1. Photos 1 thru 7
2. NDI Report

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA

24 Apr 75

MANCE/Mr Barrera

MANCD/Nondestructive Testing Lab - Sec

C5 Acft Lock Assembly

24 Apr 75

MANCE/Task 1128 Attachment 3

75-76

Cracks

1. One each Acft Ramp Lock Assembly was received by MANCD for nondestructive testing. Assembly was identified as Acft Ramp Lock Assembly, Left Side #7 Canted Fus Sta 1231, Ramp Sta 154.

2. Specimen assembly was disassembled and processed as follows:

a. All assembly components made from ferro-magnetic materials were processed by the magnetic particle method, using longitudinal and circular fields and the wet continuous method of particle application.

b. All assembly components made from non-magnetic materials were processed by the liquid penetrant method using inspection materials Type I, Method "B", MIL- I- 25135C, Group VI, with the family concept emulsifier and dry fluidized developer.

3. Inspection results:

a. Magnetic Particle Inspection: No discrepancies were noted on all ferro-magnetic components inspected.

b. Liquid Penetrant Inspection: Inspection revealed cracks on two components made of non-magnetic materials. Defective components were identified as follows:

(1) Bolt Assembly, Indicator Mechanism, Ramp Lock, P/N 4F 53 744-101A, ✓
TO 1G- 2A- 4- 1, Fig 182- 248.

(2) Bellcrank, 34K Capacity, Ramp Lock P/N 4F 53693-10C. TO 1G- 5A- 4- 1, ✓
Fig 182- 155.

4. All defective areas were marked.

Jose N. Garcia
Qty Assr Spec

REYNALDO R. RAMOS
Acting Ch, NDI Lab Sec




Photo #1
As received No #7 Hook Bellcrank Assembly.




Photo #2
Cracked Bellcrank, 34K capacity cargo ramp lock.




Photo #2A

Cracked 34K capacity cargo ramp lock (front angle)
illustrates impact damage in two directions.




Photo #3

Bolt Assembly Indicator Mechanism cargo ramp lock exhibits impact damage at three points.




Photo #3A


Illustrates impact points as well as direction of bending.




Photos #4 & #4A

Taken of the 55K Hook capacity illustrate damage to the left side of the hook. It should be noted in Attachment #10, No 5, left side bellcrank, Photo #8, that damage has also occurred on the left side.





Photos #5 & #6
Taken from the 34K capacity
cargo ramp lock fracture
face.






Photo #7

3000X

Fractograph taken along fracture surface illustrates "mud cracking" pattern, which is typical of stress corrosion.

28 April 1975

MME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

Aft Ramp Section 4-4

23 Apr 75

Task 1128, Attachment 4

142

Metallurgical Analysis

1. One failed aft ramp section 4-4 was submitted to the Metallurgical Laboratory for analysis in support of Task 1128.
2. Macro and microscopic investigation revealed most of the fractures exhibited a cleavage fracture by overload. Photo #1 identifies the location of samples taken from the aft ramp section. Photo #2 shows the direction in which the initial load was applied. Photo #3 exhibits a cleavage overload. Photo #4 shows a tearing or shearing action propagated by overload.
3. The direction of loading to cause this failure initiated underneath the left side of the leading edge of the aft ramp section (Photo #2). It progressed upward and diagonally across the ramp section to the right side. When this load initiated and progressed, another load was applied on the right side of the aft ramp section from the top side. Further substantiation of the initial load can be attested by the shearing action of the rivets in the leading edge of the aft ramp section.

SIGNED

W. H. CROCKER, Metallurgist

1 Atch
Photos #1 thru #4

SIGNED

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA




Photo 1. Identifies Location of Samples from Aft Ramp Section.




Photo 2. Shows Direction of Initial Overload.




Photo 3. Exhibits Cleavage Overload.




Photo 4. Shows Tearing and Shearing Action Propagated by Overload.

29 April 1975

MME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

Right B. L. 84 Hinge

23 Apr 75

Task #1128, Attachment #5

142

Metallurgical Analysis

1. One Right B. L. 84 Hinge was submitted for metallurgical analysis in support of MME Task #1128, Attachment #5. Photo #1.
 2. Spectrographic analysis of the three sectioned and mounted samples is as follows: (See Photo #1)
 - a. Sample #1 - 7075 aluminum alloy
 - b. Sample #2 - 7075 aluminum alloy
 - c. Sample #3 - 7075 aluminum alloy
 3. Hardness test taken on the Knoop scale and converted to the Rockwell hardness scale revealed the following:
 - a. Sample #1 - Rb-83
 - b. Sample #2 - Rb-80
 - c. Sample #3 - Rb-83
- Hardness readings taken from the three mounted samples place the 7075 aluminum alloy within the T-6 condition.
4. Initial microscopic and visual examination of the three specified areas, as seen in Photo #1, revealed the following:
 - a. Samples #1 & #2, Photos #2 & #4, which were located on the hinge left side, facing forwards, exhibited similar fractures. Metallurgical examination revealed a combination of tensile cup followed by tensile shearing to the left.
 - b. Sample #3, Photo #3, was taken from the hinge mid section and exhibited shearing in two directions.
 5. Conclusions: Failure to the Right B. L. 84 Hinge was the result of first, tension pulling followed by secondary tensile tear or shear on aircraft impact.

DAVID BARRERA, Metallurgist

1 Atch
Photos 1 thru 4

O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA



Photo #1
As received Right B. L. 84 Hinge








Photo #2
Taken from fractured surfaces marked sample #1 exhibit areas of impact (Arrow) and shearing in a reverse direction.




Photos #3
Taken from fractured sample #3 illustrates tensile tear and shearing
in two directions. (Arrows)





Photos #4
From the fractured surface marked sample #2 exhibit the same mode of fracture as shown in Photos #2



28 April 1975

ME-5/Capt Gregory/Capt Scheiding/57845

MANCE (Metallurgical Laboratory)

Left B. L. 84 Hinge

23 Apr 75

Task #1128 Attachment #6

#142

Metallurgical Analysis

1. One failed left B. L. 84 hinge was submitted to the Metallurgy Lab for analysis in support of Task #1128, Attachment #6.
2. Photographs were taken of the damage of the failed hinge. Photos 1 & 2.
3. Visual and microscopic examination of the specified fractured area revealed a cycling tensile shear mode of failure. This can be attested to by the plane of fracture from top to bottom with a tearing action between each cycle. Photo 3. Evidence of a rubbing action was observed between cycles. Three samples were selected as designated from area of concern. Samples were identified as #1, #2 and #3. Photo 3.
4. Sample #1 under microscopic analysis revealed tensile tear or shear brought about by overload. Photo 4.
5. The remaining samples exhibited the same mode of failure except the change of plane in which the fracture occurred. Photos 5 & 6. Sample #3 displays the phenomena of the reversal of the tensile shear. Photo 7. It is quite evident that the load had changed back and forth with great force.
6. Additional samples were sectioned to establish direction of load. They were designated as 1A - 2A - 2B. Photo 2. Sample 1A, the bottom fracture is typical of a tensile cup initiated by overload. Photo 8. The top fracture developed through tensile shear. Photo 8. Sample 2A, the top fracture exhibits a tensile cup in the middle and a tensile shear on the left, both by an overload mechanism. Photo 9. The bottom fracture shows a tensile shear, in two stages, induced by a bending action. Photo 9. Sample 2B failed by a double action tensile shear brought about by overload. Photo 10. All these samples attest to the directionality of the tension overload.
7. Conclusions: The load to propagate this failure was applied in tension pull, photo 2, with a secondary load developing in tensile shear. Photo 1. Extensive rubbing by vibration is also prevalent in fractures throughout the B. L. 84 Hinge.

W. H. CROCKER, Metallurgist

1 Atch
Photos 1 thru 10O. H. DOUGLASS, JR.
Chief, Metallurgical Lab Section
MA




Photo 1
Identifies the secondary directional
tension load. Also identifies the
B. L. left hinge.




Photo 2
Shows primary direction of load.
Tension. Identifies fractures to
substantiate the loading direction.
1A - 2A - 2B.