

JAMES M. ESTABROOK
EDWARD H. MAHLA
JOHN C. MOORE
MAC DONALD DEMING
GORDON W. PAULSEN
M. E. DEORCHIS
DAVID P. H. WATSON
RICHARD G. ASHWORTH
EDWARD L. JOHNSON
RICHARD B. BARNETT
MAURICE L. NOYER
SANFORD C. MILLER
FRANCIS X. BYRN
THOMAS R. H. HOWARTH
STEPHEN K. CARR
WALTER E. RUTHERFORD
R. GLENN BAUER
THEODORE M. SYSOL
CARROLL E. DUBUC
THOMAS F. MOLANPHY
LENNARD K. RAMBUSCH
JAMES J. SENTNER, JR.
RANDAL R. CRAFT, JR.
WILLIAM J. HONAN III
CHESTER D. HOOPER
EMIL A. KRATOVL, JR.
JOHN J. REILLY
BARTON T. JONES
RICHARD D. BELFORD
BRIAN D. STARER
ROBERT B. HASEROT
JOHN K. WEIR
JUAN A. ANDUZA
DONALD J. KENNEDY
RICHARD L. JARASHOW
WILLIAM F. PAN
ALAN B. WINSOR
THOMAS J. WHALEN
TEMPLE L. RATCLIFFE

HAIGHT, GARDNER, POOR & HAVENS

FEDERAL BAR BUILDING

1819 H STREET, N.W.

WASHINGTON, D.C. 20006

CABLE: MOTOR WASHINGTON

WU: TELEX 892598

TELEPHONE (202) 737-7847

BERNARD D. ATWOOD

SPECIAL PARTNER

J. WARD O'NEILL

COUNSEL

NEW YORK OFFICE

ONE STATE STREET PLAZA

NEW YORK, N.Y. 10004

TEL (212) 344-6800

CABLE: MOTOR NEW YORK

RCA TELEX: 222974

WUI TELEX: 620362

ITT TELEX: 424674

WU TELEX: 127683

PARIS AFFILIATE

FRANCOIS LEGREZ

34, AVENUE GEORGE V

75008 PARIS, FRANCE

TELEPHONE 720-8202

CABLE: MOTOR PARIS

TELEX: 640669

CARROLL E. DUBUC*

TEMPLE L. RATCLIFFE*

RESIDENT PARTNER WASHINGTON

RALPH E. CASEY*

JOHN W. McCONNELL, JR.*

OF COUNSEL WASHINGTON

* ADMITTED TO D.C. BAR

BY HAND

January 5, 1981

Jefferson Davis, M.D.
Jared Dunn, M.D.
Hyperbaric Medicine, P.A.
Methodist Plaza
4499 Medical Drive
San Antonio, TX 78229

Harry L. Gibbons, M.D.
Department of Health
610 South 200 East
Salt Lake City, UT 84111

James Gaume, M.D.

James Turnbow, Ph.D.

[REDACTED]
Palos Verdes Estates, CA 90274

[REDACTED]
Phoenix, AZ 85018

FFAC/ Kurth v Lockheed Aircraft Corporation
Our file 2041.1278.2S, 6S

Dear Doctors:

Enclosed for your review is John Edwards' follow-up report regarding incorrect aircraft measurements made by plaintiff's witness Dr. Stanley Morain in his expert report forwarded to you on November 25, 1981.

Very truly yours,

HAIGHT, GARDNER, POOR & HAVENS

By



John J. Connors

LOCKHEED-GEORGIA COMPANY
A DIVISION OF LOCKHEED CORPORATION
INTERDEPARTMENTAL COMMUNICATION

TO R. P. Barton

DEPT. 85-03 ZONE 35 DATE 14 December 1981

FROM J. W. Edwards

DEPT. 72-05 ZONE 240 EXT. 4004

SUBJECT: AIRCRAFT DIMENSION CORRECTIONS MORAIN REPORT - C5 SIAGON CRASH

The subject report makes use of certain aircraft measurements and then using these measurements, together with scaled lengths from photographs arrives at track lengths, depths, etc. Subsequently, these lengths are used in calculating deceleration g'levels.

The aircraft dimensions are incorrect in every case which inevitably leads to erroneous track lengths and g'levels.

Page 5 tire dimension.

The Morain report takes the tire dimension from figure 4 page 7 and incorrectly takes a dimension from the bottom of the fuselage to the ground line as 3.75 feet as being the tire diameter.

Actually, the tire diameter is 4.02 normally for a new tire and is expected to grow with use due to stretching. This 4.02 foot dimension is commercially available in tire catalogues.

Page 21 t-tail section.

The Morain report uses the same figure 4, page 7 to arrive at a vertical separation of 34.5 feet.

T.O. 1C-5A-3 page 1-7 shows the W.L. of the fuselage tip as 340 and page 1-10 shows the stabilizer tip as W.L. 772. This difference of 772-340 equals 432 or 36 feet. Since the trim in this flight would have been trailing edge up by approximately $\frac{1}{2}$, the distance would have been greater than 36 feet.

Actually, a more reliable figure to use, because of the slant angle of the t-tail, would have been the slant distance from the stabilizer tip to the fuselage tip which is 479.03 inches or 39.92 feet. This length is arrived at using the 432 inches vertical separation and the 206.91 inches separation in station line.

Utilizing the best picture available (copy attached), the slant measurement is .24 inches of the stabilizer and the distance from the front end troop compartment to the trending canal of 4.45.

$(4.45 \div .24) \times 39.92 = 740.18$ feet which compares to Morain 565 feet in figure 15.

Actually the most accurate length would be the troop compartment which is 75.67 feet in length. $(4.45 \div .40) \times 75.67$ equals 841.82 feet.

IDC, Edwards to Barton
Subject: Aircraft Dimension Corrections Morain
Report - C5 Siagon Crash

14 December 1981
Page -2-

Utilizing this 841.82 feet and ratioing the river to trending canal and trending to front end of the troop compartment gives a distance of 1505.69 feet from the river dike to the trending canal or 2347.51 feet which compares to 1715 feet on the Morain report page 21.

Page 28 troop compartment length.

The Morain report refers to figure 2 and notes that compartment E is 65 feet long. A variety of photos in the plaintiffs posession definitely show extra structure attached to the aft end making it considerably longer than 65 feet. Scaling this many photos, counting frames aft of the 2100 bulkhead, etc., shows the total length to be 75.67 feet, therefore, all calculations used by Morain are off by 16%.

Page 32 width of aft end of troop compartment.

The Morain report again ignores the 10 feet of extra length on the troop compartment and takes the width of 232 inches from compartment E in figure 2. The enlarging shape of the fuselage is shown in many photos and while the contour is compound and difficult to scale the actual width is 254.42 inches.




J. W. Edwards
Chief Project Engineer
Project Engineering Division

JWE:bg

Attachment

cc: Mr. Tom Almy
Haight, Gardner, Poor & Havens



$$\begin{array}{r} 2.2 \\ \times 84.82 \\ \hline 1.23 \\ + 841.82 \\ \hline \text{Total} 15347.51 \end{array}$$

