

Maintenance problems

Oil consumption of UH-1H helicopters of the 188th Assault Helicopter Company began to be a problem on 15 June 1967. A number two bearing seal was leaking excessively. Since that time, other ships have developed the same problem, and a repair kit has been assembled. Modification of engines will be accomplished as kits become available, on an as required basis or in conjunction with hot-end inspections. Necessary tools are only available at VUNG TAU.

Dau Tong

July 67