

DECLASSIFIED

~~CONFIDENTIAL~~

192 1177

PTTCZYUW RUYNTIL3946 1922300-CCCC--RUMINUA.
ZNY CCCCC ZYO RUYNSHH
P 112200Z JUL 69
FM ADMIN COMASWGRU ONE
TO COMNAVBASE SUBIC
P 110520Z JUL 69
FM FOCAF
TO COMASWGRU ONE
INFO MELBOURNE
BT

A/CY/O (PASS TO RADM KING)
(CALL)

/34/

~~CONFIDENTIAL~~ A L

COMNAVBASE SUBIC NOT ADDED PASS TO RADM KING
YOUR 100941Z FROM BOARD OF INVESTIGATION.
DETAILED REPORT OF SURVEY OF DAMAGE NOT YET AVAILABLE AND CANNOT
BE PROVIDED UNTIL AFTER SHIP DOCKS IN SYDNEY PRESENTLY PLANNED FOR
17 JUL.
2. ORDERCOST FROM COODOCK ESTIMATED AT DOLLARS AUS 380,000
3. PROVISIONAL ESTIMATED ORDER OF COST FOR TEMPORARY REPAIR
AT SINGAPORE IS POUNDS STERLING 15000 EXCLUDING POSSIBLE M.O.D. CLAIM
4. SUMMARY OF MAJOR DAMAGE IN BOW AREA
A. UNDERWATER
(1) 6FT BY 3FT HOLE STBD

PAGE TWO RUYNTIL3946 ~~CONFIDENTIAL~~

- (2) 6IN DIAM HOLE PORT
- (3) SPLIT IN KEEL AT FOREFOOT
- (4) STEM PLATE CRUSHED
- B. ABOVE WATER
- (1) GASH PORT AND STBD FOR 20 FT FROM STEM BELOW HAWSE PIPES
- (2) ROUND DOWN CRUSHED DISTORTED AND TORN. TO AFT LINE OF
PARKING CHOCKS FULL WIDTH
- (3) FAIRING AND CASTINGS OF FAIRLEAS OPENINGS TORN AND BROKEN
- (4) PLATING UNDER FLARE HOLE PORT AND STBD AT FOCSLE DECK LEVEL
- (5) CATAPULT RETARD TANK TORN PORT 6 FT AND CRUSHED STBD
- (6) STBD ANCHOR DAMAGED
- (7) INTERNAL FRAMES DECKS AND BULKHEADS IN WAY OF ABOVE DAMAGE TORN
AND BUCKLED.
- (8) 2 IN NO VENTILATION FANS LOST
- (9) D/G AND OTHER CABLES CUT AND DAMAGED
5. DAMAGE IN OTHER AREAS
- (1) NO 2 WALKWAY STBD CRUSHED 20FT
- (2) STBD FORD GUN SPONSON BUCKLED AND HOLED
- (3) GOLF ONE 40/60 MTG AND TRAINING RACK DISTORTED
- (4) STBD FORD 1.L.R. STORAGE TORN

BE THREE RUYNTIL3946 ~~CONFIDENTIAL~~
(1) SAFETY NETS FORD P AND S TORN

~~CONFIDENTIAL~~

Exhibit 710

WILDER 210017 (S-001) 0107-001-2000

ENCLOSURE (1)

ENCLOSURE (2)