

DOCKING REPORT  
DETAILED STRUCTURAL REPAIR (STEEL OR ALUMINUM)  
AND SONAR INFORMATION  
NAVSHP 223-3 (REV. 4-55)  
TO BE SUBMITTED BY ALL SHIPYARDS AND STATIONS FOR ALL STEEL OR ALUMINUM HULL REPAIRS AND SONAR INFORMATION

REPORT-BUSHIPS-9070-2

DOCKING DATE

26 March 1957

1. HULL REPAIRS AND RELACEMENT

FRAME NUMBERS (INDICATE P OR S)	STRAKE	ACTION	MATERIAL		DESCRIPTION OF CONDITION WHICH NECESSITATED ACTION
			ORIG	REPAIR	

REMARKS

Rewelded approximately 160 lineal feet of wasted weld in way of fore peak, struts and rudder.

2. SONAR

EXISTING AT UNDOCKING			REMOVED THIS DOCKING	
DOME TYPE	SERIAL	WORK DONE	DOME TYPE	SERIAL

REMARKS

Checked out and made minor repairs.

USNS GENERAL JOHN POPE (T-AP 110)

SIGNATURE	NAME, CLASS AND NUMBER OF VESSEL
-----------	----------------------------------

A-63220