

2 February 1966

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (T-AP 110)  
To: Distribution List

Subj: Material Inspection of Troop Spaces held this date

1. The following is a report on the condition of the Troop Spaces during the Material Inspection held on 2 February 1966:

COMPT 2-2 No buffer available. Very good.

COMPT 2-3 No buffer available. Check air conditioner on port side. Very good.

COMPT 3-2 Metal strips sticking out into passageway from square of hatch. Chain eye on starboard post (square of hatch) broken. Shower decks look good. Very good.

COMPT 3-3 Not inspected (OUTSTANDING previous inspections).

COMPT 4-1 No comment.

COMPT 4-2 Leak port side aft (water curtain connection - 11th rpt). This was looked at yesterday by ship's crew but not repaired. No buffer available. EXCELLENT.

COMPT 4-3 Leak in ovhd. pipe on star. side forward (11th rpt). Short in elect. outlet (7th rpt). Scuttlebutt 41-4-82-2 not working (5th rpt). OUTSTANDING. Best compartment inspected.

COMPT 4-4 No comment.

COMPT 4-5 No comment.

L.REC.RM. Check rattle in air conditioning unit. Very good.

S.REC.RM. Very good.

FWD.UPPER HEAD Water leaking under sink and over commode. Drain stopped up in shower. Very good.

FWD.LOWER HEAD 1 faucet out of order. Tile loose on deck. Pipes leaking under urinals. Very good.

BRIG Paint back of entrance door to brig.

*WB Cobb*

W. B. COBB

Distribution:

→Master

Chief Engineer (2)

First Officer

Troop Office for distribution to Troop Officers (5)

COMILDEPT

Medical Office

File