

USNS GENERAL JOHN POPE (T-AP110)
FLEET POST OFFICE
SAN FRANCISCO, CALIFORNIA

ADDENDUM #2 TO VOYAGE REPAIR LIST - VOYAGE #7

SUBMITTED: E. C. Quinn
E. C. QUINN, CH. ENGR.

APPROVED: G. W. Berlin
G. W. BERLIN, MASTER

Item No.	Priority	Subject and Description
(28)	3	<p>SUBJECT: International Shore Connection, Fabrication of;</p> <p>DATA: O.D.: 7", I.D.: 2-1/2", Bolt Circle Diameter: 5-1/4", Holes: 4, 3/4", Slotted at flange periphery.</p> <p>CONDITION: Non-Existant</p> <p>QUANTITY: Two (2)</p> <p>RECOMMEND: Fabricate and deliver to ship, two International Shore Connection Flanges.</p>
(29)	3	<p>SUBJECT: Hand Hole, #4 Boiler Economizer, Repair of</p> <p>DATA: MFG: Foster-Wheeler Corp. TYPE: "D"</p> <p>LOCATION: After Engine Room</p> <p>CONDITION: Cut across header hand hole seating surface.</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish labor and material to make necessary removal, repair header, apply hydro and prove tight.</p>
(30)	3	<p>SUBJECT: Piping, #3 Fire And General Service Pump Discharge "T", Renewal of;</p> <p>LOCATION: After Engine Room</p> <p>CONDITION: Deteriorated and holed.</p> <p>QUANTITY: One (1) 3" x 10$\frac{1}{2}$" flanged section with one 2" x 4$\frac{1}{2}$" flanged 90 degree off sticker and one $\frac{1}{2}$" boss for sage line.</p> <p>RECOMMEND: Furnish labor and material to remove flanged section and renew. (Use removed section as template)</p>

Item No.	Priority	Subject and Description
(31)	3	<p>SUBJECT: Plungers, Main Feed Pump, Rechroming and Machining of;</p> <p>DATA: MFG: Worthington Triplex Boiler Main Feed Pump 2-3/4" x 5"</p> <p>LOCATION: Shop</p> <p>CONDITION: Plungers scored and grooved</p> <p>QUANTITY: Five (5)</p> <p>RECOMMEND: Furnish labor and material to chrome and remachine to Mfg. designed specifications</p>
(32)	3	<p>SUBJECT: Pipe, #2 Evaporator Distiller Condenser Outlet, Renewal of;</p> <p>DATA: 6" x 4$\frac{1}{2}$"</p> <p>LOCATION: Evaporator Flat</p> <p>CONDITION: Holed</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish labor and material to remove and renew deteriorated flanged section. (Use removed section as template)</p>
(33)	3	<p>SUBJECT: Lubricating Oil, Samples, Analysis of;</p> <p>DATA: MFG: Socony Mobil Co. D.T.E. Extra Heavy</p> <p>LOCATION: Chief Engineer's Office</p> <p>CONDITION: 6 Month Analysis</p> <p>QUANTITY: Four (4) samples. Inlet and Outlet to Lube Oil Purifier from Forward and After Engine Rooms.</p> <p>RECOMMEND: Have oil analyzed for condition and impurities.</p>
(34)	3	<p>SUBJECT: Pipe, #2 Evaporator Feed Pump Discharge, Renewal of</p> <p>DATA: 3" x 2"</p> <p>LOCATION: Evaporator Flat</p> <p>CONDITION: HOLED</p> <p>QUANTITY: One (1) 3" x 2" section, welded at one end and flanged at Air Ejector Condenser</p> <p>RECOMMEND: Furnish labor and material and crop off and renew deteriorated section.</p>

Item No.	Priority	Subject and Description
(35)	3	<p>SUBJECT: Pipe, #2 Evaporator Brine Pump Discharge, Renewal of;</p> <p>DATA: 5" x 8' Flanged</p> <p>LOCATION: Evaporator Flat</p> <p>CONDITION: Holed</p> <p>QUANTITY: One (1) section 5" x 8' flanged with one 90 deg. bend. Galv. steel.</p> <p>RECOMMEND: Furnish labor and material to renew.</p>
(36)	3	<p>SUBJECT: Pipe, #2 Evaporator Overboard Discharge By-pass, Renewal of;</p> <p>DATA: 3" x 2'</p> <p>LOCATION: Evaporator Flat 6-125-2</p> <p>CONDITION: Deteriorated and holed</p> <p>QUANTITY: One (1) 3" x 2' section, flanged at one end and welded to 6" overboard line at other end, one 90 deg. bend.</p> <p>RECOMMEND: Furnish labor and material, crop off deteriorated section and renew.</p>
(37)	3	<p>SUBJECT: Pipe, #2 Distiller Condensate Pump Suction Repair of;</p> <p>DATA: 4" x 15' Long.</p> <p>LOCATION: Evaporator Flat 6-125-2</p> <p>CONDITION: Holed and deteriorated</p> <p>QUANTITY: One (1) 4" x 15' flanged section, 4 90 deg. bends. Galv. steel.</p> <p>RECOMMEND: Furnish labor and material remove and renew deteriorated section.</p>
(38)	3	<p>SUBJECT: Piping, #2 Evaporator Feed Pump Suction Renewal of</p> <p>DATA: 3" x 20'</p> <p>LOCATION: Evaporator Flat 6-125-2</p> <p>CONDITION: Holed and deteriorated</p> <p>QUANTITY: One (1) section galv. steel 3" x 20' flanged with one 90 deg. bend.</p> <p>RECOMMEND: Furnish labor and material to remove and renew deteriorated section.</p>

Item No.	Priority	Subject and Description
(39)	3	<p>SUBJECT: Table, Ships Laundry, Fabrication and Installation of;</p> <p>DATA: 96" Long x 36" Wide x 34" High</p> <p>LOCATION: Ships Laundry 4-118-2-Q</p> <p>CONDITION: Presently installed table is constructed of wood, which is worn and deteriorated.</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish labor and material to fabricate a table of steel framing and stainless steel top, 96" Long x 36" Wide x 34" High Install in ships laundry.</p>
(40)	3	<p>SUBJECT: Typewriter, Cleaning and adjusting of;</p> <p>DATA: UNDERWOOD (TELEGRAPHIC) Ser. 11-9635564 and 11-9636559</p> <p>LOCATION: Radio Room</p> <p>CONDITION: Typewriters need cleaning, are a little sluggish, keys occasionally stick, margin release erratic, etc.</p> <p>QUANTITY: Two (2)</p> <p>RECOMMEND: Clean and adjust as required.</p>
(41)	3	<p>SUBJECT: Typewriter, Repair and Cleaning of;</p> <p>DATA: UNDERWOOD FIVE Serial: 11-8727591</p> <p>LOCATION: Medical Records Office 01-108-2-Q</p> <p>CONDITION: Left upper case shift lock sticks when shifting to upper case.</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish labor and material to repair, clean and adjust</p>
(42)	3	<p>SUBJECT: Barber Shop, Painting of;</p> <p>LOCATION: 1-78-2-Q</p> <p>CONDITION: Faded and chipped</p> <p>RECOMMEND: Furnish labor and material to prepare surface and paint as per MSTS Spec.</p>
(43)	3	<p>SUBJECT: Armory, Painting of;</p> <p>LOCATION: 3-164-2-A</p> <p>CONDITION: Faded and chipped</p> <p>RECOMMEND: Furnish labor and material to prepare surface and paint as per MSTS Spec.</p>

<u>Item No.</u>	<u>Priority</u>	<u>Subject and Description</u>
(44)	3	<p>SUBJECT: Ship's Laundry, Painting of;</p> <p>LOCATION: 4-118-1-Q Laundry, 4-128-1-A Laundry Stores, 4-127-2-A Receiving Room, 4-118-2-Q Laundry and Thwarts Passage between two laundry rooms.</p> <p>CONDITION: Chipped, discolored and worn</p> <p>QUANTITY: Five (5) spaces</p> <p>RECOMMEND: Furnish labor and material to prepare surface and paint to MSTs Specifications</p>
(45)	3	<p>SUBJECT: Calculator, Repair of;</p> <p>DATA: SCM Marchant, Model G. 120V, 100W AC/DC Serial No. 10CM686805</p> <p>CONDITION: Inoperative</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish labor and material to repair as necessary</p>
(46)	3	<p>SUBJECT: Typewriter, Repair of;</p> <p>DATA: Underwood Five, Serial No. 15-9649460</p> <p>LOCATION: Engine Yeoman's Office</p> <p>CONDITION: Inoperative</p> <p>QUANTITY: One (1)</p> <p>RECOMMEND: Furnish Labor and material to repair as necessary</p>