

24-C 24 OCTOBER 1967 0910

USNS POPE

JO 84-710 W.T. DOOR REPAIRS

SHOP X11

REMOVE THE FOLLOWING WATERTIGHT DOORS FOR REPAIRS:

1 EA AT FANROOM, 2-141-B-E 1 EA ON WEATHER DECK, 1-55-1.

STGIP THE DOORS OF ALL DOGS AND RUBBER GASKETS, ETC.

SANDELAST DOORS AND REPAIR ENLARGED HOLES IN HINGE BLADES, REVIEW

DETERIORATED GASKET RETAINER STRIPS AND OTHER AREAS AS REQUIRED.

REPLACE WORN OR BENT HANDLES AND OTHER ATTACHMENTS.

CHECK DOORS FOR DISTORTION AND STRAIGHTEN AS REQUIRED.

PRIME AND INSTALL NEW RUBBER GASKETS.

MAKE NECESSARY REPAIRS TO DOGS AND PUSHINGS, LUBRICATE AND ASSEMBLE,

APPLY TWO FINISH COATS OF HAZE GRAY PROTECTING NEW RUBBER.

STRAIGHTEN DISTORTED AREAS OF DOOR FRAMES AND KNIFE EDGES TO A TRUE

Completed

SURFACE REPAIRING ENLARGED HOLES IN WINGLES.

REINSTALL DOORS, RENEWING HINGE PINS, ADJUST DOGS, CHALK TEST AND PROVE
TIGHT.

PRIME AND PAINT THE FRAMES AND DISTURBED AREAS IN WAY OF WORK.

SHOP X26, 71 & 72 ASSIST

SIGNED: LEONHARDT/CASSIDY/CATRON