

PRODUCT SERVICE REPORT

21334-E

SPERRY GYROSCOPE COMPANY DIVISION OF SPERRY RAND CORPORATION

DISTRICT ROUTING

SERVICE

STOCK

ACC'TG

DISTRICT PCDO-7315-SF DATE April 11/67 JOB NO. 10886-15

VESSEL <u>USNS JOHN POPE</u>		INVOICE NO.		INVOICE DATE
LOCATION		CUSTOMER		
PORT		ADDRESS		
ORIGIN OF SERVICE CALL	DISPATCHER	CAPTAIN		CITY
	AGENT		DATE	
CUSTOMER'S ORDER NO.		CUSTOMER'S REQ. NO.		STATE

PROD. NO.	PRODUCT NAME	SERIAL NO.	MANUFACTURER	TOTAL OPER. TIME	CHARGES	
171	Gyro Comp/Compass Receiver	1361	SGC	20 yrs	I G	C X
REASON FOR CALL						

Course Reorder Clock broken. Aft Steering
Uptu inoperative on occasion.

TROUBLE FOUND & WORK PERFORMED

1) Found open wire in rpt cable. Reordered cable, checked o.k. Reordered 1/4 x 20 SS Screws.

2) Hair spring and balance wheel broken. Removed clock to shop. Clock repaired and returned. Re-installed.

3) No further work requested.

