

AT/PASSAGE FROM

TO

PIER 2 BERTH #3, HUNTER'S POINT SAN FRANCISCO N.S.Y.

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

+ 8

6-JAN-1970

TUESDAY

TIME	REMARKS
	RO MR. ALEXANDER R/E MR. O'HARA 0000 - 0800 F/W REMILLARD-GWY. BUNDY
2300	F/W ROUND-RTE "A", POPE - ALL SECURE
0000	F/W ROUND-RTE "A", WEIGEL - ALL SECURE
0040	R/d TO WEIGEL, ROUTINE INSPECTION - ALL SECURE
0100	F/W ROUND-RTE "B", POPE - ALL SECURE
0200	F/W ROUND-RTE "B" WEIGEL - ALL SECURE
0300	F/W ROUND-RTE "A" - POPE - ALL SECURE
0400	F/W ROUND-RTE "A" - WEIGEL - ALL SECURE
0500	F/W ROUND-RTE "B" - POPE - ALL SECURE
0600	F/W ROUND-RTE "B" - WEIGEL - R/O TO WEIGEL - ALL SECURE
0605	WATCH RELIEVED BY IREDALE Bundy Mr. Connally 1/0 (0800-1600) IREDALE A/B - O'DELL, FL
0605	Assumed the watch - All secure.
0700	F/W on "A" route Pope
0710	Test of Pope's Kidde fire alarm systems.
0800	WHITTICO, Deck Emer. Reporting 130 VICE Pool
0800	Valerio Able STWD. UTI - do - (34926) - VICE. QUINONES
0800	Colors observed.
0800	Detex "A" route made in Weigel - All secure.
0900	Detex B rt in Pope - do
1000	Mr. LOCKARD, Safety Inspector, aboard - Away 1320
1010	Mr. BOLLEN, Ch. Safety Inspector, abt. - AWAY 1230
1010	CH. KING, YARD Safety - abt. " "
1020	Detex B rt completed in Weigel
1030	GO Grier MSTU aboard. -
1100	Detex "A" rt. ON Pope
1115	R.C. Easterbrook, Chairman Fed. Safety Council aboard
1130	Nix, A/B, called in sick for Tomorrow (FLU)
1145	Mr. PETERSON & SKOVOTH, MST5 CARGO, ABO -
1200	Detex "A" rt on Weigel - All secure.
1300	LACAR, Francisco B. (25247) Waiter, abt. - New Position
1320	Detex B rt. on Pope - All's well
1355	Mgr. Electronics workers ABO. Weigel -
1400	Detex B rt in Weigel - All's well.
1425	Watch relieved by Celada
	at schedule

AT/PASSAGE FROM		TO	
Pier 2 Berth #3 Hunters Point		Naval Shipyard - San Francisco	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
18		6 Jan. 1970	Tuesday
TIME	Mr. Wayne R/E Mr. Hurley R/E	REMARKS	
		1600 - 2400	
1430		Assumed watch - All in apparent good order	
1440		Mr. Hurley R/E Aboard and Mr. Thompson 2 nd Eng. Ashore	
1500		Made round A on Pope	
1600		Made round A on Weigel	
1705		Colors: Made round B on Pope	
1800		Made round B on Weigel	
1900		" " A on Pope	
2000		" " A on Weigel	
2100		" " B on Pope	
2200		" " B on Weigel	
2215		Watch relieved by Bundy J.B. Calera	
2230		R/O MR. ALEXANDER ABOARD - MR. WAYNE ASHORE	
2255		R/E MR. O'HARA ABOARD - MR. HURLEY ASHORE	
2300		FW ROUND - RTE "A", POPE - ALL SECURE	
		Bundy A/B	

AT/PASSAGE FROM

PIER 2 - BERTH #3, HUNTER'S POINT NAVAL SHIPYARD, SAN FRANCISCO, CA.

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

7-JAN-1970

WEDNESDAY

TIME	MR. ALEXANDER R/O MR. O'HARA R/E	REMARKS
		FW-REMILLARD Gwy-BUNDY
		0000 - 0800
0000		FW ROUND, RTE "A", WEIGEL - ALL IN APPARENT GOOD ORDER
0045		R/O TO WEIGEL, ROUTINE INSPECTION - ALL SECURE
0100		FW ROUND, RTE "B" - POPE - ALL SECURE
0200		FW ROUND, RTE "B" - WEIGEL - ALL SECURE
0300		FW ROUND, RTE "A" - POPE - ALL SECURE
0400		FW ROUND, RTE "A" - WEIGEL - ALL SECURE
0500		FW ROUND, RTE "B" - POPE - ALL SECURE
0555		R/O TO WEIGEL, ROUTINE INSPECTION - ALL SECURE
0600		FW ROUND, RTE "B" - WEIGEL - ALL SECURE
0605		WATCH RELIEVED BY ORR Bundy A/B
0610		R/O RETURN FROM WEIGEL.
0630		CH. STEWARD & PURSER ABOARD. 1/2 ABOARD. 1/2 ASHORE
0730		WEIGEL "A" ROUND MADE MR CONNALLY 1/2 (0800-1600) MR. ORR - GANWAY
0800		COLORS.
0900		TESTS ABOARD WEIGEL: CAPSTAN RUN FOR 15 MINS, ANCHOR WINDLASS 15 MINS, A.C. LAUNDRY UNIT 45 MINS, AND ENGINE ROOM BLOWERS FOR 45 MINS.
0915		DAVIS, ESSIE STEW UTILITY ABOARD FOR DUTY, JOHN DAVIS MST'S SAFETY ABD.
1005		PURSER ASHORE TO BANK. 1050 RETURNS WITH \$7,500
1040		AQUINO, MAX ASST COOK ABOARD FOR DUTY. REYES MST'S TECH. ABOARD
1155		REYES ASHORE
1230		WEIGEL "B" ROUTE MADE
1415		WATCH RELIEVED BY FRANK CELADA Geo. On
	Mr. Wayne R/O Mr. Hurley R/E	1600 - 2400 - Celada - Gwy Duran - Fire Watch
1430		Assumed Watch: All in apparent good order
1445		Mr. Hurley R/E Aboard and Mr. Thompson 2 nd Asst. Eng. Ashore.
1500		Mr. Wayne R/O Aboard. Mr. Connally 1/2 Ashore
1540		Made round A on Pope
1600		" " " " WEIGEL
1630		Mr. Hurley R/E to Weigel. Mr. Hurley R/E return 1700
1630		Duran A/B Aboard.
1650		Mr. Wayne R/O to Weigel - Return 1725
1707		Colors: Made round B on Pope
1800		Made round B on Weigel
1900		" " A on Pope
1935		Mr. Wayne R/O to Weigel. Return 2000
2000		Made round A on Weigel
2100		" " B on Pope
2100		Mr. Hurley to Weigel - Return 2145
2200		Made round B on Weigel
2300		Watch relieved by - Bundy A/B
		Celada A/B

AT/PASSAGE FROM
ZONE DESCRIPTION

PIER #2 BERTH #3

+8

TO HUNTERS POINT NSY SF.

DATE (Day, month, year)
18 JAN 1970

DAY OF WEEK

Wednesday & Thursday

TIME

R/O MR. ALEXANDER
R/O MR. O'HARA

REMARKS

F/W REMILLARD - Gwy BUNDY

0000 - 0800

2200 ASSUMED WATCH - ALL IN APPARENT GOOD ORDER

2225 R/O MR. ALEXANDER ABOARD - MR. WAYNE ASHORE

2300 F/W ROUND - RTE "A" - POPE - ALL SECURE - R/O MR. O'HARA - ABD - MR. HURLEY ASHORE

0000 F/W ROUND - RTE "A" - WEIGEL - ALL SECURE

0020 S.E. MALONE - 34571 - STWD. UTIL. - REPORTED ABD.

0042 R/O MR. ALEXANDER TO WEIGEL - ROUTINE INSP. - ALL SECURE

0100 F/W ROUND - RTE "B" - POPE - ALL SECURE

0200 F/W ROUND - RTE "B" - WEIGEL - ALL SECURE

0300 F/W ROUND - RTE "A" - POPE - ALL SECURE

0400 F/W ROUND - RTE "A" - WEIGEL - ALL SECURE

0500 F/W ROUND - RTE "B" - POPE - ALL SECURE

0530 R/O TO WEIGEL - INSP. TOUR - ALL'S WELL

0600 F/W ROUND - RTE "B" WEIGEL - ALL SECURE

0605 WATCH RELIEVED BY NIX - Bundy #3

0605 WATCH RELIEVED & ASSUMED - All in APPARENT Good ORDER

0605 1ST ASST ENG. ABOARD. 2ND ASST ENG ABOARD.

0630 CHIEF STEWARD & PURSER ABOARD.

0635 1ST MATE ABOARD - NITE MATE RELIEVED.

0735 ALARM SYSTEMS TESTED BOTH VESSELS. F/W MADE POPE ROUNDS

0755 POPE ANCHOR WINDLASS & CAPSTAN TEST RUN 1/2 HOUR
MR CONNALLY 1/6 (0800 - 1600) ERR - FIREWATCH
NIX - GANWAY

0800 COLORS

0800 DETEX ROUND MADE ON WEIGEL.

0840 JUST, VERNON MESSMAN ABOARD FOR DUTY

0900 DETEX ROUND MADE ON POPE BY MR. NIX

0930 STERN LINES TAKEN UP. CREW MEMBERS FROM MYER ABOARD

1000 DETEX ROUND MADE ON WEIGEL.

1000 CREW FROM MYER TRANSFERRING STORES FROM WEIGEL.

1015 MR. SHADY PORT STEWARD ABOARD

1100 DETEX ROUNDS MADE ON POPE. MILK & ICE CREAM DELIVERY.

1200 DETEX ROUND MADE ON WEIGEL. MEAT DELIVERY.

1200 MR. SHADY PORT STEWARD ASHORE.

1210 CAPTAIN ASHORE (FOR APPROX. 2 HRS.)

1225 STEAM SECURED UNTIL FURTHER NOTICE.

1300 DETEX ROUND MADE ON POPE.

1305 MR CLEVELAND PT. STEW ABOARD

1315 STEAM ON! MR LORENCE MTS ELEC. ABOARD.

1340 PRODUCE DELIVERY. 1345 MR LORENCE ASHORE.

1350 ~~MYER~~ MYER CREW ASHORE. STEAM HOSE BLEW UP. SECURED FOR REPAIRS BY SHOP 99.

1400 DETEX ROUND MADE ON WEIGEL.

1400 WATCH RELIEVED BY DURAN.

Guy Drex

AT/PASSAGE FROM		TO	
TIER 2 Berth #3 Hunters Point		Naval Shipyard San Francisco, Calif	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 8		8 Jan. 1970	Thursday
TIME	Mr. Wayne R/O Mr. Hurley R/E	REMARKS	CELADA - GWT Duran - F/W
		1600 - 2400	
2400	Assumed Watch: - All in apparent good order		
1445	Mr. Hurley R/E and Mr. Wayne R/O Aboard		
1455	Captain Aboard		
1500	Made round A on Weigel		
1535	Mr. Wayne R/O to Weigel. Return 1600		
1600	Made round A on Pope		
1630	Mr. Hurley R/E to Weigel. Return 1700		
1700	Colonel: Made round B on Weigel		
1800	Made round B on Pope		
1900	Made round A on Weigel		
1930	Mr. Wayne R/O to Weigel. Return 1955		
2000	Made round A on Pope		
2100	Mr. Hurley R/E to Weigel. Return 2135		
2100	Made round B on Weigel		
2200	" " B " Pope		
2230	Watch relieved by O'Dell		
2230	Mr. Alexander Aboard		
	Off Standby		
2230	ON Watch O'Dell / AB - Iredale F/W - Alexander RDC		
2300	Iredale on "A" route of Pope		
2400	" " " " Weigel		
0100	" " "B" " Pope		
0200	" " " " Weigel		
0300	" " "A" " Pope		
0400	" " " " Weigel		
0500	" " "B" " Pope		
0530	" " " " Weigel		
0545	Meyer, ABM, called in sick		
0600	Watch relieved by Nix		
	22 O'Dell		
0600	Assumed Watch - All in Apparent Good Order.		
0645	MR OHARA R/O ASHORE. MR CONNALLY RELIEVED MR ALEXANDER.		

AT/PASSAGE FROM		TO	
PIER #2 BERTH #33 S.F.N.S.Y.		HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 8		9 JANUARY 1970	FRIDAY
TIME	REMARKS RAINY		
	MR CONNALLY /O (0800-1600)		NIX - GANGWAY CORR - FIREWATCH
0615	1 ST ASST + 2 ND ASST ABOARD		
0700	F/W MAKING POPE DETEX ROUNDS		
0705	ROBERT JOHNSON ENG. DEPT. CALLED IN SICK		
0707	POPE ALARM SYSTEMS TESTED O.K.		
0730	CHIEF ENG. ABOARD.		
0800	COLORS. WEIGEL DETEX ROUNDS MADE		
0900	F/W MAKING POPE ROUNDS		
1000	POPE ROUNDS MADE		
1020	MR. LOCKHART MSTS SAFETY ABOARD		
1050	NOTIFIED MR. LOCKHART VICE ADM. DENIBRINK UNABLE TO ATTEND LUNCHEON + MEETING. NAVY PHOTO. ABOARD.		
1100	VARIOUS VISITORS FROM FEDERAL SAFETY COUNCIL ABOARD FOR MEETING + LUNCHEON.		
1145	ADMIRAL COLE + AIDE ABOARD		
1200	ALL IN APPARENT GOOD ORDER. WATCH STANDING BY GANGWAY TO ASSIST VISITORS AT GANGWAY.		
1300	ALL IN APPARENT GOOD ORDER, APPARENTLY		
1345	SAFETY COUNCIL MEETING + LUNCHEON ADJOURNED.		
1355	ADMIRAL COLE + AIDE ASHORE		
1400	ALL VISITORS ASHORE (110.)		
1430	WATCH RELIEVED BY DURAN <i>Healer</i>		
	MR. Wayne R/O 1600-2400		DURAN - Gwy.
	MR. Hurley R/E		Celada - F/W
1430	assumed the watch. All is in apparent good order.		
1440	1 ST O Mr. Connally ashore (Aboard)		
1445	MSTS. Safety Council ashore. Mr. Wayne & Mr. Hurley.		
1500	Rounds on Weigel made by Celada on Detex clock - "A" Route MR. Wayne To Weigel - Return 1520		
1515	Ch. Eng. Ch. Steward. Ch. Purser ashore.		
1600	"A" route by Duran of Detex clock station 3. Pope		
1635	Mr. Hurley R/E To Weigel. Return 1705		
1700	Colors down		
1710	"B" route by Duran of Detex clock station 5. Pope		
1810	"B" route by Celada of Detex clock sta's - Weigel		
1900	"A" route by Duran on Pope Detex clock sta's.		
1935	Mr. Wayne To Weigel - returned 1950		
2000	"A" route by Celada on Weigel Detex clock sta's		
2100	"B" route by Duran on Pope Detex clock sta's		
2100	Mr. Hurley returns from Weigel - Left 2045.		
2145	Celada Leaves To Weigel To make "B" rounds. Returne		
2225	Watch relieved by Odell. <i>Duran</i>		

AT/PASSAGE FROM Pier 2 Berth #33 Hunters Point	TO Naval Shipyard, San Francisco, Calif.
ZONE DESCRIPTION 78	DATE (Day, month, year) 10 JAN 1970
	DAY OF WEEK Sat.

TIME	REMARKS
	0000 - 0500
2225	ON Watch Iredale F/W - O'Dell AB - Alexander RDO
2300	Iredale F/W on "B" route of Pope
0000	" " " " " " Weigel
0100	" " " B " " Pope
0200	" " " " " " Weigel
0300	" " " A " " Pope
0400	" " " " " " Weigel
0500	" " " B " " Pope
0530	" " " " " " Weigel
0600	Watch relieved by Nix R O O'Dell
0600	ASSUMED WATCH - Nix G/W, ORR F/W ALEXANDER RDO
0700	DETEX ROUND ON PIPE MADE.
0730	SOUNDINGS TAKEN.
	MR. ALEXANDER RDO NIX - G/W MR. HURLEY RDO ORR - F/W
0800	0800 - 1600
0800	COLORS: DETEX ROUND MADE ON WEIGEL.
0845	MR. ALEXANDER TO WEIGEL. 0910 RETURNED.
0900	DETEX ROUND MADE ON PIPE.
1000	DETEX ROUND MADE ON WEIGEL.
1020	MR. WAYNE RDO, RELIEVED MR. ALEXANDER.
1030	MR. WAYNE TO WEIGEL.
1045	MR. HURLEY R/E ABOARD. 1050 O'HARA ASHORE
1050	MR. WAYNE REPORTS WEIGEL PHONE IS OUT OF ORDER
1100	DETEX ROUND MADE ON POPE.
1200	DETEX ROUND MADE ON WEIGEL. MR. HURLEY TO WEIGEL.
1215	NO ELEC OR SHORE POWER. = POWER FAILURE.
1300	DETEX ROUND MADE ON PIPE.
1400	DETEX ROUND MADE ON WEIGEL. NO POWER STILL OFF.
1420	WATCH RELIEVED BY DURAN. C. Gray Stif
	1600 - 2400
	Mr. Wayne R/o - Mr. Hurley R/E DURAN G/W. Celada F/W
1420	Watch relieved all is in apparent good order. Except for Electrical power failure from shore affecting the Lighting Board
1425	Captain ashore.
1500	Round "A" on Pope - Duran. Mr. Wayne To Weigel - Return 1515
1535	Power Failure restored to ship.
1555	Power Failure from shore to ship occurs again. "A" round on Weigel incompleted
1600	No rounds on Weigel during power failure - orders by Mr. Wayne
1708	EVENING colors executed. Commence "B" rounds on Pope - DURAN
1900	Commence "A" rounds of Detex clock stais - DURAN
2100	Commence "B" rounds of Detex clock stais - DURAN
2200	All is secured and in good order. Except for Power is still off.
2230	Watch relieved by O'dell. Duran.

AT/PASSAGE FROM
 Pier 2 Berth #33 Hunters Pt. TO Naval Shipyard, S.F. Calif.
 ZONE DESCRIPTION
 #8 DATE (Day, month, year) 11/11/70 DAY OF WEEK Sun

TIME	REMARKS
	0000-0800
2230	ON Watch Iredale FLW-ODE 11 A/B - Alexander RDO
2300	Iredale starts "A" route on Pope
0000	" reports all secure
0100	" starts "B" route on Pope
0200	" reports all secure
0300	" starts "A" route on Pope
0400	" reports all secure
0500	" starts "B" route on Pope
0600	" reports all secure
0600	Watch relieved by Nix. RE O'Dell
0600	ASSUMED WATCH: EMERGENCY POWER THRU-OUT THE SHIP ONLY. POWER HAS BEEN OFF FROM 1215 10 JAN. 1970.
0700	DETEX Round MADE ON POPE. EMERGENCY Lights ONLY. NO HEAT- NO VENTILATION IN HOLES, COMPARTMENTS ETC. NO BREAKFAST.
0730	Soundings- (0800 - 1600) MR ALEXANDER-RDO NIX G/W
0800	COLORS: DETEX Round MADE ON WEIGEL. MR LINDBERG-RDO ORR F/W
0900	DETEX Round MADE ON POPE. MR ALEXANDER TO WEIGEL.
1000	DETEX Round MADE ON WEIGEL.
1020	MR WAYNE RDO RELIEVED MR ALEXANDER.
1030	MASTER ASHORE.
1035	POWER BACK ON WEIGEL
1100	DETEX Round MADE ON POPE
1134	POWER BACK ON POPE
1200	DETEX Round ON WEIGEL
1225	MR HURLEY R/E NOTIFIED CHIEF ELECTRICIAN RYAN OF ELECTRICAL TROUBLE - - - - 1/2 OF BOARD NOT WORKING, FIRESCREEN DOORS WILL NOT HOLD OPEN, SOME LIGHTS & VENTILATION NOT ON. NO HEAT.
1300	DETEX Round MADE ON POPE. 1445= CHIEF ELEC ABOARD.
1400	DETEX Round MADE ON WEIGEL.
1400	WATCH RELIEVED BY BUNDY & REMILLARD (NIX)

Pier 2mb		3	NSY HUNTERS POINT	
AT/PASSAGE FROM		DATE (Day, month, year)		DAY OF WEEK
Berth #2 Berth #4 2mb		11 JAN 1970		SUNDAY
ZONE DESCRIPTION		+ 8		
TIME	REMARKS			
	RDO MR. WAYNE F/W BONDY G/W REMILLARD			
1400	Assumed the watch.			
1500	"A" Round on POPE,			
1600	"A" Round ON WEIGEL.			
1635	N/E to weigel,			
1700	Round "B" ON POPE.			
1705	N/E BACK FROM WEIGEL.			
1710	OBSERVED COLORS. SUNSET.			
1800	"B" Round ON WEIGEL.			
1835	N/M to weigel, 1850 Returned All Secure.			
1900	"A" Round ON POPE.			
2000	"A" Round ON WEIGEL			
2100	"A" Round "B" ON POPE. N/E to weigel,			
2110	MASTER ABOARD			
2130	N/E BACK FROM WEIGEL.			
2200	"B" Round ON WEIGEL. MR ALEXANDER N/M ABOARD			
2225	WATCH RELIEVED			
	Remillard			
2225	Assumed the watch. Conditions normal.			
2230	O'DELL, R.E. (AB) called to say his sick + unable to make watch tonight			
2300	"A" route in POPE. All secure.			
	J O'Dell			

AT/PASSAGE FROM		TO	DATE (Day, month, year)		DAY OF WEEK
J. F. B. N. S. Hunters Point		Pier 2 - Berth 3	12 JAN 70		Mon.
ZONE DESCRIPTION					
+8					
TIME	REMARKS				
	MR. Alexander RDO (0000-0800) IREDALE F/W & G/W				
0000	"A" Detex route made in Weigel. All secure.				
0100	Detex B rt. in Pope				
0130	RDO to Weigel - Return. 0200				
0200	B1 RT. Weigel				
0300	A RT in Pope. All secure				
0400	A Route in Weigel - All's well				
0500	Detex B route in Pope				
0530	RDO away to Weigel. Return 0545				
0600	Detex B rt in Weigel. Secure				
0620	Relieved of watch by Sindoni. A/B - Gray A/B				
0630	MR CONNALLY 1/O ABOARD MR ALEXANDER RDO				
	ASHORE, CH-STEWARD ABOARD, PURSER ABOARD.				
0700	GENOVIA MACHINIST CALLED IN SICK.				
0700	RT "A" POPE				
0800	Colors observed - R + 'A' on Weigel				
0900	RT "B" POPE - WILLIAMS OILER REPORTED THAT HE SLIPPED ON GANGWAY CLEATS AT 6.45 AM AND INJURED (TWISTED) HIS KNEE AND AT THIS TIME IT APPEARS TO BE SWOLLEN.				
0910	WILLIAMS OILER TO DISPENSARY				
1000	Rte 'B' on Weigel				
1000	called Phone Co. (Ship Repair) to report Phone on Weigel out of order was informed they would check it out.				
1040	WILLIAMS OILER TO MARINE HOSPITAL				
1100	RT "A" ON POPE				
1200	Rt 'A' on Weigel				
1225	MASTER AND CH-STEWARD TO NSC.				
1300	RT "B" POPE - SHORE STEAM SECURED.				
1315	PHONE SERVICE RESTORED ON WEIGEL				
1345	Rte 'B' on Weigel				
1410	watch Relieved by Bundy A/B & Remillard A/B				
	Gray				
	1600-2400				
	MR. WAYNE N/M Remillard A/B G/W Bundy A/B F/W				
1410	Assumed the watch.				
1440	N/E MR. HURLEY Aboard				
1450	N/M MR. WAYNE Aboard MR. CONNALLY ASHORE.				
1500	Round "A" on Pope.				
1525	N/M TO WEIGEL.				
1530	CAPTAIN Aboard.				
1600	Round "A" ON WEIGEL.				
1700	Round "B" ON POPE				
1711	Sunset, Colors.				
1800	Round "B" ON WEIGEL				
1900	Round "A" ON POPE.				
1950	N/M & F/W TO WEIGEL				

— CONTINUED —

AT/PASSAGE FROM SAN FRANCISCO <i>NAVAL SHIP YARD, HUNTERS</i> ZONE DESCRIPTION <i>FG</i>	TO Point PIER #2 BERTH #3 DATE (Day, month, year) <i>12 JAN 1970</i> DAY OF WEEK <i>Monday</i>
---	--

TIME	REMARKS
	<i>1600-2400</i>
	<i>MR. WAYNE N/M REMILLARD A/B G/W BUNDY A/B F/W</i>
<i>2000</i>	<i>F/W MAKING "A" ROUND ON WIEGEL. N/M ON INSPECTION TOUR.</i>
<i>2000</i>	<i>FOR THE PAST HOUR MRS WILLIAMS HAS BEEN TRYING</i>
	<i>TO LOCATE HER SON, THROUGH THE SHIP. WILLIAMS, E.M.</i>
	<i>DILER.</i>
<i>2020</i>	<i>N/M & F/W RETURNED FROM WIEGEL.</i>
<i>2100</i>	<i>ROUND "B" ON POPE.</i>
<i>2200</i>	<i>ROUND "B" ON WIEGEL.</i>
<i>2215</i>	<i>WATCH RELIEVED</i>
<i>2220</i>	<i>ON WATCH Iredale F/W - O'Dell A/B - Alexander RDO</i>
<i>2300</i>	<i>Iredale on "A" route of pope</i>
<i>0000</i>	<i>" " " " " Wiegell</i>
<i>0100</i>	<i>" " B " " Pope</i>
<i>0200</i>	<i>" " B " " Wiegell</i>
<i>0300</i>	<i>" " A " " Pope</i>
<i>0400</i>	<i>" " A " " Wiegell</i>
<i>0500</i>	<i>" " B " " Pope</i>
<i>0530</i>	<i>" " " " " Wiegell</i>
<i>0630</i>	<i>WATCH RELIEVED BY DURAN</i>
	<i>Mr. Connally i/o 0800-1600</i>
<i>0630</i>	<i>Assumed Watch: 1st Aboard</i>
<i>0650</i>	<i>C/steward and Purser Aboard.</i>
<i>0700</i>	<i>C/Engineer Aboard</i>
<i>0730</i>	<i>Made round A on Pope</i>
<i>0800</i>	<i>Colors up: 0810 Made round A on Wiegell</i>
<i>0900</i>	<i>Made round B on Pope</i>
<i>1010</i>	<i>Mr. John Davis Safety officer Ashore</i>
<i>1015</i>	<i>Made round B on Wiegell</i>
<i>1100</i>	<i>" " A on Pope</i>
<i>1150</i>	<i>Mr. Lovgren Port Steward MSTS Aboard</i>
<i>1200</i>	<i>Made round A on Wiegell</i>
<i>1300</i>	<i>" " B " Pope</i>
<i>1345</i>	<i>R/E Mr. Burdick Aboard</i>
<i>1350</i>	<i>Mr. Pike Aboard 2nd mate</i>
<i>1400</i>	<i>Mr. Connally to Wiegell</i>
<i>1400</i>	<i>Made round B on Wiegell</i>
<i>1430</i>	<i>WATCH RELIEVED BY A/B BUNDY</i>
	<i>F.B. Celada</i>

AT/PASSAGE FROM SAN FRANCISCO NAVAL SHIPYARD, HUNTERS POINT		TO PIER #2 BERTH #3	
ZONE DESCRIPTION +8		DATE (Day, month, year) 13 JAN, 1970	DAY OF WEEK Tuesday

TIME	REMARKS
	1600 - 2400
	N/M MR. WAYNE REMILLARD G/M BUNDY F/W
1420	ASSUMED THE WATCH.
1431	FUEL BARGE APPROACHING.
1445	N/M MR. WAYNE, ABOARD. 1500 Round "A" POPE
1505	N/M to WIEGEL
1510	1/2 N/M RETURN FROM WIEGEL.
1515	1/2 ASHORE.
1535	COMMENCED OFF LOADING FUEL. BRAVO UP.
1600	Round "A" WIEGEL. PASSED THE WORD, "NO SMOKING ON THE WEATHER DECKS."
1700	Round "B" POPE
1712	SUNSET, COLORS. BREAKDOWN LIGHT UP WHILE PUMPING OFF BUNKERS.
1750	MASTER ASHORE.
1800	Round "B" FOR WIEGEL.
1835	JUST, VERNON JR. ^{UTILITYMAN} 27083 REPORTED ABOARD, ADDITIONAL POSITION.
	MAHONEY, JEWELL E JR. UTILITYMAN 34571 REPORTED ABOARD, ADDITIONAL POSITION
1900	Round "A" ON POPE.
2000	Round "A" ON WIEGEL.
2030	N/M to WIEGEL. 2100 RETURNED.
2100	Round "B" POPE.
2200	Round "B" ON WIEGEL.
2215	WATCH RELIEVED BY ORR
2300	MR. O'HARA RE ABOARD. F/W MAKING POPE ROUNDS. Remillard
2315	MR. BURDICK ASHORE
2400	F/W MAKING WIEGEL ROUNDS

AT/PASSAGE FROM		TO	
PIER #2 BERTH #33 S.F. NAVAL SHIPYARD		HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
PLUS EIGHT		14 JANUARY 1970	WEDNESDAY
TIME	REMARKS		
	MR. ALEXANDER R/O (0000-0800) MR. O'HARA R/E		ORR - GANGWAY NIX - FIREWATCH
0000	F/W MAKING WEIGEL ROUNDS. OFF LOADING FUEL CONTINUES.		
0055	R/O TO WEIGEL		
0100	F/W MADE POPE ROUNDS		
0125	R/O BACK		
0200	F/W ROUNDS ON WEIGEL. --- SOME WATER IN COMP. 3-7 PORT SIDE ---- DRAINING SLOWLY.		
0300	F/W MADE POPE ROUNDS		
0400	F/W MADE WEIGEL ROUNDS		
0500	F/W MADE POPE ROUNDS		
0600	F/W & R/O MADE WEIGEL ROUNDS. R/O CHECK DRAFTS		
0615	WATCH RELIEVED BY CELADA <i>See. Com</i>		
	1/0 Mr. Connally 0800-1600 Celada - G/W Duran - Fire Watch		
0618	Assumed Watch! All in good order.		
0615	Mr. Thompson 2 nd Asst Eng. Aboard.		
0640	1 st Officer, Purser and Chief Steward aboard & Mr. Alexander R/O Ashore		
0650	Chief Eng. Mr. Bantz Aboard and Mr. Peck 1 st Asst Eng.		
0700	Made round A on Pope. Mr. O'Hara R/E Ashore		
0800	Colors up:-		
0825	Made round A on Weigel. Stop discharging fuel oil. 0845		
0900	Made round B on Pope		
1000	" " " " Weigel		
1030	Capt. Landry Aboard.		
1100	Made round A on Pope		
1200	" " A " Weigel		
1220	Mr. Lovgren Port Steward Aboard		
1300	Made round B on Pope		
1305	Capt Landry, 1 st Mate, Chief Eng. Chief Stwd & Port Stwd to Weigel		
1330	Chaplin Regler MSTC Callal. Will pick up gear Thursday 1-14-70		
1400	Made round B on Weigel		
1415	Mr. Smith Purser Ashore		
1420	Watch relieved by Bundy ^{12/13} F.B. Celada ^{A/B}		
	1600-2400		
	MR. WAYNE N/M REMILLARD G/W BUNDY F/W		
1420	Assumed the Watch.		
1430	MASTER, CH. ENGINEER & R/O RETURNED FROM WEIGEL		
1445	MR. WAYNE N/M ABOARD. R/O ASHORE.		
1500	Round "A" POPE. Purser & Steward Ashore JMR		
1520	N/M To Weigel for inspection. Returned 1550 1530		
1527	CARILLO AB/M 167-5 CALLED. WILL NOT BE IN TOMORROW, TAKING CHILD TO DENIST.		
1540	N/M OUT FOR DRAFTS. RETURNED 1550.		
1600	Round "A" ON WEIGEL.		
1700	Round "B" ON POPE.		
1713	Sunset, Colors.		
1800	Round "B" WEIGEL. WATER IN STEERING ENG. RM. FROM RAIN.		

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

14 JAN 1970

Wednesday

+8

Remillar I

H. E. Q.

AT/PASSAGE FROM
 PIER #2 BERTH #33 S.F. NAVAL SHIPYARD (HUNTERS POINT) S.F. CALIF.
 ZONE DESCRIPTION
 PLUS EIGHT
 DATE (Day, month, year)
 15 JANUARY 1970
 DAY OF WEEK
 THURSDAY

TIME	REMARKS
	MR. ALEXANDER R/O (0000-0800) ORR--- GANGWAY MR. BURDICK R/E NIX--- FIREWATCHMAN
0000	MOORED AS BEFORE. #3 BOILER ON THE LINE. F/W MADE WEIGEL ROUND.
0100	F/W MAKING POPE ROUNDS. R/O TO WEIGEL.
0200	F/W MAKING ROUND ON WEIGEL.
0245	MASTER ASHORE. GONE TO MARILL AT CONCORD.
0300	F/W MADE POPE ROUND
0400	F/W MADE WEIGEL ROUND
0500	F/W MADE POPE ROUND.
0600	F/W MADE WEIGEL ROUND.
0630	WATCH RELIEVED BY DURAN <i>Geo. Orr</i>
	1/0 Mr Connally 0800-1600 G.W. - Calate F/W - Duran
0630	Assumed watch: All in good order
0635	Ch. Mate, Chief Stwd. and Purser Aboard
0730	Smoke Detector & Riddle Alarm tested both ship
0730	Sounding taken both ships. Anchor Windlass, and Capstan tested for 30 minute. A route on Pope.
0800	Colors up:-
0830	Made round A on Weigel
0900	Mr. Reyes Tech. MSTS. Aboard. Made round B on Pope
0930	Mr. Connally 1/0 to Weigel. Return 1030
1030	Capt. Landry Aboard. Made round B on Weigel
1120	Mr. Lovgren Port Stwd Aboard. 1210 Ashore
1200	Mr. Bantz C/Eng. to Weigel. Return 1300
1230	Capt. Landry Ashore
1430	Watch relieved by Remillard & B R. B. Calate & B
	1600 - 2400
	N/M MR WAYNE G/W Remillard F/W Bundy
1420	Assumed the watch.
1430	R/E ABOARD & CH. ENGR. ASHORE.
1435	Stwd & Purser ASHORE.
1440	N/M ABOARD. 1445 MR. CONNALLY 1/0 ASHORE.
1500	Round "A" POPE.
1555	N/M & F/W To Weigel. N/M Returned at 1615
1600	Round "A" Weigel.
1700	Round "B" POPE.
1714	SUNSET COLORS.
1800	"B" Round on Weigel.
1900	Round "H" POPE.
2000	Round "M" Weigel
2100	Round "B" POPE.
2200	Round "B" Weigel. Watch Relieved by Orr & Nix Remillard
2222	MR ALEXANDER R/O ABOARD
2230	MR WAYNE ASHORE
2300	MR. O'HARA R/E ABOARD. F/W MAKING POPE ROUNDS
2315	MR. BURDICK ASHORE J.E.C.

AT/PASSAGE FROM		TO	
PIER #2 BERTH #33 S.F. NAVAL SHIPYARD		(HUNTERS POINT) S.F. CALIF.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
PLUS EIGHT		16 JANUARY 1970	FRIDAY
TIME	REMARKS		
	MR. ALEXANDER R/O (0000-0800) ORR--- GANGWAY MR. O'HARA R/E NIX--- FIREWATCHMAN		
0000	F/W MADE WEIGEL ROUNDS		
0045	R/O TO WEIGEL		
0100	F/W MADE POPE ROUNDS--- REPORTS THAT A PIPE IS LEAKING IN TROOP RECREATION AREA--- PORT SIDE. R/E & R/O NOTIFIED.		
0200	F/W MADE WEIGEL ROUNDS		
0300	F/W MADE POPE ROUNDS		
0400	F/W MADE WEIGEL ROUNDS. REPORTS RAIN WATER COMING DOWN STACK INTO FWD ENGINE ROOM---		
0500	F/W MADE POPE ROUNDS--- REPORTS WATER INCREASING IN TROOP REC. AREA.		
0600	WEIGEL ROUNDS MADE--- SUBSTANTIAL AMOUNT OF WATER IN COMP #7--- 2 ND , 3 RD , & 4 TH DECKS--- WATER ON 2 ND DECK APPEARS TO HAVE COME FROM SCUTTLE BUTT DRAIN.		
0605	WATCH RELIEVED BY FRANK CELADA Lbr. ORR		
	Mr. Connally R/O 0800-1600 Gwy - Celada Firewatch Duran =		
0605	Assumed Watch:		
0615	Mr. Thompson Aboard		
0635	Mr. Connally 1 st officer Aboard. Mr. Alexander Ashore		
0700	Mr. O'Hara R/E Ashore. Mr. Smith Purser & Mr. Datola chief stwd Aboard		
0710	Smoke Detector & Kidde Alarm tested		
0735	Mr. Bantz ch/Eng Aboard		
0750	Mr. Datola ch/stward Ashore		
0800	Colors up! - Soundings taken both ships		
1000	Mr. Thompson Medical Supply Representative Aboard. to Weigel. leave ship 1005.		
1035	Milk delivered on board		
1135	Mr. Datola ch/stwd. Aboard		
1315	Mr. Lovgren Port Stwd Aboard - ASHORE : 1430		
1405	Mr. Bundick R/E Aboard		
1420	Watch relieved by Fred Dale A/B		
	Mr. Wayne, R/O (1600-2400) FREDALE, G/W. O'DELL F/W		
1445	Mr. Wayne ASD. Mr. Connally ashore		
1500	Detex "A" route made in Pope. All secure		
1530	Mr. Wayne making inspection Tour in Weigel. Back 1605		
1600	Detex A route made in Weigel - All well		
1700	Detex B rt. in Pope		
1715	Sunset colors made.		
1800	Detex B rt. in Weigel - do.		
1820	Nix, A/B, called in sick. Can't stand 0000-0800 watch tonight		
1910	Detex A round in Pope. All secure		
1945	YARD Public Works reports burst fresh wtr. feed hose to Weigel. WATER SECURED. BACK ON @ 2020		
2000	Detex A rd. in Weigel - All secure		
2030	Mr. Wayne off to Weigel Return 2050		
2100	Detex B rd. made in Pope - All well		
2130	FRESH WTR. hose leading from dock to Weigel removed by YARD (5400 99)		
2200	Detex B rd in Weigel All well		
2215	Relieved of watch by Gen Orr		

PIER # 2

ZONE DESCRIPTION

PIER # 2 BERTH 33 S.F. NAVAL SHIPYARD (HUNTERS PT.) S.F. CALIF	
ZONE DESCRIPTION	DATE (Day, month, year) DAY OF WEEK
PLUS EIGHT	16 JANUARY 1970 FRIDAY

PLUS EIGHT

DATE (Day, month, year)

16 JANUARY 1970

[illegible]

FRIDAY

[illegible]

AT/PASSAGE FROM		TO	
PIER #2 BERTH #33 S.F. NAVAL SHIPYARD (HUNTERS POINT) S.F. CALIF.			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
PLUS EIGHT		17 JANUARY 1970	SATURDAY
TIME	REMARKS		
	MR. ALEXANDER R/O (0000-0800) ORR-GANGWAY-FIREWATCH		
0000	MR. O'HARA R/E WEIGEL DETEX "A" ROUNDS MADE.		
0040	R/O TO WEIGEL 0045 RETURNS		
0100	POPE ROUNDS "B" --- PIPE STILL LEAKING IN TROOP REC. AREA PT. SDE		
0200	WEIGEL ROUNDS "B"		
0300	POPE ROUND "A"		
0400	WEIGEL ROUND "A"		
0500	POPE ROUND "B"		
0600	WEIGEL ROUND "B"		
0650	WATCH RELIEVED BY CLADA H.E.O.		
	Mr. Alexander R/O 0800-1600 GUY-Celada		
0650	Assumed Watch. All in apparent good order		
0715	Made round A on Pope		
0730	Sounding taken on Pope. Mr. Alexander R/O to Weigel		
0800	Colors Up. Made round A on Weigel.		
0930	Made round B on Pope.		
0930	Mr. Wayne R/O Aboard + Mr. Alexander R/O Ashore		
1010	Mr. Burdick R/E Aboard. Made round B on Weigel.		
1025	Mr. Wayne R/O to Weigel. Return 1045		
1030	Mr. O'HARA R/E Ashore		
1045	NIX A/B Call sick with Flu. Cannot come on his watch.		
1125	Made round A on Pope		
1210	" " A on Weigel		
1300	" " B " Pope		
1400	" " " " Weigel. Mr. Wayne R/O to Weigel. Return 1430		
1445	Watch Relieved by Iredale A/B		
	F. B. Celada A/B.		
	Mr. Wayne RDO (1600-2400) IREDALE G/W - O'DELL, F/W.		
1500	Detex A round made in Pope.		
1600	Detex A round in Weigel.		
1700	Detex B rd in Pope - All secure.		
1716	Sunset. Evening colors.		
1800	Detex B rd in Weigel. All well		
1900	Detex A rd in Pope - All -		
1912	Loss of air pressure from shore - No. 3 boiler + all aux. units secured		
2000	Mr. Wayne To Weigel - Detex A round in Weigel		
2100	Detex B round in Pope - All secure		
2115	Relit boiler No 3.		
2150	Detex B round in Weigel - All secure		
2210	Relieved of watch by Geo Orr		
2220	MR. ALEXANDER RELIEVES MR. WAYNE AS R/O		
2255	MR O'HARA R/E ABOARD.		
2300	POPE "A" ROUNDS		
2400	WEIGEL "A" ROUNDS H.E.O.		

AT/PASSAGE FROM PIER #2 BERTH #33 S.F. NAVAL SHIPYARD (HUNTERS POINT) S.F. CALIF.	TO DATE (Day, month, year) 18 JANUARY 1970	DAY OF WEEK SUNDAY
ZONE DESCRIPTION PLUS EIGHT		

TIME	REMARKS
	MR ALEXANDER R/OFF. (0000 - 0800) OMR-GWY-F/W MR O'HARA R/ENG
0000	WEIGEL "A" ROUNDS MADE
0100	POPE "B" ROUNDS MADE, PIPE LEAKING IN TROOP REC. HALL
0110	R/O TO WEIGEL
0200	WEIGEL "B" ROUND MADE
0300	POPE "A" ROUND MADE
0400	WEIGEL "A" ROUND MADE
0500	POPE "B" ROUND MADE
0600	WEIGEL "B" ROUND MADE
0600	WATCH RELIEVED J.E.O.
	R/O MR. ALEXANDER - 0800 - 1600 - F/W-REMILLARD. GWY. - BUNDY
0600	ASSUMED WATCH ALL IN APPARENT GOOD ORDER
0700	F/W ROUND-RTE. "A" POPE - ALL SECURE
0740	R/O TO WEIGEL - ROUTINE INSPECTION - RETURN 0810 - SECURE
0800	COLORS EXECUTED - F/W ROUND - RTE. "A" WEIGEL - ALL SECURE
0900	F/W ROUND - RTE. "B" - POPE - ALL SECURE, EXCEPT, PIPE STILL LEAKING
0955	R/O MR. WAYNE ABD.
1000	F/W ROUND RTE "B" WEIGEL - MR. ALEXANDER ASHORE,
10:30	R/E MR. BURDICK ABD. - MR. O'HARA ASHORE
1100	F/W ROUND - RTE. "A" POPE - ALL SECURE
1200	F/W ROUND RTE. "A" WEIGEL - ALL'S WELL
1300	F/W ROUND RTE. "B" POPE - ALL'S WELL - R/O TO WEIGEL, INSPECTION
1400	F/W ROUND RTE. "B" WEIGEL - ALL SECURE
1425	WATCH RELIEVED BY IREDALE Bundy A/B
	Mr. Wayne, RDO (1600 - 2400), IREDALE G/W - O'DELL, F/W
1500	Detex A round made in Pope. All secure
1530	Mr. Wayne away to Weigel - Return 1600
1600	Detex A rd in Weigel. All's well
1700	Detex B rd in Pope. - do.
1717	Sunset - Evening colors observed.
1800	Detex B rd. in Weigel -
1900	Detex A rd. in Pope
1920	RDO + R/E away to Weigel - Return 1940
2000	Detex A rd. in Weigel
2100	Detex B rd. made in Pope.
2200	B Round Made on WEIGEL.
2205	WATCH RELIEVED ← I Before E except after C
	Iredale
2205	ASSUMED WATCH ALL IN APPARENT GOOD ORDER
2215	R/O MR. ALEXANDER ABD. - MR. WAYNE ASHORE
2255	R/E MR. O'HARA ABD. - MR. BURDICK ASHORE
2300	F/W ROUND RTE. "A" POPE - ALL'S WELL
	Bundy A/B

AT/PASSAGE FROM	TO	
PIER #2 BERTH #33 - HUNTER'S POINT	N.S.V. - SAN FRANCISCO, CA.	
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
+8	19-JAN-1970	MONDAY

TIME	REMARKS
	R/O MR. ALEXANDER R/O MR. O'HARA (0000-0800) F/W REMILLARD - GWY. BLINDY
0000	F/W ROUND - RTE "A", WEIGEL - ALL'S WELL
0100	F/W ROUND - RTE "B", POPE -
0145	R/O TO WEIGEL - RETURN 0200
0200	F/W ROUND - RTE "B", WEIGEL
0300	F/W ROUND - RTE "A", POPE
0400	F/W ROUND - RTE "A", WEIGEL
0500	F/W ROUND - RTE "B", POPE
0540	R/O TO WEIGEL - RETURN 0550
0600	F/W ROUND - RTE "B", WEIGEL
0610	MR PECK FIRST ASST. ENG. ABOARD. WATCH RELIEVED BY SINDONI 0800 - 1600 <i>Bundy MJB</i>
0610	ASSUMED THE WATCH - ON WATCH Mr Connally '10 Sindoni 1/8 - Gray, 2/8
0635	Mr Connally aboard - MR ALEXANDER R/O ASHORE
0655	Mr O'Hara ashore (R/O) - Working Party to Weigel
0715	Smoke detector + Kidde alarm o.k. on Pope (Mr Bantz aboard)
0730	Smoke detector + Kidde alarm o.k. on Weigel
0800	Executed Morning colors
1010	Master Aboard
1020	MSTS Mr Rhey's ship technician aboard
1130	Working Party to Weigel
1230	Mr Rhey's MSTS Rep ashore - Captain handry + Mr Connally to Weigel
1355	Captain handry + Mr Connally aboard
1400	Mr Burdick R/E aboard (working party back from Weigel)
1415	Watch Relieved by Iredale 1/8
	Mr. Wayne, RDO (1600 - 2400) IREDALE, S/W - <i>J Gray 1/8</i> O'DELL, F/W
1500	Detex A round made in Pope - All secure -
1520	Mr. Wayne on inspection Tour of Weigel. Return 1545
1600	Detex A rd. in Weigel - All's well.
1700	Detex B rd in Pope - do -
1718	Sunset - Evening colors -
1800	Detex B rd. in Weigel - do -
1900	Detex A rd in Pope - do -
1950	Mr. Wayne To Weigel - do -
2010	Detex A rd in Weigel - do -
2100	Detex B rd. in Pope - do -
2200	Detex B rd in Weigel - do -
2230	Relieved of watch by Celada, 1/8
	<i>T Iredale</i>

AT/PASSAGE FROM		TO	
Per #2 Box # 33 S.F. Naval shipyard Hunters Point, S.F. Ca.			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
48		20 Jan. 1970	Tuesday
TIME	REMARKS		
	MR Alexander ^{P/B} 0000-0800 DURAN ^{G.W.Y.} Celada F/W		
2230	assumed The Watch. All is in apparent good order.		
2300	made "A" route on Detex clock stairs by Duran. ^{A/B} All's Well.		
2400	made "A" route on Detex clock stairs on Weigel by Celada F/W		
	relief officer ²³⁵⁰ To Weigel - return - 0015		
0100	Made "B" round on Pope - All OK. by Duran ^{A/B} .		
0200	Made "B" round on Weigel by Celada F/W All's Well.		
0300	Made "A" round on Pope by Duran ^{A/B} . All's well.		
0400	Made "A" round on Weigel by Celada All's well		
0500	Made "B" round on POPE by Duran All's Well.		
0530	Remillard ^{A/B} called in sick, Will not be in Today for Watch.		
0600	Made "B" round on Weigel by Celada F/W All OK.		
0615	Watch relieved by Bundy ^{A/B}		
	Duran ^{G.W.Y.}		
0615	1/0 MR. CONNALLY - 0800 - 1600 - G.W.Y. BUNDY		
0615	ASSUMED WATCH-ALL IN APPARENT GOOD ORDER		
0635	CHIEF STEWARD & PURSER ABD. - MR. CONNALLY ^{1/0} ABD.,		
0640	MR ALEXANDER ^{1/0} ASHORE		
0700	MR. BANTZ ^{CH} ENGR ABD. - DECK WORK PARTY TO WEIGEL		
0705	FIRE ALARMS TESTED ON POPE - ALL O.K.		
0715	(4) STEWARD DEPT. WORK PARTY TO WEIGEL		
0735	ENGINE DEPT. WORK PARTY TO WEIGEL		
0800	COLORS EXECUTED		
0845	FIRE ALARMS ON WEIGEL TESTED - ALL O.K.		
0925	MR. CLEVELAND (MSTS) ABD.		
0940	RIGGERS ARRIVE - REMOVE & REPLACE G.W.Y.		
1025	MR HETHINGTON & MR MEASLE, LISANAY ABD TO SEE CAPTAIN		
1030	MSTS INSPECTION PARTY ABOARD (POPE & WEIGEL)		
1035	PURSER TO BANK		
1055	CHIEF MATE MEXER ^{P/B} FROM MEYER TO SEE MR. CONNALLY		
1110	Purser returned from Money Run		
1208	CAPTAIN, CHIEF MATE TO WEIGEL, CHIEF STWD, WEIGEL, AND CHIEF ENGR.		
1250	STEWARD RETURNS FROM WEIGEL		
1400	PURSER ASHORE - (WORK PARTY BACK FROM WEIGEL) Return		
1410	CAPTAIN & CHIEF OFFICER BACK FROM WEIGEL		
1415	P/E MR. BURDICK ABD.		
1425	WATCH RELIEVED BY IREDALE Bundy ^{A/B}		
1430	Purser back.		
1440	Mr. Wayne, RDO, ABOARD -		
	Mr Wayne, RDO (1600 - 2100) IREDALE F/W - O'DELL F/W		
1600	Detex A rd. in Pope. LEAK NOTED #3 HATCH from rain		
1700	Detex B rd in Pope - All secure -		
1711	Sunset - colors made		
1800	Detex A rd in Weigel.		
1900	Detex A rd. in Pope		
1945	Mr. Wayne off To Weigel. Return @ 2010		
2000	Detex B rd in Weigel. All secure		

AT/PASSAGE FROM S.F.B. N.S. Hunters Point	TO Pci 2 - Puth 3.
ZONE DESCRIPTION + 8	DATE (Day, month, year) 20 JAN 70
	DAY OF WEEK TUES.

TIME	REMARKS
	1600-2400 Continued
2100	Detex B rd in Pope. All secure.
2200	Detex B rd in Weigel - do -
2220	Mr. Alexander, 2DO 404 - aboard.
2220	Watch relieved by Duran A/B
	27 March
2220	Relieved The Watch. All is in apparent good order. MR Wayne Poashore - Mr. Alexander's Po assumes the watch.
2300	Made "A" round on Pope by Duran A/B All is well.
2400	Made "A" round on Weigel by Celada FW A/B well. Duran A/B
	G.D. 0000-0800 Duran GWY Celada FW

AT/PASSAGE FROM		TO
NAVAL SHIPYARD - HUNTERS POINT -		San Francisco Calif.
ZONE DESCRIPTION		DATE (Day, month, year)
+8		Jan. 21, 1970
		DAY OF WEEK
		Wednesday
TIME	REMARKS	
	MR. Alexander ^R / _E 0000-0800 DURAN ^{GWY} / _W Celada ^F / _W	
0000	Made "A" round on Weigel by Celada ^F / _W All's well.	
0100	Made "B" round on Pope by Duran ^A / _B All is well except for water Portside Compt "B" 3 rd deck "Pope" and Troop Library area 4-149-0. Portside "Pope"	
0200	Made "B" round on Weigel by Celada - All OK.	
0300	Made "A" round on Pope by Duran - All OK.	
0400	Made "A" round on Weigel by Celada All's well.	
0500	Made "B" round on Pope by Duran - All OK.	
0600	Made "B" round on Weigel by Celada ^F / _W All OK.	
0615	Watch relieved by Bundy ^A / _B Duran ^A / _B	
	1/0 MR. CONNALLY 0800-1600 - BUNDY - GWY.	
0615	ASSUMED WATCH, ALL IN APPARENT GOOD ORDER. ^{3/E} MR. THOMPSON, ABD.	
0625	PURSER ABOARD	
0650	MR. CONNALLY CHIEF OFFICER ABD. - MR. ALEXANDER ^R / _E ASHORE	
0705	1/E MR. O'HARA ASHORE - WORK PARTY TO WEIGEL	
0715	FIRE ALARMS ON POPE TESTED - ALL OK.	
0720	REMILLARD ^A / _B CALLED IN SICK, WONT BE IN FOR WATCH.	
0800	COLORS EXECUTED - ^{2/E} TO WEIGLE	
0833	1/0 TO WEIGLE	
0935	CHIEF STEWARD ABOARD	
0945	MR. STEVENS USN. TO SEE CAPTAIN LANDRY	
1015	LINDSEY-25886, SERAFINO. 13767, REPORT ABD, NEW POSITIONS ^{ABM.}	
1035	MR. BANTZ, CHIEF ENGR. ABOARD - PERKINS ABM. ABD, NEW POSITION	
1145	MR. DAVIS, SAFETY INSP., & PARTY - ABOARD - 1/0 TO WEIGEL	
1245	MR. DAVIS & PARTY ASHORE.	
1415	WATCH RELIEVED BY Nix Bundy ^A / _B MR. WAYNE RDO (1600-2400) NIX - GANGWAY MR. BURDICK REQ. OVR. ^F / _W	
1415	ASSUMED WATCH. All in Apparent Good Order.	
1415	MR. SHADY ABOARD WITH Deputy Supply Officer.	
1415	MR. BURDICK, REQ, ABOARD.	
1440	MR. WAYNE RDO ABOARD.	
1505	MR. SHADY & SUPPLY OFFICER ASHORE ^F / _W MAKING POPE ROUNDS.	
1510	MR. CONNALLY 1/0 ASHORE.	
1520	CHIEF ENG & PURSER ASHORE.	
1600	DETEX Round MADE ON WEIGEL. MC CARTHY ENG. STORER ^{ABM.}	
1600	SIXTEEN CASES OF EGGS ABOARD.	
1700	DETEX Round MADE ON POPE.	
1720	COLORS:	
1800	WEIGEL ROUNDS MADE. OILER MAKING ENGINE ROOM CHECK	
1825	OILER RETURNS FROM WEIGEL	
1900	DETEX Round MADE ON POPE.	
1910	MR. WAYNE TO WEIGEL. - 1945 MR. WAYNE RETURNS.	
2000	DETEX Round MADE ON WEIGEL.	
2100	POPE ROUNDS MADE	
2200	WEIGEL ROUNDS MADE.	
2200	WATCH RELIEVED BY CELADA.	

AT/PASSAGE FROM		TO	
US Naval Shipyard - Hunters Pt. San Francisco. Calif.		San Francisco. Calif.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+8		22 JAN 70	Thursday.
TIME	REMARKS		
2230	assumed the watch - All is well 21 JAN 70. Wed. Mr. Alexander R/O & Mr. Ohara R/E on watch - DURAN Gwy. Celada A/B Fire watch on Weigel making rounds.		
2300	made "A" route on Pope by Duran A/B - All is OK.		
2400	made "A" route on Weigel by Celada F/W All is OK.		
	MR. Alexander R/O MR. Ohara R/E 0000-0800 DURAN Gwy Celada F/W		
	January 22, 1970 - Thursday		
0100	Made "B" route on Detex clock stas All OK - Duran (ON POPE)		
0200	Made "B" route on Detex clock stas by Celada F/W All is well on Weigel		
0300	made "A" round on Pope - Duran All is OK.		
0400	made "A" round on Weigel by Celada. All is OK. There		
0500	Made "B" round on Pope by Duran All is good.		
0600	Made "B" route on Weigel by Celada F/W All is in good order.		
0605	Watch relieved by Remillard A/B		
	1/0 MR. CONNALLY 0800-1600 - Gwy. BUNDY - F/W REMILLARD		
0605	ASSUMED WATCH, ALL IN APPARENT GOOD ORDER		
0615	MR. THOMPSON 2/ENGR. ABD.		
0630	PURSER ABD. - R/E MR. O'HARA ASHORE		
0640	MR. CONNALLY, FIRST OFFICER ABD. MR. ALEXANDER ASHORE		
0705	WORK PARTY TO WEIGLE		
0735	1/0 MR. CONNALLY TO WEIGEL - ALSO MR. ROBINSON PORT STWD.		
0740	MR. BANTZ. CHIEF ENGR. ABD.		
0750	FIRE ALARMS TESTED ON POPE - ALL O.K.		
0800	COLORS EXECUTED - FIRE ALARMS ON WEIGEL TESTED - ALL O.K.		
0815	ANCHOR WINDLASS (POPE) TESTED, RUN 30 MIN. - O.K.		
0827	MR. KEATING, M.S.T.S. TO SEE PURSER.		
1015	CAPTAIN LANDRY TO WEIGEL, RETURNED 11:05		
1030	MILK DELIVERED TO SHIP (8 CASES)		
1155	MR. MONTGOMERY PORT STWD. ABOARD - ASHORE 1310		
1235	CAPTAIN LANDRY ASHORE, TO COMMAND OFFICE MSC.		
1300	BREAD DELIVERED TO SHIP		
1405	WATCH RELIEVED BY NIX. Bundy A/B. (1600 - 2400) NIX - G/W ORR - F/W		
1405	ASSUMED WATCH. All in APPARENT Good ORDER.		
1440	CHIEF ENGR. ASHORE. =		
1445	MR. WAYNE, RDO, ABOARD. 1450 MR. WAYNE TO WEIGEL. 1520 RETURNS.		
1500	PURSER ASHORE.		
1500	All in APPARENT Good ORDER. No Round made on POPE.		
1600	WORK DETAIL SECURED ON WEIGEL.		
1700	F/W MAKING "B" ROUND ON POPE		
1700	CAPTAIN LANDRY ABOARD -		
1722	Colors:		
1800	Round MADE ON WEIGEL. OILER TO WEIGEL 1820 RETURNS		
1900	POPE ROUND MADE. R/O TO WEIGEL - 1945 - RETURNED		
2000	WEIGEL ROUNDS MADE.		
2100	POPE ROUND MADE.		
2200	WEIGEL ROUNDS MADE.		
2200	WATCH RELIEVED BY CELADA.		

AT/PASSAGE FROM		TO	
San Francisco NAVAL Shipyard		Hunters P.T. SF. Cal. F.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+8		23 JAN. 70	Friday.
TIME	MR. Alexander R/o Mr. Ohara R/E	REMARKS	Duran GWY Celada FW
		Thursday JAN. 22. 1970	
2225		Assumed The Watch All is in apparent good order.	
2230		Mr. Alexander R/o aboard. Mr. Wayne ashore.	
2250		Mr. Ohara R/E aboard - Mr. Burdick ashore.	
2300		Made "A" route on Pope by Duran - All is OK.	
2400		Made "A" route on Weigel by Celada FW All is OK.	Duran GWY W.
		JAN. 23. '70 [0000-0800] Fri 1970.	
	MR. Alexander R/o		Duran GWY
	MR. Ohara R/E		Celada FW
0030		Relief Mate To Weigel - RETURNS 0105.	
0100		Made "B" route on Pope - All is OK. Water still in. Compt 7-3 Deck and Troop Library areas. Duran.	
0200		Made "B" route on Weigel by Celada FW All is OK.	
0300		Made "A" route on Pope by Duran All is OK.	
0400		Made "A" route on Weigel by Celada all OK.	
0430		Iredale A/B called in sick. Will not be here Today.	
0500		Made "B" route on Pope by Duran All is OK.	
0530		Routine morning call to Bos'n.	
0540		Garde ABM, called in sick. Will not be in Today.	
0600		1st asst Eng. was called.	
0615		Genovia Machinist called in - will be in Late. This morn.	
0615		Finished "B" rounds on Weigel by Celada FW all is Fine.	
0630		Ch. Stew G.D. Purser aboard.	
0635		MR. Connally 1st Mate ashore ^{aboard}	
0640		MR. Alexander R/o ashore.	
0650		MR. Ohara R/E ashore.	
0705		Gray A/B relieves The watch.	Duran.

1 REDALE

OFF 15th of OCTOBER

	MON	TUE	WED	THU	FRI	SAT	SUN
NIX	OFF	OFF	^G 8-16	^F 0-8	^G 8-16	^F 16-24	^G 8-16
IREDALE	^G 16-24	^F 8-16	OFF	OFF	^G 0-8	^F 0-8	^G 16-24
LARKIN	^G 0-8	^F 16-24	^G 16-24	^F 8-16	OFF	OFF	^G 0-8
PBIOTI	OFF	^F 0-8	^G 0-8	^F 16-24	^G 16-24	^F 8-16	OFF
PBRKINS	OFF	^G 0-8	^F 0-8	^G 16-24	^F 16-24	^G 8-16	OFF
JACKSON	^F 0-8	^G 16-24	^F 16-24	^G 8-16	OFF	OFF	^F 0-8
BUNDY GRAYSON	^F 16-24	^G 8-16	OFF	OFF	^F 0-8	^G 0-8	^F 16-24
ORR	OFF	OFF	^F 8-16	^G 0-8	^F 8-16	^G 16-24	^F 8-16

^G = GANWAY - USNS POPB

^F = FIREWATCH USNS POPB AND USNS WIGGLES

Web List effective 15 Oct. 1969, Wednesday.