

USS GEN John Pope ZONE DESCRIPTION + 7 DATE Thursday 26 Sept, 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM Bath 30 Pier 2 Hunters TO Point San Francisco Calif

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett W/O 0800 — 0800 G/W Mr. A/B
	Assuming The watch vessel moved Port side mooring lines
	all secured Rat Guards in Good order Gangway properly secured
	on watch Tipton & Celada A/B's Detex clock on both USNS GEN
	Wm Weigel & GEN John Pope making hourly Round Through ship
	2245 MR Diegle N/E Aboard MR Wilson R/E ashore 2255 MR Barrett
	N/M Aboard MR Christensen R/M ashore all in apparent Good order
	0000 Detex Clock Rounds made all secured also all secured to both ships
	0100 all secured on both ships 0300 all secured on both ship's Fore & Aft
	0400 Detex Clock Rounds made on both ship's 0500 all secured Fore & Aft
	0600 Clock Rounds made all in apparent Good order 0645 Watch Relieved by Flynn
	A/B Mr. A/B
	0800 - 1600
	Moored as before, On Watch Mr. Collinge /O
	Flynn A/B at the gangway, Nix F/W, making rounds
	on USNS. Weigel & USNS. John Pope
	0745 Robinson port Steward Aboard
	0815 Master Aboard
	0915 Deck Dept. discharging Frozen & dry stores, Truck #25-96025
	1100 Deck Dept. K.O. for Lunch
	1130 Master ashore
	1200 Deck Dept. Turn to
	1300 Mr. Collinge /O inspecting USNS. Weigel
	1445 Watch relieved by Movillion /O
	Paul H. Z. Jr.
	DAVOCOL A/B - 1600 - 2400 - Movillion A/B
	1500 ALL IN ORDER - WATCH PROPERLY RELIEVED
	1500 MR. CHRISTENSEN R/O ABOARD - ATLANTO A/B GANGWAY
	1515 MR. CHRISTENSEN TO WEIGEL FOR INSPECTION - DETEX ROUNDS MADE
	Aboard POPE & WEIGEL - SOUNDINGS TAKEN by Movillion on POPE.
	DAVOCOL ON THE WEIGEL.
	1600 MR. CHRISTENSEN ABOARD POPE - ALL SECURE ON POPE & WEIGEL
	1600 R/E TO WEIGEL FOR INSPECTION
	1620 DAVOCOL ABOARD POPE - ALL SECURE ON WEIGEL
	1700 R/E ABOARD POPE. ALL IN ORDER IN ENGINE SPACES ON WEIGEL -
	MR. CHRISTENSEN TO WEIGEL FOR INSPECTION.
	1725 MR. CHRISTENSEN ABOARD POPE.
	1800 ALL SECURE ON POPE & WEIGEL
	1845 MR. CHRISTENSEN TO WEIGEL FOR INSPECTIONS
	1900 MR. CHRISTENSEN ABOARD POPE. ALL SECURE ON WEIGEL & POPE
	2015 R/E TO WEIGEL FOR INSPECTION
	2025 MR. CHRISTENSEN TO WEIGEL FOR INSPECTION
	2027 R/E ABOARD POPE.
	2145 MR. CHRISTENSEN TO WEIGEL FOR INSPECTION

USS GEN. JOHN POPE ZONE DESCRIPTION +7 DATE THURSDAY 26 SEPT. , 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM BERTH 30 Pier 2 HUNTERS TO POINT SAN FRANCISCO CALIF

TIME	RECORD OF ALL EVENTS OF THE DAY - 1600 - 2400 CONTINUED -
2215	WATCH RELIEVED BY MAHI A/B Vikander Ailano AB
	GEN. John Pope FRIDAY 27, SEPT 1968 MR Barrett W/O G/W MAHI A/B
	0400 - 0800
	Assuming the watch vessel moved Port side Berth 30 Pier 2 Hunters Point SF on watch TIPTON & Celado A/B's making Detex Clock Rounds aboard Gen. Wm Weigel & Gen. John Pope hourly 2230 MR Barrett A/B aboard MR Christ- ensen ashore MR DIEGEL A/B aboard MR Wilson R/E ashore all in apparent Good order aboard both ships
0400	morning lines & Rat Guards all secured also all secured Fore & Aft
0600	Detex Clock Rounds made 0300 Detex Clock Rounds made all secured
0800	all in apparent Good order also all secured aboard both vessels
0800	all in Good order aboard both ships 0630 watch Relieved by FLYNN A/B MAHI A/B
	0800 - 1600
	Moored as before, On Watch, Mr. Collinge I/O Flynn A/B at the gangway, FRUTZ F/W making Detex clock rounds on Gen Weigel & Gen John Pope
0800	Master aboard, Port Steward Robinson aboard
1200	Mr Smith, Purser ashore to Bank
1345	Mr. Smith aboard with \$35000
1400	Gangway all in good order
1430	GANGWAY RELIEVED BY ORR A/B Paul H. Flynn
1500	MASTER ASHORE - DAVOL A/B TO WEIGEL FOR FIREWATCH - MOVILLION TAKING SOUNDINGS - POPE
1510	MR CHRISTENSON MADE TOUR OF INSPECTION OF GEN. WEIGEL - ALL IN GOOD ORDER
1545	OIL SAMPLE LEFT AT GANGWAY PICKED UP ON WATCH? MR CHRISTENSON R/I
1600	F/W DAVOL REPORTS ALL SECURE ON GEN WEIGEL ORR A/B GANGWAY, MOVILLION F/W, DAVOL F/W
1700	MR CHRISTENSON MAKES INSPECTION OF WEIGEL - ALL IN APPARENT GOOD ORDER
1800	DAVOL REPORTS IN FROM WEIGEL - MOVILLION REPORTS ALL SECURE ON POPE
1859	DECK LITES TURNED ON POPE & WEIGEL - SUNSET - MR. CHRISTENSON MAKES INSPECTION WEIGEL
2030	MR CHRISTENSON COMPLETES TOUR OF WEIGEL - F/W REPORT ALL IN GOOD ORDER
2200	MR CHRISTENSON COMPLETES INSPECTION OF WEIGEL
2215	DAVOL REPORTS ALL SECURE ON WEIGEL
2220	WATCH RELIEVED BY MAHI 2nd Com

USS GEN John Pope ZONE DESCRIPTION + 7 DATE SATURDAY 27 SEPT, 19 68
(Day) (Date) (Month)
AT/PASSAGE FROM BETH 30 PIER 2 HUNTERS POINT TO SAN FRANCISCO, CALIF

TIME	RECORD OF ALL EVENTS OF THE DAY
	<u>0600 - 0800</u> <u>Grw mahr A/B</u>
	<u>Vessel moved as before on watch Dabakis + FRUTAZ A/B's</u>
	<u>on security & detex clock rounds on both ships hourly 2240 MR</u>
	<u>DIEGLE N/E aboard MR Wilson N/E ashore MR Barrett N/M aboard MR</u>
	<u>Christensen R/O ashore all in apparent good order on both ships</u>
<u>0600</u>	<u>detex clock rounds made on both ships all in apparent good order</u>
<u>0700</u>	<u>all in apparent good order 0300 morning lines & Rat Guards checked</u>
<u>0400</u>	<u>clock rounds made all secured 0500 all secured on both ships</u>
<u>0600</u>	<u>rounds made all secured 0635 watch relieved Carroll A/B</u>
	<u>mahr A/B</u>
	<u>0800-1600</u>
	<u>CARROLL A/B - ORR A/B FLYNN A/B BARRETT R/O</u>
<u>0700</u>	<u>AB's ORR AND FLYNN making rounds - TAKING SOUNDINGS</u>
<u>0800</u>	<u>ALL ORDERS AND REGULATIONS BEING OBSERVED</u>
<u>0900</u>	<u>ALL ORDERS AND REGULATIONS BEING OBSERVED</u>
<u>1000</u>	<u>AB's ORR AND FLYNN making detex clock rounds</u>
<u>1100</u>	<u>R/E Engineer Aboard - R/O ABOARD</u>
<u>1100</u>	<u>R/O MR. CRISTIANSEN INSPECTING GEN. WEIGEL</u>
<u>1200</u>	<u>ALL IN ORDER - AB's ORR AND FLYNN MAKING ROUNDS</u>
<u>1300</u>	<u>ALL IN ORDER - ALL ORDERS & REGULATIONS BEING ENFORCED</u>
	<u>MR. CRISTIANSEN R/O INSPECTING GEN. WEIGEL</u>
<u>1400</u>	<u>ALL IN ORDER</u>
<u>1430</u>	<u>Relieved By JACKSON A/B</u>
	<u>W Carroll</u>
	<u>16-2400</u>
<u>1500</u>	<u>RELIEF OFF. INSPECTION GEN WEIGEL</u>
<u>1500</u>	<u>ALL IN ORDER WATCH RELIEVED</u>
<u>1500</u>	<u>BLUE & DAVACOL MAKING ROUNDS ON POPE AND WEIGEL</u>
	<u>ABOARD THE POPE AND WEIGEL SOUNDINGS ARE BEING TAKEN</u>
<u>1600</u>	<u>R/O ABOARD POPE ALL SECURE</u>
<u>1700</u>	<u>R/O MADE INSPECTION OF GEN. WEIGEL</u>
<u>1700</u>	<u>ROUNDS MADE ABOARD GEN POPE & WEIGEL ALL SECURE</u>
<u>1800</u>	<u>ROUNDS MADE ABOARD GEN POPE & WEIGEL ALL SECURE</u>
<u>1900</u>	<u>R/O MADE INSPECTION OF GEN. POPE & WEIGEL</u>
<u>2000</u>	<u>ROUNDS MADE ON GEN POPE AND WEIGEL</u>
<u>2040</u>	<u>R/O MADE INSPECTION ON GEN WEIGEL</u>
<u>2100</u>	<u>R/O MADE INSPECTION ON GEN. WEIGEL</u>
<u>2100</u>	<u>ROUNDS MADE ON GEN. POPE AND WEIGEL</u>
<u>2230</u>	<u>RELIEVED BY MAHI A/B</u>

USS GEN John Pope ZONE DESCRIPTION 47 DATE Sunday 29 SEPT, 19 48
(Day) (Date) (Month)
AT/PASSAGE FROM BEITH 32 PIER 2 Hunters Point TO San Francisco Calif

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett W/O ——— 0800 G/W make A/B
	assuming the watch — on watch Celada & Frutaz A/B's
	on detex clock rounds aboard Gen with Weigel & Gen John Pope
	hourly. MR Diesel N/E aboard at 2245 2355 MR Wilson R/E ashore
	MR Barrett N/O aboard MR Christensen R/O ashore all secured
0600	All in apparent good order 0100 all secured Fore & aft
0600	Detex clock rounds made 0310 all secured
0415	meeting lines & Rat Guards checked 0500 rounds completed on
	both ships hourly 0600 Detex clock rounds made all secured
0630	Watch Relieved by Carroll A/B R/E A/B
	0800-1600
	Carroll G/W ORR F.W. FLYNN F.W. BARRETT R/O
0700	Detex Rounds made on Weigel
	Soundings also TAKEN
0800	Continuous Rounds of Weigel and Pope Being Made
0900	Continuous Rounds of Weigel & Pope Being Made
1000	Continuous Rounds of Weigel & Pope Being Made
1030	R/E Aboard
1100	MR. CRISTIANSEN R/O To Weigel
1200	Continuous Rounds of Weigel & Pope
1300	Continuous Rounds of Weigel & Pope Being made
	MR. CRISTIANSEN inspecting GEN. Weigel
1400	Continuous Rounds of Weigel & Pope
1430	Relieved By Jackson A/B
	1600-2400
1430	AB'S BLUE & DAVAROL ARE MAKING ROUNDS ON GEN POPE & WEIGEL
1430	WATCH HAS BEEN RELIEVED
1500	R/O MADE AN INSPECTION ON THE GEN WEIGEL
1600	ROUNDS MADE ON POPE & WEIGEL ALL SCORE
1700	ROUNDS MADE ON POPE & WEIGEL ALL SCORE
1700	R/O MADE AN INSPECTION OF GEN WEIGEL
1800	ROUNDS MADE ON GEN POPE & WEIGEL ALL SCORE
1800	R/O MADE INSPECTION OF GEN WEIGEL
1900	ROUNDS MADE ON GEN POPE & WEIGEL ALL SCORE
1900	R/O MADE AN INSPECTION OF GEN WEIGEL
2000	ROUND MADE ON GEN POPE & WEIGEL
2040	R/O MADE INSPECTION ON GEN WEIGEL
2100	ROUNDS MADE ON THE GEN. POPE & WEIGEL
2100	R/O MADE AN INSPECTION ON GEN WEIGEL
2200	ROUND MADE ON GEN. POPE & WEIGEL
2200	R/O MADE AN INSPECTION ON GEN. WEIGEL
2230	Relieved by FRUTAZ A/B

USS Gen. John Pope ZONE DESCRIPTION +7 DATE Monday 30 Sept, 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM BERTH 30 Pier 2 HUNTERS POINT TO SAN FRANCISCO, CALIFORNIA

TIME	RECORD OF ALL EVENTS OF THE DAY
	0000 - 0800
	Moored as before on watch MR BARRETTE R/O
	MR. Daigle R/E GANGWAY FRUTAZ AB
	CELADA AB TIPTON AB
2300	Assumed Tipton F/W on the Weigle made his
	Round the DETEX Clock Every Hour. Celada
	made his Round on the Pope the DETEX Clock
	Every Hour.
2400	All secure
0000	Mr. Barrette R/O made her round on the Weigle.
0100	All secure
0200	Mr. Barrette R/O made her round on the Weigle.
0300	All secure
0400	Mr. Barrette R/O made her round on the Weigle.
0500	All secure
0600	Mr. Barrette R/O made her round on the Weigle.
	All secure
0640	Watch relieved by <u>Carroll</u> AB
0647	1 ST MATE ABOARD - MR BARRETT R/O + MR DAIGLE R/E ASHORE
0700	DAYWORKERS TURN TO - 4 MEN FROM SULTAN ABOARD FOR DAYWORK
0720	FIREMAIN SHUT DOWN UNTIL FURTHER NOTICE
	(0800 - 1600)
0800	ON WATCH: MR COLLINGS 1/0, ORR 1/3 GANGWAY, DABALOS 1/3
0825	CAPTAIN HEINZ ABOARD
0840	OIL BARGE TIED UP ALONGSIDE GEN. WEIGEL
1100	DAYWORKERS K.O. FOR LUNCH
1130	DECK DEPT. RESUMES WORK OFFLOADING STORES AT GANGWAY
1400	SECURED WORKING STORES AT GANGWAY
1430	WATCH RELIEVED BY CARROLL 1/3 <u>Geo. Orr</u>
1435	MR. WILSON R/E ABOARD
	1600 - 2400
	Carroll G/W Blue F/W Movillian F/W MR CRISTIANSEN R/O
1500	R/E CRISTIANSEN inspecting Weigle - Detex Rounds made
1600	Detex Rounds of Pope and Weigle Being made
1700	R/E CRISTIANSEN inspecting Weigle
1800	Detex Rounds of Weigle & Pope
1900	R/E CRISTIANSEN inspects Weigle
2000	Detex Rounds Being Made on Pope & Weigle
2040	R/E CRISTIANSEN inspected Weigle
2200	R/E CRISTIANSEN inspects Weigle
2230	Watch Relieved By - FRUTAZ
	<u>Carroll</u>

USS Gen. John Pope ZONE DESCRIPTION +7 DATE Tuesday Oct 19 1968
 AT/PASSAGE FROM Borth 30 Pier 2 Hunter Point San Francisco California

TIME	RECORD OF ALL EVENTS OF THE DAY 0000 - 0800
	Moored as before Mr. Barrette R/O Mr. Daigle R/O Friday A.B. Langway Dabaloz O.B. Tipton A.B.
0300	Assume On Watch Tipton made his round the Detex clock on the Weigel every hour. Dabaloz made his round the Detex clock every hour on the Pope.
0400	All secure
0500	Mr. Barrette R/O made his round on the Weigel.
0600	All secure
0700	Mr. Barrette R/O made his round on the Weigel.
0800	All secure
0900	Mr. Barrette R/O made his round on the Weigel.
1000	All secure
1100	Mr. Barrette R/O made his round on the Weigel.
1200	All secure
1300	Watch relieved by Mr. Lee Orr A.B.
	Friday A.B.
0635	ZENTNER, FRANK A/B REPORTED ABOARD VICE RACO
0650	HARPER, CHAS. CARPENTER REPORTED ABOARD
0700	DECK DEPT. TURNS TO OFF LOADING STORES AT GANGWAY - 9 MEN FROM SULTAN
0755	CAPTAIN HEINZ ABOARD
	(0800 - 1600)
0800	ON WATCH: MR COLLINGS ¹ / ₂ , ORR ¹ / ₂ GANGWAY, JACKSON ¹ / ₂
1100	DECK DEPT K.O. FOR CHOW
1128	MR CATRON PORT ENGINEER ABOARD
1130	CAPT. HASKEL + PORT STEWARD SHADDY ABOARD 1145 ASHORE WITH CAPT HEINZ
1245	CAPT. ABOARD
1410	CAPT. HASKEL + MR. SHADDY ASHORE
1430	WATCH RELIEVED BY CARROLL A/B Lee Orr
1435	MR WILSON ¹ / ₂ ABOARD
	1600 - 2400
	Carroll G/W Blue F.W. Movil Lion F.W. CRISTIANSEN R/O
1500	MR. CRISTIANSEN R/O INSPECTS Weigel - Detex Rounds on Pope + Weigel
1600	Detex Rounds of Weigel + Pope made
1700	R/O MR. CRISTIANSEN To Weigel
1800	Detex Rounds of Weigel and Pope made
1900	R/O MR. CRISTIANSEN INSPECTION OF Weigel
2000	Detex Rounds of Weigel and Pope
2100	R/O MR. CRISTIANSEN INSPECTS Weigel
2200	Detex Rounds of Weigel and Pope R/O INSPECTS Weigel
2220	Relieved By MAHI A/B
	W Carroll

USS GEN John PopeZONE DESCRIPTION #7DATE Wednesday 7
(Day) (Date)OCT
(Month), 19 68AT/PASSAGE FROM Berth 30 Pier 2 Hunters Point TO SAN FRANCISCO CALIF

TIME	RECORD OF ALL EVENTS OF THE DAY
	<u>0800 - 1500</u>
	<u>MR Barrett w/o</u> <u>G/W make A/B</u>
	<u>Assuming the watch on watch Dabaras & Tipton A/B's Detex Clock</u>
	<u>Making Rounds on both ships same as before morning lines & Port</u>
	<u>Guards checked all secured 2240 MR Diegel N/E aboard MR Wilson</u>
	<u>R/E ashore 2250 MR Barrett N/W aboard MR Christensen ashore</u>
<u>0000</u>	<u>MR Diegel N/E to Weigel to Pump Bikes 0100 all secured on both ships</u>
<u>0200</u>	<u>Detex Clock Rounds made all secure 0300 all in apparent good order</u>
<u>0400</u>	<u>more, all secured as before 0500 Detex Clock Rounds made on both decks</u>
<u>0600</u>	<u>all in apparent good order 0640 watch relieved by Carroll A/B make A/B</u>
	<u>0800 - 1600</u>
	<u>Carroll G/W FLYNN A/B JACKSON A/B MR. COLLINGE I/O</u>
<u>0700</u>	<u>Deck Dept. D/W turns to Discharging Stwd. Stores</u>
<u>0725</u>	<u>CAPTAIN HEINS ABOARD</u>
<u>0900</u>	<u>FLYNN A/B MAKING ROUNDS with clocks</u>
<u>0935</u>	<u>SMOKE DETECTOR #9-2 TESTED</u>
<u>1000</u>	<u>Deck Dept. continues Discharging Steward Stores</u>
<u>1003</u>	<u>CAPTAIN Ashore</u>
<u>1100</u>	<u>Crew Knocks off for Lunch</u>
<u>1130</u>	<u>Deck Crew Returns to Work</u>
<u>1300</u>	<u>Deck Crew Discharging Stwd. Stores</u>
<u>1305</u>	<u>CAPTAIN ABOARD</u>
<u>1330</u>	<u>Finish Discharging Stores for Day</u>
<u>1400</u>	<u>All in Order - FIRE WATCH BY FLYNN</u>
	<u>1600 - 2400</u>
	<u>DAVACOL A/B (W) - MR. CHRISTIANSEN R/O - MOUTILLON A/B (W)</u>
<u>1500</u>	<u>Assumed the Watch, All in Order. R/O MAKING INSPECTION OF</u>
	<u>WEIGEL, DAVACOL AND MOUTILLON TAKING SOUNDINGS AND MAKING</u>
	<u>DTEX ROUNDS ABOARD POPE AND WEIGEL</u>
<u>1505</u>	<u>MASTER Ashore</u>
<u>1600</u>	<u>All Secure ABOARD POPE AND WEIGEL.</u>
<u>1700</u>	<u>All in Apparent Good Order - R/O MAKING INSPECTION OF WEIGEL</u>
<u>1800</u>	<u>All in Apparent Good Order</u>
<u>1900</u>	<u>All in Apparent Good Order - R/O MAKING INSPECTION OF WEIGEL</u>
<u>2000</u>	<u>All in Apparent Good Order</u>
<u>2040</u>	<u>R/O MAKING INSPECTION OF WEIGEL</u>
<u>2100</u>	<u>All in Apparent Good Order</u>
<u>2200</u>	<u>R/O MAKING INSPECTION OF WEIGEL - All in Apparent Good Order.</u>
<u>23</u>	<u>Watch Relieved</u>
	<u>C.D. Bluf.</u>

USS Gen. John Pope ZONE DESCRIPTION +7 DATE Thursday 3 Oct, 1968
(Day) (Date) (Month)
AT/PASSAGE FROM Hunter's Point Naval Shrd. Pier 2 #30W SAN FRANCISCO, CALIFORNIA

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett w/o 0400 — 0800 G/W make A/B assuming the watch vessel moved as before on watch MR Diegle N/E MR Barrett N/W Celada & Tipton A/B's Detex clock making rounds on Gen. Wm Wiegel & crew John Pope maring lines & Rat Guards checked all deck lights on both ships burning bright all in apparent good order. 0100 both vessels are in good order 0200 all in apparent good order 0300 both vessel moved as before 0400 Detex clock rounds made 0500 all in apparent good order 0600 Detex clock rounds made 0645 Watch Relieved by Flynn A/B 0700 Mr. A/B
	0800 - 1600
	Flynn A/B Mr. Collinge
0700	Deck Dept discharging Steward Stores
0745	Captain Heins aboard
0900	A/B ALATILANO making rounds with Detex clock on both Gen. Pope & Gen Wiegel
1000	Gangway all secure
1300	Mr. Posey aboard
1330	Master & Chief Steward ashore
1400	Mr. Posey ashore
1430	Watch relieved by A/B Dabalos Paul H. Flynn
	1600 - 2400
1445	Mr. Christensen A/B - Mr. O'Hara Night Engineer. Dabalos, A/B - (G.W) Dabalos A/B. Movilion A/B
1500	Assumed the watch, All in Order. Dabalos F.W. on the Weigel - Movilion F.W. on the Pope. All fire watch Report every hour.
1500	Mr. Christensen A/B made inspection on the Weigel - All lines fore & aft & Rat Guard O.K. with two Brestlines of the Bow of the Pope, One Brest line forward to the Weigel. All in Order about the ships.
1600	Mr. Christensen A/B made inspection on the Weigel, All O.K. with one Brest line Aft of the Pope to the Weigel - All fire watch Report all's well about the ships.
1700	Fire watch of the Pope & of the Weigel Report all O.K.
1800	Mr. Christensen A/B made inspection on the Weigel all O.K. Fire watch on the Pope & of the Weigel Report all O.K.
1900	Fire watch on the Pope & of the Weigel Report all O.K.
2000	Mr. Christensen A/B made inspection on the Weigel all O.K. All fire watch Report all's well about the ships.
2030	Mr. O'Hara Night Engineer to the Weigel to check Eng. Room.
2100	All fire watch Report all's well about the ships, Mr. O'Hara Back in.
2200	Mr. Christensen A/B made inspection on the Weigel, All O.K. All fire watch Report all's well about the ships.

USS GEN John Pope ZONE DESCRIPTION +7 DATE FRIDAY 4 OCT, 19 68
(Day) (Date) (Month)
AT/PASSAGE FROM Berth 30 Pier 2 Hunters TO Point San Francisco CA

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett w/o 1400 — 0800 G/W MAHI A/B
	Vessel moored as before mooring lines & Port Guards checked all
	Secured A/Bs on watch Tipton & Celada 2245 MR Diegel N/E aboard
	MR O'Hara R/E ashore 2300 MR Barrett N/M aboard MR Christensen
	R/M ashore assuming the watch all in apparent good order on both ships
0800	All secured on both ships 0900 all in apparent good order Fore & Aft
1200	All secured — 0300 all secured — 0400 all secure — 0500 all secured
1600	All secured 0635 Watch Relieved by Dabalos A/B mahi A/B
	0800-1600
	Mr. Collinge w/o Flynn OM
0700	Deck Dept. turn to. Dabalos FW making clock rounds on the U.S.N.S. Gen. J. Pope, Frutag FW making clock rounds on the U.S.N.S. Gen. Weigel
0945	Master aboard
1000	Don Cameron A/B reported aboard
1100	gangway all in good order, FW reporting all secure
1130	Master ashore 1230 Master aboard
1430	Watch relieved by A/B Orr
1440	RELIEF ENGINEER MR O'HARA ABOARD. ORR ^A BEANGWAY, DAVOCOL ^B ON WEIGEL NOVILLION ^A ON POPE FIREWATCH
1455	RELIEF OFFICER MR CHRISTENSON ABOARD 1515 COMPLETES TOUR OF GEN. WEIGEL
1535	MASTER ASHORE 1600 FW ON WEIGEL REPORTS ALL IN GOOD ORDER
1700	MR CHRISTENSEN COMPLETES TOUR OF WEIGEL. NOVILLION FW REPORTS ALL SECURE ON POPE
1800	DAVOCOL FW ON WEIGEL REPORTS ALL SECURE
1900	MR CHRISTENSEN COMPLETES TOUR OF WEIGEL FW REPORTS ALL SECURE ON POPE
2000	FW DAVOCOL REPORTS ALL SECURE ON WEIGEL
2040	MR CHRISTENSEN + MR O'HARA COMPLETE TOUR OF WEIGEL
2100	FIREWATCH REPORT ALL SECURE ON BOTH VESSELS
2200	MR CHRISTENSEN COMPLETES A TOUR OF THE WEIGEL
2215	FIREWATCH REPORTS ALL SECURE ON WEIGEL
2220	WATCH RELIEVED BY MAHI ^A B 2200 OM

USS GEN JOHN POPE ZONE DESCRIPTION +7 DATE Saturday 5 at 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM Beth 30 Pier 22 Hunters TO Point San Francisco Calif

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett W/O 1100 — 0800 G/W MAHI? A/B
	Classed moved as before on watch Fruta & Celada A/B's to
	Detex Clock Rounds on USNS Gen Wm Weigel & Gen John Pope
2230	MR Barrett R/O aboard MR Christensen N/A ashore
2245	MR Diegel A/E aboard MR O'Hara R/E ^{ashore} aboard making lines
	checked all secured Gangways Rat Guards & deck lights on both
	ships all in good order MR Barrett W/O & MR Diegel A/E making
	odd pairs Round to both ships all in apparent good order Fore & Aft
0000	all secure - all all secure 0200 all secure
0300	all secure 0400 all secure 0500 all in order on both ships
0600	all in apparent good order 0615 watch Relieved by Peterson A/B
	MAHI A/B
	0800 — 1600
	MR Barrett W/O 0722 A/B Flynn A/B Peterson A/B
0700	A/B's 0722 & Flynn making rounds & taking soundings
0800	A/B's Report everything in order & secure
0900	A/B's Report everything in order & secure on Gen Weigel
	& Gen. Pope.
1000	A/B's Report everything in order & secure
1100	Mr Christensen Relieved Mr Barrett as his note
	on duty
1105	Mr Christensen Completed Tour of Weigel
	everything secure & in order
1200	A/B's 0722 & Flynn Reports all secure
1300	A/B's 0722 & Flynn Reports all secure
	Mr Christensen Completed Tour of Gen Weigel
	everything in order & secure.
1400	A/B's 0722 & Flynn Reports all secure
1430	WATCH Relieved By A/B Blue
	Carl Peterson
	1600 - 2400
	JACKSON A/B (FW) — MR. CHRISTIANSEN R/O — DAVACA A/B (FW)
1500	Assumed the Watch, All in Order, R/O Making Inspection of
	Weigel, JACKSON AND DAVACA Taking Soundings And Making
	Detex Rounds Of Pope And Weigel
1600	All In Apparent Good Order
1700	R/O Making Inspection Of Weigel - All In Apparent Good Order
1800	All In Apparent Good Order
1900	R/O Making Inspection Of Weigel - All In Apparent Good Order
2000	All In Apparent Good Order
2040	R/O Making Inspection Of Weigel
2100	All In Apparent Good Order
2200	R/O Making Inspection Of Weigel - All In Apparent Good Order
2230	All In Order - Watch Relieved By MAHI.
	W.D. Bluff.

USS GEN John Pope ZONE DESCRIPTION +7 DATE Sunday 6 Oct, 1945
(Day) (Date) (Month)
AT/PASSAGE FROM Berth 30 Pier 2 Hunters Point TO SAN FRANCISCO Calif

TIME	RECORD OF ALL EVENTS OF THE DAY
	<u>0800 - 0800</u> <u>G/W Mahi A/B</u>
	Assuming the watch vessels moved as before on watch Mr Barrett w/o Mr Diegel N/E Celada & Frutaz A/B's Detex Clock Rounds on both USNS Gen Weigel & Gen John Pope Mr Diegel aboard 2240 Mr O'Hara N/E ashore 2230 Mr Barrett w/o aboard Mr Christensen R/O ashore. w/o & N/E to make add hrs Rounds on Gen Weigel
0800	All secured 0100 all secured 0200 all secured 0300 all secured
0400	all secure 0500 all secure 0520 Frutaz A/B Reports a broken water line on the USNS Gen Weigel 0600 all secured on both ships
0640	Watch Relieved by Petersen A/B <u>Mahi A/B</u>
	<u>0800 - 1600</u>
0800	Mr Barrett w/o OTT A/B Flynn A/B Peterson A/B Assumed the watch 021 + Flynn A/B's Taken soundings + Detex Clock Rounds. All secure & in order. Mr Barrett w/o + Mr Diegel N/E making tour of Gen Weigel, Everything secure & in order.
0900	A/B's 022 + Flynn Reports All secure & in order.
1000	A/B's 022 + Flynn Reports All secure & in order. Mr Barrett w/o + Mr Diegel N/E making tour of Gen Weigel All secure.
1030	Mr O'Hara N/E Aboard relief for Mr Diegel N/E
1045	Mr Christensen Aboard relief for Mr Barrett
1200	Mr Christensen & Mr O'Hara inspection tour of Gen Weigel everything secure & in order.
1130	Jackson cannot in unable to report for watch
1200	A/B's 022 + Flynn Report All secure & in order
1300	Mr Christensen & Mr O'Hara N/E inspection tour of Gen Weigel everything secure & in order. A/B's 022 + Flynn report all secure.
1400	A/B's 022 + Flynn Report All secure.
1430	Watch Relieved by Blue A/B
	<u>1600 - 2400</u>
	<u>Mr. Christensen R/O</u> <u>DAVACOL A/B (FW)</u>
1500	Assumed the watch, All in order, R/O MAKING INSPECTION OF USNS GEN WEIGEL DAVACOL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ON POPE AND WEIGEL HOURS.
1540	DAVACOL MAKING DETEX ROUNDS ON WEIGEL
1640	DAVACOL REPORTS ALL IN ORDER ABOARD WEIGEL AND RETURNS TO POPE
1700	R/O MAKING INSPECTION OF THE WEIGEL
1740	DAVACOL MAKING ROUNDS ON WEIGEL
1840	DAVACOL REPORTS ALL IN ORDER ABOARD WEIGEL AND RETURNS TO POPE
1900	R/O MAKING INSPECTION OF THE WEIGEL
1940	DAVACOL MAKING ROUNDS ON WEIGEL
2040	DAVACOL REPORTS ALL IN ORDER ABOARD WEIGEL AND RETURNS TO POPE
2040	R/O MAKING INSPECTION OF WEIGEL
2140	DAVACOL MAKING ROUNDS ON WEIGEL

19

SAN FRANCISCO, CALIFORNIA

BERTH 30 - DECK 2

TIME

RECORD OF ALL EVENTS OF THE DAY

2200	R/O MAKING INSPECTION OF VEIGEL
------	---------------------------------

2225	DAVACOL R. ^{COB#} REPORTS ALL SECURE ON URGEL, RETURNS TO POPE
------	---

2230 All In Order Watch Released By MAHE TIPTON CALLED IN AND SAID HE MAY BE LATE.

USS Gen. John Pope ZONE DESCRIPTION 47 DATE Monday 7 Oct, 19 68
 AT/PASSAGE FROM Barth 30 Pier 2 Hunter Point San Francisco California

TIME	RECORD OF ALL EVENTS OF THE DAY
	0000 — 0800
	On watch Mr Barrett R/O Mr Daigle R/O Frantz Gangway Celada A.B. Tipton called a little bit later.
2300	Celada A.B. made her round on the Pope every hour with Detex clock and reporting to the bridge. Tipton A.B. made her round on the Weigel every hour with Detex clock.
2400	All secure
0000	Mr. Barrett R/O made her round on the Pope and all secure.
0100	Mr. Barrett R/O made her round on the Weigel. All secure.
0200	Mr. Barrett R/O made her round on the Pope.
0300	Mr. Barrett R/O made her round on the Weigel. All secure.
0400	Mr. Barrett made her round on the Pope all secure
0500	Mr. Barrett R/O made her round on the Weigel. All secure
0600	Mr. Barrett R/O made her round on the
0630	Pope. All secure. Watch relieved by Gen. Greg. A.B. (Mr. Frantz A.B.)
0655	MR BARRETT R/O ASHORE MR DAIGLE R/O ASHORE
0715	CAPTAIN HEINZ ABOARD
0730	DABALOS F/W REPORTS ALL SECURE ON THE POPE MR COLLINGS W/O (0800 - 1600) ORR A/B GANGWAY DABALOS A/FIREWATCH
0800	DABALOS TO WEIGEL FOR FIREWATCH ROUNDS
0935	DABALOS REPORTS ALL IN GOOD ORDER ON GEN. WEIGEL AND RETURNS TO GEN. POPE
1000	ALL IN APPARENT GOOD ORDER — DABALOS MAKING REGULAR ROUNDS
1240	DABALOS TO WEIGEL
1420	DABALOS COMPLETES TOUR OF WEIGEL
1430	WATCH RELIEVED BY BLUE A/B Gen. Orr MR. CHRISTENSEN R/O — 1600 — 2400 PETERSON A/B — MOVILLION A/B
1500	Assumed The Watch All Secure & in order. Mr Christensen making inspection tour of Gen Weigel, Blue & Movillion taking soundings & making hourly Detex clock rounds.
1530	Master Ashore
1600	AB's Blue & Movillion Reports All secured & in order
1700	Mr Christensen & Mr O'Hara made inspection tour of Gen Weigel All Secure & in order. AB's Blue & Movillion Reports All Secure & in order
1800	AB's reports All Secure & everything in order.
1900	AB's report All Secure Mr Christensen & Mr O'Hara made tour of Gen Weigel.
2000	AB's report All Secure. 2100 AB's report All Secure. Mr Christensen & Mr O'Hara made tour of Gen Weigel. 2200 Mr Christensen & Mr O'Hara made tour of Gen Weigel. AB's report all secure everything in order.
2245	Watch Relieved By FRATAZ ⁹² Carl P. Russo

USS GEN. JOHN POPE ZONE DESCRIPTION +7 DATE Tuesday 8 Oct. 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM BERTH 30 PEIR 2 HUNTERS POINT SAN FRANCISCO

TIME	RECORD OF ALL EVENTS OF THE DAY
	0000-0800
2300	MOORED AS BEFORE ON WATCH MR. BARRETT R/O
	MR. DAIGLE R/E FRUTAZ A.B. GANGWAY,
2400	TIPTON A.B. made his round on the WEIGEL
	WITH THE DETEX CLOCK EVERY HOUR.
0000	Dabalos A.B. failed to report for his 0000-0800 watch and duties.
0000	MR. BARRETT R/O made his round on the WEIGEL.
0000	TIPTON made his round on the WEIGEL ALL SECURE.
0100	MR. BARRETT R/O made his round on the POPE.
0100	TIPTON made his round on the POPE WITH DETEX CLOCK.
	ALL SECURE.
0200	MR. BARRETT R/O made his round on the WEIGEL.
	ALL SECURE.
0200	TIPTON A.B. made his round on the WEIGEL
	ALL SECURE
0300	MR. BARRETT R/O made his round on the WEIGEL POPE
	ALL SECURE
0300	TIPTON A.B. made his round on the POPE
	WITH DETEX CLOCK. ALL SECURE.
0400	MR. BARRETT R/O made his round on the WEIGEL.
0400	TIPTON A.B. made his round on the WEIGEL WITH
	THE DETEX CLOCK. ALL SECURE.
0500	MR. BARRETT R/O made his round on the POPE.
0500	TIPTON A.B. made his round on the POPE WITH
	THE DETEX CLOCK. ALL SECURE.
0600	MR. BARRETT R/O made his round on the WEIGEL.
0600	TIPTON A.B. made his round on the WEIGEL WITH
	THE DETEX CLOCK. ALL SECURE.
	WATCH RELIEVED BY GEO. ORR A.B.
	CHRISTENSEN A.B.
0645	MR. BARRETT R/O + MR. DAIGLE R/E ASHORE. 2 MEN FROM SULTAN ABOARD FOR DAYWORK
0750	CAPTAIN HEINZ ABOARD
	MR. COLLINGS R/O (0800-1600) ORR R/O GANGWAY DABALOS F/W
0830	MR. LOVGREN PORT STEWARD ABOARD
0900	DABALOS R/O MAKING FIREWATCH PATROL
1015	MR. LOVGREN ASHORE
1140	DABALOS REPORTS ALL IN GOOD ORDER ABOARD BOTH VESSELS
1330	DABALOS REPORTS ALL SECURE - GEORGE GRIER MSTU REPRESENTATIVE ABOARD
1340	GRIER ASHORE
1425	WATCH RELIEVED BY PETERSON <i>See On</i>
	Mr. Christensen R/O 1600-2400 Mr. O'Hara R/E Blue, Morrison AA.
1430	Assumed the watch ALL SECURE & in order.
1500	Mr. Christensen & Mr. O'Hara R/E made tour on Gen Weigel
	ALL SECURE & in order A/B's report ALL SECURE &
	Everything in order.
1530	Master Ashore.

USNS GENERAL JOHN POPE T-AP110 ZONE DESCRIPTION +7 DATE TUESDAY 8 OCTOBER 1968
(Day) (Date) (Month)
AT/PASSAGE FROM HUNTERS POINT NAVAL SHIPYARD S.F. CALIF. PIER #2 BERTH #30

TIME

RECORD OF ALL EVENTS OF THE DAY

1600 A/B's Blue & Motion reports All secure & in order on both vessels.
1700 Mr Christensen w/ Mr O'Hara R/E made inspection Tour of Gen Heigel, A/B's Blue & Motion reports All secure & in order
1800 A/B's Blue & Motion Reports All secure & in order
1900 Mr Christensen w/ Mr O'Hara R/E made inspection Tour of Gen Heigel All secure & in order
A/B's Blue & Motion reports All secure & in order
2000 A/B's Blue & Motion reports All secure & in order.
2100 Mr Christensen w/ Mr O'Hara made inspection Tour of Gen Heigel All secure A/B's Blue & Motion Reports All secure & Everything in order.
2200 A/B's Blue & Motion Reports All secure & in order
2220 Mr Christensen & Mr. O'Hara made inspection Tour of Gen Heigel All secure & in order.
2240 Watch Relieved By MAN1.

Carl Peterson

USS Gen John Pope ZONE DESCRIPTION +7 DATE wednesday 9 oct, 1968
 (Day) (Date) (Month)
 AT/PASSAGE FROM Berth 30 Pier 2 Hunters Point TO San Francisco, Calif

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett W/O 0400 — 0600 G/W Mahi A/B
	vessel moved as before on watch MR Barrett W/O MR Diegel W/E Tipton & Dabalas A/B's making Detex clock rounds on vessel Gen Wm Weigel & Gen John Pope hourly 2200 MR Diegel W/E aboard MR O'Hara R/O ashore 2300 MR Barrett W/O aboard MR Christensen W/O ashore assuming the watch at G/W 0600 all in apparent good order also all in apparent good order 0700 all secure 0800 all secure 0900 all secure 0500 all secure 0600 all secure 0635 watch relieved by Flynn A/B Mahi A/B
	0800 - 1600
	Mr. Collinge W/O Flynn A/B
0700	Deck Turns to
0815	Smoke Detector Bell Alarm & Kiddie Alarm, Tested both in working order
0820	Captain Heing aboard
0900	Port Steward Mr. Robinson aboard
1000	Center W/O making rounds on Gen. Weigel & Gen. Pope and reporting all secure
1100	Gangway all in good order
1200	Deck Dept Turns to
1430	Watch relieved by Blue W/O Paul H. Flynn
	1600 - 2400
	Davacol W/O — Mr. Christensen R/O — Moulliton W/O
1500	Assumed the watch - All in Order. Mr. Christensen making inspection of the Weigel. Davacol and Moulliton taking soundings and making Detex rounds on Pope and Weigel. R/O inspecting Weigel's engine spaces.
1515	Master Ashore, Mr. Robinson Port Steward Ashore
1600	All in Order aboard Pope and Weigel
1700	All in Order aboard Pope and Weigel. R/O and R/E inspecting Weigel.
1800	All in Order aboard Pope and Weigel.
1900	All in Order aboard Pope and Weigel. R/O and R/E inspecting Weigel.
2000	All in Order aboard Pope and Weigel
2040	R/O and R/E inspecting Weigel
2100	All in Order aboard Pope and Weigel
2200	All in Order aboard Pope and Weigel. R/O and R/E inspecting Weigel
2230	All in Order - Watch Relieved by Mahi A/B
	END OF WATCH A/B

USS GEN John Pope ZONE DESCRIPTION + 7 DATE Thursday 10 Oct, 19 68
 (Day) (Date) (Month)
 AT/PASSAGE FROM Berth 30 Pier 2 Hunters Point TO SAN FRANCISCO CALIF

TIME	RECORD OF ALL EVENTS OF THE DAY
	MR Barrett R/O 0800 G/W Mr. A/B
	Mooed as before Rat Guards & mooring lines checked all secured on watch Tipton & Celada A/B's making hourly Detex Clock Rounds on Gen. Wm Weigel & Gen John Pope MR Barrett R/O & Mr. Diegel N/E making hourly rounds on both ships assuming the watch 0800 all in apparent good order and all secured 0800 all secured 0300 all secured 0445 Watch Relieved by Flynn A/B
	0800 - 1600
	Mr. Collinge R/O Flynn R/O, Zenter R/W
	Mooed as before 0700 Deck Dept. turns to, Zenter R/W making clock round on usns Gen Pope all secure Cameron A/B making rounds on usns Gen Weigel
0800	Captain Heing aboard
1000	PARKS #343 call in sick
1100	Gangway all in good order
1300	Mr. Collinge R/O inspecting Gen Weigel
1300	Mr. Smith, Purser ashore to bank
1410	Purser aboard from bank with \$10,000 cash
1445	Watch relieved by Dabalos R/O
1455	Master of the ship Capt Heing ashore - Paul H. Zenter
	1600 - 2400 - Dabalos, G.W. & Watch
1500	Mr. Christensen R/O - Mr. O'Hara Night Engineer - Davaco (R/W. on the bridge) - Movillow R/O on the bridge Pope
1520	Mr. Christensen R/O made inspection on the usns Gen. Weigel
1600	Fire watch on the Gen. Weigel & fire watch on the Gen. Pope making rounds with Detex Clock all's well about the ships Fore & Aft & Rat Guard in the lines all O.K.
1700	R/O made inspection in the Gen. Weigel all O.K. Two fire watch with Detex Clock made rounds all O.K.
1800	Fire watch in the Gen. Weigel & in the Gen. Pope with Detex Clock all in good order.
1900	R/O made inspection on Gen. Weigel all O.K. Fire watch on both ships Report every hours all O.K.
2000	Fire watch on Gen. Weigel & on the Gen. Pope made rounds with Detex Clock all's well about the ships
2040	R/O made inspection on the Gen. Weigel all O.K.
2100	Two fire watch with Detex clock made rounds in both ships all O.K.
2200	R/O made inspection on Gen. Weigel all O.K. Two fire watch in both ships made rounds with Detex Clock all's well about the ships.
2225	G.W. Watch Relieved Properly by Mr. Nix R/O Dabalos R/O

USN GEN John POPE ZONE DESCRIPTION +2 DATE Friday 11 OCT 1968
AT/PASSAGE FROM BERTH 30 PIER #2 HUNTERS POINT NAVY YARD SAN FRANCISCO, CALIF

TIME	RECORD OF ALL EVENTS OF THE DAY
	0000 - 0800
	ON WATCH: MR BARRETT RDO; MR DAIGLE REO; G/W NIX ABN; TIPTON AB MAKING HOURLY DETEX CLOCK ROUNDS ON GEN WM. WEIGEL & CELADA AB MAKING HOURLY DETEX CLOCK ROUNDS ON GEN. John POPE. MOORED PORT SIDE BERTH 30 PIER #2 HUNTERS POINT S.F., CALIF.
2300	ALL IN APPARENT GOOD ORDER. 0100 - F/W ON BOTH WEIGEL & POPE REPORT ALL IN APPARENT GOOD ORDER. 0100 ALL IN APPARENT GOOD ORDER.
0200	ALL IN APPARENT GOOD ORDER. 0300 F/W WEIGEL & POPE REPORTS "ALL IS WELL."
0400	ALL IN APPARENT GOOD ORDER. 0500 ALL IN APPARENT GOOD ORDER.
0600	ALL IN APPARENT GOOD ORDER.
	0800 - 1600
	Moored as before On Watch Mr Collinge 1/c Flynn A/B Frutaz F/W 0700 Deck Dept. turns to Frutaz F/W making Detex Clock rounds on Gen Weigel. AN Gen. John Pope
0800	Captain Heinz aboard
1100	Deck Dept. KO For Lunch 1200
1130	Port Steward Mr. Love green aboard
1200	F/W reported all secure on both ships
1300	Mr. Collinge inspected Gen. Weigel
1430	Watch relieved by Orr A/B
1445	R/E MR O'HARA ABOARD
1450	CAPTAIN HEINZ ASHORE - LEFT ORDERS TO CLOSE ALL WEATHERDECK OPENINGS - TRIM COWL VENTS FWD.
1455	MR CHRISTENSEN R/O ABOARD - DAYACOL F/W TO WEIGEL MOVILLION F/W ON POPE
1520	MR CHRISTENSEN MADE INSPECTION OF GEN. WEIGEL - ALL IN GOOD ORDER
	MR. CHRISTENSEN R/O MR. O'HARA R/E (1600 - 2400) ORR A/B BEANWAY, DAYACOL F/W, MOVILLION F/W
1600	ROUTINE WATCH - FIREWATCHES MAKING ROUNDS
1700	FIREWATCHES REPORT ALL SECURE - MR. CHRISTENSEN MADE TOUR OF GEN WEIGEL
1800	ALL SECURE
1900	FIREWATCHES REPORT ALL SECURE ---- MR CHRISTENSEN MADE INSPECTION GEN. WEIGEL
2040	ALL SECURE ---- MR CHRISTENSEN COMPLETES INSPECTION OF GEN. WEIGEL
2100	ROUTINE WATCH --- FIREWATCHES MAKING ROUNDS AND REPORTING REGULARLY
2200	MR. CHRISTENSEN AND MR. O'HARA MAKE TOUR OF THE GEN. WEIGEL
2230	WATCH RELIEVED BY ZENTNER 2/c. Con
	0000 - 0800
	MR. BARRETT RDO; MR. DAIGLE REO; G/W F.F. ZENTNER; F/W FRUTAZ F/W CELADA - MOORED AS BEFORE
2300	
	OVER

GEN. JOHN POPE ZONE DESCRIPTION +7 DATE SATURDAY 12 OCT. 1968
(Day) (Date) (Month)
AT/PASSAGE FROM BERTH 30 PIER 2 HUNTERS POINT NAVAL YARD, SAN FRANCISCO

TIME	RECORD OF ALL EVENTS OF THE DAY
	0000 - 0800
	MR. BARRETT P/O. MR. DAIGLE R/O = GEN. FRUTAZ & CELADA IN = MOORED AS BEFORE =
2300	IN FRUTAZ MAKING DETEX CLOCK ROUNDS ON GEN. WM. WEIGEL IN CELADA MAKING DETEX CLOCK ROUNDS ON GEN. JOHN POPE
0000	RAT GUARDS & LINES CHECKED ON BOTH SHIPS = ALL SECURE =
0100	ALL SECURE BOTH SHIPS = 0200 = ALL SECURE
0300	ALL SECURE = 0400 ALL SECURE = 0500 ALL SECURE = INSPECTIONS MADE OF BOTH SHIPS BY MR. BARRETT P/O AND MR. DAIGLE R/O.
0600	HOURLY ROUNDS OF DETEX CLOCKS MADE ON BOTH SHIPS
0630	WATCH RELIEVED BY PETERSON A/B F.F. Zentner
0630	Mr Barrett P/O 0800 - 1600 Flynn A/B Orr. A/B Assumed The Watch, Everything secure. A/B's Orr & Flynn making Detex Clock Rounds on The Gen. Pope & Gen Weigel. Also Took Soundings.
0700	A/B's Orr & Flynn reports All secure & in order.
0800	Mr Barrett P/O & Mr Daigle R/O made inspection tour of Gen Weigel & Gen Pope, All secure A/B's Orr & Flynn reports All secure & in order.
0900	A/B's Orr & Flynn reports All secure & in order
1000	Mr Barrett P/O & Mr Daigle R/O made tour of both ships All secure. A/B's Orr & Flynn reports All secure.
1100	Mr. Christensen Aboard Mr O'Hara Aboard made inspection tour of both ships All secure. A/B's Orr & Flynn report All secure & in order.
1200	A/B's Orr & Flynn report All secure & in order.
1300	Mr Christensen P/O Mr O'Hara R/O made tour of both ships All secure A/B's Orr & Flynn report All secure.
1400	A/B's Orr & Flynn Reports All secure
1430	Watch relieved by Blue
	Carl Pitman
	JACKSON A/B DAVACON A/B 1600 - 2400 MR. CHRISTIANSEN P/O
1500	Assumed The Watch, All In Order. P/O AND R/O MAKING INSPECTION OF WEIGEL. JACKSON AND DAVACON TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD POPE AND WEIGEL.
1600	All In Order ABOARD POPE AND WEIGEL
1700	All In Order P/O AND R/O INSPECTING WEIGEL
1800	All In Order ABOARD POPE AND WEIGEL
1900	All In Order P/O AND R/O INSPECTING WEIGEL
2000	All In Order ABOARD POPE AND WEIGEL.
2040	All In Order P/O AND R/O INSPECTING WEIGEL
2100	All In Order
2200	All In Order P/O AND R/O INSPECTING WEIGEL
2230	WATCH RELIEVED BY ZENTNER A/B

USNS GEN. JOHN POPE

ZONE DESCRIPTION +7

DATE SUNDAY 13th OCT 1968

AT/PASSAGE FROM BERTH 30 PIER 2

HUNTERS POINT "SAN FRANCISCO"

TIME

RECORD OF ALL EVENTS OF THE DAY

0000 - 0800

MR. BARRETT^{PO} = MR. DAIGLE^{PE} = ZENTNER^{FW} = FRUTAZ^{FW} = CELADA^{FW}
"MOORED AS BEFORE"2300 ^{FW} FRUTAZ MAKING DETEX CLOCK ROUNDS ON GEN. WM. WEIGEL
^{FW} CELADA MAKING DETEX CLOCK ROUNDS ON GEN. JOHN POPE

RAT GUARDS + LINES CHECKED ON BOTH SHIPS = ALL SECURE:

0000 ^{FW}'S REPORT ALL SECURE = 0100 ALL SECURE = 0200 ALL SECURE =

0300 ALL SECURE = 0400 ALL SECURE = 0500 ALL SECURE

0600 HOURLY ROUNDS OF DETEX CLOCKS MADE ON BOTH SHIPS.

ROUTINE INSPECTIONS MADE DURING WATCH OF BOTH SHIPS BY ^{PO} + ^{PE}.0630 WATCH RELIEVED BY PETERSON^{PO}ZENTNER^{PO}

0800 - 1600

~~0630~~ Mr Barrett^{PO} Mr Daigle^{PE} Peterson^{FW} Orr^{FW} Flynn^{FW}0630 Assumed The Watch A/B's Orr + Flynn making hourly
detex clock rounds of both ships. Also took bilge soundings0700 Mr ~~Barrett~~^{PO} Mr Daigle^{PE} Made inspection tour
of both ships All secure + in order. A/B's Orr + Flynn
reports All secure + in order.

0800 A/B's Orr + Flynn reports All secure + in order

0900 Mr Barrett^{PO} Mr Daigle^{PE} Made tour of both ships
A/B's Orr + Flynn reports All secure1000 A/B's ~~reports~~ Orr + Flynn reports All secure1100 Mr Christensen^{PO} Aboard Mr. O'Hara^{PE} Aboard made inspection
tour of both ships All secure. A/B's Orr + Flynn reports
All secure + in order.

1200 A/B's Orr + Flynn reports All secure + in order

1300 Mr Christensen^{PO} + Mr O'Hara^{PE} Made inspection tour of both
ships. A/B's Orr + Flynn reports All secure + in order.

1400 A/B's Orr + Flynn reports All secure + in order.

1430 Watch relieved by Blue A/B.

Carl Peterson

JACKSON A/B DAVACOL^{PO} 1600-2400 MR. CHRISTENSEN^{PO} MR. OHARA^{PE}1500 ASSUMED THE WATCH, ALL IN ORDER. ^{PO} AND ^{PE} MAKING INSPECTION OF WEIGEL.JACKSON AND DAVACOL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD
POPE AND WEIGEL.

1600 All In Order

1700 All In Order, ^{PO} AND ^{PE} INSPECTING WEIGEL

1800 All In Order

1900 All In Order, ^{PO} AND ^{PE} INSPECTING WEIGEL

2000 All In Order

2040 All In Order, ^{PO} AND ^{PE} INSPECTING WEIGEL.

2100 All In Order

2200 All In Order, ^{PO} AND ^{PE} INSPECTING WEIGEL2230 Watch relieved by FRUTAZ^{PO}

C.D. Bluff.