



JOINT CASUALTY RESOLUTION CENTER

LIAISON OFFICE
AMERICAN EMBASSY
APO SAN FRANCISCO 96346

REFERENCE: T84-208
10 October 1984

FROM: JCRC-LNB

TO: COMMANDER, JCRC

SUBJ: Crash of T-28 Aircraft at Nghe-Tinh During 1969.

SOURCE:

- a. Name: SC
- b. SD
- c. POB: SD
- d. Former position: SD
- e. Present location: SD
- f. Identification data SD
- g. DOI: 1969
- h. Map used: Sheet 5847-4; Series L7014
- i. Date of interview: 24 Sep 84
- j. Name of interviewer: Garnett E. Bell
- k. Other: Arrived DT 18 Mar 84 (landroute)

Source, a 48 YOA male Hmong refugee and former SD provided information concerning his observation of a T-28 aircraft which crashed at Muang Sen, Nghe An Province during 1969.

Information:

Source stated that sometime during early 1969 (couldn't remember month) in the early morning hours he observed a T-28 aircraft crash into Muang Sen Village. Source recalled that there was no firing at the aircraft when it dived down to attack an underground rice storage facility at Muang Sen (VG1045). Source saw the aircraft begin to dive from a high altitude and continue diving almost straight down until it impacted into the storage facility. The aircraft exploded upon impact and Source heard from PAVN troops in the area that the aircraft was completely destroyed and that no remains of the pilot were found. Source stated that there was a fire caused by the crash into the rice storage area and that village officials took photographs of the crashsite and damaged area. Source did not observe or hear about any personal effects of the pilot. Source recalled that the crashsite was located in an area of Muang Sen called Khe Loi Loi (khe Looij Lowi). Source was not able to provide further information concerning the incident. Source also provided information in JCRC-LNB LTR RPTS T84-207 and T84-209.

AN