

ELECTRONICS DIVISION

SHIP USNS POPE	DATE 31 DEC 1966
INSPECTOR HURSWILL	☐ MAINTENANCE SHOP ☐ CONTRACTOR

ELECTRONIC REPAIRS TO BE ACCOMPLISHED THIS AVAILABILITY

~~RADAR~~ RCA ^{N/A} 75

1. CHECK TR AND XTALS
2. AFC FALLS OUT ON LOW RANGES
3. MAKE ALL INDICATOR ADJUSTMENTS

~~FATHOMETER~~ RAYTHEON

1. INOPERATIVE

~~LIFE BOAT RADIO~~ STB

1. ARCING INSIDE OF TRANSMITTER ON 500 KCS

~~51J4 COLLINS RECEIVER~~

1. REPLACE IF POT
2. CHECK SWITCH FOR SELECTOR 1,2, & NO COUPLING LOOSE

~~551P RCA RECEIVER~~

1. LOW GAIN
2. TUNING CONDENSER NOISEY

~~X 8500 RECEIVER KNOB BAND SPREAD MISSING READJUST~~

~~MACKAY POWER SUPPLY~~

1. FND BOWER SUPPLY DEFECTIVE

~~MACKAY TRANSFER SWITCH~~

1. DEFECTIVE

~~SOUND ROOM~~

1. TAPE AMPLIFIER DEFECTIVE
2. AFT RECEIVER NOB INOP
3. CHECK ANTENNA PORT AND STB FOR XMM LOW RESISTANCE READING
4. SUPPLY 2 EA 8 INCH SPEAKERS FOR EM

~~RADIO TELEPHONE 214 D MACKAY~~

1. RECEIVER INTERMITTENT ESPECIALLY ON CHAN 4
 2. REMOVE KNOB ON LOCAL REMOTE SWITCH AND RETURN TO 8500
- ~~SUPPLY KNOB FOR RADIO TELEPHONE~~