

ELECTRONICS DIVISION

SHIP USNS POPE	DATE 29 AUG 66
INSPECTOR Lance / Hale	☐ MAINTENANCE SHOP ☐ CONTRACTOR

ELECTRONIC REPAIRS TO BE ACCOMPLISHED THIS AVAILABILITY

3010B RCVR = REPLACE RF CHOKE & TEMPORARY
COMPONENTS. INSTALL NEED ^{BURB FOR} PROTECTING
THE R.F. CIRCUIT


51J4 RCVR = CLEAN BANDWIDTH SWITCH.

✓ AMPHENOL WALKIE TALKIE = PROVIDE TELESCOPIC ANT. TO R/C.

1/B # 2 (PORT) = 500KC VARIOMETER CONTROL PRODUCES
NOISE IN RCVR.

~~REINSTALL~~ SECURE FRONT PANEL HINGES TO CASE.

RADHCS = CALIBRATION DUE & ELIMINATE 2 IN
PDR-27JS.



PDR-43 # C-30
= D-647

PDR-27J * D-647

* D-659

* D-677

* D-648

PROVIDE = 1 ea 4D22, SPA-KLEEN, HEADSET