

15-9

15 JULY 66

0917

LENS POPE

JOS-710

ELECTRONICS REPAIRS

SUPP. NO. 1

SHOP (67)

REQUEST THE FOLLOWING DEFICIENCIES BY CORRECTED THIS

AVAILABILITY:

1. N1B-75 RADAR

DONUT AT CENTER OF SWEEP, CHECK ~~7M~~ TR VOLTAGE, REPLACE AND
TUNE IF INCORRECT, CHECK MODULATOR TUBE. ~~XXX~~ EST. 4 HRS.

2. 214D RADIOTELEPHONE

REPLACE ALL WIRES FROM CHANNEL ~~XXXXXX~~ SELECTOR SWITCH TO
TANK COIL. REDUCE TRANSMITTER OUTPUT TO 200-220 MA. ALL
CHANNELS. EST. 8 HRS.

3. L/B ~~NNN~~ NO. 2 (PORT)

~~NN~~ RECEIVER SENSITIVITY LOW. EST. 4 HRS.

SIGNED: LORENCE M6110

CHECKED: KR