

# EMERGENCY MANEUVERING ~ MINE EVASION

RETURN TO BASE COURSE

TRANSFER TO LEFT  
RIGHT RUDDER

MINE IS NOW WELL ASTERN  
AND CLEAR.  
SHIP RETURNS TO BASE COURSE

MINE NOW PAST THE PORT  
QUARTER ~ WATCH OFFICER  
ORDERS EASING OF RUDDER,  
STEADING OF SHIP ON NEW  
COURSE.



TRANSFER TO  
RIGHT AND  
AWAY FROM  
MINE  
LEFT RUDDER

MINE IS NOW ABEAM ~  
WATCH OFFICER ORDERS  
"FULL LEFT RUDDER" TO  
TRANSFER TO  
RIGHT THROW STERN AWAY  
FROM MINE.

MINE IS NOW BROAD ON  
THE BOW BUT CLEAR AND  
DIRECTLY IN LINE WITH THE  
PORT QUARTER ~ CHECK SWING  
OF THE SHIP'S STERN TOWARDS  
THE MINE BY SHIFTING THE  
RUDDER SLIGHTLY TO THE LEFT  
STEADYING ON THE NEW  
LINE OF ADVANCE.

TRANSFER TO  
RIGHT BEGINS  
LEFT RUDDER

TRANSFER TO LEFT  
FULL RIGHT RUDDER  
MINE SIGHTED

MINE SIGHTED DEAD AHEAD ~  
WATCH OFFICER ORDERS "FULL  
RIGHT RUDDER" ~ STARTS  
BOW SWINGING ~ THEN EASES  
RUDDER AS REQUIRED.