

SAMPLE ENTRY TO MACHINERY WORK BOOK

July 29, to
August 4, 1966

Air Compressor not functioning properly. Compressor secured for complete overhaul. Stripped compressor down completely, renewed bearing, replaced oil and compression rings, new leather valves, checked all bearings and sound satisfactory. Crank shaft good. #3 cylinder liner scored, needs replacing. No spare. Unloader adjusted and test run satisfactory. Spare Parts used: 3 sets of Rings complete, 3 sets of Valves, New Crankshaft Bearing and etc..

Sept. 30, 1966

Changed oil in sumps, wiped clean, no dirt or scale.