

Time 1115

3-7-68

1110

Working on The #1 Emerg.

Diesel Fire Pump Engine

The Canadian 3rd Ass. Engt was

connecting The Battery cable

To The battery ^{terminal} post, in doing

so there was an Arc causing

an explosion of an ~~accumulator~~

Accumulation of Hydrogen

Gas that blew a hole in the

top of the battery, I was

sprayed in the face with

Electrolyte from the battery,

some of the Electrolyte

went into my right eye, I

washed my face & eye with

Fresh water and then reported

to the dispensary in bldg 310

for further treatment

~~SECRET~~

CANNAR -

Address