

Entered in log 3/7

At 1110, 7 March 1968, John L. BURDICK, 18236, UnLieJrEngr was working on the #1 Emergency Diesel Fire Pump engine. A Canadian 3rd Asst. Engr was connecting cable to the terminal of the battery and in doing so there was an arc causing an explosion of the battery. Electrolyte sprayed in the face of Mr. BURDICK. Electrolyte entered his right eye. He immediately washed it with fresh water and then reported to the Medical Clinic in Building 310 for treatment.