

5.

While removing motor from vacuum cleaner to empty the dust bag one lead was apparently pulled loose causing a contact to ground creating a flash burn on Bill's left palm.

7. The electrical cord connection to the motor is quite substantial, however, an additional safety precaution will be made by forming a loop in the cord and taping it to the frame of the vacuum cleaner. All hands were again instructed to remove the connector plug before working on any portable electric equipment.