

SHIP USNS GEN. JOHN POPE (T-AP 110)		CONTRACTOR TRIPLE "A"
SPECIFICATION NO. 70-11	SPECIFIC ITEM NO. 409	ADDENDUM NO. 1
ITEM NO. ARMATURE REWIND:	DESCRIPTION OF WORK	

Contractor renew used commutators found defective by sub contractor upon testing and visual examination when coils were removed.

DATA: (b) One (1) eac commutator vent set E01-172-1 3/4 H.P. 230 VDC, 3.9 amps, 1750 RPM.

DATA: (f) One (1) ea. commutator vent set E-1-127-2, 1 $\frac{1}{2}$ HP to 3 HP, 230 VDC, 6 to 12 amps, RPM 1320 to 1750.

DATA: (e) Life boat davit motor armature. Defective locking collar found between commutator and armature core. Weld into original position.

RECEIVED

OCT 20 1969

USNS POPE T-AP110