

AMERICAN BUREAU OF SHIPPING

45 BROAD STREET, NEW YORK 4, N. Y.

(This form is to be used in confirmation of class only)

Report No. 11,333

San Francisco, California
May 17, 1951

S. S. GENERAL JOHN POPE

THIS IS TO CERTIFY that the undersigned Surveyor to this Bureau did, at the request of the owner's representative, attend the S. S. "GENERAL JOHN POPE" on the 16th day of May, 1951 and subsequent date, as the vessel lay afloat at Berth #4, Naval Supply Center, Oakland, California, in order to examine and report upon holed tank in way of No. 7 double bottom tank, and report as follows:

1. The No. 7 double bottom tank top, starboard side, was found to be holed through approximately $1\frac{1}{4}$ " in diameter outboard of after manhole and worn thin in way of the 50# steam line relief valve drain. The double bottom tank was gas freed and suitable repairs effected by welding radius $1\frac{1}{2}$ " doublers in way of the aforementioned plating. Upon completion of repairs the tank was subjected to a head test and found satisfactory.

In the opinion of the undersigned, the vessel is considered to be seaworthy and fit to retain her present classification with this Bureau.

B. KURTE, SURVEYOR