

Office Phone: EAst 0010
Residence Phone: ADAMS 1400

IF NO ANSWER CALL
ALDER 8412

WALTER McCRAY
DIVER

COMPLETE DIVING EQUIPMENT
PORTABLE DIVING EQUIPMENT . . . MARINE CONSTRUCTION
PILE DRIVING . . . BULKHEADS . . . DOCKS

2370 FAIRVIEW AVENUE NORTH
SEATTLE 2, WASH.

REPORT OF DIVER'S SURVEY

Vessel's Name..... General John Pope

Request for Survey by..... Mr. Hammerstrom

Nature of Accident..... Loose rolling-chock

Date and Time of Examination..... March 4, 1955 11:00 A.M.

Condition of Water..... Clear

REMARKS

I, the undersigned diver, did on the above date make an underwater inspection of the rolling-chocks of the above named vessel.

I found that about 6 ft. of the forward end of the starboard rolling chock was loose from the hull and about 3 ft. of the forward end of the after section loose. I burnt these off and examined the rest of the starboard rolling chock and found no further damage.

I hereby certify that the above statement is true to the best of my belief.

John O'Brien
Submarine Diver.