

Office Phone: EAst 0010
Residence Phone: ADams 1400

IF NO ANSWER CALL
HEMLOCK 7261

WALTER McCRAY
DIVER

COMPLETE DIVING EQUIPMENT AND DERRICK BARGE
PORTABLE DIVING EQUIPMENT . . . MARINE CONSTRUCTION
PILE DRIVING . . . CLAM SHELL DREDGING

2370 FAIRVIEW AVENUE NORTH
SEATTLE 2, WASH.

REPORT OF DIVER'S SURVEY

Vessel's Name..... General John Pope.....

Request for Survey by..... Mr. Hammerstrom.....

Nature of Accident..... Loose rolling check.....


Date and Time of Examination..... March 4, 1955 11:00 A.M......

Condition of Water..... Clear.....

REMARKS

I, the undersigned diver, did on the above date make an underwater inspection of the rolling-checks of the above named vessel.

I found that about 6 ft. of the forward end of the starboard rolling check was loose from the hull and about 3 ft. of the forward end of the after section loose. I burnt these off and examined the rest of the starboard rolling check and found no further damage.



I hereby certify that the above statement is true to the best of my belief.

John C'Brien

Submarine Diver.