

19 April 1967

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (T-AP 110)
To: Distribution List

Subj: Material Inspection of Troop Spaces

1. The following is a report on the condition of Troop Spaces during the Material Inspection held this date:

COMPT 2-3 VERY GOOD

COMPT 2-2 Clean paint chips on corners. Clean dirt underneath the Air Condition Unit on starboard side. Cover metal strips with pillows. VERY GOOD

FWD UPPER HEAD Hot water valve leaking in shower. Port side heater steam pipe leaking. VERY GOOD

FWD LOWER HEAD 1 commode out of order. Holes in urinal pipe plugged up. Clean dirt around corners. VERY GOOD

COMPT 4-1 Vent screen needs cleaning. VERY GOOD

BRIG EXCELLENT

COMPT 3-2 Clean dirt under the Air Condition Unit on starboard side. Remove stain in showers. VERY GOOD

COMPT 4-2 VERY GOOD

COMPT 4-3 Scuttlebutt #40-4-67-1 still stopped up. Ventilation not working too well. Too warm. Best compartment. Much improvement. No inspection on Thursday, 20 April 1967. EXCELLENT

COMPT 3-3 Inadequate ventilation. Too warm. Scrap gums on deck. Remove stain in showers. VERY GOOD

COMPT 4-4 Inadequate ventilation. Too hot. VERY GOOD

LARGE TRP REC ROOM Training class in progress.

SMALL TRP REC ROOM Religious services in progress.

COMPT 4-5 Inadequate ventilation. Too warm. VERY GOOD

COMPT 4-6 Clean dirt underneath the bunks and scuttlebutt. VERY GOOD

COMPT 2-7 Request electrician check inoperative lights. Clean dirt underneath the Air Condition Unit on port side. VERY GOOD

AFT LOWER HEAD Urinal system on starboard side stopped up. Drain in shower stopped up. (2nd report). Only 2 showers working in this head. Best head. Much improvement. EXCELLENT

AFT UPPER HEAD VERY GOOD

COMPT 4-7 2 scuttlebutts out of order. Clean dirt on corners. VERY GOOD

L. H. Severin
L. H. SEVERIN
Acting

Distribution:

Master

COMILDEPT

Chief Engineer (3)

First Officer

Chief Steward

Bulletin Board - Officer's Lounge

Troop Office for distribution to Compartment Commanders (15)

File