

Captain's Inspection

11 August 1967

The following is a report of the Captain's Inspection held this date, with general remarks following at the end of same.

1. 02-116-1-L Dirt underneath the mattress and in spring.
2. Shower- 03 Aft. (Qtr, Mstrs') Put new hooks on shower curtain and drop 2-3 inches.
3. 1-170-2-L Shower curtains filled with mold.
4. 1-170-1-L Toilet seats green and filthy - CLEAN UP
5. ATTENTION: MASTER AT ARMS... remove all posters on bulkheads that are put up with masking tape and replace with frames.
6. Ch. Electr's State Room Shorten shower curtains in Wash Room
7. 2-155-4-L Install ventilation duct overhead.
8. 2-170-4-L Clean up tile and deck.
9. 2-173-6 Remove lewd pictures from the bulkhead.
10. All Laundry Rooms Post operating instructions for the operation of washing machines.
11. All Quarters Replace dirty wastebaskets with new ones.
12. 3-130-3-L Replace vent. duct.
13. 3-126-1-L Replace vent. duct and wastebasket.
14. 3-118-3-E Stain deck in CO₂ Room.
15. CPO MESS (Stbd.) Vent. duct not functioning- Fan does not oscillate. Ch. Electrician- lower fan 2-3 inches overall.
16. Crew Scullery Make fan to oscillate. Step up exhaust on the dishwasher. * Shine up brass valve stems and paint valves.
17. Mil. Mess (Port Side) Put roach spray in the storage cabinet.
18. 1st. Engnr. Polish valve stems with crocus cloth and paint the handles jet black or glossy black before arrival in San Francisco.
19. 3-144-2-L Replace wastebasket.

Captain's Remarks:

Watch out for the shower curtains: many of them are filled up with mold.

The overall condition of the ship is very good. We will have one more inspection prior to arrival in San Francisco, one week from today.

Louvers from the ventilation ducts will not be removed primarily due to the imbalance of the whole system.

H.C. Denney
(Master)