

USNS GENERAL JOHN POPE (T- AP 110)
c/o Fleet Post Office
San Francisco, California 96601

HLH: na
3 May 1968

From: Master
To: All Ship's Personnel.

Subj: Inspection of Crew Quarters and facilities, report of.

1. The following were the results of Master's Inspection conducted this date:

2-130-4-L	No comment
2-149-4-L	Dust under bunks
2-152-2-L	Very good. Note: All electrical equipment to be properly grounded and tagged. All Department heads are to mention this subject in their next safety meeting.
5-158-4-L	Dust on bulkhead
F-M-C-V	
2-159-2	Check and repair overhead panel. Safety Hazard
Crew's Wash room	
2-164-2-L	Paint this area completely
2-165-2-L	Paint this area completely
2-167-4-L	do do do do . Mold on bottom of deck; change shower curtain
2-167-2-L	Unsatisfactory
2-167-3-L	Paint complete area
Wash room	
2-170-4-L	Paint complete area.
Crew's Shower	
2-170-6-L	Overhead insulation pulled down. Fix same
2-170-0-L	Overhead passageway light fixture needs to be installed. Safety hazard
2-173-2	
Dryer room	Tile broken away in urinal area. Paint entire area
2-176-2-L	Aft bulkhead very dirty
2-179-2-L	do do do do
2-183-2-L	No comment
2-188-2-L	Clean around urinal and toilet bowls.
MilDept	
2-190-2-Q	Clean cover of exhaust vent
3-144-1-L	Clean around entire area
3-151-1-L	Dust on louver
3-135-1-L	Faucet is leaking
Fire Station	
3-135-1	Remove paint inside all fire station valves.
3-126-1-L	Dirty medicine cabinet
Fire Ext.	
3-129-1	Clean fire extinguisher
Fr. 140-1-3	Paint sign as required
3-167-3-L	Area needs painting and cleaning
3-183-1-L	Dirty Deck
3-174-2-L	Replace motor cover
Water fountain	
Attn: Engine Dept.	Clean out fuel area passageway (1) 3rd Deck

General comments: Install all bunk cards where missing. There will be another inspection next Friday (10 May 1968). All deficiencies noted during this inspection are expected to be corrected by then.

H. L. HEINZ
H. L. HEINZ