

USNS GEN. JOHN POPE (T-AP 110)

c/o FLEET POST OFFICE
SAN FRANCISCO, CALIFORNIA

8 December 1969

From: Master, USNS GEN. JOHN POPE (T-AP 110)
To: Department Heads, USNS GEN. JOHN POPE (T-AP 110)

Subj: Captain's Inspection; report of

The following is a report of the Captain's Inspection held 5 December 1969, with general remarks following at the end of the report:

1. 1-68-1-L Good. Head now corrected. Secure area.
2. 1-84-1-L Excellent
3. 1-85-1-Q & 1-85-3-L Good.
4. 1-86-2-L Good.
5. 1-83-2-L Fine.
6. 1-74-2-L Good. Much improved.
7. 1-71-2-L Unoccupied. Clean and secure.
8. 1-68-2-L Lock and secure.
9. Officer's Dining Salon Great improvement. Noted with pleasure.
10. 1-127-4-A No improvement. Square away.
11. Cleaning Gear Lkr O.K. Maintain at present level.
12. 1-132-2-Q Stencil temperatures as directed previously.
Install thermostat at sink that will function.
13. 1-138-2-Q Stencil proper temperatures as directed previously.
14. 1-127-01-Q (Galley) Steam kettles much improved. Rivets missing in lids need replacing. Temperatures not posted. Thermostat at sink needs replacing. Sink needs maintenance.
Non-skid mats are worn.
15. 1-134-1-Q Stencil temperatures as directed previously. Canopener in good sanitary condition of maintenance.
16. 1-127-3-Q Stencil temperatures. Secure small Silex for night watch in lieu of present coffee-maker.
17. 1-127-1-A (Strm) Improved.
18. Ladderwell (P) -Fr 127 Clean all levels and remove trash and debris.
19. 2-134-4-L Need towels. Head/Shower unimproved. De-odorizer needed.

"Think Safety—Talk Safety—and Sell Safety"

Captain's Inspection of 5 December 1969, continued:

2-133-2-L	Poorly lit. Replace light bulb.
2-135-2-L	Square away personal gear. Clean under sink. Empty wastebasket daily. Clean Head/Shwr. Shower curtain uncorrected.
2-138-4-L	Square personal gear. Clean sink thoroughly.
2-141-2-L	Clean sink, Head/Shwr as directed previously.
2-144-2-L	Square away personal gear. Sink needs cleaning.
2-147-2-L	Very good. Light out in head.
2-149-4-L	Very good. Great improvement.
2-153-2-L	Improved. Very good.
2-155-2-L	Urinal still stained. Clean sink top and bottom. Install de-odorizer. Improved from last week.
2-155-4-L	Good.
2-158-2-L	Square away personal gear.
2-162-2-L	Clean sink top and bottom.
2-164-2-L	Lock as previously directed.
2-164-4-L	Good.
2-167-4-L	Satisfactory. Maintain as at present.
2-167-6-L	Clean sink top & bottom.
2-167-2-L	Urinal stained. No de-odorizer.
2-173-6-L	Sink dirty.
2-176-2-L	Except for sink bottom, very good.
2-179-2-L	Very good.
2-183-2-L	Square away.
2-188-2-L	Sink needs cleaning.
2-189-2-L	Very good.
2-193-2-L	Good.
Cleaning gear locker	Still needs field day.
Linen Locker (2nd Dk, (B)	Under De& Dept control. Clean and keep locked.

Captain's Inspection of 5 December, 1969, continued:

Troop Office (3-162-2-Q)	Remove & stow items as prev. directed.
3-140-2-L (Head)	Needs daily maintenance. Much improved.
3-155-2-L, 3-152-2-L, 3-150-2-L	Very good. Areas not lived in at present.
3-126-1-L & 3-138-1-L	Clean both areas thoroughly. Field day.
3-149-1-L & 3-144-1-L	Clean both areas thoroughly.
Troop Galley	Much improved due to proper storing of provisions. Very good. Ice-boxes need thermometers and temperatures stenciled.

In conclusion, many improvements noted with pleasure. Progress is slow but steady. Everyone is to be commended for their part in maintaining the ship at its present level. It is important that we continue to progress to correct the deficiencies noted above.


ROBERT E. LANDRY, Master