

1 February 1966

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (TAP 110)
To: Distribution List

Subj: Material Inspection of Troop Spaces held this date

1. The following is a report on the condition of the Troop Spaces during the Material Inspection held on 1 February 1966:

COMPT 2-2 Inoperative elect. outlet overhead starboard side at square of hatch, portion of compartment cannot be buffed (inoperative all trip). Very good.

COMPT 2-3 Very good.

COMPT 3-2 Vent blower unit on port side not working properly. Metal strips sticking out into passageway from square of the hatch. Chain eye on starboard post (square of hatch) broken. Install vapor globes on all overhead lights in shower room. Use steel wool to clean shower decks. Very good.

COMPT 3-3 Leak in ovhd. pipe on after starboard side. OUTSTANDING.

COMPT 4-1 No comment.

COMPT 4-2 Leak port side aft (water curtain connection - 10th rpt). Very good.

COMPT 4-3 Leak in ovhd. pipe on star. side forward (10th rpt). Short in elect. outlet (6th rpt). Scuttlebutt 41-4-82-2 not working (4th rpt). EXCELLENT. Second best compartment on ship.

COMPT 4-4 No comment.

COMPT 4-5 No comment.

L.REC.RM. Excellent.

S.REC.RM. Excellent.

FWD.UPPER HEAD 5 drain knobs missing from wash basins. 3 shut-off valves missing from showers. 2 mirrors loose. 1 mirror broken. Oil leak on deck. Water leaking in forward part of head. Very good.

FWD.LOWER HEAD 1 faucet out of order. 1 commode has no water. 7 soap trays missing. Tile loose under commode. Pipe leaking both under and above urinal on port side. 1 commode leaking on port side. Very good.

W.B.Cobb
W. B. COBB

Distribution:

Master
Chief Engineer (2)
First Officer
Troop Office for distribution to Troop Officers (5)
COMILDEPT
Medical Office
File