

25 January 1966

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (TAP 110)
To: Distribution List

Subj: Material Inspection of Troop Spaces held this date

1. The following is a report on the condition of the Troop Spaces during the Material Inspection held on 25 January 1966:

COMPT 2-2 Check elect. outlet overhead on starboard side at square of the hatch - Inoperative (several reports). No way to use buffer. Very good.

COMPT 2-3 Good.

COMPT 3-2 2 bunks missing bunk bottoms. Metal Strips sticking out into passageway from square of the hatch. Much gear on bunks. Very good.

COMPT 3-3 1 commode runs continuously. Very good.

COMPT 4-1 Very good.

COMPT 4-2 Leak port side aft (water curtain connection - 5th rpt); valve handle is also broken. Light out on starboard side (2nd rpt). AC unit 4-61-2 on port side inoperative. Very good.

COMPT 4-3 Leak in ovhd. pipe on star. side forward (5th rpt). Short in elect. outlet - Buffer cord burned. No ticking on 11 mattresses.

COMPT 4-4 Bad odor in this compartment.

COMPT 4-5 No comment.

L.REC.RM. Very good.

S.REC.RM. Very good.

FWD.UPPER HEAD 1 mirror broken. 2 toilets no water. 4 toilets will not shut off. 2 toilets have leaking pipe. Oil leak on both sides of compartment. 2 mirrors coming loose from bulkhead. 4 wash basins have drain knobs missing. Water pipe in aft. star. side of head leaking badly. 4 water faucets will not shut off. 3 water knobs missing. VERY GOOD.

FWD.LOWER HEAD 5 commodes stopped up. 1 shower does not work, 14 faucets do not work. 6 mirrors missing. VERY GOOD. Shine brass above urinal.

W.B.Cobb
W. B. COBB

Distribution:

Troop Office for distribution to Troop Officers (5)

Chief Engineer (2)

First Officer

Master

File