

31 January 1966

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (TAP 110)
To : Distribution List

Subj: Material Inspection of Troop Spaces held this date

1. The following is a report on the condition of the Troop Spaces during the Material Inspection held on 31 January 1966:

COMPT 2-2 Inoperative elect. outlet overhead starboard side at square of hatch, portion of compartment cannot be buffed (inoperative all trip).
Very good.

COMPT 2-3 Very good.

COMPT 3-2 Vent blower unit on port side not working properly. Metal strips sticking out into passageway from square of the hatch. Chain eye on starboard post (square of hatch) broken. Compartment too warm.
Very good.

COMPT 3-3 OUTSTANDING and getting better every day.

COMPT 4-1 No comment.

COMPT 4-2 Light fixture on starboard side inoperative (6th rpt). Leak port side aft (water curtain connection - 9th rpt). Very good.

COMPT 4-3 Leak in ovhd. pipe on star. side forward (9th rpt). Short in elect. outlet (5th rpt). Scuttlebutt 41-4-82-2 not working (3rd rpt). 9 light bulbs burned out. EXCELLENT - second best compartment on the ship.

COMPT 4-4 No comment.

COMPT 4-5 No comment.

L.REC.RM. Very good.

S.REC.RM. Very good.

FWD.UPPER HEAD 1 toilet stool leaking. Ovhd. valve on after starboard side still leaking. Very good.

FWD.LOWER HEAD 1 shower inoperative. 7 soap trays missing. 1 commode inoperative. Tile coming loose under commode. Leak beneath urinal. Leak at bottom of plumbing drain.


W. B. COBB

Distribution:

→ Master
Chief Engineer (2)
First Officer
Troop Office for distribution to Troop Officers (5)
COMILDEPT
Medical Office
File