

29 January 1966

From: Commanding Officer, Military Department, USNS GEN. JOHN POPE (TAP 110)
To: Distribution List

Subj: Material Inspection of Troop Spaces held this date

1. The following is a report on the condition of the Troop Spaces during the Material Inspection held on 29 January 1966:

COMPT 2-2 Inoperative elect. outlet overhead starboard side at square of hatch, portion of compartment cannot be buffed (inoperative all trip).
Very good.

COMPT 2-3 Very good.

COMPT 3-2 Vent blower unit on port side not working. Metal strips sticking out into passageway from square of the hatch. Chain eye on starboard post (square of hatch) broken. Compartment too warm. Very good.

COMPT 3-3 Valve leaking on steam supply pipe, starboard side aft. Too warm in compartment at night. OUTSTANDING.

COMPT 4-1 No comment.

COMPT 4-2 Light fixture on starboard side inoperative (5th rpt). Leak port side aft (water curtain connection - 8th rpt). AC unit 4-61-2 on port side inoperative (4th rpt). EXCELLENT. Request Engineering Department give this compartment some much-needed attention.

COMPT 4-3 Leak in ovhd. pipe on star. side forward (8th rpt). Short in elect. outlet (4th rpt). Scuttlebutt 41-4-82-2 not working (2nd rpt). EXCELLENT.

COMPT 4-4 No comment.

COMPT 4-5 Very good.

L.REC.RM. Very good.

S.REC.RM. Very good.

FWD.UPPER HEAD 2 overhead pipes leaking. Valve for sink is off on aft, starboard side. No hot water in the only fresh water shower. Very good.

FWD.LOWER HEAD 7 soap trays missing. 1 shower doesn't work. 1 pipe leaking under sinks. Tile broken under commode. Slow leak under urinal at pipp. Very good.

W. B. Cobb
W. B. COBB

Distribution:

→ Master
Chief Engineer (2)
First Officer
Troop Office for distribution to Troop Officers (5)
COMILDEPT
Medical Office
File