

USNS GENERAL JOHN POPE (T-AP110)

DATE 11/1/67

PRIORITY 3

REPAIR LIST REQUEST

SUBJECT PIPE, #2 DIESEL FIRE PUMP, REPAIR OF:

DATA N/A

LOCATION AFTER FIRE PUMP ROOM

CONDITION DETERIORATED AND LEAKING

QUANTITY/SIZE ONE (1) 2" X 1/4" NIPPLE LONG. WELDED ONE END FLANGED OTHER END.

RECOMMENDATION FURNISH LABOR AND MATERIAL TO REPLACE PIPE NIPPLE.

*Completed*

R.C. QUINN, CHIEF ENGINEER

SIGNATURE