



DEPARTMENT OF THE NAVY
MILITARY SEA TRANSPORTATION SERVICE, PACIFIC
N.S.C., OAKLAND, CALIFORNIA 94625

Date 11/12/69


To: Master, USNS Gen. John J. Pope
From: Director, Safety Division, P-25

Subj: Report of Safety Inspection, QUARTERLY READINESS

Ref: (a) COMSTSINST 5100.17

Encl: (1) Copy of Safety Deficiency List
(2) Copy of Safety Deficiency Completion List

1. A safety inspection of the USNS POPE (TAP110) at HUNTERS POINT was conducted on 11/3/69. Safety deficiencies noted at that time are listed in enclosure(1). Earliest practicable correction of the noted deficiencies is essential to the continued safe operation of your ship.
2. Should the Master take exception to any of the findings of the inspection, his comments are invited.
3. It is therefore recommended that the Master take the following action in accordance with reference (a), Article 1-1-5c(1) (g) and 1-1-6b(2).
 - a. Correct all deficiencies which fall within the capabilities of the ship's force.
 - b. Submit work requests to the Engineering Office, MSTSPAC, for assistance or correction of all deficiencies which are beyond the capabilities of ship's force.
 - c. Assign the highest priority and maintain follow-up records until correction is accomplished.
4. To follow up on the correction of deficiencies, it is requested that the enclosed Safety Deficiency Completion List be forwarded to P-25 prior to the expiration of 60 days subsequent to the formal and/or informal safety inspection.


C.W. LOCKARD

Copy to: P-3 D
P-01 ~~P-01~~
P-01B P-4E
P-25 ~~P-25~~

RECEIVED

NOV 17 1969

USNS POPE T-AP110