

Safety readiness Inspection
~~on~~ the USNS General John
Pope (TAP 110)

11/3/69

Duck Dept

S.D. #1. The shroud on the radar
mast is broken
T. #1 Replace the Broken Shroud

S.D. #2 Lifeboat #1 has one gripe missing,
avit span missing and manropes
missing

R. #2 Replace missing gear to conform to
current Coast Guard regulation and Constraint
CG-160-038
5100.17 article 2-2-3-M

S.D. #3 all cargo hel blocks have not
been equipped ^{with} preventer wires

R. #3 install Preventers on hel blocks to comply
with Constraint 5100.17 art. 2-2-4-(C)-3.

S.D. #4 Man overboard canisters on bridge
wings empty

T. #4 Replace marker buoys and date
before going back into operation

S.D. #5. Main incinerator room 03-108-0
has fire equipment, lockers, duck, air
compressor Stowed front of the incinerator.
K. #5 Clear out excess gear and restow
in it's proper area

S.D. #6 Emergency boat locker 01-102-2
has been chairs, electric chippers and
other deck maintenance equipment stowed
on top of emergency gear
K. #6 Remove gear not required, clean
and restow locker per Cominst 5100.17
at 2-1-2

S.D. #7 Lifeboat embarkation ladders washing
away at the following boat stations: #1-6-8-9
10-11

K. #7 Replace or perform corrective maintenance
on all the above listed ladders as necessary
to prevent further deterioration. Har Ship Maint
030

S.D. #8 Fusible link in ^{engine room} fire damper
missing at 2-128-1

H. #8. Install fusible link in damper to put back in operation.

S. V. #9. Fire Station 2-186-0 Not hooked up

H. #9 Connect up fire hose and other gear & put in proper working order

S. V. #10 applicator missing at Fire Station 5-130-1

H. #10 Replace missing applicator

S. V. #11 Phenolic plate for fire Station 4-210-2
not mounted

H. #11 Mount plate at fire Station

S. V. #12 Cermac tile coming off deck in
transit of fire toilet 2-168-1

H. #12 Replace missing tile or submit work order

S. V. #13 Back Stay turnbuckles adrift in
bottom of number #7 hold 5-188-0

H. #13 Lash or other wise secure
back stay turnbuckles.

5. N. 14. Life jacket placards missing or not mounted in crew Staterooms as follows

3-166-1

3-174-1

3-183-3

3-170-1

3-188-1

3-177-1

6. N. 14. Install life jacket placards as necessary to comply with Cominst 5100.17

Note: Life rafts (rigid) are not in the floatation racks but still ashore being renovated and not available at this inspection

Note: Lifeboats are in process of U.S.C.B. certification

Note: Instructions for operating equipment need renewing and in some cases up grading to conform with recent changes (Life boat - watches operating instructions especially)

Note: Fire fighting equipment needs attention, to replace missing equipment at Fire Stations & fire extinguishers must be weighted annually, with empty racks being filled. Closes should be hooked up and all station labelled properly & permanently.