

USNS General John J. Pope (P110)
Safety readiness inspection
Steward Rpt

11/3/69

Note: Stores are not stowed in dry
tous lockers as the ship is being
used to ware house the stores from
ships being deactivated and due to
shortage of personnel to process these
tous, must leave them set out on
the open hatch creating a walking and
tripping hazard.

Comments;

The general condition of the Ship is good.

All safety deficiencies from the last inspection are recurring, due to manpower shortage. The ship's personnel could not make, in addition to their other duties, corrections to the safety deficiencies.

The weather decks continue to deteriorate as does the life boat equipment and the cargo ^{and stanching rigging} car due to the lack of maintenance.

The fire fighting equipment needs inspecting and maintenance with the replacing of missing equipment.

Manpower seems to be the problem as the lack of it.

John Davis
Safety Officer