

USNS POPE

1. VENT HINGE COVERS: ALL VENT HINGED COVERS ON OPEN DECK AREAS SHOULD BE CHECKED FOR HINGE OPERATION, GASKET CONDITION, GASKET FIT, AND KNIFE EDGE CONDITION.
2. DECK DRAIN PIPE: 01-192-1 DECK DRAIN PIPE RUSTED AND DETEIORATED THROUGH. RECOMMEND COMPLETE RENEWAL FROM DECK DRAIN TO DECK END
3. RAIL SECTIONS: PORT AND STABOARD, ALL REMOVABLE RAIL SECTIONS IN LINE WITH CARGO HATCH OPERATIONS REQUIRE FREEING-UP, SCALE, PRIME, AND PAINT OF DECK PADS.
4. STERN ANCHOR PAD AND DECK: AREA UNDER STERN ANCHOR PAD, HEAVY RUST AND SCALE. RECOMMEND REMOVING ANCHOR, CHIP, PRIME, AND PAINT ANCHOR AND DECK AREA. FREE ANCHOR SHANK. RENEW ALL DETEIORATED BRACKET -
5. WIRE CABLE HANGERS: 1-191-2 HEAVY RUST, DETEIORATION, RENEW HANGERS (5) ENTIRELY WITH NEW.
6. WTD DRIP SHIELDS: CROP OFF AND RENEW AS ORIGINAL DRIP SHIELDS AT LOCATIONS: (1-191-2) (1-191-1) (1-174-2) (1-174-1) (1-55-2) (1-55-1) HEAVY RUST AND DETEIORATION

7. Focsle Deck: SPOT CHIP, PRIME, PAINT TO MST'S SPECS

8. CARGO BOOM BUILDERS PLATE: ALL CARGO BOOM PLATES ARE PAINTED OVER, NOT READABLE, AND INDICATIONS OF RWT AND SCALE UNDERNEATH. REMOVE, CLEAN, SPOT CHIP, PRIME, PAINT AND REPLACE PLATES.

9. STANDPIPES: (02-110-1)(02-110-2) PIPES HEAVY RUST DETEIORATION AND HOLED THRU. RECOMMEND RENEWAL OF PIPES FROM DECK LEVEL UP.