

AT/PASSAGE FROM Qui Nhon		TO Subic Bay P.I.
ZONE DESCRIPTION - 8		DATE (Day, month, year) 27 Sept 67
		DAY OF WEEK Weda
TIME	REMARKS	
	0000-0800	
	ON Watch. MR Purchase Jackson, M. QM	
	A/BW. CLARK & Christensen. - F/W. BROWN.	
2345	Assumed The Watch. Anchored as Before.	
	All in Apparent Good Order.	
0030	Liberty Boat came Along Side and Departed	
0100	All in Apparent Good Order.	
0200	All is Well. F/W Reported	
0300	All is Well F/W Reported.	
0400	All is Well F/W Reported	
0500	All is Well	
0600	All is Well	
0610	Liberty Boat came Along Side and Departed	
0700	All is Well	
0740	Watch Relieved by Warzee QM	
	McKinley Jackson QM	
	ON WATCH Mr NATSIOS JR/2nd Warzee QM Smullen A/B Nix M/A	
0740	Assumed Watch. Anchored as Before. All is Well	
0755	Liberty Launch Alongside	
0800	Liberty Launch Away	
0900	ALL is well	
0940	MSTS Rep on Board	
0958	MSTS Rep Away	
1000	ALL is well	
1058	Liberty Launch Alongside 2 men from Naval Exchange	
	Repair Dept on Board to Repair Vending Machines	
1103	Liberty Launch Away	
1104	ALL is well	
1200	ALL is well	
1300	ALL is well	
1400	Liberty Launch Alongside - Repair party ashore - ALL is well	
1405	Liberty Launch Away	
1500	ALL is well	
1515	Overboard Drill	
1545	Watch Relieved by Overacker OH/1st ALL is well	
	1600 ~ 2400 All Wayne QM	
	ON WATCH MR. PIKE 2/O, Overacker OH/1st, I. FRANKLIN A/B/W	
	STEINFORT A/B/W, FRANKLIN F/W.	
1730	Liberty Boat Alongside	
1740	Liberty Boat Away	
1830	Liberty Boat Alongside	
1935	Liberty Away	
0100	Watch Relieved by Clark	

AT/PASSAGE FROM	TO	
SUBIC BAY	PHILIPPINES	
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
- 8	28 SEPT 1967	THURSDAY

TIME	REMARKS
	0000 To 0800
0100	ANCHORED AS BEFORE ON WATCH MR. PURCHASE 3 RD OFF, CLARK A/B, CHRISTENSEN O/S. AND BROWN F/W MAKING ROUNDS OF DUTY CLOCK STATIONS. ALL IN APPARENT ORDER.
0200	F/W REPORTS SHIPS SECURE.
0300	ALL IN APPARNT GOOD ^{ORDER} ORDER.
0400	F/W REPORTS ALL SECURE.
0500	ALL IN APPARENT GOOD ORDER.
0600	F/W REPORTS ALL SECURE.
0610	LIBERTY BOAT ALONG SIDE.
0615	LIBERTY AWAY.
0700	ALL SECURE.
0745	WATCH RELIEVED BY WARZEE Q/M
	0800 - 1600 R. Clark
	ON WATCH Mr KREATZ 3/0 WARZEE QM 3MEALER 1/3 NIX 1/4
0800	MADE COLORS - ALL IS WELL
0808	LIBERTY LAUNCH ALONGSIDE
0812	LIBERTY LAUNCH AWAY - ALL IS WELL
0900	ALL IS WELL
1000	ALL IS WELL
1110	LIBERTY LAUNCH ALONGSIDE
1115	LIBERTY LAUNCH AWAY ALL IS WELL
1200	ALL IS WELL
1300	ALL IS WELL
1330	ALL IS WELL WATCH RELIEVED BY MR SHEEHAN
	00 Wayne QM
1400	ALL IS WELL.
1428	LIBERTY BOAT ALONGSIDE
1434	LIBERTY BOAT AWAY
1500	ALL IS WELL
1600	ALL IS WELL WATCH RELIEVED BY M ^R OVERACKER
	1600 - 2400 M ^R Sheehan
	ON WATCH Mr Pike 2/0, OVERACKER C/M, FRANKLIN A/B/W, STEINFORT A/B/W
	FRANKLIN F/W.
1730	LIBERTY BOAT ALONGSIDE
1745	LIBERTY BOAT AWAY
2000	LIBERTY BOAT ALONGSIDE
2010	LIBERTY BOAT AWAY
	ALL IS WELL WATCH RELIEVED BY K. CLARK A/B/W

AT/PASSAGE FROM		TO	
SUBIC BAY PHILIPPINES			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
1-5		29 SEPT 1967	FRIDAY
TIME	REMARKS		
	0000 TO 0800		
02345	ASSUMED WATCH ANCHORED AS BEFORE ON WATCH		
	MR. PURCHASE 3/0 CLARK A/B ON THE 9 DECK		
	CHRISTENSEN 1/5 ON THE FANTAIL, BROWN F/W		
	MAKING ROUNDS OF DATEX WATCH CLOCK		
	STATIONS ALL IN APPARENT GOOD ORDER.		
0445	LIBERTY BOAT ALONGSIDE.		
0500	LIBERTY BOAT AWAY.		
0600	F/W REPORTS ALL SECURE.		
0700	SHIPS ALL SECURE.		
0800	F/W REPORTS ALL IN APPARENT GOOD ORDER.		
0900	SHIPS ALL SECURE.		
1000	F/W REPORTS ALL IN APPARENT GOOD ORDER.		
1100	SHIPS ALL SECURE, OBSERVED SUNRISE SECURED ALL STANDING LIGHTS		
1200	LIBERTY BOAT ALONGSIDE 1ST OFF ABD.		
1300	LIBERTY BOAT AWAY.		
1400	YO 130 ALONGSIDE PORT SIDE TO TRANSFER WATER		
1500	PORT SIDE FUEL PORT OPEN		
1600	SHIPS ALL SECURE.		
1700	WATCH RELIEVED BY WARZEE QM		
	R Check		
	0800-1600		
	ON WATCH MR KREATZ 3/0 WARZEE QM SMELLEN A/B NIX 1/4 ANCHORED		
	AS BEFORE ALL IS WELL		
0810	LIBERTY LAUNCH ALONGSIDE		
0815	LIBERTY LAUNCH AWAY		
0900	ALL IS WELL		
1000	ALL IS WELL		
1105	LIBERTY LAUNCH ALONGSIDE		
1115	LIBERTY LAUNCH AWAY		
1145	WATCH RELIEVED BY De Luna QM		
	R Warz QM		
	1200-1600		
	On watch: Mr Purchase 3/0, Mr Sheenan 3/0, de Luna QM,		
	Clark + Stanford AB's, Guy Nix 1/4 MAA. Vessel anchored		
	as before Starboard Accommodation Ladder for G-way		
1200	Liberty has expired on board. Deck Seowatch is set.		
1200	All in apparent good order		
1229-1238	MSTS Rep boat alongside w/ MSTS Rep. Mail abd. & Mail ashore		
1235	Departure Draft taking by Mr. Sheenan 3/0		
1238-12	Securing Accommodation Ladder		
1243	QM shifted to the bridge		
1250	Set Special Sea Detail		

AT/PASSAGE FROM SUBIC BAY P.I.	TO DANANG VIET NAM
ZONE DESCRIPTION - 802900T	DATE (Day, month, year) 1 OCT 67
	DAY OF WEEK SUNDAY

TIME	REMARKS
	08-12
	ON WATCH MR KRENTZ 3/4 PM OVERCLOCK - RM. JACKSON M AB/W FRANKLIN & SMELLER.
0800	Assumed The Watch. Anchored DANANG HARBOR # 15
0800	made Colors. All is Well.
0835	LIBERTY Boat came along side and Departed
0855	PILOT came ABOARD
0900	SPECIAL Sea DETAIL.
1030	Assumed QUARTER DECK WATCH
1035	PUT GANGWAY ON SHIP.
1035	MSTS. Rep. came ABOARD.
1035	ADVANCE PARTY came ABOARD.
1040	LIBERTY Commenced FOR SHIPS CREW
1100	Commenced Landing TROOPS.
1107	MSTS. Rep. Departed Ship WITH SHIPS MAIL
1117	PILOT Departed Ship.
1126	PILOT ABOARD.
1128	ALL TROOPS ABOARD.
1135	Secured GANGWAY.
1140	Secured QUARTER DECK WATCH.
	McIntyre J. B. Orr

AT/PASSAGE FROM		TO	DATE (Day, month, year)	DAY OF WEEK
HA NANG Vietnam		OKINAWA	5 OCT 67	THURSDAY
TIME	REMARKS			
	08-12			
	ON WATCH MR KRENTZ 3/6 21/6M OVERSEER. QM JACKSON AIR FRANKLIN & Smeiler			
0750	GANGWAY ON BOARD. ASSUMED THE WATCH			
0805	Telephone man came aboard with phone			
0800	Pilot left ship. Made colors.			
0805	Liberty commenced for ship crew.			
0805	Sailing board set.			
0805	Water hose hooked up			
0805	Started offloading troops			
0815	All troops of ship			
0900	All in apparent good order.			
1000	All in apparent good order			
1115	Fueling hose hooked up to ship			
1145	Watch relieved by De Luna Q.M.			
	McKinley Jackson Q.M.			
	1200-1600			
	On watch: Mr Purchase 3/6, Mr Sheenan 3/6, de Luna Q.M. Steinford AB Guy Nix M.A. Vessel moored as before Port side to White Beach Dock Buckner Bay, Okinawa. G-way @ Side Port 2-115-2" & second g-way. Side Port 3-160-2 with 1 ab Steinford standing by. Port side Fueling Port open.			
1200	All is well. Master & 1st Off. ashore 1355 aboard			
1305-1605	Taking fuel abd. "Bunker"			
1205-1305	Taking stores thru Side Port 3rd fwd port side for stewards dept. 50 cases lettuce, 20 cases onions, by Bosn & 4 abm.			
1315	L/S 1 gang 10 men #2 hatch			
1600	Watch relieved by Warzee de Luna Q.M.			
1600-2000	On watch Mr Pike 2/6 Mr Natsios 3/6 Warzee Q.M. Page 1/6 Schell 2/6			
1610	FIRST TROOPS EMBARKING FROM FIRST DETAIL ASHORE			
1605	FUEL OIL ON BOARD			
1640	FIRST DETAIL OF TROOPS ON BOARD			
1700	ALL IS WELL			
1708	CAPTAIN HEWITZ AND 1st MATE COHEN ASHORE			
1800	LIBERTY FOR 1st DETACHMENT OF TROOPS ALL IS WELL			
1900	ALL IS WELL			
1927	CHIEF ENGINEER ON BOARD			
1945	ALL IS WELL 1/6 FRANKLIN RELIEVES WATCH WITH LOCKER KEYS All Warzee Q.M.			

AT/PASSAGE FROM

White Beach, Okinawa

TO

ZONE DESCRIPTION

-9

DATE (Day, month, year)

6 Oct. 1967

DAY OF WEEK

Friday

TIME

REMARKS

0000-0400

Vessel moored portside to @ White Beach Dock, Buckner Bay, Okinawa. Two gangways one @ mid ship 2nd dk. & the other @ 3rd dk aft port side with AB Steinford standing by. Port Fueling Port open w/ Fresh Water hoses hooked up. On watch: Mr Purchase 3/6 Mr Shoonan 3/6 de Luna QM Clark & Steinford AB's. Franklin F/W making rounds w/ Detex clock reporting to The bridge every hour.

0000 All is well. Master + 1st Off. aboard

0030-0130 Stevedores KO for chow

0040 CO Mildept. abd. Lt. Hawkins

0300 All in apparent good order

0400 Cargo oper. in progress. Watch relieved by Warzee QM
de Luna QM

0400 - 0800

On watch Mr Pike 3/6 Mr Nations 3/6 Warzee QM Paige 1/6

0500 All is well

0600 All is well

0700 All is well

0738 STEVEDORES ON BOARD

0743 Watch relieved by JACKSON QM. All is well

AA Wayne QM

08-12

ON WATCH MR KREITZ 3/6 QM Overaker - QM JACKSON, M
AB/W FRANKLIN & Smeller

0745 Assumed The Watch. Moored as before.

0800 Made calls All is well

0900 All in APPARENT good order.

0915 STEVEDORES LEFT SHIP.

0935 3RD DK FUELING PORT CLOSED - SECURED FOR SEA.

0945 3RD DK Side port closed

1000 All APPARENT good order

1005 PAUL D.W. LEFT SHIP WITH SHIPS MAIL.

1020 3RD DK Side port secured for sea.

1035 HARRIS P. Capt, T. HARRIS pilot came aboard. M.J. QM.

1037 Commenced Loading Troops.

1050 Secured QUARTER DECK WATCH. McKinney Junior QM.

OKI NAWA
ZONE DESCRIPTION
+7

TO ~~TO~~ SAN DIEGO CALIF

10-20-67

DAY OF WEEK
Friday

115

TELEPHONE CUSTODY RECEIPT

20 OCTOBER 1967

(DATE)

USNS GEN JOHN W. POPE (T-AP 110)

NAME OF SHIP & HULL NUMBER

This Telephone is "FOR OFFICIAL USE ONLY"

I hereby accept custody of the below listed equipment and assume the responsibility of its return in the same condition as when received. THE FLEET SUPPORT OFFICE will be notified one (1) hour prior to ships departure, to permit inspection and removal of the equipment by the FLEET SUPPORT OFFICE PERSONNEL.

Call FLEET SUPPORT OFFICE extensions: 3624 or 3625 for trouble and removal.

	<u>QUANTITY</u>	<u>SERIAL NO.</u>
TELEPHONE INSTRUMENT	<u>1</u>	<u>5</u>
SAN DIEGO TELEPHONE BOOK	<u>NONE</u>	<u>NONE</u>
TELEPHONE EXTENSION LINES	<u>1</u>	<u>NONE</u>
OTHER	<u>NONE</u>	<u>NONE</u>

Cotton B.A. SF-1

NAME OF PERSON INSTALLING EQUIPMENT

SIGNATURE OF PERSON RECEIVING EQUIPMENT

TELEPHONE NUMBER ASSIGNED SHIP: _____

TELEPHONE & EQUIPMENT REMOVED FROM SHIP BY:

(NAME)

(TIME & DATE)