

MILITARY SEA TRANSPORTATION SERVICE

BRIDGE-GANGWAY LOG

USNS ~~GEN. JOHN POPE~~
TAP 110

CAPTAIN ROSENBLAD MASTER
FROM 0000 6 JULY 1969
BERTH 30 PIER 2 HUNTERS POINT
NAVAL SHIPYARD - SAN FRANCISCO
CALIFORNIA.

15 JULY = CAPTAIN HASKELL ABOARD
AUGUST 18TH "AAA" SHIPYARD PIER #66

CAPTAIN SWORTFIGEUR ASSUMED COMMAND 22 AUG. 69

Edward SYLVA - - - - - EL. SOBRANTE

893-3016

E. SHAYERS CH. Elect

Oakland

T. Kenney R/O

San Francisco

NAME	CITY	PHONE NO.
CAPTAIN ROSENBERG SWORTFEUR	OAKLAND	
MR CONNALLY	OAKLAND	
MR BARRETT R/O	SAN FRANCISCO	
MR BANTZ CH/ENG	SAN LEANDRO	
MR. SHERMAN R/O	SAN FRANCISCO	
MR. DUNIGKE R/O	SAN FRANCISCO	
MR HURKEY R/E	SAN FRANCISCO	
MR THOMPSON ASST	ALAMEDA	
MR DATTOLA CH/STEW.	SAN MATEO	
MR SMITH PURSER	SAN OFF MATEO	
MR. SPECTOR R/E	SAN JOSE	
L. PERKINS A/B	SAN FRANCISCO	
J. JACKSON A/B	OAKLAND	
G. CARRON A/B	OAKLAND	
G. ORR A/B	ALAMEDA	
A. FRUTAZ A/B	SAN OFF FRANCISCO	
G. NIX A/B	SAN FRANCISCO	
D. DAVOCAL A/B	SAN OFF FRANCISCO	
P. LARKIN A/B	DUBLIN	
J. MATEO A/B	SAN FRANCISCO	
A. GRAYSON A/B	ALAMEDA	
R. BUNDY A/B	RICHMOND	
Jedale	Petaluma (code 70)	
PELETI	SANTA ROSA OFF	CODE 707
CELADA F.B. A/B	SAN FRANCISCO	
POTTER	SAN FRANCISCO	

AT/PASSAGE FROM PIER 2 BIRTH 30 HUNTER'S POINT NAVAL SHIPYARD SAN FRANCISCO	TO
ZONE DESCRIPTION +7	DATE (Day, month, year) 6 JULY 1969
	DAY OF WEEK SUNDAY

TIME	REMARKS
	0000
0000	MOORED PORTSIDE TO PIER 2, BIRTH 30, SAN FRANCISCO NAVAL SHIPYARD AT HUNTER'S POINT CALIFORNIA. WITH FOUR (4) HEADLINES & TWO (2) BREASTLINES TO PIER. ONE (1) WIRE PREVENTER, ONE (1) BREST ACROSS TO U.S.N.S. WEIGEL AND TWO (2) SPRINGS FORWARD. FOUR (4) STERNLINES, ONE (1) WIRE PREVENTER, ONE (1) BIGHT ACROSS TO WEIGEL. TWO (2) SPRINGS AFT. VESSEL'S PLANT SECURED, RECIEVING ALL SERVICES FROM THE DOCK. U.S.N.S. POPE AND U.S.N.S. WEIGEL IN NINETY (90) TO ONE HUNDRED TWENTY (120) ^{DAY} READY RESERVE STATUS, WITH SECURITY BASED ON U.S.N.S. POPE.
	ON WATCH: MR BARRETT ^{R/O} = MR LEGGETT ^{R/E} = CAMERON ^{R/W} FRUTAZ ^{F/W} = CELADA ^{F/W} .
	CELADA ON POPE = FRUTAZ ON WEIGEL MAKING DETEX CLOCK ROUNDS. RAT GUARDS = MOORING LINES = GANGWAY: LIGHTS ALL IN GOOD ORDER.
0100	ALL SECURE ON BOTH SHIPS. ^{R/O} = ^{R/E} MADE ROUNDS OF BOTH SHIPS.
0200	ALL SECURE ON BOTH SHIPS.
0300	ALL SECURE. ^{R/O} = ^{R/E} MADE INSPECTION OF WEIGEL.
0400	ALL SECURE ON BOTH SHIPS.
0500	ALL SECURE ON BOTH SHIPS.
0525	JACKSON, J. - 165-9 AB CALLED IN SICK - WANT BE IN TODAY.
0600	ALL SECURE. ^{R/O} = ^{R/E} MADE ROUNDS OF POPE & WEIGEL.
0630	WATCH RELIEVED BY MATEO ^{R/O} (0800 - 1600) ^{R/E}
0800	MR BARRETT ^{R/O} MR LEGGETT ^{R/E} ORR-GWY MATEO - FIREWATCH
	MOORED AS BEFORE. LINES, RATEVARDS, & GANGWAY SECURE. COLORS. FIREWATCH MAKING ROUNDS ON BOTH VESSELS & REPORTING REGULARLY.
0900	ROUTINE WATCH. ALL IN APPARENT GOOD ORDER. ^{R/O} & ^{R/E} MADE INSPECTIONS
1000	ALL IN GOOD ORDER
1010	^{R/E} MR. HURLEY RELIEVES MR. LEGGETT
1055	^{R/O} MR. SHERMAN RELIEVES MR. BARRETT
1100	ALL IN APPARENT GOOD ORDER. ^{R/O} & ^{R/E} MADE ROUTINE INSPECTIONS
1200	ALL SECURE
1300	ALL IN ORDER.
1400	ALL IN GOOD ORDER. ^{R/O} INSPECTING GEN. WEIGEL
1410	WATCH RELIEVED BY LARRY PERKINS ^{R/O} Geo. On
1410	assumed the watch - Perkins ^{R/O} - Perlet ^{R/E} Weigel Davocal ^{F/W} - POPE -
1500	F/W BOTH VESSELS - ON Detex ROUNDS - REPORTING hourly ALL IN APPARENT GOOD ORDER - (CONT)

AT/PASSAGE FROM
ZONE DESCRIPTION

Ship #30 - Hunters Point - North shipyard - S.F. Dist

TO

DATE (Day, month, year)

DAY OF WEEK

6-July-1969

Monday

TIME

REMARKS

1600-2400
Mr. Hurley Rte. m. Parkins G. W. D. D. W. Pope: Rte. W. Weigel
1600 R/O R/E on insp. rounds - Weigel & Pope - Report - all in good order
FW BOTH vessels - Report - all in good order
1700 FW BOTH vessels - Report - all in good order
1800 All in apparent good order
1900 FW Report all in good order
2000 All in apparent good order
2035 R/O on insp. rounds - Sunset colors observed
2100 R/E on insp. Rds: Weigel & POPE - All in apparent good order
FW BOTH vessels - Report - all in good order
2200 FW BOTH vessels Report - all in good order
Properly relieved of gangway duties

L. M. Perkins

AT/PASSAGE FROM <i>Berth #30 Pier 2 Hunters Point</i>	TO <i>Naval Shipyard S.F.</i>	
ZONE DESCRIPTION <i>PLUS SEVEN</i>	DATE (Day, month, year) <i>7 JULY 1969</i>	DAY OF WEEK <i>MONDAY</i>

TIME	REMARKS
	0000-0800
	MOORED AS BEFORE.
	ON WATCH: MR. BARRETT R/O MR. LEGGETT R/E
	FRUTAZ R/B Gangway Watch. Celada F/W on the
	Pope made his Round with Detex clock hourly.
	every hour he report the Gangway.
	Tipton F/W on the Weigel making his Round
	with Detex clock hourly and report to the Tw.
	All Lines Rat Guard in good order.
0000	MR. BARRETT R/O and MR. LEGGETT R/E made
	Their Round on the Weigel and the Pope
0100	Both Ships Weigel and the Pope in good order.
0200	all Rat Guard and Lines are in good order.
0300	MR. BARRETT R/O MR. LEGGETT R/E made their
	Round on the Weigel and the Pope.
0400	Both Ships Lines and Rat Guard in good order.
0500	Ships Gangway are in good order.
0600	MR. BARRETT R/O MR. LEGGETT R/E made their Round
	on both ships Weigel and the Pope.
0630	Watch Relieved by Geo. Orr C/Monity
0635	CAPTAIN ROSENBLAD & Y SKOVOTH ABOARD. R/O RELIEVED.
0700	DAY WORKERS TURN TO.
0727	TEST OF SMOKE DETECTOR & KIDDE ALARM BELLS
	MR SKOVOTH Y (0800-1600) ORR-GWY LARKIN F/W
0800	MOORED AS BEFORE. COLORS. LINES, RATE GUARDS & GANGWAY ALL SECURE.
0900	ROUTINE WATCH. ALL IN APPARENT GOOD ORDER.
1000	ALL IN APPARENT GOOD ORDER
1100	ALL SECURE.
1200	ALL SECURE
1300	ROUTINE WATCH. ALL IN ORDER.
1405	WATCH RELIEVED BY LARRY PERKINS R/B Geo. Orr
1405	ASSIGNED THE WATCH - PERKINS R/B (POPE R/E Weigel F/W Mateo F/W)
1420	MR. HURLEY R/E ABOARD
1500	F/W BOTH VESSELS ON DETEX ROUNDS - REPORTING HOURLY
1515	MR. SHERMAN R/O ONBOARD
1530	CAPT ROSENBLAD - ASHORE
	MR. SHERMAN R/O (1600-2400) PERKINS R/B: CAPPELL F/W POPE: Mateo F/W Weigel
1600	MR HURLEY R/E ON ROUNDS BOTH VESSELS - F/W BOTH VESSELS REPORT ALLS WELL
1630	R/O ON ROUNDS Weigel & Pope - all in apparent good order
1700	F/W REPORT - all in good order
1800	all in apparent good order
1900	F/W's REPORT - all well - R/O on ROUNDS Weigel & Pope -
2000	F/W BOTH VESSELS - REPORT all in good order
2035	SUNSET - colors observed
2100	R/E ON ROUNDS Weigel & Pope
2200	F/W SECURED - all in good order
2205	watch relieved by Frutaz R/B - L.M. Perkins

AT/PASSAGE FROM Berth 30 Pier 2 Hunter's	TO Point Naval Yard San Francisco
ZONE DESCRIPTION	DATE (Day, month, year) 8 July 19-69 DAY OF WEEK Tuesday

TIME	REMARKS
	0000 - 0800
	Moored as before.
	ON WATCH: MR. BARRETT ^{R/E} MR. LEGGETT ^{R/E} FRUTAZ ^{R/B} Gangway watch.
	Larkin FW on the Pope Making his Round Hourly and Report on the Pope.
	Tipton FW on the Weigel, making his Round hourly and report on the Pope Gangway.
0000	Both ships are in good order.
0100	MR. BARRETT ^{R/E} MR. LEGGETT ^{R/E} made their Round in both ships.
0200	All ships Lines and Rat Guard in good order.
0300	MR. BARRETT ^{R/E} MR. LEGGETT ^{R/E} made their on both ships.
0400	Both ships Gangway, Rat Guards hooking Lines are in good order.
0500	All Lines Rat Guard are in good order.
0600	MR. BARRETT ^{R/E} MR. LEGGETT ^{R/E} made their Round in both ships Weigel and Pope.
0636	WATCH Relieved By Goo, ORR ^{R/E} FRUTAZ ^{R/B} .
0645	CAPTAIN ROSENBLAD ABOARD. ^{R/E} ABOARD. ^{R/E} RELIEVED.
0700	DAYWORKERS TURN TO.
0715	TEST OF SMOKE DETECTOR & FIRE ALARMS COMPLETED, ^{R/E} ASHORE MR SKOVOTH ^{R/E} (0800 - 1600) ORR-GWY JOE JACKSON FW
0800	MOORED AS BEFORE. LINES, RAT GUARDS, GANGWAY SECURE. COLORS.
0900	ROUTINE WATCH - ALL IN GOOD ORDER
1000	ALL SECURE.
1100	ROUTINE WATCH - ALL IN GOOD ORDER, APPARENTLY
1200	ALL SECURE.
1300	ALL SECURE.
1400	ALL SECURE.
1415	WATCH RELIEVED BY LARRY PERKINS ^{R/B} Goo ^{R/E}
1415	assumed the watch - MR. HURLEY ^{R/E} - PURSER to Post Office
1500	MR. SHERMAN ^{R/E} ABOARD Capell FW on Weigel. Mater FW on Pope PURSER ABOARD FROM POST OFFICE.
1530	CAPT ROSENBLAD ASHORE
1600	^{R/E} MR. SHERMAN ^{R/E} (1600 - 2400) PERKINS ^{R/E} Mater ^{R/E} Capell FW on Weigel
1600	^{R/E} ON ROUNDS Weigel & Pope FW on Detox ROUNDS - ALL IN APPARENT GOOD ORDER
1620	PHONE CALL FOR MR SKOVOTH ^{R/E} FROM MR. CIRC (Materola) 349-3111
1640	^{R/E} ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
1700	FW ON BOTH VESSELS - REPORT ALL IN GOOD ORDER
1800	ROUTINE BOUNDS - ALL IN GOOD ORDER.
1900	FW BOTH SHIPS REPORT ALL IN GOOD ORDER
2035	SUNSET - COLORS OBSERVED - ^{R/E} ON ROUNDS - ALL IN GOOD ORDER
2100	FW BOTH VESSELS - REPORT - ALL IN GOOD ORDER
2120	CAMERON ^{R/B} CALLED - "UNABLE TO MAKE WATCH - MINOR ACCIDENT" msg taken by SMP - passed on to MR. SHERMAN - Cont

AT/PASSAGE FROM

TO

ZONE DESCRIPTION

TIME

REMARKS

1600-2400

2125 R/R R/R report - all in good order

2200 D/L's - secured - all in apparent good order

2210 MR. LEGGETT R/R - ABOARD - MR. HURLEY R/R ASHORE

2230 watch relieved by order of Mr Barrett R/O

" MR. BARRETT R/O aboard

2235 L. M. Perkins

MR. BARRETT R/O ON BOARD

AT/PASSAGE FROM

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

PIER 2 BERTH 30 HUNTERS POINT NAVAL SHIPYARD
 +7 9 JULY 1969 WEDNESDAY

TIME	REMARKS
	0000 - 0800
2300	MR BARRETT R/MATE, MR LEGGETT, ^{R/ENG} CLARKIN ^{A/B} TIPTON F/W WEIGEL, & POPE TO MAKE RDS. BOTH SHIPS. 2300 RD WEIGEL SECURE.
2345	TIPTON ABOARD MAKE DETEX RD ON POPE.
2400	ALL SECURE POPE.
0100	F/W REPORTS SECURE WEIGEL.
0200	F/W'S CHECKS "POPE" ALL IN GOOD ORDER.
0300	F/W'S REPORTS ALL IN GOOD ORDER, SECURE (WEIGEL)
0400	ALL SECURE.
0500	SECURITY RD MADE, ALL AREAS SECURE.
0555	SUNRISE OBSERVED.
0600	F/W MADE DETEX RDS OF POPE, ALL IN GOOD ORDER.
0615	1ST ASSISTANT ENG. ABOARD, R/ENG. LEFT SHIP
0630	WATCH RELIEVED BY CAPELL. ^{A/B}
	<i>D. Larkin</i>
	Mr. Skoveth ^{1/6} (0800 ~ 1600) Capell ^{A/B} G, J. Jackson ^{A/B} F
0630	Assumed the watch. All in apparent good order.
0645	Captain Rosenblad, Master, aboard.
0700	All in apparent good order.
0800	Colors. All in apparent good order.
0805	Test of ship's fire alarm system. In order. Gangway notified following tests this date: Diesel generator (30 min), anchor windlass (1 hr.), Capstan (1 hr.), bilge air valves, emergency fire pumps (1 hr.), rectifiers.
0900	All in apparent good order.
1000	All in apparent good order.
1100	All in apparent good order.
1200	All in apparent good order.
1230	Truck w/ GSKS supplies arrives.
1300	All in apparent good order.
1315	P.T. & T man changed pay phone number to: 822-9900
1330	Base Oper. Small Craft Warning: Effective 1300 for 9 hrs winds NW to W 12 to 19 knots gusts to 24 knots seas slight in all parts of harbor.
1340	Perkins ^{A/B} called to speak to Mr Skoveth ^{1/6}
1400	All in apparent good order
1430	Relieved of gangway duties by Perkins ^{A/B}
	<i>Robert D. Capell</i>
1430	WATCH ASSUMED - MR HURLEY R/E ABOARD
1510	MR SHERMAN ^{1/6} ABOARD
1530	CAPT ROSENBLAD ASHORE
	<i>MR. SHERMAN & O</i> <i>MR. HURLEY</i> ^{1/6} 1600-2400 Perkins ^{1/6} Davenport - Perkins ^{1/6}
1600	MR HURLEY R/E ON ROUNDS - Weigel & Pope - F/W'S BOTH VESSELS REPORT - ALL'S WELL
1640	R/O - MR SHERMAN ON ROUNDS - ALL IN APPARENT good order
1700	F/W BOTH SHIPS - REPORT - ALL'S WELL (1600-2400 - CONT.)

AT/PASSAGE FROM

ZONE DESCRIPTION

Per 2 - BERTH 30 - Hunter's

TO

Point Nalgaard - San Francisco

DATE (Day, month, year)

9 - July - 1969

DAY OF WEEK

Wednesday

TIME

REMARKS

1600

2400

1800 Flw Report all in good order

1900 Flw Report all in good order

2000 R/L ON GOUNDS - Both vessels - all in good order -

2035 Sunset colors observed

2100 R/L ON GOUNDS BOTH vessels - all in good order

2200 Flw - BOTH SHIPS - REPORT - ALL IN GOOD ORDER

Mr Leggett R/L - aboard - Mr Hurley R/L ASHORE

2200 watch relieved by CAMERON Q/B

L. J. Perkins

AT/PASSAGE FROM		TO	
PIER 2 BIRTH 30 HUNTERS POINT		NAVAL SHIPYARD SAN FRANCISCO	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
T 7		10 July 1969	THURSDAY
TIME	REMARKS		
	0000-0800		
	MR BARRETT P/O = MR HERGETT P/E = CAMERON F/W = TIPTON F/W = QUILADA F/O MOORING LINES - RAT GUARDS - GANGWAYS - LIGHTS all in GOOD ORDER. TIPTON F/W ON WEIGEL - QUILADA F/W ON POPE. BOTH MAKING DETEX CLOCK ROUNDS.		
0100	All SECURE ON BOTH SHIPS. P/O - P/E MADE INSPECTION OF WEIGEL.		
0200	All SECURE ON BOTH SHIPS.		
0300	All SECURE. P/O - P/E MADE INSPECTION OF WEIGEL.		
0400	All SECURE ON BOTH SHIPS.		
0500	All SECURE. P/O - P/E MADE ROUNDS OF WEIGEL.		
0600	All SECURE ON BOTH SHIPS.		
0630	WATCH RELIEVED BY CAPELL P/O W. J. Skovroth P/O		
	Mr. Skovroth P/O (0800 ~ 1600) CAPELL P/O G, NIX P/O F		
0630	Assumed the watch. All in apparent good order.		
0645	Captain Rosenblad; Master, aboard.		
0700	All in apparent good order.		
0725	Test of ship's fire alarm system. In order.		
0800	Colors. All in apparent good order.		
0900	All in apparent good order.		
1000	All in apparent good order.		
1100	All in apparent good order.		
1103	Purser to the bank.		
1130	Deck dept. safety meeting.		
1131	Purser returns from bank with \$3000.00.		
1200	All in apparent good order. Deck dept. safety meeting ajourned.		
1300	All in apparent good order.		
1400	All in apparent good order.		
1430	Relieved of gangway duties by LARKIN (1435) Robert DeLapell		
1435	WATCH RELIEVED AND ASSUMED ALL IN GOOD ORDER.		
1500	F/W MAKING RDS. WEIGEL + POPE. ALL SECURE.		
1535	MASTER LEFT SHIP 1/6 LEFT SHIP. MR SHERMAN P/MATE ON BD		
	1600-2400		
1600	MR SHERMAN P/O, MR HURLEY P/ENG, LARKIN P/O (Gangway) DELETI F/W WEIGEL + DAVACOL P/O F/W POPE, RDS MADE, SECURE.		
1700	MR HURLEY COMMETS RDS OF WEIGEL + POPE. ALL SECURE.		
1710	W/T DOORS CLOSED. DETEX RDS MADE.		
1800	F/W'S REPORT DETEX SECURITY RDS MADE ALL AREAS SECURE.		
1900	F/W REPORT ALL SECURE. ALL AREAS BOTH VESSELS.		
2000	F/W REPORT SECURE - 2030 Colors EXECUTED.		
2100	P/ENG. MADE RDS WEIGEL AND POPE P/O CHECKED VESSELS		
2200	ALL SECURE DETEX RDS MADE		
2230	WATCH RELIEVED BY CAMERON, all in good order. D. Larkin P/O		

AT/PASSAGE FROM

PIER 2 BERTH 30 HUNTERS POINT

ZONE DESCRIPTION

47

TO

NAVAL SHIPYARD, SAN FRANCISCO

DATE (Day, month, year)

11 July 1969

DAY OF WEEK

FRIDAY

TIME

REMARKS

0000-0800

MR BARRETT ^{R/D} SPECTOR ^{R/E} CAMERON ^{F/W} TIPTON ^{F/W} CE/ADA ^{F/W}0000 MOORING LINES, RAT GUARDS, GANGWAY, & ALL LIGHTS
IN GOOD ORDER. TIPTON ^{F/W} ON DETEX CLOCK ROUNDS
ON WEIGEL/CE/ADA ON CLOCK ROUNDS ON POPE.

ALL IN GOOD ORDER.

0100 ALL SECURE. ^{R/D} ^{R/E} MADE INSPECTION OF BOTH
POPE & WEIGEL.

0200 ALL SECURE ON BOTH SHIPS.

0300 ALL SECURE. ^{R/D} ^{R/E} INSPECTED WEIGEL/POPE

0400 ALL SECURE ON BOTH SHIPS.

0500 ALL SECURE. ^{R/D} ^{R/E} INSPECTED POPE & WEIGEL.

0600 ALL SECURE ON BOTH SHIPS.

0630 WATCH RELIEVED BY ORR ^{R/B}0645 ^{R/E} ASHORE. ^{R/D} RELIEVED.

0655 CAPTAIN ROSENBLAD ABOARD.

0715 TEST OF SMOKE DETECTING & FIRE ALARMS - O.K.

MR. SKOVOTH ^{R/D} (0800-1600) ORR-GWY CAPELL ^{F/W}

0800 MOORED AS BEFORE. LINES, RAT GUARDS, GANGWAY SECURE. COLORS EXECUTED.

0900 ALL IN APPARENT GOOD ORDER.

1000 ALL SECURE.

1130 ENGINE DEPT. SAFETY MEETING.

1200 SAFETY MEETING ADJOURNED. 21 MEN WERE PRESENT.

1300 ROUTINE WATCH. ALL IN ORDER.

1430 WATCH RELIEVED BY LARKIN ^{R/B} Geo. On1500 ^{F/W}'S REPORT ALL SECURE, ^{R/E} HURLEY ON BD.

1530 MASTER LEFT SHIP.

1535 MR CUNNALLY ^{R/D} MADE ON BD.1545 MR SKOVOTH ^{R/D} LEFT SHIP.

1600-2400

1600 ^{F/W} REPORTS ALL SECURE BOTH VESSELS, CHECKED ALL
LINES, DRAFTS - ALL IN GOOD ORDER ^{R/D} CHECKS SHIPS.ON WATCH - MR CUNNALLY ^{R/D} - MR HURLEY ^{R/E} - LARKIN (G)
DAVADOL ^{R/D} ^{F/W} ON POPE. PELETI ^{R/D} ^{F/W} "WEIGEL"

ALL DETEX SECURITY RDS BEING MADE. ALL SECURE.

1630 W/T DOORS WEIGEL & POPE SECURED & CHECKED

1700 ^{F/W}'S REPORT ALL SECURE - MR HURLEY CHECKS ALL ENG SPACES.

1800 RDS MADE. ALL SECURE.

1900 ^{F/W}'S MADE SECURITY RD OF BOTH SHIPS. ALL IN GOOD ORDER

2000 ALL SECURE

2032 COLORS EXECUTED - LIGHTS BRIGHT, ALL N/LITES & TRUCK LTS.

2100 SECURITY RDS MADE - ALL AREAS BOTH VESSELS. SECURE.

2200 ^{R/E} HURLEY MADE 2100 INSPECTION, SECURE IN ALL ENG AREAS.

2230 WATCH RELIEVED CAMERON.

P. Larkin

AT/PASSAGE FROM PIER 2 BERTH 30 HUNTERS POINT	TO NAVAL SHIPYARD, SAN FRANCISCO
ZONE DESCRIPTION 47	DATE (Day, month, year) 12 JULY 1969
	DAY OF WEEK SATURDAY

TIME	REMARKS
	0000-0800
0000	MR BARRETT P/O=MR SPECTOR P/E=CAMERON S/W=FRUTAZ H/W=CE/ADA F/W MOORING LINES=RAT GUARDS=GANGWAY=& LIGHTS ALL IN GOOD ORDER. FRUTAZ H/W ON FIREWATCH &N WEIGEL/CE/ADA ON POPE= BOTH MAKING DETEX CLOCK ROUNDS & REPORTING REGULARY.
0100	ALL SECURE P/O=P/E MADE INSPECTION OF BOTH SHIPS.
0200	ALL SECURE ON BOTH SHIPS.
0300	ALL SECURE ON BOTH SHIPS. P/O=P/E MADE INSPECTION OF WEIGEL.
0400	ALL SECURE ON BOTH SHIPS.
0500	ALL SECURE P/O=P/E MADE INSPECTION OF WEIGEL.
0600	ALL SECURE ON BOTH SHIPS.
0630	WATCH RELIEVED BY ORR H/W
	MR. BARRETT P/O MR. SPECTOR P/E (0800-1600) ORR-GWY JACKSON F/W-POPE MATED F/W-WEIGEL
0800	MOORED AS BEFORE. LINES, RATEGUARDS, & GANGWAY SECURE. COLORS,
0900	P/O & P/E COMPLETE TOUR OF INSPECTION ABOARD BOTH VESSELS
1000	ROUTINE WATCH. NO ACTIVITY. ALL IN GOOD ORDER.
1020	MR HURLEY P/E ABOARD RELIEVES MR. SPECTOR
1105	MR. CONNALLY RELIEVES MR. BARRETT.
1200	P/O & P/E MADE INSPECTION OF BOTH VESSELS
1300	ALL IN APPARENT GOOD ORDER.
1400	ALL SECURE.
1430	WATCH RELIEVED BY LARRY PERKINS H/W
1430	WATCH ASSUMED
1500	F/W ON BOTH VESSELS -REPORT- ALL WELL MR. CONNALLY CLIP -ALL OK Perkins H/W: D. S. Col. W. Perkins H/W
1600	F/W BOTH VESSELS REPORT ALLS WELL
1700	F/W BOTH VESSELS -REPORT- ALL WELL
1800	P/E ON ROUNDS BOTH VESSELS -ALL IN GOOD ORDER
1900	F/W REPORT ALLS WELL
2000	P/E -ON ROUNDS- BOTH VESSELS -ALL IN good order.
2035	SUNSET- COLORS OBSERVED
2100	F/W -BOTH VESSELS REPORT- ALL IN GOOD ORDER
2210	WATCH RELIEVED BY CAMERON
	LARRY PERKINS

AT/PASSAGE FROM		TO	
PIER 2 BERTH 30 HUNTERS POINT NAVAL SHIPYARD		SAN FRANCISCO	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
4-7		13 July 1969	SUNDAY
TIME	REMARKS		
	0000-0800		
0000	MR BARRETT ^{R/O} = MR SPECTOR ^{R/E} = CAMERON ^{G/W} = FRUTAZ ^{F/W} = CE/ADA ^{F/W} MOORING LINES = RAT GUARDS = GANGWAY = & LIGHTS IN GOOD ORDER. FRUTAZ ^{F/W} ON WEIGEL = CE/ADA ^{F/W} ON POPE BOTH MAKING DETEX CLOCK ROUNDS & REPORTING REGULARLY.		
0100	ALL SECURE: ^{R/O} = ^{R/E} MADE INSPECTION OF BOTH POPE & WEIGEL.		
0200	ALL SECURE ON BOTH SHIPS.		
0300	ALL SECURE. ^{R/O} = ^{R/E} MADE ROUNDS OF WEIGEL.		
0400	ALL SECURE ON BOTH SHIPS.		
0500	ALL SECURE ^{R/O} = ^{R/E} MADE ROUNDS OF WEIGEL.		
* 0600	ALL SECURE ON BOTH SHIPS.		
* 0545	MATEO ^{A/B} (165-14) CALLED IN SICK. WANT BE ABLE TO STAND HIS WATCH TODAY.		
0620	WATCH RELIEVED BY ORR ^{A/B} MR BARRETT ^{R/O} MR SPECTOR ^{R/E} (0800 - 1600) ORR-GWY JOE JACKSON ^{F/W}		
0800	MOORED AS BEFORE. LINES, RAT GUARDS, GANGWAY SECURE. COLORS EXECUTED.		
0900	^{R/O} & ^{R/E} COMPLETE TOUR OF BOTH VESSELS		
1000	ROUTINE WATCH. ALL IN APPARENT GOOD ORDER.		
1015	MR MASTERS ^{R/E} ABOARD 1040 MR SPECTOR ASHORE		
1050	MR CONNALLY ^{R/O} ABOARD 1100 MR BARRETT ASHORE		
1200	ALL IN APPARENT GOOD ORDER. ^{R/O} & ^{R/E} INSPECTING BOTH VESSELS		
1245	PERKINS ^{A/B} CALLED IN SICK. UNABLE TO STAND WATCH TONIGHT.		
1300	ALL IN APPARENT GOOD ORDER		
1400	ALL SECURE. ^{R/O} & ^{R/E} MAKING ROUNDS BOTH VESSELS		
1430	WATCH RELIEVED BY PELETI ^{A/B} Geo. Orr		
1430	Watch assumed ^{R/O} Mr Connally aboard. ^{R/E} aboard. ^{F/W} Dava Col both ships. Peleti ^{A/B} . ^{W/R} mooring lines = Rat Guards = Gangway = Lights, all in good order.		
1500	^{F/W} Both Vessels Report Alls Well		
1530	All Secure ^{R/O} = ^{R/E} made Inspection of Both vessels		
1600	^{F/W} Both vessels Report All well.		
1700	^{R/E} on Rounds Both vessels all in good orders		
1730	^{F/W} Report all Secure. all areas both vessels.		
1800	^{R/O} = ^{R/E} made Inspection of both Ships. all in good order		
1830	^{F/W} Report all Secure all areas both vessels		
1930	^{F/W} Both vessels Report alls Well		
2000	^{R/E} = ^{R/O} on Rounds - both vessels all in good order		
2032	Sunset Colors observed		
2100	^{R/O} = ^{R/E} on Rounds both vessels all in apparent Good order		
2115	^{F/W} making rounds both vessels all in good order Watch Relieved by FRUTAZ ^{A/B} G/W Peleti		

AT/PASSAGE FROM		TO	
Berth 30 Pier 2 Hunters Point Naval Shipyard San Francisco		DATE (Day, month, year)	
ZONE DESCRIPTION		DAY OF WEEK	
+ 7		14 July 19-69 Monday	
TIME	REMARKS		
	0000 - 0800		
	MOORED as before. ON Watch Mr. Barrett ^{R/O} & Mr. Spector ^{R/E}		
	Frutaz A/B Gangway Watch. Celada FW on the Pope		
	making his Round with Detex clock hourly.		
	Tipton FW on the Weigel making his Round with Detex		
	clock hourly and Report to the Gangway		
0000	Both ships Lines Ratguard are in good order.		
0100	Mr. Barrett ^{R/O} and Mr. Spector ^{R/E} their Round on		
	both ships.		
0200	Both FW report all secure.		
0300	Both ship & are secure		
0400	Mr. Barrett ^{R/O} and Mr. Spector ^{R/E} made their Round on		
	both ships Weigel and Pope.		
0500	Lines, Ratguard and Gangway in both ships in good order.		
0600	Mr. Barrett ^{R/O} and Mr. Spector ^{R/E} made their Round both ships.		
0630	Watch Relieved by Goe ORR ^{A/B} Frutaz ^{A/B}		
0700	DAY WORKERS TURN TO		
0735	SHORE STEAM SECURED		
0740	SHIPS FIRE ALARM SYSTEMS TESTED		
0800	MR SKOVOTH ^{R/O} (0800-1600) ORR-6WY JACKSON FW		
	MOORED AS BEFORE. COLORS.		
0900	ALL IN APPARENT GOOD ORDER.		
1015	SHORE STEAM BACK ON.		
1100	ALL IN APPARENT GOOD ORDER. CAPTAIN HASKELL ABOARD.		
1200	ALL SECURE		
1300	ALL SECURE		
1400	CAPTAIN HASKELL ASSUMES COMMAND FROM CAPTAIN ROSENBLAD		
1401	CAPTAIN HASKELL ASHORE, CAPTAIN ROSENBLAD ASHORE.		
1410	PURSER TO POST OFFICE 1425 RETURNS		
1415	MR MASTERS ^{R/E} ABOARD		
1430	WATCH RELIEVED BY GRAYSON ^{A/B} ^{Mr. Orr}		
	MATED 7/W		
	MR. Burge ^{R/O} 1600-2400 Copell ^{R/W} GRAYSON ^{A/B}		
1430	Assumed watch, all in apparent good order.		
1450	Mr. Burge, R/O aboard.		
1600	FW making hourly rounds Pope and Weigel, all secure.		
1700	R/O made rounds of both ships.		
1800	All secure about both ships.		
1900	FW reports all secure.		
2000	Mr. Burge R/O, Mr. Masters, R/E made inspection of Pope and Weigel.		
2033	"Sunset", colors observed.		
2100	FW made rounds. All in apparent good order.		
2200	All secure about the ship.		
2215	Watch relieved by Frutaz		

AT/PASSAGE FROM		TO	
Benth 30 Pier 2 Hunter's Point Naval Shipyard San Francisco Calif.		DATE (Day, month, year)	
ZONE DESCRIPTION		DAY OF WEEK	
+ 7		15 July 19-69	
		Tuesday	
TIME	REMARKS		
	0000 - 0800		
	Moored as before		
	On Watch: Mr. Barrett P/O Mr. Spector P/O Frutcz P/O		
	Larkin FW on the Pope made his Round with Detex Clock every hour.		
	Tipto FW on the Weigel made his Round with Detex Clock every hour and Report to the Pope.		
0000	Both ships Lines Rat Guard and Gangway are in good order		
0100	MR. BARRETT P/O MR. MASTER made their 1st both ship		
0200	Both ships Lines and Rat Guard & Gangway in good order		
0300	Both Fire Watch Report every hour all secure.		
0400	MR. BARRETT P/O made his Round on the Weigel.		
0500	All Lines Rat Guard, Gangway are in good order.		
0600	MR. BARRETT P/O MR. SPECTOR P/O made their Round both ships		
0630	Watch Relieved by Goe. ORR AM Frutcz		
0635	1/0 ABOARD - 1 st ENG. - 2 nd ENG ABOARD - MR SPECTOR ASHORE		
0715	MR. BARRETT ASHORE.		
	MR SKOVOTH P/O (0800-1600) ORR-GWY J. JACKSON FW		
0800	MOORED AS BEFORE. COLORS		
0900	ALL SECURE. CAPTAIN HASKELL ABOARD.		
1000	ALL SECURE. JACKSON FW		
1100	ALL IN ORDER.		
1200	ALL SECURE		
1300	ROUTINE WATCH. ALL IN ORDER		
1415	WATCH RELIEVED BY LARRY PERKINS Gen. On		
1420	CAPTAIN HASKELL ASHORE		
1420	ADMITTED THE WATCH HALL IN APPARENT GOOD ORDER		
1430	MR. MASTERS P/O ABOARD		
1440	MR. BURGE P/O MR. MASTERS P/O Perkins P/O Master P/O Pope Capell P/O Weigel		
1500	CAPELL FW Weigel MASTERS FW ON DETEX ROUNDS hourly REPORTING		
	1600-2400		
1600	ROR/E P/O BOTH ON ROUNDS - ALL IN GOOD ORDER		
1700	FW BOTH VESSELS ON DETEX ROUNDS - ALL IN GOOD ORDER		
1730	P/O ON ROUNDS BOTH VESSELS - all in good order		
1800	P/O ON ROUNDS BOTH VESSELS all in good order		
1900	FW ON ROUNDS - REPORT ALL IN GOOD ORDER		
2032	Sunset - colors observed -		
2100	BOY P/O ON ROUNDS - all in good order		
"	FW both vessels report all in good order		
2215	Watch relieved by Comdr. AB		
	L. D. Perkins		

TIME	REMARKS
	0000-0800
0000	MR BARRETT ^{R/D} =MR SPECTOR ^{R/E} =CAMERON ^{G/W} =LARKIN ^{F/W} =TIPTON ^{F/W} MOORING LINES=GANGWAY=RAT GUARDS=& LIGHTS ALL IN GOOD ORDER. LARKIN ^{F/W} ON POPE & TIPTON ^{F/W} ON WEIGEL BOTH MAKING DETEX CLOCK ROUNDS & REPORTING HOURLY.
0100	ALL SECURE. ^{R/D} = ^{R/E} MADE INSPECTION OF WEIGEL & POPE.
0200	ALL SECURE ON BOTH SHIPS.
0300	ALL SECURE. ^{R/D} = ^{R/E} MADE INSPECTION OF WEIGEL.
0400	ALL SECURE ON BOTH SHIPS.
0500	ALL SECURE. ^{R/D} = ^{R/E} MADE INSPECTION OF WEIGEL & POPE.
0600	ALL SECURE ON BOTH SHIPS. WATCH RELIEVED BY CAPELL ^{A/B}
	1600-2400
0600	Mr. Skoveth ^{1/0} (0800~1600) Capell ^{1/13 G} , Assumed the watch all in apparent good order.
0700	All in apparent good order.
0800	Colors. All in apparent good order.
0835	Test of ship's fire alarm system. In order. Captain Haskell aboard.
0900	All in apparent good order.
1000	All in apparent good order.
1100	All in apparent good order. Gangway notified of following tests this date; anchor windlass (1hr.), Capstan (1hr.), emer- gency fire pumps (1hr.), bilge air valves. (Diesel generator out of order.)
1200	All in apparent good order.
1300	All in apparent good order.
1345	Captain Haskell ashore
1400	All in apparent good order.
1430	Relieved of gangway duties by Perkins ^{A/B} Robert D. Lapell
1430	MR. MASTER ^{R/E} ABOARD
1430	MR. BURGE ^{R/E} ABOARD - Soundings taken from BOTH SHIPS ON ROUNDS MR. BURGE^{R/D} (1600-2400) Perkins^{G/W}; Davison^{F/W}; Perkins^{F/W} Weigels
1600	FW BOTH VESSELS - DETEX ROUNDS - REPORTING - ALL IN GOOD ORDER
1700	FW BOTH SHIPS ON ROUNDS BOTH SHIPS - ALL IN APPARENT GOOD ORDER
1800	FW & R/E ON ROUNDS BOTH VESSELS - REPORT all in good order
1900	FW & R/E ON ROUNDS BOTH VESSELS - REPORT all in good order
2000	FW BOTH VESSELS report all in good order
2030	Snipet - colors observed - R/E
2100	R/E - FW ON ROUNDS BOTH VESSELS - Report all in good order
2200	FW secured - all in apparent good order
2210	Watch relieved by Cameron A/B

J. D. Perkins

AT/PASSAGE FROM	TO	
PIER 2 BERTH 30 HUNTERS POINT SAN FRANCISCO NAVAL SHIPYARD		
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
+7	17 July 1969	THURSDAY

TIME	REMARKS
	0000-0800
0000	MR BARRETT ^{P/O} MR SPECTOR ^{P/E} CAMERON ^{P/W} TIPTON ^{P/W} DELADA ^{P/W} MOORING LINES: GANGWAY: PAT GUARDS & LIGHT IN GOOD ORDER. TIPTON ^{P/W} ON WEIGEL = DELADA ^{P/W} ON POPE. BOTH MAKING DETEX CLOCK ROUNDS.
0100	ALL SECURE. ^{P/O} ^{P/E} MADE INSPECTION OF BOTH POPE & WEIGEL.
0200	ALL SECURE ON BOTH SHIPS.
0300	ALL SECURE. ^{P/O} ^{P/E} MADE INSPECTION OF WEIGEL.
0400	ALL SECURE ON BOTH SHIPS.
0500	^{P/O} ^{P/E} MADE INSPECTION OF WEIGEL - ALL SECURE.
0600	ALL SECURE ON BOTH SHIPS.
0630	MR SKOVOTH ^{1/0} ABOARD. WATCH RELIEVED BY CAPELL ^{A/B} Don Cameron ^{P/B}
	Mr Skovoth ^{1/0} (0800 ~ 1600) Capell ^{A/B} G, Grayson ^{A/B} F/W
0630	Assumed the watch. All in apparent good order.
0700	All in apparent good order.
0710	Steam on board secured untill further notice
0800	Colors. All in apparent good order.
0805	Test of ship's fire alarms. All in order.
0820	Captain Haskell, Master, aboard.
0900	All in apparent good order.
1000	All in apparent good order.
1050	Purser ashore to Bank.
1150	Purser aboard with (seven) \$7,000.00.
1200	All in apparent good order.
1300	All in apparent good order.
1400	All in apparent good order.
1430	All in order. Relieved of gangway duties by Larkin ^{A/B} Robert A. Capell
1430	WATCH ASSUMED, F/W'S RELIEVED RDS BEING MADE
1455	MR BURGE ON BD. MR MASTER'S ^{P/ENG} RELIEVED ^{ENG} THOMPSON.
	1600-2400
	MR BURGE ^{P/W} - MR MASTER'S ^{P/ENG} - LARKIN ^{1/0} - DELETI ^{P/W} (POPE) ^{P/DAVACOL}
1605	F/W'S REREPORT SECURE, ^{1/0} SKOVOTH LEFT SHIP, SHORE LEAVE - COMM.
1530	RECEIVED MSG. FROM NSC-MSTS MESSAGE CENTER THAT MONDAY JULY 21 WILL BE A HOLIDAY - FOR BOTH PAY & LEAVE PURPOSES, ^{P/W} BURGE RECEIPTS FOR. (COPY TO ^{1/0})
1600	F/W'S REPORT ALL SECURE. RDS MADE, ALL IN GOOD ORDER.
1700	ALL SECURE.
1800	^{P/ENG} MASTER'S MAKES RD OF POPE + WEIGEL ENG. SPACES. SECURE
1900	F/W REPORT SECURE
2000	^{P/MASTE} MADE SECURITY CHECK BOTH VESSELS
2030	CLOCKS EXECUTED - NIGHT LIGHTS CHECKED
2100	SECURE BOTH VESSELS.
2200	F/W REPORT SECURE, ALL IN GOOD ORDER.
2230	WATCH RELIEVED BY CAMERON ^{A/B} ^{1/0} Larkin

AT/PASSAGE FROM		TO	
PIEC 2 BEETH 30 HUNTERS POINT NAVAL SHIPYARD SAN FRANCISCO			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		18 July 1969	FRIDAY
TIME	REMARKS		
	0600-0800		
0600	MIC BARRETT ^{P/O} - MR SPECTOR ^{P/E} - CAMERON ^{F/W} - TIPTON ^{F/W} - CELADA ^{F/W} MOORING LINES - RAT GUARDS - GANGWAY - LIGHTS ALL IN GOOD ORDER. TIPTON ^{F/W} ON WEIGEL - CELADA ^{F/W} ON POPE - BOTH MAKING DETEX CLOCK ROUNDS & REPORTING HOURLY.		
0600	ALL SECURE ^{P/O} - P/E MADE INSPECTION OF POPE & WEIGEL.		
0630	ALL SECURE ON BOTH SHIPS.		
0630	ALL SECURE ^{P/O} - P/E MADE INSPECTION OF POPE & WEIGEL.		
0640	ALL SECURE ON BOTH SHIPS.		
0650	ALL SECURE ^{P/O} - P/E MADE INSPECTION OF POPE & WEIGEL.		
0650	ALL SECURE ON BOTH SHIPS.		
0630	WATCH RELIEVED BY ORR ^{P/B}		
0640	1/0 ABOARD		
0715	1/0 ASHORE		
0730	TEST OF SMOKE DETECTING + FIREALARMS COMPLETED SATISFACTORILY MR. SKOVOTH 1/0 (0800-1600) ORR-GWT FRUTAZ - F/W		
0800	MOORED AS BEFORE. COLORS		
0903	CAPTAIN HASKELL ABOARD		
1000	ROUTINE WATCH. ALL SECURE.		
1110	CAPTAIN ASHORE.		
1200	ALL IN APPARENT GOOD ORDER		
1300	ROUTINE WATCH. ALL IN GOOD ORDER.		
1400	ALL IN GOOD ORDER		
1430	WATCH RELIEVED BY PAT LARKIN ^{P/B} - MR MASTERS ^{P/E} ABOARD.		
1445	MR MASTERS ^{P/ENG} MR BURGE ^{P/O} ON BD Sec. On		
1500	F/W'S REPORT SECURE.		
1515	1/0 ASHORE, SHORE LEAVE COMMENCED.		
	1600-2400		
	MR BURGE ^{P/O} MR MASTERS ^{P/ENG} LARKIN ^(G) DAVACOL + PELETI (WEIGEL)		
1600	F/W'S REPORT ALL SECURE RDS MADE. (PUSHER ASHORE)		
1700	SECURITY RDS MADE ^{P/O} CHECKED BOTH SHIPS CONDITIONS NORMAL. LINES + GANGWAYS SECURE.		
1800	F/W'S REPORT SECURE.		
1900	P/O + P/ENG CHECK POPE + WEIGEL AT (1930) ALL IN GOOD ORDER.		
2000	RDS MADE ALL IN GOOD ORDER.		
2030	COLORS EXECUTED - R/MAK + ENG. CHECK WEIGEL.		
2100	RECEIVED REPORTS FROM WEIGEL + POPE SECURE IN GOOD ORDER.		
2200	CELADA IN. F/W RELIEVED.		
2230	WATCH RELIEVED BY BUNDY ^{P/B}		
2235	P/E MR. SPECTOR ABOARD - MR. MASTERS ASHORE		
2250	P/O MR BARRETT ABOARD - MR. BURGE ASHORE		
2300	F/W - BOTH VESSELS - MAKING HRLY. RDS - ALL SECURE		
	R. Bundy		

TIME	REMARKS
	0000-0800
0000	R/O MR. BARRETT- R/E MR. SPECTOR- BUNDY G/W- CELADA F/W (POPE) FRUTAZ F/W (WEIGEL) G.WY.-LIGHTS- LINES- RAT GUARDS- ALL IN GOOD ORDER. F/W- BOTH VESSELS- REPORT ALL SECURE.
0100	R/O + R/E MAKE INSPECTION- BOTH VESSELS- F/W- REPORT- ALL SECURE
0200	F/W- BOTH VESSELS REPORT- ALL IN APPARENT GOOD ORDER
0300	R/O + R/E ROUTINE INSP. BOTH VESSELS- F/W- REPORT- ALL SECURE
0400	F/W- BOTH VESSELS- REPORT- ALL SECURE
0500	R/O + R/E MAKE INSPECTION BOTH VESSELS- F/W- REPORT- ALL SECURE
0600	F/W- BOTH VESSELS- REPORT ALL SECURE J. JACKSON A.B. CALLED IN SICK
0630	WATCH RELIEVED BY ORR. R. Bundy
0700	R/O + R/E MADE ROUTINE INSPECTIONS. ALL IN GOOD ORDER. MR BARRETT R/O MR SPECTOR R/E (0800 - 1600) ORR- GANWAY MATED- FIREWATCH POPE WEIGEL
0800	MOORED AS BEFORE. LINES, GANWAY + RATEGUARDS SECURE. COLORS EXECUTED.
0900	R/O + R/E MADE ROUTINE INSPECTIONS
1000	ALL IN APPARENT GOOD ORDER
1015	MR. MASTERS R/E ABOARD - MR SPECTOR ASHORE.
1100	MR BURGE R/O ABOARD - MR. BARRETT ASHORE
1200	ALL SECURE. R/O + R/E COMPLETE TOUR OF BOTH VESSELS
1300	ALL SECURE
1400	R/O + R/E MAKING INSPECTIONS
1415	WATCH RELIEVED BY LARRY PERKINS R/B Geo. On
1415	WATCH ASSUMED - ON watch - Perkins G/W: DOVACO P/W, POPE; PELLETI F/W Weigel LINES- RAT GUARDS, SECURE- MR. BURGE R/O: MR. MASTERS R/E- ALL IN GOOD ORDER
1500	F/W BOTH VESSELS ON DETEX ROUNDS- HOURLY REPORTING- ALL'S WELL- (SOUNDINGS TAKEN) MR BURGE R/O MR. MASTERS R/E (1600-2400) Perkins G/W DOVACO P/W POPE- PELLETI F/W Weigel
1600	R/O + R/E ON ROUNDS BOTH VESSELS- all in good order F/W BOTH VESSELS ON DETEX ROUNDS- REPORT- all in good order
1700	F/W'S REPORT- all in good order -
1800	R/O on rounds both vessels - all in good order
1900	R/E + F/W - ON ROUNDS BOTH VESSELS - all in good order
2000	F/W ON BOTH VESSELS- report- all in good order
2029	2029 Sunset - colors observed
2100	all in apparent good order- both vessels R/O on rounds both vessels
2210	Watch relieved by Bundy A/B
	L.M. Perkins
2215	R/E MR. SPECTOR ABOARD - MR. MASTERS ASHORE
2240	R/O MR. BARRETT ABOARD - MR BURGE ASHORE
2300	F/W- BOTH VESSELS- MAKING HRLY. RDS - ALL SECURE R. Bundy

AT/PASSAGE FROM

TO

PIER 2 - BERTH 30 - HUNTERS POINT NAVAL SHIPYARD - SAN FRANCISCO

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

#7

20-JULY-1969

SUNDAY

TIME	REMARKS
	0000-0800
	R/O MR BARRETT - R/E MR. SPECTOR - BLINDY F/W - CELADA F/W (POPE) FRUTAZ F/W (WEIGEL)
0000	G.W.Y. - LIGHTS - LINES - RAT GUARDS - ALL IN GOOD ORDER. F/W BOTH VESSELS - REPORT ALL SECURE
0100	R/O + R/E MAKING Rds. BOTH VESSELS - F/W REPORT - ALL SECURE
0200	F/W BOTH VESSELS - REPORT - ALL IN GOOD ORDER
0300	R/O + R/E MAKE ROUTINE INSP. BOTH VESSELS - F/W REPORT ALL SECURE
0400	F/W BOTH VESSELS - REPORT - ALL IN ORDER
0500	R/O - R/E MAKE Rds. BOTH VESSELS - F/W REPORT - ALL SECURE
0600	F/W BOTH VESSELS - REPORT - ALL SECURE
0630	WATCH RELIEVED BY ORR
	R. Bundy
0700	R/O + R/E MADE ROUTINE INSPECTIONS OF BOTH VESSELS. MR. BARRETT R/O (0800-1600) ORR - GANWAY MATED - FIREWATCH MR. SPECTOR R/E
0800	MOORED AS BEFORE. COLORS EXECUTED.
0900	R/O + R/E MADE ROUTINE INSPECTIONS
1000	ALL SECURE
1020	MR HURLEY R/E ABOARD MR. SPECTOR ASHORE.
1055	MR. BURGE R/O ABOARD MR. BARRETT ASHORE.
1100	R/O + R/E MADE INSPECTIONS
1200	ALL IN APPARENT GOOD ORDER
1300	ALL SECURE
1317/40	MEN ON THE MOON
1415	WATCH RELIEVED BY EARTHMAN LARRY PERKINS Geo. On
1415	watch assumed - LINES - RAT GUARDS - all in good order - sounding taken
1500	DAVACO F/W, POPE + FRUTAZ F/W WEIGEL; ON DETEX BOUNDS - HOURLY REPORTING MR. BURGE R/O (1600-2400) PERKINS R/O; DAVACO F/W POPE; FRUTAZ F/W WEIGEL MR. HURLEY R/E
1600	R/E ON BOUNDS BOTH VESSELS - F/W BOTH VESSELS - REPORT - ALL IN GOOD ORDER (R/O ON BOUNDS)
1700	F/W BOTH VESSELS REPORT - all in good order
1800	all in apparent good order - F/W report - all secure
* 2000	all in apparent good order - F/W report - all in good order
* 2028	SUNSET - colors observed - R/O ON BOUNDS BOTH VESSELS - all in good order
* 2000	Approx. time of "MAN'S FIRST STEP ON THE MOON"
2100	R/E ON BOUNDS BOTH VESSELS - all in good order
2200	all in apparent good order
2210	MR SPECTOR R/E ABOARD - MR. HURLEY R/E ASHORE
2215	watch relieved by Frutaz
	L. D. Perkins