

AT/PASSAGE FROM		TO	
PIER 2 - BERTH 33 - HUNTER'S POINT		NAVAL SHIPYARD - SAN FRANCISCO	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		8 - NOV - 69	SATURDAY
TIME	REMARKS		
	R/O MR. KENNEY R/E MR. SPECTOR 0000 - 0800 F/W IREDALE - GWY, BUNDY		
0000	R/O + F/W TO WEIGEL FOR SECURITY RND. - ALL SECURE		
0100	F/W ROUND RTE "B" POPE - ALL SECURE		
0200	F/W ROUND RTE "B" WEIGEL - ALL SECURE		
0300	F/W ROUND RTE "A" POPE - ALL SECURE		
0400	F/W ROUND RTE "A" WEIGEL - ALL SECURE		
0500	F/W ROUND RTE "B" POPE - ALL SECURE		
0600	F/W ROUND RTE "B" WEIGEL - ALL SECURE		
0615	WATCH RELIEVED BY PERKINS R/O R. Bundy		
	MR. KENNEY R/O MR. SPECTOR R/E (0800 - 1600) PERKINS - GANWAY - PLETI FIREWATCH		
0700	F/W MADE DETEX ROUND "A" Detex. Pope all in good order		
0750	F/W TO WEIGEL ON DETEX ROUNDS - all in good order - "A" ROUTE		
0800	COPIES - PROPERLY OBSERVED		
0900	F/W MADE ROUTE "B" - DETEX. All in apparent good order		
1000	F/W TO WEIGEL ON "B" ROUTE All in apparent good order		
- do -	MR. LINDBERG R/E ABOARD - MR. SPECTOR R/O ASHORE		
1045	MR. SHERMAN R/O ABOARD - MR. KINNEY ASHORE		
1100	F/W ON "B" ROUTE POPE		
1200	Soundings taken - R/O + F/W to Weigel		
1300	F/W completed "A" & "B" ROUTE ON WEIGEL		
1400	F/W ON "B" ROUTE POPE		
1415	Watch Relieved by - Geo Ore		
1415	CAPT. & MRS LANDRY ABOARD		
1445	POPE "A" ROUNDS MADE		
1540	WEIGEL "A" ROUNDS MADE MR. SHERMAN R/O MR. LINDBERG R/E (1600 - 2400) ORR --- GANWAY NIX --- FIREWATCH		
1645	POPE "B" ROUNDS MADE		
1703	COLORS SMARTLY EXECUTED BY ORR & NIX		
1745	WEIGEL "B" ROUNDS MADE. HORSWILL, VERWEEST, & MORALES ASHORE		
1915	OILER WILLIAMS TO WEIGEL POPE ROUNDS MADE		
1945	WEIGEL "A" ROUNDS MADE		
2015	CAPT. & MRS. LANDRY ASHORE		
2100	POPE "B" ROUNDS MADE		
2145	WEIGEL "B" ROUNDS MADE		
2200	MR. SPECTOR R/E RELIEVES MR. LINDBERG		
2225	WATCH RELIEVED BY LARKIN Geo. Ore		
2230	RELIEVED AND ASSUMED THE WATCH, IN APPARANT GOOD ORDER		
2300	F/W JACKSON ON "A" RD. WEIGEL, 2305 R/O KINNEY ON BD.		
2320	MR KINNEY ON BD, MR SHERMAN RELIEVED		

CELERY HEARTS

DILL PICKLES

RIPE OLIVES

CLAM CHOWDER

SALTINE CRACKERS

HEARTS OF LETTUCE

CRAB COCKTAIL

ROAST PRIME RIBS AU JUS

GRILLED SEA BASS WITH BUTTER SAUCE, LEMON WEDGE

COLD CUTS WITH POTATO SALAD

BAKED IDAHO POTATOES

WHITE FLUFFY RICE

ASPARAGUS TIPS

GREEN BEANS

POPPY SEED ROLLS

BUTTER

BLUE CHEESE

SALTINE CRACKERS

CHILLED PRESERVED FRUIT

APPLE PIE A LA MODE

CHILLED FRUIT JELLO

COFFEE

TEA

COCOA

FRESH MILK

PHIL DATTOLA
CHIEF STEWARD

R. E. LANDRY
MASTER

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 NAVAL SHIPYARD		SAN FRANCISCO BAY, HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		8 TH NOV - 1969	SUNDAY
TIME	REMARKS		
	R/DO MR KINNEY F/W JACKSON R/ENG MR SPECTOR 0000 - 0800 (G) LARKIN		
2400	JACKSON F/W ON DETEX RD WEIGEL, OILER (POPE) TO WEIGEL E/R		
0030	F/W + OILER REPORT WEIGEL SECURE ENG RMS + LIVING AREAS BRIDGE + AFT STRG.		
0100	ROUND MADE DETEX POPE		
0200	ROUND MADE OF WEIGEL, ALL SECURE.		
0300	RD. OF POPE MADE, FOUND ALL SECURE.		
0400	F/W JACKSON REPORTS ALL SECURE ON WEIGEL.		
0500	DETEX RDS. MADE, ALL IN GOOD ORDER, SECURE		
0600	F/W TO WEIGEL FOR SECURITY RD.		
0615	REPORT RECEIVED ALL SECURE.		
0630	WATCH RELIEVED BY		
0620	RDO MR KINNEY PATROL C. Larkin MR SPECTOR REL 0800 - 1600 NIX-GUY ARR F/W ORR F/W		
0620	ASSUMED WATCH - ALL IN APPARENT GOOD ORDER.		
0700	DETEX ROUND MADE ON POPE.		
0800	COLORS: DETEX ROUND MADE ON WEIGEL.		
0830	SOUNDINGS TAKEN.		
0900	DETEX ROUND MADE ON POPE.		
1000	DETEX ROUND MADE ON WEIGEL.		
1005	MR LINDBERG R/E RELIEVES MR. SPECTOR		
1045	MR SHERMAN (RDO) ABOARD TO RELIEVE MR KINNEY.		
1100	DETEX ROUND MADE ON POPE.		
1200	DETEX ROUND MADE ON WEIGEL. ALL IN APPARENT GOOD ORDER.		
1300	DETEX ROUND MADE ON POPE.		
1400	DETEX ROUND MADE ON WEIGEL.		
1410	WATCH RELIEVED BY FREDALE & BUNDY.		
1410	Mr. Sherman, RDO (1600 - 2400) Bundy, F/W. FREDALE, G/W		
1410	Assumed the watch.		
1500	F/W making detex "A" round in Pope. Reports all well.		
1600	Detex "A" round in Weigel - All secure - RDO accompanying -		
1702	Sunset - Evening colors observed -		
1715	Detex round - route "B" made - All secure		
1800	Detex "B" round in Weigel - All secure - Sounding Taken in Weigel -		
1900	Detex "A" round in Pope - All's well.		
2000	Detex round "A" made in Weigel w/ RDO - All secure		
2100	Detex round "B" made in Pope - All secure		
2200	Detex round "B" made in Weigel - A-OK -		
2205	Mr Spector, R/E ABOARD - Mr Lindberg takes		
2225	watch relieved by LARKIN, A/B		
2235	MR KINNEY R/DO ON BD. J Fredale		
2300	MR SHERMAN LEFT SHIP.		
2334	F/W REPORT A RTE POPE SECURE		

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 SAN FRANCISCO BAY		NAVAL SHIPYARD HUNTERS POINT.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		10 NOVEMBER 1969	MONDAY
TIME	REMARKS		
	RDO KINNEY (G) LARKIN R/ENG. SPECTOR 0000 - 0800 (F) JACKSON		
2400	F/W LEAVES FOR DETEX RD WEIGEL. 0030 Oiler To WIEGEL.		
0100	REPORT RECEIVED, ENG. RMS INITIAL SECURE -		
0200	POPE REPORTED SECURE. BY F/W.		
0215	F/W TO WIEGEL FOR DETEX RD OF SAHA		
0300	SECURITY RD MADE POPE, ALL SECURE.		
0400	DETEX ROUND ON WIEGEL, ALL SECURE.		
0500	SECURITY RD. MADE, ALL SECURE.		
0600	SECURITY WATCH TO WIEGEL, FOR DETEX RD. & VNUOI		
	CHECK OF ALL AREAS (CHECK BOATSWAIN) FOR CALL.		
0630	WIEGEL REPORTED, AS SECURE GOOD ORDER.		
0630	WATCH RELIEVED BY BOATSWAIN 0610 2ND ENCON RD R/ENG ASHORE		
0630	AGLIALO, FRANCESCO C 17801 (BAKER) STW. DEPT. ABOARD		
	FOR DUTY.		
0635	WATCH RELIEVED BY MR KINNEY RDO FOR BILL MEAL.		
	MACHINIST GENOVIA, ALBERT S. CALLED IN SICK UNABLE		
	TO COME TO WORK.		
0645			
	0800 - 1600		
0645	Watch Relieved - ON WATCH MR WAYNE 1/0 SINDWITAB		
0700	DETEX ROUND ON WIEGEL ALL SECURE		
0720	CH STEWARD ASHORE		
0800	COLORS EXECUTED		
0815	CAPTAIN COME ABOARD		
0815	DETEX ROUND MADE ON POPE ALL SECURE		
0925	CH STEWARD ABOARD		
0930	Detex A Round on Weigel All Secure		
1000	" B " " " Pope All Secure		
1225	CAPTAIN ASHORE		
1200 x	DETEX ROUND "A" - ON POPE - ALL SECURE		
1200 x	" " " "A" ON WIEGEL ALL SECURE		
1400	DETEX ROUTE "B" ON POPE ALL SECURE		
1415	WATCH RELIEVED BY BUNDY		
	A. Anderson ABW		
1440	MASTER ABOARD		
1450	R/O MR. SHERMAN ABOARD.		
1500	F/W DETEX Rnd. "A", POPE - 1/0 MR. WAYNE ASHORE - STOPPED LOADING RAFTS		
1545	F/W TO WIEGEL DETEX RND "A", TUG Y.E. 116 AWAY - ALL SECURE		
	R/O MR. SHERMAN (1600 - 2400) BUNDY GWY - TREDALE F/W		
1701	SUNSET. COLORS EXECUTED - F/W ROUND RTE "B" POPE. ALL SECURE		
1800	F/W ROUND RTE "B" WIEGEL - 1/0 INSPECTION RND WIEGEL - ALL SECURE		
1900	Bundy assumes F/W duties - "A" Round in Pope. All secure		
2000	RDO & F/W TO Weigel on "A" round. Report all secure		
2100	Detex round "B" made in Pope - All secure		
2130	Capt. + Mrs. Landry depart vessel.		
2200	Detex Rd. "B" in Weigel. All secure. Mr Spector, R/E AOD. Mr Hurley away.		
2230	Watch relieved by Perrins, A/B		

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 San Francisco Naval Shipyard - Hunters Point			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		11-November-60	Tuesday
TIME	MR KENNEY RD IN SPECTOR	REMARKS	PERKINS
2230		Watch assumed - All-in Apparent good order	
0000		FW-ON DETEX ROUNDS ALL-SECURE - "A" ROUTE	
0100		FW-ON DETEX ROUNDS WEIGEL "A" ROUTE	
0200		FW-ON "B" ROUTE POPE - Oiler made rounds on WEIGEL	
0300		FW-ON "B" ROUTE WEIGEL	
0400		FW-ON "A" ROUTE POPE	
0500		FW-ON WEIGEL "POW" "A" & "B"	
0600		FW-completed Rounds	
0600		morning calls made - watch called-	
0620		Watch relieved by Bundy	
			Perkins
	R/O MR. KENNY R/E MR. SPECTOR	0800-1600 BUNDY, GWY, TREDALE, F/W	
0620		ASSUMED WATCH ALL IN APPARENT GOOD ORDER	
0700		F/W ROUND RTE "A" POPE, ALL SECURE	
0800		COLORS EXECUTED - F/W ROUND RTE "A" WEIGEL - SOUNDINGS TAKEN	
0845		TRANS-BAY ELECT. CONTRACTOR ABD. (P.A. SYSTEM) (ASHORE 1015)	
0900		F/W ROUND RTE "B" POPE - ALL SECURE	
1000		R/E MR HURLEY RELIEVES MR. SPECTOR - F/W RND RTE "B" WEIGEL - ALL SECURE	
1100		CAPTAIN & MRS. LANDRY ABOARD - F/W RND RTE "A" POPE	
		KRABBENSCHMIDT TO ABD. RELIEVES MR. KENNY	
1130		R/E TO WEIGEL ROUTINE INSPECTION	
1200		F/W DETEX ROUND WEIGEL - ALL SECURE	
1250		R/O TO WEIGEL - ROUTINE INSP. - ALL SECURE	
1300		F/W ROUND RTE "B" POPE - ALL SECURE	
1400		F/W ROUND RTE "B" WEIGEL - ALL SECURE	
1435		WATCH RELIEVED BY JACKSON #1B MASTER ASHORE R Bundy	
	R/O MR. KRABBENSCHMIDT R/E MR. HURLEY	(1600 - 2400) JACKSON JF GANAWAY LARKIN FIREWATCH	
1435		ASSUMED THE WATCH ALL IN APPARENT ORDER	
1530		WATCH MAKING ROUNDS ON POPE A & B	
1600		WATCH RELIEVED FOR CHOW	
1620		WATCH RETURN FROM CHOW	
1705		SUNSET COLORS EXECUTED	
1720		F/W WENT TO WEIGEL MADE A & B ROUNDS	
2000		F/W MADE ROUNDS ON POPE A & B ROUNDS	
2100		MR. SPECTOR ABOARD RELIEVES MR. HURLEY	
2135		WATCH RELIEVED by PELETI	
2200		F/W & R/O Completed security Round "A" & "B" Route Weigel	
2235		Captain MR LANDRY & MRS LANDRY ASHORE.	Joseph Jackson

AT/PASSAGE FROM		TO	
PIER 3 BERTH #33 HUNTERS Point		NAVAL SHIP YARD SAN FRANCISCO. CALI	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		12 NOVEMBER 1969	WEDNESDAY
TIME	REMARKS		
	R/O MR SPECTOR R/O MR KRABBERS SHERMAN 0000 - 0800 PELETI GAVENAY PERKINS F/W WATCH ASSUMED ALL IN APPARENT GOOD ORDER		
2300	F/W ROUND MADE POPE ROUTE "A" ALL SECURE		
2330	R/O MR SHERMAN ABOARD RELIEVED MR KRABBENSCHMIDT		
0000	F/W ROUND RTE "A" WEIGEL ALL SECURE.		
0100	F/W Round RTE "B" POPE ALL SECURE		
0200	F/W Round RTE "B" WEIGEL ALL SECURE		
0300	F/W Round RTE "A" POPE ALL SECURE		
0400	F/W Round RTE "A" WEIGEL ALL SECURE		
0500	F/W Round RTE POPE "B" ALL IN APPARENT GOOD ORDER		
0530	F/W Completed Security Round on Pope of all Complment ALL SECURE		
0610	WATCH RELIEVED by NIX		
	Pelet APB - MR WAYNE 10 0800 - 1600 NIX - GW ORR - FW 0610 ASSUMED WATCH - ALL IN APPARENT GOOD ORDER. MR THOMPSON 2 nd ASST ENG. RELIEVED MR SPECTOR R/O 0635 CHIEF STEWARD & PURSER ABOARD. 0650 MR WAYNE FIRST OFFICER ABOARD. 0720 CH. ENGINEER ABOARD. POPE DETEX ROUNDS MADE 0721 TEST OF ALARM SYSTEMS O.K. 0800 COLORS OBSERVED. DETEX Round MADE ON WEIGEL. 0820 MASTER ABOARD. 0900 DETEX Round ON POPE. ALL IN APPARENT GOOD ORDER. 1000 DETEX Round ON WEIGEL. ALL IN APPARENT GOOD ORDER. 1100 DETEX Round ON POPE. ALL IN APPARENT GOOD ORDER. 1200 DETEX Round ON WEIGEL. ALL IN APPARENT GOOD ORDER. 1300 DETEX Round ON POPE. ALL IN APPARENT GOOD ORDER. 1350 MR HURLEY R/O ABOARD. 1400 DETEX Round ON WEIGEL. ALL IN APPARENT GOOD ORDER. 1420 WATCH RELIEVED BY LARKIN 1500 F/W JACKSON MADE A/RD. 900 ON BD KEARNEY MR KRABBENSCHMIDT R/O MR HURLEY R/O 600 - 2400 LARKIN (E) JACKSON (E) 1515 A/RD MADE ON POPE - F/W REPORTS SECURE (1630) 1600 A/RD MADE ON WEIGEL - F/W REPORT SECURE (1630) 1630 RELIEVED BY R/MATE FOR MEAL (1605 - 1625) 1700 (1635) RELIEVED BY MATE FOR COLORS - EXECUTED CLOCKS CORRECTED. 1800 F/W TO WEIGEL FOR R/O - DETEX CLOCKS. 1835 F/W RETURNS WEIGEL SECURE. 1832 MASTER LEFT SHIP. R/O TO WEIGEL. 1900 F/W COMMENCED A/RTE DETEX CLOCKS - F/W REPORTS ALL SECURE (2150) 2000 F/W JACKSON TO WEIGEL FOR A/RD. (2450) 2035 F/W RETURNS FROM WEIGEL, COMPLETED A ROUND SHIP IS SECURE IN FND AREA 2100 F/W COMMENCED B/RD. POPE. - 2135 F/W REPORTS SECURE. (AFT AREA) 2200 F/W + R/O TO WEIGEL. FOR B/RD. 2230 WATCH RELIEVED BY NIX + ORR. 2245 MR SHERMAN ABOARD 2250 MR SPECTOR ABOARD P. Larkin NOTE JACK IS F/W - ATTACHED FOR COLORS. KEYS TO BAKER IN ENVELOPE. CALL BOATSWAIN.		

AT/PASSAGE FROM		TO	
P. I. E. #2 BERTH #33 HUNTERS PT		NAVAL SHIPYARD S.F. CALIF.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
		13 NOVEMBER 1969	THURSDAY
TIME	REMARKS		
	MR SHERMAN R/O MR SPECTOR R/E (0000 - 0800) ORR - GANGWAY NIX - FIREWATCHER		
2245	ASSUMED WATCH. ALL IN APPARENT GOOD ORDER.		
2300	DETEX ON POPE. MR WILLIAMS SHERMAN ABOARD.		
0000	DETEX ROUND ON WEIGEL - ALL IN APPARENT GOOD ORDER.		
0100	DETEX ROUND ON POPE. ALL IS WELL.		
0200	DETEX ROUND ON WEIGEL. ALL IN APPARENT GOOD ORDER.		
0300	DETEX ROUND ON POPE. ALL IS WELL.		
0400	DETEX ROUND ON WEIGEL. ALL IS SWELL.		
0500	DETEX ROUND MADE ON POPE --- ALL IS FINE.		
0600	DETEX ROUND MADE ON WEIGEL - A-OK.		
0600	LARKIN ^{ABM} CALLED IN SICK. MR SHERMAN NOTIFIED		
0602	GARDE, ALFREDO CALLED IN SICK		
0610	MR THOMPSON 2 ND ENG. RELIEVES MR. SPECTOR R/E.		
0625	WATCH RELIEVED BY JOE JACKSON. <i>Geo. Orr</i>		
	(0800 - 1600) JACKSON J.F. GANGWAY SINDONI A. FIREWATCH		
0625	ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER		
0635	MASTER ON BOARD		
0655	WATCH RELIEVED FOR CHOW		
0700	MR SHERMAN R/O ASHORE		
0720	WATCH RETURN FROM CHOW		
0723	TESTED FIRE AND SMOKE DETECTOR AND ON WEIGEL		
0800	COLOR OBSERVED. SINDONI MAKING F/W		
	WATCH ROUNDS ON WEIGEL ALL SECURE		
0800	F/W MADE ROUNDS ON GEN. POPE ALL SECURE		
0945	F/W TO WEIGEL FOR DETEX ROUNDS.		
0950	FRIST OFF ON BOARD		
1050	WATCH RELIEVED FOR NOON MEAL		
1120	WATCH RETURN FROM NOON MEAL		
1125	SHIPS BOATSWAIN RETURN FROM SPECIAL SERVICE WITH TELEVISION.		
1200	F/W MADE ROUNDS ON POPE ALL SECURE		
1200	F/W ROUND MADE ON WEIGEL ALL SECURE		
1300	F/W ROUND MADE ON POPE ALL SECURE		
1400	FW ROUND MADE ON WEIGEL ALL SECURE		
1410	MASTER ASHORE		
1415	WATCH RELIEVED BY PERKINS		
1415	ASSUMED - THE WATCH - ALL IN APPARENT GOOD ORDER		
1500	MR KELLOG R/O - F/W ON "A" ROUTE - MR WAYNE ^{OK} ASHORE - PERKINS - FIREWATCH MR KELLOG R/O - (1600 - 2400) PERKINS - FIREWATCH MR HURLEY R/E - PERKINS - GANGWAY		
1600	F/W - MADE "A" ROUTE - LANS - WEIGEL - HAVE ELECTRICAL LAMP - 6- ^{OK} 71		
1700	F/W ON "B" ROUTE - POPE - SUNSET - COLORS OBSERVED		
1800	F/W "B" RTE WEIGEL - CWF REEFER - TESTED REEFER Bx - bell - ALARM SYSTEM - ^{Good} ORDER		
1820	F/W RETURN FROM ROS ON WEIGEL - ALL SECURE		
1900	F/W ON "A" ROUTE POPE - REPORTS ALL SECURE		
1920	R/O KELLOGG TO WEIGEL - ON - ROUNDS OF INSPECTION		
1945	R/O - RETURNS FROM ROUNDS ON WEIGEL - ALL IN - GOOD ORDER		
	B Keys for BAKER ON CLIP BOARD AT GANGWAY - CONT.		

AT/PASSAGE FROM <i>Glen #2 - BERTH #33 - HUNTER'S POINT NAVAL SHIPYARD - SAN FRANCISCO</i>	TO <i>San Francisco</i>
ZONE DESCRIPTION <i>17</i>	DATE (Day, month, year) <i>13-NOV-'69</i>
	DAY OF WEEK <i>THURSDAY</i>

TIME	REMARKS
	MR. KELLOGG RDO MR. HURLEY RDO <i>(1600-2400) CONT.</i> <i>PERRIN 8-GRANBURY</i> <i>DELET - FIREWATCH</i>
<i>2000</i>	<i>FLW TO WEIGEL ON DETEX RDS.</i>
<i>2040</i>	<i>FLW RETURN "A" & "B" RDS MADE ON WEIGEL</i>
	<i>ALL-IN-APPARENT good order</i>
<i>2100</i>	<i>FLW ON "B" RTE - POPE - R/O to WEIGEL ROUTINE INSP.</i>
<i>2130</i>	<i>RDO - RETURNED FROM INSP of WEIGEL</i>
	<i>ALL-IN-GOOD ORDER ABOARD WEIGEL</i>
<i>2200</i>	<i>MR. SPECTOR R/E ABOARD</i>
<i>- do -</i>	<i>MR. HURLEY R/E ASHORE</i>
<i>2225</i>	<i>WATCH RELIEVED BY FREDALE</i>
	<i>S. M. Perkins</i>

AT/PASSAGE FROM SFB N S. Hunters Point	to Pier 2 - Berth 33
ZONE DESCRIPTION +7	DATE (Day, month, year) 14 NOV 69
	DAY OF WEEK FRI -

TIME	REMARKS
	MR Sherman, RDO (0000-0600) Bundy, F/W - IREDALE, F/W
2225	Assumed the watch - Conditions normal -
2300	DeTex round "A" made in Pope. All secure -
0000	RDO & F/W away TO Weigel - security patrol - A rt. all secure
0100	DeTex "B" round made in Pope. - All secure
0200	DeTex "B" round made in Weigel - All's well -
0300	DeTex "A" round made in Pope. All secure -
0400	RDO & F/W away TO Weigel - Notes "A" route all secure
0500	DeTex "B" round made in Pope. All's well -
0550	MATED, J: ABM (167-5) called in sick - Will not be in Today.
0600	DeTex "B" round made in Weigel - All secure
0600	Watch relieved by Nix, A/B
0600	GARDE, ABM, phoned in sick - Will not be in Today.
	MR. WAYNE 1/0 (0800 - 1600) ^{MR NIX = GNY} ^{MR ORR = F/W}
0600	ASSUMED WATCH - All in APPARENT GOOD ORDER.
0600	MR. THOMPSON ON BOARD (1st ASST) - MR SPECTER ASHORE.
0635	CHIEF STEWARD ABOARD. PURSER ABOARD.
0645	1/0 MR WAYNE ABOARD
0700	1/0 SHERMAN ASHORE. DAYWORKERS TURN-TO.
0712	SMOKE DETECTOR & KIDDE ALARMS TESTED - ---- O.K. (POPE)
0715	NIX MAKING DETEX ROUNDS "A" ROUTE POPE
0720	CH. ENGINEER ABOARD
0727	SMOKE DETECTOR & KIDDE ALARMS ON WEIGEL TESTED - ---- O.K.
0800	COLORS: DETEX "A" ROUNDS MADE ON WEIGEL
0837	1/0 TO WEIGEL 0905 RETURNS
0900	POPE "B" ROUNDS MADE
0920	MASTER ABOARD.
1000	DETEX ROUND ON WEIGEL.
1045	2 TELEPHONE MEN ABOARD TO INSTALL PAY PHONE.
1100	DETEX ON POPE. All in APPARENT GOOD ORDER.
1125	CHIEF REEFER FR DONALDSON ABOARD.
1200	DETEX ROUNDS "A" ROUTE MADE ON WEIGEL
1300	DETEX ROUNDS - B ROUTE MADE ON POPE
1335	J. RINGS OILER ABOARD. (POOL)
1345	MASTER ASHORE.
1400	WEIGEL "B" ROUNDS MADE.
1400	TELEPHONE MEN ASHORE. MR HURLEY REO ABOARD.
1430	WATCH RELIEVED BY PALETI.
1450	CIENG ASHORE.
1455	1/0 ASHORE

Ray M. Nix

AT/PASSAGE FROM
 PIER 2 BERTH #33 HUNTERS POINT
 ZONE DESCRIPTION
 +7

NAVAL SHIP YARD S. FRANCISCO. CALIF

DAY OF WEEK

14 NOVEMBER 1969 FRIDAY

26

AT/PASSAGE FROM
PIER 2 BERTH 33 HUNTER'S POINT, NAVAL SHIPYARD, SAN FRANCISCO, CA.
 ZONE DESCRIPTION
+7

TO
 DATE (Day, month, year)
15-NOV-69
 DAY OF WEEK
SATURDAY

TIME	REMARKS
	R/O MR. SHERMAN R/O MR. LINDBERG 0000-0800 BUNDY GWY. - TREDALE F/W
0000	F/W ROUND RTE "A" POPE - ALL IN APPARENT GOOD ORDER.
0100	R/O + F/W TO WEIGEL - SECURITY PATROL - ALL WELL ON "B" RTE.
0200	F/W ROUND - RTE "B" POPE - ALL SECURE
0300	F/W ROUND - RTE "A" - WEIGEL - ALL SECURE
0400	F/W ROUND - RTE "A" - POPE - ALL SECURE
0500	R/O + F/W TO WEIGEL - SECURITY ROUND - ALL WELL ON "B" RTE.
0600	F/W ROUND - RTE "B" POPE - ALL SECURE
0630	WATCH RELIEVED BY PERKINS A/B R. Bundy
0630	WATCH ASSUMED - ALL IN APPARENT GOOD - RELIEF OFFERS AS ABOVE
0700	PELETI F/W - TO WEIGEL ON DETEX RDS - PERKINS AT GANGWAY "A".
0800	MR SHERMAN A/B MR LINDBERG (0800-1600) PERKINS - GANGWAY PELETI - FIREWATCH
0800	COLORS PROPERLY EXCUTER - F/W ON DETEX "A" RTE ON POPE - ALL SECURE
-00-	SOUNDINGS - TAKEN - ON POPE
0900	F/W TO WEIGEL "B" RTE AND SOUNDING - ALL SECURE - R/O TO WEIGEL ON INBP RDS
0930	MR HURLEY R/O ABOARD
1000	F/W ON "B" RTE POPE - MR. LINDBERG R/O ASHORE
1030	DRIGGER 2 REFER ENG - ABOARD 1200-2000 WATCH
1100	F/W ON WEIGEL ON "A" RTE - MR KELLOGG R/O ABOARD MR. SHERMAN ASHORE
	CEREMONIES IN PROGRESS ON DOCK - TRANSFER OF DESTROYER
1145	CEREMONIES COMPLETED - DOCK AREA COMPLETELY CLEAR
1200	F/W ON RDS "A" ON POPE - ALL SECURE
1230	F/W ON "B" RTE POPE - ALL SECURE
1245	CAPT. LANDY + MRS. ABOARD
1300	F/W TO WEIGEL - "B" RTE - ALL IN APPARENT GOOD ORDER -
1400	ALL SECURE -
1430	WATCH RELIEVED BY OPE
1500	DETEX ROUNDS "A" MADE ON POPE L M Perkins
1520	MASTER'S GUESTS ABOARD
1600	DETEX ROUND ON WEIGEL, "A" ROUTE MR KELLOGG R/O MR HURLEY R/O (1600-2400) MR ORR - GANGWAY MR NIX - FIREWATCH
1658	COLORS OBSERVED.
1700	DETEX ROUNDS "B" MADE ON POPE. ALL IN GOOD ORDER - ... APPARENTLY.
1800	DETEX ROUNDS "B" MADE ON WEIGEL. ALL SECURE.
1845	MASTER'S GUESTS ASHORE.
1900	POPE DETEX ROUNDS ("A") MADE. ALL IN ORDER.
1925	CAPTAIN + MRS. LANDRY ASHORE
2000	Small Craft warnings for next 12 hours. Mr Harley relieved by duty REP. DETEX ROUNDS ON WEIGEL
2100	POPE DETEX ROUNDS MADE
2200	MR HURLEY R/O RELIEVED BY MR. LINDBERG
2200	WEIGEL DETEX ROUNDS MADE.
2230	WATCH RELIEVED BY PAT LARKIN Geo. Orr
2300	F/W JACKSON ON "A" RD WEIGEL + POPE (POPE) F/W REPORT "A" RD (1/2) POPE IS SECURE. DETEX CLOCK PUNCHED 21 STATIONS.
2335	R/MATE SHERMAN ON RD, R/MATE KELLOGG LEFT SHIP

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL SHIPYARD		HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		16 NOV 1969	SUNDAY
TIME	REMARKS		
	MR SHERMAN RDO 2400-0800 LARKIN (G) MR KELLOGG R/D O JACKSON F/W		
2400	F/W JACKSON & R/MATE SHERMAN TO WEIGEL FOR RD.		
0135	MATE & F/W RETURN ALL SECURE WEIGEL 'A' RTE		
0140	F/W REPORTS POPE SECURE 'B' RTE		
0200	F/W TO WEIGEL FOR SECURITY RD. 'B' RTE		
0230	F/W RETURNS REPORTS WEIGEL SECURE, ALL STATIONS.		
0300	F/W MAKES ROUND OF POPE.		
0330	F/W REPORTS POPE SECURE		
0400	F/W TO WEIGEL.		
0430	F/W RETURNS REPORT WEIGEL, SECURE.		
0500	DETEx RD ON POPE. ALL SECURE.		
0600	F/W & R/D O TO WEIGEL		
0610	R/D O RETURNS FROM WEIGEL.		
0630	F/W RETURN FROM 'B' RD WEIGEL. - ALL SECURE		
0630	WATCH RELIEVED BY NIX & ORR. D Larkin		
0635	NO COFFEE, NO WATER, COOK, NO GROUNDS		
	MR SHERMAN Y O 0800 - 1600 NIX - GNY ORR - F/W		
0630	WATCH ASSUMED = NO COFFEE. NO HOT ^{WATER} FOR COFFEE. BREAKFAST ISN'T READY.		
0715	POPE DETEx ("A") ROUNDS MADE		
0740	BILGE SOUNDINGS TAKEN.		
0800	COLORS: DETEx ROUND ON WEIGEL. "A"		
0900	POPE DETEx ("B") ROUNDS COMPLETED		
1000	MR HURLEY, REO, ABOARD. DETEx ROUND ON WEIGEL. "B"		
1030	MR KELLOGG RDO ABOARD TO RELIEVE MR SHERMAN.		
1100	DETEx ROUND ON POPE.		
1200	DETEx ROUND ON WEIGEL.		
1300	DETEx ROUND ON WEIGEL.		
1340	MASTER ABOARD.		
1400	DETEx DETEx ROUND ON WEIGEL.		
1400	WATCH RELIEVED BY IREDALE & BUNDY - All is well.		
	MR Kellogg, RDO (1600 - 2400) Bundy, F/W IREDALE, F/W		
1405	Assumed the watch - All secure.		
1500	Detex "A" round made in Pope - All secure		
1500	RDO completes inspection Tour in Weigel - All's well.		
1600	Detex "A" rd. in Weigel - All secure.		
1648	Sunset - Evening colors smartly executed.		
1700	CAPT. & MR Landry ashore.		
1700	Detex "B" rd. in Pope - All secure		
1800	Detex "B" rd. in Weigel - All's well.		
1900	Detex A rd. in Pope - do -		
2000	Detex A rd in Weigel - do -		
2100	Detex B rd. in Pope do.		
2130	RDO away To Weigel -		
2200	Detex "B" Rd. in Weigel. All secure. MR SPECTOR R/S, ABB -		
2225	Watch relieved by LARKIN, A/B		

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL SHIPYARD		HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		17 NOVEMBER	MONDAY
TIME	REMARKS		
	MR SHERMAN MR SPECTOR	0000	0800
2230	RELIEVED AND ASSUMED THE WATCH. ALL IN GOOD ORDER MR SHERMAN R/O ON BD. MR KELLOG RELIEVED LEFT SHIP F/W JACKSON RELIEVED THE WATCH.		
2300	F/W ON RD'S OF POPE.		
2335	F/W REPORTS RD MADE		
2400	MR SHERMAN R/O MR SPECTOR R/O 0000 - 0800	LARRIN (G) JACKSON (F/W)	
2400	F/W + R/O SHERMAN TO WEIGEL FOR A' RD.		
0035	F/W + R/O RETURN REPORT, WEIGEL SECURE.		
0100	F/W ON DETEX RD POPE. REP POPE SECURE		
0200	F/W TO WEIGEL, REPORTS WEIGEL SECURE (0235)		
0300	F/W DETEX RD'S ON POPE. REPORTS SECURE (0330)		
0400	F/W TO WEIGEL. (0440) F/W REPORTS WEIGEL SECURE.		
0500	F/W ON RD OF POPE. 0545 F/W REPORTS SECURE.		
0510	CALLED BOATSWAIN'S CALLS MADE.		
0610	1ST/ASST ENG. ON BD. MR SPECTOR R/ENG LEFT SHIP 0615		
0630	F/W REPORTS SECURE WEIGEL		
0635	WATCH REL. BY ABM DAY WORKER D. Larkin		
0635	MR. WAYNE, /O 0800-1600	MEYER - G/W SINDONI - F/W	
0635	ASSUMED THE WATCH -		
0700	ROUND "A" ON POPE - MR. SHERMAN, /O ASHORE -		
0715	TEST OF ALARMS O/K		
0800	COLORS EXECUTED		
0800	F/W ROUND "A" ON WEIGEL		
0815	MASTER ABOARD		
0900	ROUND "B" ON POPE -		
1000	F/W ROUND "B" ON WEIGEL - MR WORKERS ABOARD		
1100	ROUND "A" ON POPE -		
1200	F/W ROUND "A" ON WEIGEL		
1300	ROUND "B" ON POPE -		
1400	F/W ROUND "B" ON WEIGEL		
1400	RELIEF ENG ABOARD.		
1400	WATCH RELIEVED	Meyer	
	R/O MR. KELLOG R/O MR. HURLEY	(1600 - 2400) BUNDY G/W - IREDALE F/W	
1420	ASSUMED WATCH ALL IN APPARENT GOOD ORDER		
1455	R/O MR. KELLOG ABD. /O MR. WAYNE ASHORE		
1500	F/W ROUND RTE "A" POPE - /O TO WEIGEL - ROUTINE INSP. - ALL SECURE		
1550	F/W ROUND RTE "A" WEIGEL - ALL SECURE		
1555	NOTIFIED MR. ROSENCRANS, YARD MAINTENANCE, GANGWAY OF USNS WEIGEL IS OFF STEEL PLATE ON DUNK.		
1657	SUNSET - COLORS EXECUTED. F/W RND, RTE "B" POPE - ALL SECURE		
1800	F/W TO WEIGEL DETEX RND. RTE "B" ALL SECURE		
1830	R/O away To Weigel - IREDALE ASSUMES G/W duties -		
1900	Detex Rd. "A" made in Pope. All secure. CAPT. + Mrs LARNEY ASHORE -		
2000	Detex Rd. A made in Weigel - All's well.		
2100	Detex "B" rd. in Pope. O.K. (2130 R/O TOURS WEIGEL)		
2200	Detex "B" rd. in Weigel - All secure. - MR SPECTOR ABD.		
2210	Relieved of watch by Perkins A/B		

AT/PASSAGE FROM

ZONE DESCRIPTION

San Francisco Bay Naval Shipyard

TO

DATE (Day, month, year)

Hunters Point

DAY OF WEEK

18 November 1969

Tuesday

TIME

REMARKS

MR. SHERMAN R/O
MR. SPECTOR R/E

(0000-0800)

PERKINS - GANGWAY
PELETI - FIREWATCH

2210

WATCH ASSUMED - ALL IN APPARENT GOOD ORDER

2240

R/O MR. SHERMAN ABOARD - R/O MR. KELLOGG ASHORE

2245

PELETI F/W TO WEIGEL ON DETEX RDS "A" RTE. - ALL SECURE

2315

F/W RETURNS REPORTS - ALL SECURE

0000

F/W "A" ROUNDS IN POPE - ALL SECURE

0100

R/O F/W - "B" RDS - ON WEIGEL

0120

R/O F/W - RETURN - ALL SECURE

0200

F/W - "B" RDS - POPE - ALL SECURE

0300

F/W - "A" RDS - WEIGEL - ALL SECURE

0400

F/W - "A" RDS - POPE - ALL SECURE

0500

F/W - "B" RDS - WEIGEL - ALL SECURE

0600

F/W "B" RDS - POPE - ALL SECURE - 1st ABORD R/E ASHORE

0610

watch relieved by BUNDY AB

L. M. Perkins AB

1/0 MR. WAYNE

0800 - 1600 BUNDY - GWY. - TREDALE F/W

0630

ASSUMED WATCH, ALL IN APPARENT GOOD ORDER

0625

PURSER & CHIEF STEWARD ABD.

0650

1/0 MR. WAYNE ABOARD - MR. SHERMAN ASHORE

0700

JOHN POPOVICS (POOL MAN, OILER) ABD. F/W RND. RTE. "A" WEIGEL

0730

FIRE ALARMS WEIGEL TESTED - O.K. - CHIEF ENGR. ABOARD

0745

CARL PIERCE WIPER REPORTS ABOARD

0750

Test of Pope's fire alarm systems.

0800

COLORS EXECUTED - F/W RND. RTE. "A" POPE - ALL SECURE

0820

CAPTAIN & MRS. LANDRY ABOARD

0900

F/W RND. RTE. "B" WEIGEL - ALL SECURE - 2 M+R MEN ABD. WEIGEL

1000

F/W RND. RTE. "B" POPE - ALL SECURE

1050

F/W RND. RTE. "A" WEIGEL - ALL SECURE

1200

F/W RND. RTE. "A" POPE - ALL SECURE - MST. U. REP. ABOARD

1300

F/W RND. RTE. "B" WEIGEL - M+R MEN OFF THE WEIGEL - ALL SECURE

1330

JOAN DAVIS ABD.

1335

SHIPS POWER ON POPE SHIFTED TO SHORE POWER

1400

R/E MR. HURLEY ABOARD - F/W RND. RTE. "B" POPE - ALL SECURE

1425

WATCH RELIEVED BY JACKSON R. Bundy

MR. Hurley R/E

MR. Kellogg R/O (1600 - 2400)

JACKSON J.F. G/W
LARCIN F/W

1425

RELIEVED THE WATCH ALL IN APPARENT good order

1445

MR. Kellogg R/O CAME ON BOARD

1450

MR. WAYNE 1/0 ASHORE

1545

F/W REPORTS ALL SECURE ON A ROUTE ON POPE

1600

WATCH RELIEVED FOR CHOW

1630

WATCH RETURN FROM CHOW

1635

F/W TO WEIGEL

1635

JOHN DAVIS ASHORE MST'S INSPECTOR

1656

SUNSET MADE COLORS

1700

F/W MADE A & B ROUNDS 4 and 5 o'clock

1745

MASTER CAPT. LANDRY ASHORE

AT/PASSAGE FROM

TO

SAN FRANCISCO NAVAL SHIP YARD HUNTERS POINT

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

+ 7

18 NOV. 1968 TUESDAY

TIME

REMARKS

1600	F/W MAKING ROUNDS ON B ROUTE ON POPE
1815	OILER LEFT FOR INSPECTION OF WEIGEL
1820	F/W REPORTS B ROUTE ON POPE ALL SECURE
1830	R/O MR. KELLOGG MADE AN INSPECTION ON THE WEIGEL
1840	F/W TO WEIGEL TO MAKE ROUNDS
2000	F/W REPORT ALL SECURE ON GEN. WEIGEL FOR 7 & 8 O'CLOCK A & B ROUNDS.
2100	MR. SPECTOR R/O ON BOARD
2130	F/W MADE ROUNDS ON POPE A & B ROUND 9 & 230
2135	R/O RETURN FROM MAKING AN INSPECTION OF WEIGEL
2135	F/W TO THE WEIGEL TO MAKE LAST ROUNDS
2215	WATCH RELIEVED by PELET.
2245	MR. SHERMAN R/O.O. Relieved MR. KELLOGG R/O.O. Joseph H. Jackson

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 HUNTER'S POINT		NAVAL SHIP YARD SFRANCISCO CALI	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		19 NOVEMBER 1969	WEDNESDAY
TIME	REMARKS		
	MR SHERMAN R/O MR SPECTOR R/E 0000-0800 PERKINS F/W		
2245	WATCH ASSUMED ALL IN APPARENT GOOD ORDER		
2250	PERKINS F/W TO WEIGEL ON DETEX ROUND "A" RTE ALL SECURE		
2315	F/W RETURNS REPORTS ALL SECURE		
0000	F/W MADE ROUND OF POPE "A" ROUTE ALL SECURE		
0050	R/O-F/W "B" ROUTE ON WEIGEL.		
0125	R/O-F/W RETURN FROM WEIGEL. ALL SECURE.		
0200	F/W MADE ROUND ON POPE ROUTE "B" ALL SECURE		
0300	F/W ROUND MADE ON WEIGEL "A" ROUTE ALL SECURE		
0400	F/W MADE ROUND ON POPE "A" ROUTE ALL SECURE.		
0455	R/O-F/W TO WEIGEL ON "B" ROUTE		
0505	MR SHERMAN R/O RETURN FROM AN INSPECTION OF WEIGEL ALL IN GOOD ORDER.		
0525	F/W RETURNS & REPORTS ALL IN APPARENT GOOD ORDER		
0600	F/W ROUND ROUTE "B" MADE OF POPE ALL IN GOOD ORDER		
0605	MR SPECTOR R/O ASHORE		
0610	WATCH RELIEVED BY NIX		
	MR WAYNE 'O 0800-1600 MR NIX - GANGWAY MR ORR - FIREWATCH		
0610	WATCH ASSUMED - ALL IN APPARENT GOOD ORDER.		
0630	CHIEF STEWARD & PURSER ABOARD.		
0655	'O WAYNE ABOARD 0700 MR SHERMAN ASHORE		
0715	SMOKE & KIDDE ALARMS (POPE) TESTED O.K.		
0725	POPE DETEX ("A") ROUND COMPLETED		
0800	COLORS: O'DELL VISEING BUNDY ABOARD.		
0810	WEIGEL DETEX ("B") ROUND MADE		
0820	'O TO WEIGEL 0850 RETURN		
0822	CAPTAIN & MRS LANDRY ABOARD.		
0900	NIX ON POPE DETEX ROUNDS (B)		
0930	MR. SHADY - 1 CAPT - 1 COMMDR - & 1 CIVILIAN ABOARD		
1000	WEIGEL "A" ROUNDS MADE		
1030	MR. SHADY & PARTY ASHORE.		
1030	MINIX & GRIER MSTU ABOARD		
1100	NIX ON POPE DETEX ROUNDS ("A")		
1105	CAPTAIN BAILEY ABOARD		
1200	DETEX ROUND MADE ON WEIGEL.		
1220	CAPTAIN BAILEY ASHORE		
1300	NIX ON POPE DETEX ROUNDS (B)		
1300	DIESEL FIRE PUMP TEST RUN (1255-1300)		
1300	DIESEL EMERGENCY GENERATOR TEST RUN (1215-1245)		
1300	'O TO WEIGEL 1315 RETURNS - DETEX ROUND ON POPE.		
1400	WEIGEL DETEX ROUNDS MADE. R/E HURLEY ABOARD.		
1413	MINIX & GREER ASHORE		
1430	WATCH RELIEVED BY LARKIN.		
1430	RELIEVED AND ASSUMED THE WATCH, NORMAL		
1435	1 ST ACT ENG. ASHORE.		
1500	F/W ON A/RD. - MASTER & GUEST ASHORE.		
1530	F/W REPORTS SECURE CHENG - PURSER CH. STEWARD & 1 ST ADM.		
1550	F/W LEFT POPE FOR WEIGEL RD. CONT'D NEXT PAGE		

19 NOVEMBER - CONTINUED FROM PREVIOUS

AT/PASSAGE FROM SAN FRANCISCO BAY NAVAL SHIPYARD	TO HUNTERS POINT
ZONE DESCRIPTION +7	DATE (Day, month, year) 19 NOVEMBER
	DAY OF WEEK WEDNESDAY

TIME	REMARKS
	RDO KELLOG R/ENG. HURLEY/600 - 2400 LARRIN (G) JACKSON F/W
1600	MTR ELECT. TECH. LEFT SHIP. WATCH REL. FOR MEAL BY R/O.
1620	JACKSON F/W REP. A' RD WEIGEL SECURE.
1700	F/W ON B ROUND POPE COLORS EXECUTED, REL. BY RDO.
1730	B' RTE. SECURE.
1800	B' RTE WEIGEL, F/W TO WEIGEL
1840	REC REPORT WEIGEL SECURE. SECURED HEAD (G/FD) R/ENG.
1900	A' RTE F/W ON POPE. R/D O KELLOG TO WEIGEL FOR CHECK
1930	POPE SECURE A'
2000	F/W TO WEIGEL A RTE. F/W REPORTS ALL SECURE
2035	F/W B' RTE POPE. 21RD F/W REPORTS ALL SECURE.
2110	R/D O TO WEIGEL FOR ROUTINE CHECK (2ND)
2115	F/W TO WEIGEL FOR DETEX RD.
2130	RDO + F/W RETURN, WEIGEL IS SECURE, F/W STILL ABOARD W'
2215	F/W RETURNS FROM WEIGEL, ALL IS SECURE ALL DETEX STATIONS
2230	WATCH RELIEVED BY ORR
2235	MR. SHERMAN ABOARD
2240	MR. KELLOGG ASHORE
2255	MR. SPECTOR ABOARD
2257	MR. HURLEY ASHORE
2300	NIX ON POPE DETEX ROUNDS (A')
2400	ALL SECURE. R/O + F/W TO WEIGEL.

AT/PASSAGE FROM PIER #2 BERTH #33 HUNTERS	TO POINT NAVAL SHIPYARD S.F. CALIF.
ZONE DESCRIPTION	DATE (Day, month, year) 20 NOVEMBER 1969
	DAY OF WEEK THURSDAY

TIME	REMARKS
	MR SHERMAN R/O MR SPECTOR R/E (0000-0800) GEORGE ORR --- GANGWAY GUY NIX --- FIREWATCH
0000	MOORED AS BEFORE. LINES, GANGWAY + RATGUARD SECURE
0015	R/O + F/W RETURN FROM WEIGEL "A" ROUNDS MADE
0100	NIX MAKING POPE "B" ROUNDS
0200	WEIGEL "B" ROUNDS MADE
0300	F/W MAKING POPE "A" ROUNDS
0400	F/W MAKING WEIGEL "A" ROUNDS R/O TO WEIGEL
0500	F/W MAKING POPE "B" ROUNDS
0555	MR SPECTOR R/E ASHORE.
0600	F/W COMPLETED LAST LAP "B" ON WEIGEL
0615	WATCH RELIEVED BY PAT LARKIN <i>Geo Orr</i>
0615	RELIEVED AND ASSUMED THE WATCH GOOD ORDER.
0645	CH STWD + PURSER ON BD. 1ST ASST ON BD. TO RELIEF R/ENG.
0650	1/0 ON BD. 0700 R/O SHERMAN LEFT SHIP. <i>P. Larkin</i> 1/0 WAYNE CH ENG BENTZ (0800-1600) LARKIN (F.W.)
0700	Watch Relieved By (LARKIN) AB
0710	Key to Weigel Taken By Garrett Elec.
0712	Tested Fire Alarms on Pope
0720	" " " " Weigel
0725	F.W. - Making A Route Pope (Delay to see 1/0) +
0800	A Route on Weigel - Completed 0840 SECURE, Colors MADE POPE
0845	Captain Landry on Board (+ Guest) SHIP'S FORCE TAKING ON STORES.
0900	F/W - making B Route on Pope 1st officer to Weigel
1005	F/W - " B Route " Weigel
1035	Purser to Bank.
1045	RELIEVED THE BOSUN - "B" RTE WEIGEL IS SECURE.
1100	Purser Returned From Bank with \$4000.00 "A" RTE. DETEX START
	F.W. Making (A) Route ON Pope
1130	WEIGEL TEST RAN ANCHOR WINDLASS FOR 15 MINS.
	CAPTAN #1 & #2 FOR 15 MINS., AC LAUNDRY VENT Sys. FOR 1/2 HR.
1140	"A" ROUND COMPLETE ALL SECURE.
1200	F.W. Making B Route on Weigel
1235	WEIGEL SECURE - ALL STATIONS
1300	F.W. Making Rounds on Pope MAKING ROUNDS ON Pope
1400	F.W. Making Round on Weigel All Secure on Weigel, Mr. Hurley R.E.D. on Board.
1420	PERKINS - ON BOARD - RELIEVE BOSUN
1430	CAPT - LANDRY + Wife ASHORE
1440	1st officer ASHORE - MR KELLOGG R/O - ASHORE, ABOARD.

AT/PASSAGE FROM

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

Pier #2 - Berth 33 Hunter's Point Naval Shipyard - San Francisco

20 November 69 Thursday

1-7

TIME	REMARKS
	McKellogg - RDS Mr. Hurley RE 1600 - 2400 - Perkins - Gangway Telet - FIREWATCH
1500	ROUNDS MADE-ON Weigel & Pope - beginning of Weigel "A"
1600	ROUNDS-MADE-ON POPE "A"
1605	SUNSET - Colors-observed
1700	Flw made "B" ON Weigel
1800	Flw ON RDS - POPE "B"
1900	Flw ON - RDS - Weigel "A" - "Rte"
1930	Rd ON-BOARD - Weigel - INSP - RDS -
2000	Rd ON-BOARD - POPE - ALL-SECURE "A"
-do-	Flw ON RDS - POPE - "A" Rte →
2100	Flw toiler to Weigel - Detex Rds + routine Eng - insp -
2100	Flw ON "B" Rds - Weigel -
2200	Flw ON - "B" Rds - POPE -
-do-	Mr SPECTOR Rte - ON board - Mr Hurley ASHORE
2200	Flw - complete Rds - ON Weigel & POPE
2230	Watch Relieved by TREDWELL AB
	Mr Perkins

AT/PASSAGE FROM		TO	
SFBNS Hunters Point		Pier 2 Berth 35	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		21 Nov 69	Fri
TIME	REMARKS		
	Mr. Sherman, RDO Mr Spector ^{R/E} (0000 - 0800) IREDALE, A/B		
2230	Assumed the watch. Conditions normal - Vessel quiet		
2240	Mr Sherman RDO, ABOARD - Mr Kellogg ashore		
0020	No F/W Relief. IREDALE TO ASSUME F/W - Peletti on GIW -		
0025	R/O Mr Sherman & F/W "A" Round Weigel ALL SECURE		
0045	R/O & F/W Returns FROM Weigel ALL SECURE		
0100	F/W MADE ROUND "A" POPE ALL SECURE		
0200	F/W MADE ROUND "B" WEIGEL ALL SECURE		
0300	F/W MADE ROUND "B" POPE ALL SECURE		
0400	F/W MADE ROUND "A" WEIGEL ALL SECURE		
0425	Mr Sherman R/O Completed his Inspection on Weigel. All in Good Order.		
0435	Mr Sherman Returns FROM Weigel		
0500	F/W MADE ROUND "A" POPE ALL SECURE		
0550	Mr Spector R/O ASHORE		
0600	F/W MADE ROUND "B" ALL SECURE		
0615	Watch Relieved by Nix		
	Mr. WAYNE 'O 0800 - 1600 ^{NIX - GANGWAY} ^{ORR - FIRE WATCH}		
0600	WATCH ASSUMED. All in APPARENT GOOD ORDER.		
0605	1 st ASST ENG. ABOARD.		
0635	CHIEF STEWARD & PURSER ABOARD.		
0650	MR WAYNE FIRST OFFICER ABOARD.		
0700	F/W MAKING A ROUTE DETEX ROUNDS ON POPE		
0705	MR. SHERMAN ASHORE		
0730	KIDDE ALARMS & SMOKE DETECTORS TESTED ON POPE & WEIGEL.		
0800	COLORS: F/W MAKING "A" ROUNDS ABOARD WEIGEL		
0825	BASE FIRE INSPECTOR MR. CONSTANTINE ABOARD FOR TOUR OF VESSEL.		
0830	CAPTAIN & MRS LANDRY ABOARD		
0900	F/W MAKING DETEX ROUNDS (B) ON POPE.		
0945	FIRE INSPECTORS FROM HUNTERS POINT ASHORE. NEW SECOND ELBO. GARCIA ABOARD.		
1000	F/W MAKING DETEX ROUNDS (B) ON WEIGEL.		
1055	VERWEYST MST'S ELECTRONICS ABOARD		
1100	F/W MAKING DETEX ROUNDS (A) ON POPE		
1105	BOB LINBERGH, PLUMBER ABOARD FOR DUTY VICE T		
1110	VAN BUSKIRK, WILLIAM FIREMAN ABOARD VICE WALLACE		
1115	CHIEF ENG ABOARD.		
1200	DETEX ROUND MADE ON WEIGEL (A)		
1300	F/W MAKING DETEX ROUNDS (B) ON POPE		
1305	CAPTAIN & MRS LANDRY ASHORE		
1400	DETEX ROUND MADE ON WEIGEL.		
1405	WATCH RELIEVED BY PELETI		
	Amy Nix (AB)		

Jimmy Nix (AB)