

AT/PASSAGE FROM

TO

NAVAL SHIP YARD SAN FRANCISCO CALIF

ZONE DESCRIPTION

Pier 2 BERTH #33 HUNTER'S POINT

DATE (Day, month, year)

21 NOVEMBER 1969

DAY OF WEEK

FRIDAY

TIME

MR KELLOG R/D.O.
MR HURLEY R/D.O.

REMARKS

Peletti - Gangway Watch. Perkins F/W.

1600 - 2400

1430 Assumed the Watch Condition NORMAL

1440 MR WAYNE 1/0 Ashore & Chief Engineer Ashore

1445 MR KELLOG R/D.O. Aboard

1450 C/PURSER & Ch/Steward Ashore.

1500 F/W MADE Round "A" ROUTE WEIGEL ALL SECURE

1610 2 MST'S ELECTRICIANS ASHORE.

1615 F/W MADE Round "A" ROUTE POPE ALL SECURE

1655 Colors observed ALL SECURE

1705 F/W MADE Round "B" WEIGEL ALL SECURE

1800 F/W MADE Round "B" POPE ALL SECURE

1850 MR KELLOG R/D & F/W Round made ON WEIGEL "A" ROUTE ALL SECURE

1910 MR KELLOG R/D RETURNS FROM WEIGEL. ALL in APPARENT GOOD ORDER

2000 F/W MADE Round "A" POPE ALL SECURE

2100 F/W MADE Round "B" WEIGEL ALL SECURE

2130 MR KELLOG R/D TO WEIGEL FOR Routine Inspection

2145 MR KELLOG R/D RETURNS aboard ALL in GOOD ORDER

2200 MR SPECTOR R/D aboard Relieved MR HURLEY Ashore

2205 F/W MADE HIS LAST "B" Round ON POPE ALL SECURE

2215 F/W Completed Security Round of both Vessels ALL in GOOD ORDER

2235 Watch Relieved by ODELL A/B.

Tolita A/B.

AT/PASSAGE FROM	TO
SFBNS Hunters Point +7	Pier #2 Berth 33
ZONE DESCRIPTION	DATE (Day, month, year) DAY OF WEEK
	22 Nov. 1964 SAT.

TIME	REMARKS
	Mr. Sherman R.D.O. Mr. Spector R.D.O. (0000-0800) O'Dell AB IREDALE A/B
2235	Assumed the watch Condition Normal- vessel quiet
2300	Mr. Sherman R.D.O. Aboard- Mr. Kellogg Ashore
2300	F/W IREDALE starts round of Pope
2400	" " + R.D.O. " " " Weigel
0045	" " " Return From " " " All secure
0100	" " starts Round of Pope "B" rte.
0150	" " " " " Weigel "B" "
0220	" " returns From " " " All secure
0300	" " starts A Route of Pope
0350	" " Finishes " " " All secure
0400	" " + R.D.O. go to Weigel
0415	" " Return From " " "
0455	" " Starts Round of Pope - All secure
0540	" " " " " Weigel
0605	" " Finished " " " "
0615	Watch relieved by Perkins A/B
	RE O'Dell
0615	Watch assumed- all in apparent good order-
0715	F/W on Detex of "A" RT - SOUNDINGS - TAKEN - POPE
0800	SUNRISE colors observed (0800-1600)-
- do -	F/W to Weigel - "A" RTE
0900	F/W "B" RTE - Weigel POPE
1000	MR SPECTOR R/D ABOARD ^{BEFORE} - DON-ROBERT R/D - ABOARD
1000	F/W "B" Weigel - SMOKE-DETECTOR ALARM SWITCH changed over
1100	F/W "A" RTE- POPE - MR WERNETTE R/D ABOARD
	MR WERNETTE R/D ^{MR ROBERT R/D} (1200-1600) PERKINS - GANGWAY VETI - FIREWATCH
1200	CAPT & MRS Landry ABOARD
	F/W - "A" RTE Weigel - All secure - R/D to Weigel - Insp - RDS
1300	F/W - "B" RTE POPE
1400	F/W & Oiler to Weigel - F/W on "B" RTE
1410	WATCH - Relieved by Orr-
1500	F/W MAKING DETEX ROUNDS ("A") ON POPE
	MR WERNETTE R/D ^{MR ROBERT R/D} (1600-2400) ORR - GANGWAY NIX - FIREWATCH
1600	F/W MAKING DETEX ROUNDS ("A") ON WEIGEL.
1654	COLORS
1700	F/W MAKING DETEX ROUNDS (B) ON POPE
1800	F/W MAKING DETEX ROUNDS (B) ON WEIGEL
1820	MR & MRS. LANDRY ASHORE
1900	F/W MAKING DETEX ROUNDS (A) ON POPE
1902	A/B JOE JACKSON CALLED IN SICK (PULLED BACK MUSCLE) WILL BE IN MONDAY.
1905	MSTS MESSAGE CENTER CALLED TO REPORT: "A TIDAL WAVE EXPECTED IN S.F. BAY AT 2307 ZULU."
2000	F/W MAKING WEIGEL (A) ROUND
2100	F/W MAKING POPE (B) ROUND
2110	TIDAL WAVE CANCELED
2110	F/W MAKING WEIGEL (B) ROUNDS MR. SPECTOR RELIEVES MR ROBERT
2110	WATCH RELIEVED BY LARKIN Over Orr

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL SHIPYARD HUNTERS POINT.			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		23 NOV. 1969	SUNDAY
TIME	REMARKS		
	MR SHERMAN RDO MR SPECTOR RDO - 0800 (E) LARKIN		
2230	WATCH RELIEVED AND ASSUMED.		
2300	REL. BY RDO WERNADETTE, AT GANGWAY, WATCH LEFT FOR SECURITY RD. 2335 A' ROUND POPE SECURE. (DET EX) RDO SHERMAN ON BD. RDO WERNADETTE LEFT SHIP.		
2400	REL. BY MR SHERMAN, TO WEIGEL FOR SECURITY RD.		
2435	A RTE. WEIGEL SECURE. RETURN TO POPE. REL. RDO		
0100	LEFT FOR B' RD. POPE.		
0135	COMPLETED B' RD. OF POPE ALL SECURE. (26 STA)		
0200	REL BY RDO WIRTH TO WEIGEL B' RD. (24 STA) DET EX. SWITCHED TO. ODD # ON SMOKE DETECTOR POPE.		
	" " " # ON " " WEIGEL.		
0230	RETURNED FROM WEIGEL (B' RTE) 1/2 OF SHIP SECURE.		
0300	ON A' RD. OF POPE - REL. BY MR SHERMAN		
0335	COMPLETED A' RD POPE (21 STATIONS) ALL SECURE.		
0410	COMMENCED A RD WEIGEL.		
0440	COMPLETED A RD. SECURE WEIGEL		
0520	COMMENCED B' RD WEIGEL. POPE (REL BY RDO DOTT)		
0545	B ROUTE SECURE - CALLED STEW DEPT + BOSON.		
0600	GANGWAY WATCH REL. BY RDO FOR SECURITY RD OF WEIGEL		
0630	COMPLETED SEC RD OF WEIGEL, CLOCKS TO RDO SHERMAN FOR CHG. OF DISC. ALL SECURE BOTH VESSELS.		
	MR SHERMAN RDO MR. SPECTOR RDO 0800 - 1600 NIX GWD Larkin ORR F/W		
0630	WATCH ASSUMED. ALL IN APPARENT GOOD ORDER		
0700	DET EX Round ON POPE.		
0800	COLORS: DET EX Round ON WEIGEL.		
0900	DET EX Round ON POPE. A.O.K.		
0945	MR. ROBAAT RDO RELIEVED MR SPECTOR.		
1000	DET EX Round ON WEIGEL.		
1030	MR KELLOGG RDO RELIEVED MR. SHERMAN.		
1100	DET EX Round ON POPE.		
1200	DET EX Round ON WEIGEL		
1300	DET EX Round ON POPE. ALL IS WELL.		
1400	DET EX Round ON WEIGEL. ALL IN APPARENT GOOD ORDER.		
1410	WATCH RELIEVED BY IREDALE		
	MR. Kellogg, RDO (1600 - 2400) ODR II F/W IREDALE S/W		
1430	RDO makes inspection Tour in Weigel - All secure		
1500	Det ex round "A" made in Pope - All secure Return - 1520		
1600	Det ex round "A" in Weigel - -do- Finish 1635		
1654	Sunset - Evening colors executed.		
1700	Det ex round B in Pope - All secure Finish - 1725		
1800	Det ex rd "B" in Weigel -do- Completed - 1840		
1845	RDO making security patrol in Weigel -		
1900	Det ex rd "A" in Pope. All secure - " 1930		
2005	Det ex rd "A" in Weigel -do- " 2045		
2100	Det ex rd "B" in Pope - All well. RDO on inspection Tour of W.		

AT/PASSAGE FROM

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

SAN FRANCISCO BAY NAVAL SHIP YARD HUNTERS POINT

+7 24 NOV 1969 MONDAY

TIME	REMARKS
	MR SHERMAN MR SPECTOR 0000 - 0800 G LARKIN
0000	REL. BY RDO. LEFT FOR SEC. RD WEIGEL
0030	COMPLETED WEIGEL RD. ALL SECURE. (G) WATCH BEING REL. BY RDO
0035	RDO TO WEIGEL 0100 RDO RETURNS FROM WEIGEL, SECURE
0115	ENG. TO WEIGEL F/R SECURE 0125
0200	COMMENCED 'B' RD. POPE, COMPLETED 'B' RD WEIGEL
0235	COMPLETED 'B' R POPE (COMMENCED 0300)
0500	COMMENCED 'A' RD POPE. - 0530 (REL. D/O RELIEFS FOR SEC. RDS CALLS MADE (NO CALL LIST) BOSUN ONLY BAKER + COOK ON BOARD
0525	COMPLETED A RD OF SHIP ALL SECURE, NORMAL SPOOR.
0600	LEFT FOR WEIGEL FOR A RD (MODIFIED SCHEDULE) REL. BY RDO. NO COFFE (INSTANT!) NO CALL FOR COOK, NO ONE IN GALLEY
0630	COMPLETED A' ROUND WEIGEL (1/2 FWD SECURE) - NO RELIEF IN SIGHT. ABM TO BE ASSIGNED.
0640	WATCH RELIEVED BY ABM - SINDONI ABM (D. Larkin)
0650	PURSER ABOARD. Watch Relieved By GRAY + SINDONI
0650	Mr Wayne 1/0 aboard
0700	ROUTE 'A' ON POPE MADE ALL SECURE
0710	CH. ENG. ABOARD.
0725	CH STEWARD ASHORE WILL RETURN 9AM.
0800	Colors Executed - Left for B-Route on Weigel
0835	Master Aboard
0840	-B- Rtc on Weigel complete all secure
0900	ROUTE "B" ON POPE MADE ALL SECURE
1000	Route 'A' on Weigel made All Secure
1000	Mr Connolly 1/0 aboard
1100	RT "A" ON POPE MADE ALL SECURE
1200	RTE 'B' on Weigel All Secure
1210	Mr Wayne Ashore - Mr Connolly assumes the 1/0 position ✓
1225	Deck Yeoman on Mail Run
1235	Deck Yeoman Backs from Mail Run
1255	Chief Electrician reports test run of Degaussing system on Weigel and Pope from 0700 to 1130 Also cell test of all Batteries and charge of same on both ships
1300	RT "B" ON POPE ALL SECURE. PURSER ASHORE
1400	Rtc "A" on Weigel All Secure Purser aboard
1430	Watch Relieved by O'Dell 1/3 Mr Kellogg, RDO (1600-2400) REDALE, Fw Gray O'Dell, Fw
1500	Detex Rd "A" in Pope - All secure
1600	Detex Rd "A" in Weigel - do.
1654	Sunset - Evening colors executed.
1700	Detex Rd "B" in Pope - All well.
1800	Detex Rd "B" in Weigel - do.
1900	Detex Rd "A" in Pope - do.
1930	Capt. + Mrs Landry ashore
2000	Detex Rd "A" in Weigel - All secures
2100	Detex Rd "B" in Pope - do.
2200	Detex Rd "B" in Weigel - do.
2215	Relieved of watch by Perkins

27. Shuleb

AT/PASSAGE FROM		TO	
S. FBNS			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		NOVEMBER 25	Tuesday
TIME	REMARKS		
	MRS SHERMAN R/O	0800-0800 PERKINS - 60MS LADY PELETTI - FIREWATCH	
2215	Watch Relieved - All SECURE		
2210	MR SPECTOR R/O - ABOARD -		
2300	MR SHERMAN ABOARD - "A" RTE - MADE "POPE"		
0000	R/O MADE RDS ON WEIGEL / F/W ON RDS WEIGEL - "A" RTE		
0100	F/W - "B" RTE - POPE - All SECURE		
0200	F/W - "B" RTE WEIGEL - All SECURE		
0300	F/W "A" RTE POPE - All SECURE		
0400	R/O - F/W - to WEIGEL - "A" RTE		
0500	F/W - "B" POPE - ALL-SECURE - OKER To - WEIGEL		
0600	F/W - "B" RTE - WEIGEL All SECURE - MR SPECTOR R/O ASHORE		
0615	WATCH RELIEVED BY IREDALE		
Link Perkins			
0800 - 1600			
0630	On Watch Iredale F/W O'Dell A/B		
0645	Mr Connelly R/O Aboard		
0700	Mr. Sherman R/O Ashore		
0700	Iredale F/W starts "A" route on Pope		
0715	" " finishes " " " " " " All secure		
0800	Colours observed		
0800	Iredale F/W starts "A" route on Weigel		
0820	" " finishes " " " " " " All Secure		
0825	Master + Mrs. Aboard		
0825	Alarm systems checked - O.K.		
0850	Iredale F/W finishes "A" route on Weigel All secure		
0900	" " starts "B" " " " " Pope		
0920	" " finishes " " " " " " " "		
0950	Mr. Reyes Aboard		
0955	3 MSTs electronics men Aboard signed visitors log		
1000	Iredale F/W to Weigel for "B" rte.		
1005	Mr. Ericson, MSTs inspector, aboard.		
1020	Iredale F/W finishes "B" rte. on Weigel - OK.		
1045	Mr Connelly R/O to NSC.		
1050	Iredale F/W starts "A" route on Pope		
1100	Mr Reyes Ashore		
1100	Mr Ericson "		
1102	O'DELL, AB gangway watch, ashore to dispensary for treatment of headache caused by head injury of 23 Nov 1964 - Relieved by Bos'n		
1200	F/W Completed A Route on Weigel		
1300	F/W " " A " " " Pope		
1400	F/W " " B " " " Weigel All SECURE		
	REO Mr Hurley ON BOARD		
1440	MR Kellogg ON BOARD		

AT/PASSAGE FROM

S.F.B.N 5
ZONE DESCRIPTION

+ 7

TO

HUNTER POINT NAVAL SHIPYARD

DATE (Day, month, year)

NOV. 25

DAY OF WEEK

TUE.

TIME

REMARKS

MR. HURLEY R/E

JACKSON JF GANWAY

1440

MR. KELLOGG R/O (1600 - 2400) LARKIN F/W

1446

RELIEVED THE WATCH ALL IN APPERNT GOOD ORDER

1501

MR. CONNLEY 1/0 ASHORE, MR. KELLOGG ON BOARD

1515

LARKIN F/W MADE ROUNDS ON A ROUTE

1530

A ROUND COMPLETED ALL SECURE

1555

WATCH RELIEVED FOR CHOW

1615

WATCH RETURN FROM CHOW

1625

FIRE WATCH REPORTS ALL SECURE ON WEIGEL A ROUTE

1653

SUNSET - COLORS EXECUTED

1710

F/W MAKING ROUNDS ON GEN. POPE B ROUTE

1735

FIREWATCH REPORT ALL SECURE

1805

MASTER LEFT THE SHIP

1810

FIRE WATCH LEFT SHIP FOR ROUNDS ON WEIGEL

1830

R/O LEFT SHIP TO WEIGEL FOR INSPECTION

1840

FIRE WATCH RETURN FROM WEIGEL ON B ROUTE ALL SECURE

1855

R/O RETURN FROM GEN WEIGEL ALL SECURE

1905

F/W MAKING ROUNDS ON GEN POPE A ROUTE

1927

FIRE WATCH COMPLETED A ROUND ON POPE

2000

F/W WATCH TO WEIGEL MAKING ROUNDS ON A ROUTE

2030

FIRE WATCH RETURN ^{FROM} WEIGEL ALL SECURE

2100

F/W MAKING ROUNDS ON GEN. POPE ROUTE B

2110

MR. SPECTOR R/E ON BOARD

2115

MR. KELLOGG LEFT THE SHIP TO INSPECT THE WEIGEL

2120

FIRE WATCH REPORTS ALL SECURE ON GEN POPE

2135

R/O MR. KELLOGG RETURN TO THE SHIP ALL SECURE

2155

F/W LEFT SHIP TO WEIGEL

2218

FIRE WATCH MADE LAST ROUND ON 1600-2400 WATCH B ROUTE ALL SECURE


2230

WATCH RELIEVED BY PLETI

Jackson JF

AT/PASSAGE FROM PIER 2 BERTH #33 HUNTER'S POINT	TO NAVAL SHIP YARD S. FRANCISCO CALI
ZONE DESCRIPTION + 7.	DATE (Day, month, year) 26 NOVEMBER 1969
	DAY OF WEEK WEDNESDAY

TIME	REMARKS
	R/O SPECTOR MR ANDERSON R/O 0000 - 0800 Gangway Feletti. F/W PERKINS
2230	ASSUMED THE WATCH. ALL IN APPARENT GOOD ORDER.
2255	F/W MADE ROUND ON POPE "A" ROUTE
2310	F/W COMPLETED "A" ROUNDS ALL SECURE.
2320	MR ANDERSON R/O. RELIEVED MR KELLOG R/O
2330	MR KELLOG R/O ASHORE
2350	F/W TO WEIGEL "A" ROUTE
0025	F/W COMPLETED HIS ROUNDS ON WEIGEL. ALL SECURE.
0055	F/W MADE ROUNDS ON POPE "B" ROUTE
0115	F/W RETURNS COMPLETED ROUNDS. ALL SECURE
0200	F/W TO WEIGEL "B" ROUTE
0230	F/W COMPLETED ROUNDS ON WEIGEL. ALL SECURE.
0235	MR ANDERSON R/O TO WEIGEL FOR ROUTINE INSPECTION
0250	MR ANDERSON R/O RETURNS FROM WEIGEL ALL SECURE.
0255	F/W MADE ROUNDS ON POPE "A" ROUTE
0310	F/W COMPLETED "A" ROUND ALL SECURE
0350	F/W TO WEIGEL "A" ROUTE
0420	F/W RETURNS COMPLETED ROUNDS ALL SECURE.
0455	F/W MADE LAST "B" ROUND ON POPE
0515	F/W COMPLETED LAST ROUND POPE ALL SECURE
0550	F/W MADE HIS LAST "B" ROUND ON WEIGEL.
0600	F/W RETURNS FROM WEIGEL ALL SECURE WATCH RELIEVED BY NIX A/B. Feletti A/B.
	MR. CONNELLY 1/0 0800 - 1600 NIX GNY ORR F/W
0600	WATCH ASSUMED: ALL IN APPARENT GOOD ORDER
0605	THOMPSON 2 ND ASST ENG RELIEVED MR. SPECTOR R/O. 1 ST ASST ENG. ABOARD
0635	CHIEF STEWARD + PURSER ABOARD.
0700	F/W MAKING "A" ROUNDS POPE
0709	TEST OF POPE ALARM SYSTEMS O.K.
0710	MR. CONNALLY 1/0 ABOARD
0712	TEST OF WEIGEL ALARM SYSTEMS OK.
0725	MR. ANDERSON 8/0 ASHORE CH. ENGINEER ABOARD
0800	COLORS: F/W MAKING DETEX ROUND ON WEIGEL.
0900	DETEX ROUND ON POPE.
0900	TEST ON WEIGEL - ANCHOR WINDLASS + CAPSTANS RUN 15 MIN AG LAUNDRY - RUN 1/2 HOUR. EMERGENCY DIESEL GEN 20 MIN BUT MALFUNCTIONING.
0930	INSTS ELEC ABOARD. WORKING ON WEIGEL P.A. SYSTEM.
0935	MR SHADY ABOARD. 1055 --- ASHORE
1000	DETEX ROUND ON WEIGEL MADE.
1100	DETEX ROUND ON POPE MADE.
1200	DETEX ROUNDS ON WEIGEL - TEST MADE ON POPE - EMERG. GEN TESTED - FIRE PUMP - RUN 30 MIN - STEER GEAR MOTORS TESTED. ANCHOR WINDLASS + CAPSTANS RUN 30 MIN.
1200	NEW DECK DEPT WATCH LIST POSTED. EFFECTIVE NOV. 28, 1969
1300	DETEX ROUNDS ON POPE
1400	DETEX ROUND ON WEIGEL. MR HURLEY (R/O) ABOARD.
1415	WATCH RELIEVED BY LARKIN



AT/PASSAGE FROM

PIER #2 BERTH 33 HUNTERS POINT N.S.Y. S.F. CALIF.

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

26 NOVEMBER 1969

WEDNESDAY

TIME	REMARKS (CONTINUED)
1420	RELIEVED AND ASSUMED THE GANGWAY WATCH. ORR + NIX LEFT SHIP, RELIEVED. JACKSON F/W ON BD.
1520	CH. ENG, PURSER, STEWARD LEFT SHIP
1540	1/0 LEFT SHIP. MR KELLOG ON BD.
1541	JACKSON F/W REPORTS 'A' RD (2) STATIONS SECURE)
	MR KELLOG 90/600 - 2400 JACKSON F/W
	MR HURLEY R/ENG LARKIN (G)
1600	F/W TO WEIGEL FOR 'A' RD OF SHIP.
1635	WEIGEL SECURE, 'A' RD. F/W REPORT. R/DO TAKES DRAFTS. (2)
1645	COLORS EXECUTED BY WATCH (2) AS PER SOPA.
1700	F/W ON 'B' RTE POPE. 1735 COMPLETED 'B' ALL SECURE
1800	F/WATCH TO WEIGEL FOR SECURITY RD. 'B'
1830	F/W REPORTS WEIGEL 'B' RTE SECURE.
1900	F/W ON 'A' RTE POPE. R/DO ON RDS POPE.
1925	F/W JACKSON REPORTS 'ALL SECURE.' WEIGEL.
1940	R/DO KELLOG MADE INSPECTION WEIGEL + POPE.
2000	F/W REPORTS WEIGEL SECURE.
2100	F/W REPORTS POPE SECURE - DETEX ROUND MADE B
2200	F/W TO WEIGEL 'B' RTE. R/DO RETURNS FROM WEIGEL - ALL SECURE.
2230	F/W JACKSON RETURNS FROM WEIGEL 'B' RTE IS SECURE.
2231	WATCH RELIEVED BY NIX + ORR. - Det Larkin
2300	MR. SPECTOR RELIEVES MR. HURLEY. F/W MAKING POPE ROUNDS
2305	MR. ANDERSON RELIEVES MR. KELLOGG
2400	FIRE WATCH TO WEIGEL

Her On

AT/ FROM		DATE (Day, month, year)		DAY OF WEEK	
PIER #2 BERTH #33 HUNTERS PT. N.S.V. S.F. CALIF.		27 NOVEMBER 1969		THURSDAY	
ZONE DESCRIPTION					
TIME	(HAPPY TURKEY DAY) REMARKS				
0000	R/O MR. ANDERSON (0000-0800) ORR-GANGWAY R/E MR. SPECTOR NIX-FIREWATCH				
0000	F/W MAKING WEIGEL ROUNDS				
0100	F/W MAKING POPE ROUNDS				
0200	F/W MAKING WEIGEL ROUNDS				
0300	F/W MAKING POPE ROUNDS				
0400	F/W MAKING WEIGEL ROUNDS.				
0500	F/W MAKING POPE ROUNDS				
0600	F/W MAKING WEIGEL ROUNDS				
0610	WATCH RELIEVED BY JOE JACKSON Geo. Orr				
0610	R/O MR. ANDERSON JACKSON J.F. GANGWAY R/E MR. SPECTOR (0800-1600) LARKIN P. F/W				
0610	RELIEVED THE WATCH ALL IN APPARENT GOOD ORDER				
0635	R/O LEFT THE SHIP FOR INSPECTION OF WEIGEL				
0655	R/O RETURN FROM GEN. WEIGEL ALL SECURE				
0706	F/W MAKING ROUNDS ON GEN. POPE A ROUTE				
0725	ROUNDS MADE ON POPE ALL SECURED				
0745	SOUNDING HAS BEEN TAKING REEFER 4 1/2 FEET ON POPE				
0800	MADE COLORS				
0800	F/W LEFT SHIP FOR WEIGEL				
0835	F/W RETURN FROM WEIGEL ROUNDS MADE ON A ROUTE AND SOUNDING WERE TAKEN				
0855	R/O MADE TRIP TO WEIGEL				
0900	R/O RETURN FROM GEN. WEIGEL ALL SECURE				
0910	F/W LARKIN MAKING B ROUTE ON GEN. POPE				
0935	F/W REPORTS ALL SECURE ON GEN. POPE B ROUTE				
1000	MR. SPECTOR R.E.O. ASHORE MR. HURLEY R.E.O. ON BOARD				
1015	F/W LEFT SHIP FOR GEN. WEIGEL				
1045	F/W REPORTS GEN. WEIGEL ALL SECURE ON B ROUTE				
1040	MR. KELLOGG ON BOARD RELIEVED MR. ANDERSON R/O				
1100	WATCH RELIEVED FOR CHOW				
1125	WATCH RETURN FROM CHOW				
1145	F/W REPORT ALL SECURE ON POPE ROUTE A				
1230	F/W LEFT SHIP FOR ROUNDS ON GEN. WEIGEL				
1250	LARKIN F/W REPORTS ALL SECURE ON GEN. WEIGEL				
1300	F/W MAKING ROUNDS ON B ROUTE LAST ONE ON (0800-1600)				
1330	ROUNDS COMPLETE ON GEN. POPE				
1355	F/W TO WEIGEL FOR LAST ROUND ON WATCH B ROUTE				
1415	F/W REPORTS ALL SECURE ON GEN. WEIGEL				
1430	WATCH RELIEVED BY LARRY M. PERKINS Joseph J. Jackson				
1430	R/O MR. KELLOGG (1600-2400) PERKINS-GANGWAY R/E MR. HURLEY PELETI-FIREWATCH				
-00-	R/O & R/E TO WEIGEL ROUTINE INSP.				
1455	R/O & R/E ABOARD - ALL IN GOOD ORDER				
1500	F/W ON "A" RTE - POPE				
	F/W - REPORTS - ALL SECURE "A"				
	F/W ON "A" RTE - WEIGEL				
	F/W - REPORTS - ALL SECURE - Weigel -CONT-				

AT/PASSAGE FROM Pier #2 - Berth #33 Hunters Pt. - Naval Shipyard - San Francisco Calif TO DATE (Day, month, year) DAY OF WEEK

TIME	REMARKS
1652	MR Kellogg - R/O
1700	MR HURLEY - R/E (1600-2400) PERKINS - GANGWAY PILLETI - FIREWATCH
1700	1652 SUNSET - colors properly observed
1700	F/W ON "B" RTE POPE
1715	F/W - REPORTS ALL SECURE
1735	F/W - TO WEIGEL "B" RTE - R/E TO WEIGEL
1820	F/W - REPORTS ALL SECURE WEIGEL - R/E RETURNS
1830	R/O ON RDS. WEIGEL
1850	R/O REPORTS ALL SECURE ON WEIGEL
1900	F/W ON "A" RTE - POPE
1920	F/W REPORTS ALL SECURE ON POPE
1950	F/W TO "A" RTE - WEIGEL
2000	F/W REPORTS - ALL SECURE ON WEIGEL
2100	F/W ON "B" RTE ON POPE - R/O ON INSP RDS - WEIGEL
2145	ERRDA WMS OILER CALLED MSG FOR CHIEF ENGR "WMS.
→	PLANE GROUNDDED IN ATLANTA GA. DUE TO RAIN. WMS EXPECTS TO ARRIVE ON BOARD 0900 FRIDAY NOV 28 '69 "
2150	F/W ON "B" RTE WEIGEL
2200	MR SPECTOR R/E ^{ABOAR} ABOAR - MR. HURLEY R/E ASHORE
2230	WATCH RELIEVED BY O'DELL

L. M. Perkins

FROM/PASSAGE FROM		TO	
S.F.B.N.S. Hunters Point		Pier 2 - Berth # 33	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		28 Nov 69	FRI
TIME	REMARKS		
	0000 — 0800		
2230	Watch relieved by Tredale F/W & O'Dell A/B		
2300	Mr. Andersen aboard R.D.O.		
2300	Mr. Kelly 1/600 Ashore		
2300	Tredale F/W starts "A" r'te. on Pope		
2330	" " Finishes " " " " All secure		
2400	" " starts " " " " Weigel		
0030	" " Finishes " " " " " "		
0100	" " starts B " " " " Pope		
0130	" " Finishes " " " " " "		
0200	" " starts A " " " " Weigel		
0230	" " Finishes " " " " " "		
0300	" " starts B " " " " Pope		
0330	" " Finishes " " " " " "		
0400	" " starts " " " " Weigel		
0400	Mr. Andersen R.D.O. to the " "		
0430	" " " & Tredale F/W back from Weigel		
0500	Tredale F/W starts round of Pope, "A" r'te.		
0520	" " Finishes " " " " " "		
0535	" " starts " " " " Weigel " "		
0600	" " Finishes " " " " " "		
0600	Mr. Anderson goes to Weigel for Round		
0605	Watch relieved by Orr		
0605	1 ST ASST ABOARD. MR. SPECTOR ASHORE R.E. O'Dell NIX - GANGWAY ORR - F/W		
0605	MR. CONNELLY 1/0 0800 - 1600		
0605	ASSUMED WATCH; ALL IN APPARENT GOOD ORDER.		
0650	1/0 CONNALLY ABOARD		
0705	MR. ANDERSEN 2/0 ASHORE. F/W MAKING POPE ROUNDS. CHSTEN & PURSER AED.		
0706	POPE ALARM SYSTEMS TESTED O.K.		
0707	CHIEF ENGINEER ABOARD		
0727	WEIGEL ALARM SYSTEM CHECKED O.K.		
0800	COLORS: DETEX ROUND ON WEIGEL.		
0815	STORES TO UNLOAD.		
0900	DETEX ROUND ON POPE		
1000	DETEX ROUND ON WEIGEL. ALL IN APPARENT GOOD ORDER. SINDONI, AB, RELIEVED ORR ON FIRE WATCH.		
1100	DETEX ROUND MADE ON POPE. ALL IN APPARENT GOOD ORDER.		
1200	J. LEO MSTU ABOARD. DETEX ROUND ON WEIGEL.		
1300	DETEX ROUND MADE ON POPE. A. OK		
1400	DETEX ROUND MADE ON WEIGEL. A. OK		
1400	MR. HURLEY REO ABOARD.		
1415	WATCH RELIEVED BY PELETI.		
1420	ELECTRONIC		
	Long in Ship AB		

AT/PASSAGE FROM		TO	
PIER 2 BERTH #33 HUNTER'S POINT		NAVAL SHIP YARD S. FRANCISCO CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
#7		28 NOVEMBER 1969	FRIDAY
TIME	MR KELLOG R/D.O MR HURLEY R/D.O	1600-2400	REMARKS DELET GANGWAY WATCH PERKINS FIRE WATCH
1430	ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER		
1445	MR CONNELLY '10 ASHORE & MR KELLOG R/D.O ABOARD		
1456	MR SMITH CH PURSER & CH STWARD ASHORE		
1500	J. LEO MSTU ASHORE		
1505	CH/ENG & ASST ASHORE		
1505	F/W ON "A" ROUND POPE		
1520	F/W RETURNS ON HIS ROUND ALL SECURE		
1550	F/W TO WEIGEL "A" ROUND		
1605	M/R ELECTRONIC TECHNICIAN ASHORE		
1620	F/W COMPLETED HIS ROUND ON WEIGEL ALL IN APPARENT GOOD ORDER		
1652	COLORS OBSERVED SECURE		
1700	F/W ON POPE "B" ROUND		
1725	F/W COMPLETED ROUND ON POPE ALL SECURE		
1750	F/W TO WEIGEL "B" ROUND		
1830	F/W RETURNS ON ROUND ALL SECURE		
1830	R/D.O MR KELLOG TO WEIGEL FOR HIS INSPECTION		
1850	MR KELLOG RETURNS FROM WEIGEL ALL IN APPARENT GOOD ORDER		
1900	F/W MADE ROUND ON POPE "A" ROUTE		
1915	F/W RETURNS ON HIS ROUNDS ALL SECURE		
1940	MR HURLEY R/D.O LEFT THE POPE TO WEIGEL FOR HIS INSPECTION		
1956	F/W MR HURLEY RETURNS FROM WEIGEL ALL IN GOOD ORDER		
2025	F/W RETURNS FROM HIS ROUNDS ON WEIGEL ALL SECURE		
2050	F/W ON HIS ROUND "B" POPE		
2110	F/W RETURNS FROM HIS ROUND ALL SECURE		
2115	MR KELLOG R/D.O LEFT POPE TO WEIGEL FOR HIS INSPECTION		
2135	MR KELLOG R/D.O RETURNS FROM WEIGEL ALL IN GOOD ORDER		
2150	F/W ON HIS LAST ROUND ON "B" ROUTE WEIGEL		
2220	F/W RETURNS FROM HIS ROUND ALL SECURE		
2230	WATCH RELIEVED BY ODELL A/B		
2230	ON WATCH Iredale F/W		

AT/PASSAGE FROM SF BNS Hunters Point	TO Rer #2 Berth 33
ZONE DESCRIPTION + 7	DATE (Day, month, year) 29 Nov. 69
	DAY OF WEEK SAT.

TIME	REMARKS
	0000 - 0800
2230	ON Watch Iredale Flw + O'Dell A/B
2250	Mr. Sherman aboard (RDO) Mr. Kellogg's Ashore
2300	Iredale Flw ON "A" route of Pope
2315	MR HORN RDO Aboard
2400	Iredale Flw + Mr Sherman RDO to Weigel for "A" route
0020	" " " " " " back from " " " OK.
0100	" " MAKING "B" round of Pope
0200	" " " " " " Weigel
0220	" " FINISHES " " " "
0300	" " STARTS "A" " " Pope
0330	" " FINISHES " " " "
0400	" " STARTS "A" " " Weigel
0425	" " FINISHES " " " "
0500	" " STARTS "B" " " Pope
0530	" " FINISHES " " " "
0540	" " STARTS " " " " Weigel
0600	" " FINISHES " " " " All secure
0600	Watch relieved by Nix PE O'Dell
	MR HORN RDO MR. SHERMAN RDO 0800 - 1600 NIX GANGWAY ORR FIRE WATCH
0600	ASSUMED WATCH: All in APPARENT GOOD ORDER.
0700	DETEX Round MADE ON POPE. 0704 SUN RISE.
0730	SOUNDINGS TAKEN
0800	COLORS: DETEX Round ON WEIGEL MADE. A. OK
0900	DETEX Round ON POPE.
1000	DETEX Round ON WEIGEL MADE.
1030	MAKELLOG RDO RELIEVED MR. KELLOG . SHERMAN
1100	DETEX Round ON POPE WEIGEL MADE.
1110	MR HURLEY RDO RELIEVED MR HORN.
1200	DETEX Round ON WEIGEL MADE. A OK
1300	DETEX Round ON POPE MADE. All in APPARENT GOOD ORDER.
1400	DETEX Round ON WEIGEL MADE.
1400	WATCH RELIEVED BY PELETI.

Shay Nix

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 HUNTER'S POINT		NAVAL SHIPYARD SAN FRANCISCO, CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		29 NOVEMBER 1969	SATURDAY
TIME	MR KELLOG R/D MR HURLEY R/E-O	REMARKS	DELETI, GANGWAY WATCH PERKINS FIRE WATCH
		1600-2400	
1430		ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER	
1430		MR KELLOG R/D LEFT FOR HIS SECURITY ROUND ON WEIGEL	
1500		MR KELLOG R/D RETURNS FROM HIS INSPECTION ALL IN GOOD ORDER	
1505		F/W MADE HIS "A" ROUND ON POPE	
1530		F/W RETURNS FROM HIS ROUNDS ALL IN APPARENT GOOD ORDER	
1555		F/W LEFT MADE HIS "A" ROUNDS ON WEIGEL	
1600		R/D RELIEVED GANGWAY WATCH FOR CHOW.	
1615		F/W RETURNS FROM HIS ROUND ON WEIGEL ALL SECURE	
1630		MR HURLEY R/E-O LEFT POPE TO WEIGEL INSPECTION	
1652		COLORS OBSERVED SECURE. & F/W MADE HIS "B" ROUND ON POPE	
1700		MR HURLEY R/E-O RETURNS FROM HIS INSPECTION ALL IN GOOD ORDER	
1715		F/W RETURNS ON HIS ROUND ALL SECURE	
1750		F/W TO WEIGEL MADE "B" ROUND	
1820		F/W RETURNS FROM ROUND ALL SECURE	
1900		R/D MR KELLOG LEFT FOR INSPECTION ON WEIGEL & F/W MADE ROUND "A" POPE	
1915		F/W RETURNS FROM ROUND ALL SECURE	
1920		MR KELLOG R/D RETURNS FROM HIS INSPECTION ALL SECURE	
1950		F/W LEFT MADE HIS "A" ROUND ON WEIGEL	
2020		F/W RETURNS FROM HIS ROUND ALL SECURE	
2100		MR HURLEY R/E-O TO WEIGEL ROUTINE INSPECTION. F/W ON "B" ROUND POPE	
2115		F/W RETURNS FROM HIS LAST ROUND ON POPE ALL SECURE	
2130		MR KELLOG MADE HIS LAST INSPECTION ON WEIGEL	
2135		MR HURLEY R/E-O RETURNS ALL IN GOOD ORDER	
2150		MR KELLOG RETURNS REPORT ALL IN APPARENT GOOD ORDER	
2155		F/W LEFT MADE HIS LAST ROUND "B" ON WEIGEL	
2200		MR SHERMAN R/D ABOARD RELIEVED MR KELLOG R/D	
2210		MR KELLOG R/D ASHORE	
2220		F/W RETURNS FROM HIS LAST ROUNDS ON WEIGEL ALL SECURE	
2230		WATCH RELIEVED BY ODELL A/B	
		Deleti A/B	

10 JAN 70

0 DEU } 0-8
1 ESTAL }

NK-ORR-8-11

1215 "Electr power failure
from shore

1535 Elec. power restored

1555 Elec power failure

DURAN,
COLADA

1830 Startal Emergency Diesel Gen.

2000 - no Shore power

11 JAN 70

0000 - no elec power available

0940 AC power restored to ship

1030 - Elec power on water.

1135 Elec power restored to POPPE

AT/PASSAGE FROM

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

SF BNS Hunters Pt. Pier #2 Berth 33

+7

30 Nov. 1969

SUNDAY

TIME	REMARKS
	0000-0800
2230	ON Watch Iredale F/W - O'Dell A/B Mr. Sherman RDO
2300	Mr. Horn RDO Aboard
2300	Iredale F/W starts "A" round on Pope
2400	" + RDO " " " Weigel
0100	" " " " " Pope
0200	" " " " " Weigel
0300	" " " " " Pope
0400	" ↓ RDO " " " Weigel
0500	" " " " " Pope
0530	" " " " " Weigel - All Secure
0600	Watch relieved by Nix
	Mr. Sherman RDO Mr. Horn RDO 0800-1600 NIX gangway OUR F/W
0600	ASSUMED WATCH: All in APPARENT Good ORDER.
0700	DETEX Round ON POPE MADE.
0800	COLORS: DETEX Round ON WEIGEL MADE.
0900	DETEX Round MADE ON POPE.
1000	DETEX Round MADE ON WEIGEL
1035	MR WAYNE RDO RELIEVED MR. SHERMAN.
1100	MR. HURLEY R/E ABOARD MR HORN, ASHORE.
1150	MR WAYNE TO WEIGEL - F/W MAKING DETEX Round ON WEIGEL.
1208	MR WAYNE RETURNS FROM WEIGEL. MR HURLEY TO WEIGEL.
1300	DETEX Round MADE ON POPE.
1400	DETEX Round MADE ON WEIGEL
1430	WATCH RELIEVED BY LARKIN.
1415	RELIEVED + ASSUMED THE WATCH. <i>Erny Nix</i>
1430	JACKSON F/W ON RD.
A' 1500	F/W JACKSON ON RD ON POPE 'A'.
1530	F/W REPORTS 'A' RD, DETEX CLOCK SECURE. (1/2 POPE) RDO WAYNE R/E ENG 1600-2400
* 1540	R/D WAYNE TO WEIGEL.
1550	" " RETURNS, JACKSON F/W TO WEIGEL
A' 1620	F/W REPORT WEIGEL SECURE.
1650	COLORS EXECUTED AHEAD SOPA. REL BY RDO FOR COLORS + MEAL. (20 MIN)
B' 1700	F/W ON POPE RDS 'B'. 1735 F/W REPORTS 'B' RTE DETEX SECURE
B' 1750	F/W TO WEIGEL FOR 'B' RTE DETEX STATIONS F/W REPORTS (1820 SECURE)
A' 1800	A/RD SEC. REPORT F/W ALL STATIONS.
* A' 3000	F/W TO WEIGEL ROUTINE RD (1950) RDO WAYNE TO WEIGEL
2030	F/W REPORTS WEIGEL A' RTE SECURE.
* 2035	MASTER. (CAPTAIN LANDRY) ON RD.
B' 2100	F/W TO WEIGEL. REPORTS POPE 'B' SECURE
2200	F/W REPORTS 'B' RTE WEIGEL SECURE ALL STATIONS
2225	WATCH RELIEVED BY IREDALE + O'DELL

AT/PASSAGE FROM ST BNS Hunters Pt.	TO Pier #2 Berth 33
ZONE DESCRIPTION +7	DATE (Day, month, year) Dec 1, 1969
	DAY OF WEEK Monday

TIME	REMARKS
	0000-0800
2230	ON Watch Iredale F/W - O'Dell A/B
2245	Mr SHERMAN, R.D.O. Aboard - Mr Wayne R.D.O. ashore
2250	Mrs Gray called - husband, Kyle Gray sick. Will not be in today
2300	Iredale F/W & Mr. Sherman R.D.O. "A" route, Pope
2400	" " " " " " "A" " Weigel
0100	" " " " " " "B" " Pope
0200	" " " " " " "B" " Weigel
0300	" " " " " " "A" " Pope
0400	" " " " " " "A" " Weigel
0500	" " " " " " "B" " Pope
0545	" " " " " " "B" " Weigel
0605	Iredale - F/W reports all secure
0610	Watch relieved by Sindoni R.D.O. R.E. O'Dell
MR. CONNELLY, /O	0800--1600 MEYER & SINDONI
0700	ROUTE "A" MADE ON POPE
0700	MR. SHERMAN R/O ASHORE.
0800	Johnson L. Called sick. ENG Fireman & Water tender
0800	COLORS - ROUTE "A" ON WEIGEL
0900	RT "B" MADE ON POPE
1000	RT "B" MADE ON WEIGEL
1100	RT "A" MADE ON POPE
1200	RT "A" MADE ON WEIGEL
1300	RT "B" MADE ON POPE
1355	MR. HURLEY R/O ABOARD -
1400	RT "B" MADE ON WEIGEL
1430	WATCH RELIEVED BY LARKIN Watch relieved
1440	R.D.O. WAYNE ON B.D. JACKSON F/W ON B.D.
1445	/O CONNELLY LEFT SHIP.
1500	CH. ENG. LEFT SHIP. CH. STEWARD & PURSER LEFT. /ASS & /P/ LEFT
A' 1505	F/W ON A' RD. POPE. WATCH 1600-2400 MR WAYNE (GILBERT) MR HURLEY (F) JACKSON
1600 1515	MASTS SAFETY OFFICER ON B.D. TO MASTERS OFFICE.
1535	R.D.O. WAYNE TO WEIGEL FOR ROUTINE CHECK.
1600	MR WAYNE ON B.D. MSTS INS. GARRISON ON B.D. TO SEE R.D.O.
1605	WATCH REL. FOR MEAL BY R.D.O.
1649	COLORS AS SOPAC MSTS INSPECTOR & SAFETY OFF LEFT SHIP CLEAR
A	F/W REPORT RD MADE WEIGEL R/ENG. OFF TO WEIGEL, MR HURLEY SEC
B' 1700	B' RD SECURE POPE
1735	MASTER LEFT SHIP.
B' 1800	B' RD WEIGEL, REP REC. SECURE. B' RTE, ALL STATIONS.
A 1900	A' POPE. REPORT REC. ALL SECURE. POPE A' RD ALL SECURE
A 2000	F/W TO WEIGEL. 2025 - ALL SECURE.
B 2100	POPE B' RTE SECURE REC. REPORT. R/ENG TO WEIGEL FOR F/R CH
B 2200	WEIGEL B' RTE SECURE. R/ENG RETURNS 2125 F/W REPORTS SECURE
2230	WATCH RELIEVED BY IREDALE. D. Larkin

AT/PASSAGE FROM	S.F. B.N.S Hunters Pt.	TO	Pier #2 Berth 33
ZONE DESCRIPTION	+7	DATE (Day, month, year)	2 Dec. 1969
		DAY OF WEEK	Tuesday

TIME	REMARKS
	0000 - 0800
2300	Fredale FW - Odell A/B + Sherman RDO. on Watch
2300	" " starts Round of Ship - "A" route - Pope
2400	" + RDO " " " " " " Weigel
0100	" " " " " " "B" " Pope
0200	" " " " " " "B" " Weigel
0245	CAPT. Ashore
0300	Fredale FW to route "A" ON Pope
0400	" " " " " " "A" " Weigel
0500	" " " " " " "B" " Pope
0530	" " " " " " " " " Weigel
0600	Mr Sherman RDO. Ashore
0620	" " " " aboard
0630	Watch relieved by Perkins A/B Rd Odell
	CONNELLY 1/0 (0800 - 1600) PERKINS - GANGWAY PELETI - FIREWATCH
0630	WATCH ASSUMED - GANGWAY - SHORELINE'S - RATTGUARDS - ALL SECURE
0715	SMOKE DETECTOR + Kidde Alarm tested on POPE (FW "A" RDS ON POPE) + Weigel
0745	SANITATION SYSTEM SECURED forward of frame #105 approx 2 hrs Robert P. Johnson - FIREMAN FW (ENG) CALLED IN FOR SH-MS4 TO CHF. ENGR.
0800	COLORS PROPERLY EXECUTED - FW - ON "A" RTE - WEIGEL
0900	FW - ON - "B" ROUTE - POPE - ALL SECURE
1000	FW - ON - "B" ROUTE - WEIGEL - SANITATION FWD IN OPERATION
1010	CAPT. LANDRY ABOARD
1100	FW - ON "A" RTE - ALL SECURE - 1145 SHADY A - PORT STWD - ABOARD
1200	FW - ON "A" RTE - WEIGEL
1230	MR. SHADY PORT STWD ASHORE - CHF STWD ASHORE
1300	FW - ON - "B" RTE - POPE - CHF STWD ABOARD
1400	FW - ON - "B" RTE - FW SECURED DETEX RDS both vessels all in apparent good order
- do -	Thompson Wiper ASHORE to TROVAC
1430	WATCH RELIEVED BY Perkins
1600 - 2400	RDO WAYNE RJENG. HURLEY L.M. Perkins (B) PERKINS (E) JACKSON
1430	RELIEVED AND ASSUMED THE WATCH.
1445	MR WAYNE RDO ON BDO
A 1500	1/0 CONNOLLY LEFT SHIP. RJENG. HURLEY ON BDO.
1535	RDO WAYNE TO WEIGEL. FW REPORTS 'A' RD SECURE.
1550	RDO ABOARD FROM WEIGEL. WATCH RELIEVED FOR MEAL. WEIGEL SECURE
A 1600	WON DECK. RELIEF ENG. TO WEIGEL. FW TO WEIGEL
1630	RJENG RETURNS NEKE SECURE. (1735)
B 1650	FW ON RDS. POPE. 'B' RTE. REPORTED COMPLETED + SECURE
1651	COLORS EXECUTED AS PER S.O.P (NAVY)
B 1800	FW TO WEIGEL, 1830 FW REPORTS WEIGEL SECURE.
A - 1900	FW ON RD POPE. 1935. FW REPORTS SECURE. MASTER LEFT SHIP
A 2000	RDO TO WEIGEL FW TO WEIGEL. MASTER ON BDO. RJ. RETURNS FW REP SECURE
2030	RJENG TO WEIGEL.
B 2100	POPE SECURED ON DETEX RD.
B 2200	WEIGEL SECURED ON DETEX RD.
2230	WATCH RELIEVED BY GRE. + NIX P. Louch

* CONTINUED

AT/PASSAGE FROM		TO	
PIER BERTH #33 - HUNTER'S POINT - SAN FRANCISCO - BAY - NAVAL SHIPYARD			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
47		3 DECEMBER 1969	WEDNESDAY
TIME	REMARKS		
	MR. SHERMAN ^R / _O MR. O'HARA ^R / _E (0000-0800) MR. GEORGE ORR ^N / _B GANGWAY MR. GUY NIX ^N / _B FIREWATCH		
* 2240	MR. SHERMAN ABOARD		
* 2250	MR. WAYNE ASHORE		
* 2300	MR. O'HARA ^R / _E ABOARD MR. HURLEY ASHORE. F/W MAKING POPE ROUNDS		
* 2400	F/W MAKING WEIGEL ROUNDS. SHERMAN TO WEIGEL		
0100	F/W MAKING POPE ROUNDS.		
0200	F/W MAKING WEIGEL ROUNDS.		
0300	F/W MAKING POPE ROUNDS.		
0400	F/W MAKING WEIGEL ROUNDS. SHERMAN TO WEIGEL		
0500	F/W MAKING POPE ROUNDS.		
0600	F/W MAKING WEIGEL ROUNDS.		
0620	WATCH RELIEVED BY LAURENCE M. PERKINS D.E.O.		
	MR. CONNELLY ^R / _O (0800-1600) PERKINS - GANGWAY PELETI - FIREWATCH		
0620	assumed the watch - all in apparent good order		
0640	MR. Connelly ^R / _O aboard		
0700	Mr. Sherman ashore - F/W MAKING "A" RTE POPE - PERKINS, H.D. upon ashore - REASSIGNMENT		
0715	KIDDE + SMOKE ALARMS TESTED ON POPE AND WEIGEL		
0800	COLORS PROPERLY OBSERVED & EXECUTED - F/W MADE "A" RTE - WEIGEL		
- do -	MR. LYON ³ / _O ASSIGNED JESSE / AS MEMBER OF SHIP POOL		
0900	F/W ON "B" RTE POPE - ALL SECURE		
1000	F/W ON "B" WEIGEL -		
- do -	2nd Lt. REPORTS TESTS RAN: ANCHOR WINDLASS 5 mins: -		
	- CAPSTANS #14 + 2: ⁵ / ₅ MINS - A.G. LAUNDRY Unit 1 hr + 1/2 -		
	MEGGER: #142 STEERING GEAR MOTOR - GYRO MOTOR		
1100	F/W ON "A" RTE, VISITORS + WELGE, CMDR; SUSTARICH (MR) - MSTS "SHADDOY" (PORT STAIN)		
1200	F/W ON "A" RTE - WEIGEL - ALL SECURE		
1245	- SHADDOY; CMDR WELGE; SUSTARICH; MSTS SUPPLY ASHORE.		
1300	F/W ON "B" RTE POPE - WATCH RELIEVED BY HEMPHILL - L.M. Perkins		
1400	F/W ON B RTE WEIGEL All Secure (1445 MR. HURLEY ON BD)		
1430	RELIEVED THE WATCH (BOSON) 1600-2400		
1500	RDO WAYNE ON BD. 1/6 CONNELLY LEFT SHIP		
1510	CHENG. LEFT, 1/ASS. + 2ND ASS. LEFT. PURSER LEFT. STEW. LEFT.		
A'	F/W REPORTS A RD. SECURE.		
1530	RDO WAYNE TO WEIGEL. 1600 RDO RETURNS, SECURE		
1600	REL. BY RDO FOR MEAL. 1620 REL. MATEC ASSUMED WATCH		
A' 1645	RDO REL. FOR COLORS A' RD WEIGEL BY F/W SECURE. REL. ENG. TO WELGE		
1651	COLORS AS PER SOPA. REL. ENG. SAID WEIGEL IS SECURE. ENG. WELGE		
B. 1700	B' RTE POPE REP SECURE. (1835		
B 1835	B RTE WEIGEL SECURE.		
A 1900	A' RTE POPE SECURE. MASTER TO BASED 1/6 TO WEIGEL		
A 2000	A RD WEIGEL SECURE, (G) WATCH + PLING TO WEIGEL RIG LT.		
B 2100	B. RD POPE (2135) F/W REPORTS POPE SECURE.		
2200	F/W TO WEIGEL FOR SECURITY RDO. F/W REPORTS SECURE		
2230	WATCH JACKSON + LARKIN RELIEVED BY ORR + NIX.		
NOTE	MR. WAYNE 1600-2400 WATCH LARKIN (G) MR. HURLEY JACKSON F/W		

* CONTINUED
NEXT PAGE