

AT/PASSAGE FROM PER #2 PERL 33 HUNTERS POINT - SAN FRANCISCO BAY	TO NAVY NAVAL SHIPYARD
ZONE DESCRIPTION + 7	DATE (Day, month, year) 4 DECEMBER 1969
	DAY OF WEEK THURSDAY

TIME	REMARKS
	MR SHERMAN R/O MR O'HARA R/E (0000-0800) MR. ORR A/B GANGWAY MR NIX A/B FIREWATCHMAN
* 2235	MR. SHERMAN R/O ABOARD
* 2240	MR. WAYNE ASHORE
* 2257	MR. O'HARA R/E ABOARD
* 2300	MR. HURLEY ASHORE. F/W MAKING POPE DETEX ROUNDS
0000	F/W MAKING WEIGEL ROUNDS
0100	F/W MAKING POPE ROUNDS. MR. SHERMAN TO WEIGEL
0200	F/W MAKING WEIGEL ROUNDS
0300	F/W MAKING POPE ROUNDS
0400	F/W MAKING WEIGEL ROUNDS MR. SHERMAN TO WEIGEL
0500	F/W MAKING POPE ROUNDS
0600	F/W MADE WEIGEL ROUNDS. MR. SHERMAN CHECKS DRAFT. 1 ST ASS'T ABOARD
0620	WATCH RELIEVED BY MR. LARRY PERKINS A/B <i>See On</i>
	MR. CONNELLY 1/0 (0800-1600) PERKINS - GANGWAY PELETI - FIREWATCH
0620	watch assumed - all in apparent good order
0630	Mr Sherman R/O Ashore - 1/0; PURSER; CH- STWD - ABOARD
0635	Mr O'Hara R/E Ashore
0700	F/W MADE "A" RTE ON POPE - CH- ENGR ABOARD - CARP taking soundings
0715	RAMOS FIREMAN CALLED IN - PERSONAL BUSINESS - MAY take full day - will report tomorrow msg relayed to Eng - yeoman -
	ALARMS; STROKE AND KIDDE; TESTED ON POPE AND WEIGEL
0800	colors properly executed - F/W ON "A" RTE WEIGEL
0900	F/W ON "B" RTE - MSG FOR DRIGGERS ^{PETER} ENG - CALL VAN HUKER M.S.T.U. Monday 8-DEC-69 VAN HUKER CALLED 0900 - Sam DUNKLE Wiper (POOL) to CH- STWD - ASSIGNMENT
1000	F/W ON "B" RTE WEIGEL
1100	F/W - completes "A" RTE POPE - ALL SECURE
1130	Purser ashore (Money Run)
1200	Purser aboard - all well - F/W - "A" RTE completion - WEIGEL
1300	CAPT. Landry ashore - F/W - completes "B" RTE POPE
1400	F/W completes "B" RTE ON WEIGEL
1425	WATCH RELIEVED BY Larkin AB
	<i>L. M. Perkins AB</i>
1430	RELIEVED AND ASSUMED THE WATCH (SEE POOL LOG)
A 1500	F/W ON "A" RD POPE. (2) MEN ON BD VERBAL ORDER TO CH- STEWARD MR WAYNE RDO ON BD. (1440) MR HURLEY R/ENG ON BD
1505	CH STEWARD, PURSER + CH. ENG + ASSTS LEFT SHIP.
1515	PORT STEWARD ABOARD, PICKED UP INVOICES, LEFT SAME!
1540	RDO WAYNE TO WEIGEL FOR INSPECTION CHECK. 1600 RETURNS SECURE.
A 1600	REL FOR MEAL BY RDO. ASSUMED WATCH 1620. F/W TO WEIGEL, 1625 REP SECURE
1650	COLORS AS PER S.O.P.A. REL BY MATE. R/ENG HURLEY TO WEIGEL FOR INSPECT
B 1710	R/ENG RETURNS WEIGEL IS SECURE. F/W TO WEIGEL, 1725 WEIGEL IS OK
B 1800	F/W TO WEIGEL 1835 F/W REPORTS WEIGEL SECURE.
A 1900	"A" RD POPE F/W ON RDO RDO TO WEIGEL. 1942 RETURN SECURE RET.
A 2000	A RD WEIGEL. F/W REPORTS SECURE. R/ENG TO WEIGEL, 2035 R/SECURE
B 2100	B RD. POPE 2140, F/W REPORTS SECURE
B 2200	F/W TO WEIGEL, 2230 F/W RETURNS, REPORTS SECURE.
2230	WATCH REL. BY NIX + ORR. <i>Black 9/5</i>

* CONTINUED NEXT PAGE

T/PASSAGE FROM		#	
PIER #2 BERTH #33 HUNTERS POINT		N.S.Y. S.F. CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
		5 DECEMBER 1969	FRIDAY
TIME	REMARKS		
	MR SHERMAN R/O MR O'HARA R/E	(0000-0600)	MR GEO. ORR A/B --- GANWAY MR GUY NIX B --- FIREWATCHMAN
* 2235	MR. SHERMAN R/O ABOARD		
* 2240	MR. WAYNE ASHORE. MASTER ABOARD		
* 2245	MR. O'HARA R/E RELIEVES MR. HURLEY		
* 2300	F/W MAKING POPE ROUNDS		
0000	F/W MAKING WEIGEL ROUNDS --- MR. SHERMAN THERE ALSO		
0100	F/W MAKING POPE ROUNDS		
0200	F/W MAKING WEIGEL ROUNDS		
0300	F/W MAKING POPE ROUNDS		
0400	F/W MAKING WEIGEL ROUNDS --- MR. SHERMAN TOO 2		
0500	F/W MAKING POPE ROUNDS		
0545	MR. SHERMAN OBSERVES THE DRAFT		
0600	F/W MADE WEIGEL ROUND		
0610	1 st ENG ABOARD.		
0615	WATCH RELIEVED BY PERKINS & PELETI.		
	L. Per. MR. CONNELLY R/O (0800-1600) PERKINS - GANWAY PELETI - FIREWATCH		
0615	WATCH ASSUMED - ALL IN APPARENT GOOD ORDER		
0640	MR. SHERMAN ASHORE - MR SMITH - PURSER - MR CONNELLY ABOARD		
0700	F/W ON "A" RTE POPE - MR O'HARA R/E ASHORE - SOUNDINGS BEING TAKEN - BOTH VESSELS		
0715	CHF - ENGR. ABOARD		
0800	F/W ON "A" RTE WEIGEL 0830 - GENOVIA - MACHINIST CALLED "AUTO TROUBLE WILL BE [unclear]"		
0840	CHF ENGR INFORMED VIA TONE - "BRADLEY - FIREMAN ON 5 DEC '69"		
0900	F/W - ON "B" RTE POPE -		
1000	F/W - ON "B" RTE WEIGEL		
1100	F/W - ON "A" RTE POPE		
1200	F/W - ON "A" RTE WEIGEL		
1245	WAS OILER CALLED - IN CONFERENCE WITH INTERNAL REVENUE SERVICE - "will not be in today"		
1300	F/W ON "B" RTE COMPLETION POPE - ALL IN GOOD ORDER		
1400	F/W - ON "B" RTE COMPLETION WEIGEL - ALL SECURE		
1415	GENOVIA - MACHINIST CALLED "AUTO STILL IN REPAIR - WON'T MAKE THE DAY" (CHF ENGR [unclear])		
1425	WATCH RELIEVED BY IREDALE AB - L.M. Perkins Mr. Wayne, RDO - (1600-2400) IREDALE, G/W - O'DELL, F/W		
1425	Assumed the watch - All secure		
1440	Mr. Hurley R/E ABOARD - Mr. Connolly ashore.		
1500	F/W on "A" rt. in Pope - Report all's well. 1630		
1535	Mr. Wayne, RDO on inspection in Weigel - All secure		
1600-1700	F/W on "A" rt. in Weigel - All secure		
1630	Mr Hurley making inspection Tour in Weigel		
1650	Sunset - Evening colors smartly executed.		
1700	DeTex "B" rd. in Pope - All secure notes F/W @ 1725		
1755	CAPT Landry ashore -		
1800	DeTex round "B" in Weigel - All secure		
1900	DeTex rd. "A" made in Pope - Mr. Wayne away To Weigel		
2000	DeTex "A" rt. in Weigel - F/W reports all secure 2025		
2100	DeTex B round in Pope - F/W reports all's well -		
2200	DeTex round B made in Weigel - do		
2210	Relieved of watch by Guy Nix		

AT/PAGE 1 FROM

PIER TWO BERTH THIRTY-THREE
ZONE DESCRIPTION

HUNTERS PT. N.S.Y. ST. CA.

DATE (Day, month, year)

6 DEC 1969

DAY OF WEEK

SATURDAY

TIME	REMARKS
*2235	MR. SHERMAN ABOARD
*2240	MR. WAYNE ASHORE
*2310	MR. O'HARA RELIEVES MR. HURLEY F/W MADE POPE ROUNDS MR. SHERMAN R/O MR. O'HARA R/K 0000-0800 MR. GEO. ORR - GANGWAY MR. GUY NIX - FIREWATCH
0025	CAPTAIN LANDRY ABOARD - WEIGEL ROUND MADE
0100	DETEX Round made on POPE
0200	DETEX Round made on WEIGEL --- MR. SHERMAN THERE TOO
0300	F/W MADE POPE ROUND
0400	F/W MADE IT ON WEIGEL --- MR. SHERMAN TOO
0500	F/W ON POPE ROUNDS
0600	F/W MADE WEIGEL ROUNDS
0620	WATCH RELIEVED BY LARRY PERKINS <i>Larry Perkins</i>
	MR. SHERMAN R/O MR. O'HARA R/K (0800-1600) PERKINS - GANGWAY PELETI - FIREWATCH
0620	watch assumed - All-in - APPARENT GOOD ORDER
0700	F/W ON - "A" - RTE - POPE
0800	COLORS - EXECUTED - F/W & R/O ON RDS WEIGEL - SOUNDINGS TAKEN WEIGEL "All day"
0900	F/W ON - "B" RTE POPE - SOUNDINGS TAKEN AND RECORDED
1000	F/W ON - "B" RTE WEIGEL - MR. LINDBERGH ABOARD - MR. O'HARA R/O ASHORE F/W SWITCHED SMOKE DETECTOR MOTOR ON WEIGEL
1030	MR. WAYNE R/O ABOARD - MR. SHERMAN R/O ASHORE
1100	F/W "A" RTE - POPE - completed - all secure
1200	R/O to WEIGEL - F/W ON - "A" RTE - WEIGEL - (1200-1600) MR. WAYNE R/O ASHORE MR. LINDBERGH R/O
1300	F/W completes "B" RTE on POPE
1400	F/W ON "B" RTE completion on WEIGEL - R/O to WEIGEL
1425	WATCH RELIEVED BY TREDALE <i>Larry Perkins</i>
	MR. WAYNE, RDO (1600 - 2400) TREDALE, G/W - O'DELL, F/W
1425	Assumed the watch. Conditions normal.
1500	DETEX "A" round made in Pope. F/W notes all secure 1530
1600	DETEX "A" rd. in Weigel - do - 1635
1640	MR Wayne making inspection Tour in Weigel
1649	Sunset - Evening colors executed.
1700	DETEX A rd made in Pope. F/W notes all secure 1740
1800	DETEX B rd. made in Weigel - do - 1835
1900	DETEX A rd. made in Pope - do - 1925
1915	Mr. Wayne on inspection Tour in Weigel -
2000	DETEX A rd. made in Weigel - F/W reports all secure 2050
2100	DETEX B rd. made in Pope - F/W notes all secure
2120	Leaking, i.e., stopped up urinal + deck drain noted in Heat -
	2-167-2 - Isolation valve secured to prevent further flooding
2150	DETEX round B made in Weigel. F/W reports all well @ 2210
2212	Relieved of watch by NIX
2215	MR O'HARA R/O ABOARD
2240	MR. SHERMAN R/O ABOARD <i>Larry Perkins</i>
2245	MR. WAYNE ASHORE
2300	THE FIREWATCH IS MAKING A DETEX ROUND ON THE POPE

AT/PASSAGE FROM
P, ER #2 BERTH #33 HUNTERS POINT N.S.Y. S.F. CALIF
ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

7 DEC. 1969

SUNDAY

TIME	REMARKS
	MR. SHERMAN R/O (0000-0800) MR. ORR A/B GANGWAY MR. O'HARA R/E MR. NIX A/B FIREWATCHMAN
0000	F/W TO THE WEIGEL. R/O TOO.
0100	F/W WALKING THE POPE
0200	F/W TOURS THE WEIGEL
0300	F/W AROUND THE POPE
0400	F/W + R/O TO THE WEIGEL
0500	F/W DOING HIS THING ON POPE
0600	F/W COMPLETES WEIGEL ROUND.
0615	WATCH RELIEVED Geo Orr by JACKSON J.F.
0635	MR. SHERMAN R/O JACKSON J.F. GANGWAY MR. O'HARA R/O 0800-1600 LARKIN FIREWATCH
0650	RELIEVED THE WATCH ALL IN APPERT GOOD ORDER
0715	WATCH RELIEVED FOR CHOW
0715	WATCH RETURN FROM CHOW
0715	WATCH MAKING ROUND ON DETEX CLOCK ON POPE A RT.
0715	WATCH REPORTS ALL SECURE ON POPE
0800	WATCH LEFT SHIP FOR WEIGEL FOR DETEX
0800	COLORS EXECUTED
0816	R/O TO WEIGEL FOR INSPECTION
0825	R/O & FIRE WATCH RETURN FROM WEIGEL ALL SECURE
0900	F/W MAKING RDS ON POPE B RT.
1000	CAPT. LANDRY MASTER LEFT THE SHIP -
1030	F/W RETURN TO SHIP FROM WEIGEL
1035	MR. SHERMAN R/O ASHORE MR. WAYNE ON BOARD
1050	MR. LINBERG R/E ON BOARD
1100	MR. O'HARA ASHORE
1120	F/W MADE RDS ON GEN POPE A RT. ALL SECURE
1158	R/O & F/W LEFT SHIP FOR WEIGEL
1215	R/O RETURN FROM THE WEIGEL
1230	F/W RETURN FROM WEIGEL & SOUNDING TAKEN DRY
1300	F/W MAKING ROUNDS ON POPE B RT.
1315	F/W COMPLETED RDS ON POPE ALL SECURE
1406	F/W TO WEIGEL FOR RDS ON DETEX
1425	WATCH RELIEVED by IREDALE A/B Joseph J. Jackson MR. WAYNE, RDO (1600-2400) IREDALE, F/W. O'DELL, F/W
1500	Detex "A" rd. made in Pope - F/W notes all secure 1530
1515	MR. WAYNE, RDO, makes inspection Tour in USNS Weigel.
1545	CAPT. LANDRY ABOARD.
1600	Detex "A" round made in Weigel - F/W notes all well 1625
1650	Sunset - Evening colors smartly executed.
1700	Detex "B" rd. in Pope - F/W notes all secure @ 1730
1800	Detex "B" rd. made in Weigel - do - @ 1825
1830	MR. WAYNE, RDO, away To Weigel
1900	Detex A rd. in Pope - All secure
2000	Detex A rd. in Weigel - All secure
2100	Detex B rd made in Pope - F/W reports all secure 2140
2140	Detex B round made in Weigel - All secure
2215	Watch relieved by JACKSON

J. Jackson

AT/PASSAGE FROM	TO
PIER 2 BERTH 33	HUNTERS POINT NAVAL SHIP YARD
ZONE DESCRIPTION	DATE (Day, month, year)
+ 7	12-8-69
	DAY OF WEEK
	SAT MON

TIME	REMARKS
	MR. O'HARA R/E MR. SHERMAN R/O (0000-0800) JACKSON J.F. C/W LARKIN P. R/W
2240	ASSUMED THE WATCH ALL IN APPERT GOOD ORDER
2255	MR. LINBERG ASHORE R/O
2300	F/W ON RDS ON POPE A RT.
2325	" MADE RDS ON A RT.
2355	F/W TO WEIGEL F/W RETURN FROM WEIGEL ALL SECURE
0000	F/W MAKING ROUNDS ON POPE
0150	F/W LEFT SHIP FOR WEIGEL F/W RETURN FROM WEIGEL ALL SECURE
0310	F/W MAKING ROUNDS ON POPE ALL SECURE
0405	R/O LEFT SHIP FOR WEIGEL 0410 R/O RETURN ALL SECURE
0405	F/W LEFT SHIP FOR WEIGEL F/W RETURN FROM WEIGEL 0430 ALL SECURE
0500	RDS MADE ON POPE by F/W
0545	REEFER BOX IN MAIN GALLEY WAS SMOKING 90T NIGHT ENG. CUT OFF POWER ALL SECURE
0550	F/W LEFT SHIP FOR WEIGEL F/W RETURN TO SHIP ALL SECURE
0625	WATCH RELIEVED (SINDONI - CONNALLY I/O) 8-DEC-1969 Joseph H. Jackson
0650	MR CONNELLY I/O ABOARD - MR SHERMAN R/O ASHORE.
0655	MR O'HARA R/E ASHORE - 0700 RT "A" ON POPE
0715	SANITARY SYSTEM CLOSE FOR 2 HR.
0800	COLORS MADE - RT "A" ON WEIGEL
0900	RT "B" ON POPE
0950	CLEVELAND PORT STEW. ABOARD.
1000	RT "B" ON WEIGEL
1025	CLEVELAND PORT STEW. ASHORE
1100	RT "A" ON POPE
1200	RT "A" ON WEIGEL
1300	RT "B" ON POPE
1325	PURSER ASHORE
1400	RT "B" ON WEIGEL
1400	PURSER ABOARD.
1430	WATCH RELIEVED BY IREDALE MR. WAYNE, RDO (1600-2400) IREDALE C/W. O'DELL, F/W
1500	DeTex "A" round made in Pope. F/w notes all secure @ 1525
1540	DeTex "A" rd. made in Weigel - do 1600
1600	MR. WAYNE, RDO, making security round in USNS Weigel.
1600	MR Electronic Tech. & Mr. Erickson, ashore -
1650	Sunset. Evening colors executed. Master ashore
1700	DeTex "B" round made in Pope. F/w notes all secure 1730
1800	DeTex B round in Weigel - do - 1835
1904	DeTex A route made in Pope.
1930	Mr Wayne To Weigel on inspection Tour
2000	DeTex A route in Weigel - All secure
2100	DeTex A RT in Pope. All secure
2130	DeTex B RT. in Weigel do.
2200	Relieved of watch by Pelati, A/B

AT/PASSAGE FROM		TO	
PIER 2 BERTH 33 HUNTER'S POINT		NAVAL SHIP YARD SAN FRANCISCO CALI	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		9 DECEMBER 1969	TUESDAY
TIME	MR SHERMAN R/D O MR O'HARA R/O	REMARKS	
		PERKINS FIRE WATCH	
		0000-0800	
2240	MR WAYNE R/D O ASHORE & MR SHERMAN R/D O ABOARD		
2250	MR O'HARA R/O ABOARD & MR HURLEY ASHORE		
2255	F/W ON ROUND ON POPE "A" ROUTE		
2315	F/W RETURNS FROM ROUND ALL SECURE		
2350	F/W TO WEIGEL ROUNDS ON "A" ROUTE		
2355	MR SHERMAN R/D O LEFT POPE TO WEIGEL		
0000	MR SHERMAN R/D O RETURNS FROM WEIGEL ALL IN GOOD ORDER		
0030	F/W RETURNS FROM WEIGEL ALL SECURE		
0055	F/W ON HIS ROUNDS ON POPE "B" ROUTE.		
0100	MR O'HARA R/O ASHORE		
0115	F/W RETURNS FROM HIS ROUNDS ALL SECURE		
0140	MR O'HARA R/O ABOARD		
0200	F/W TO WEIGEL ROUND "B" ROUTE		
0225	F/W RETURNS FROM WEIGEL ALL SECURE		
0300	F/W ON HIS ROUNDS "A" ROUTE ON POPE		
0315	F/W RETURNS FROM HIS ROUNDS ALL SECURE		
0400	F/W & MR SHERMAN TO WEIGEL ROUTE "A"		
0415	F/W RETURNS FROM WEIGEL ALL SECURE		
0425	MR SHERMAN RETURNS FROM WEIGEL ALL SECURE		
0500	F/W MADE ROUND "B" ROUTE ON POPE ALL SECURE		
0550	MR SHERMAN R/D O & F/W TO WEIGEL "B" ROUNDS		
0555	MR SHERMAN RETURNS FROM WEIGEL ALL IN APPARENT GOOD ORDER		
0610	MR THOMSON 2ND ENG ABOARD & MR PECK 1ST ENG ABOARD		
0615	F/W RETURNS FROM HIS LAST ROUNDS ON WEIGEL ALL SECURE		
0625	WATCH RELIEVED by ^{JACKSON} MR LARKIN A/B.		
	MR CONLEY 1 st (0800-1600)	JACKSON 1 st GANGWAY LARKIN FIRE WATCH	
0630	RELIEVED THE WATCH ALL IN APPARENT GOOD ORDER		
0710	F/W MADE ROUNDS ON POPE "A" RT		
0715	TEST OF THE SHIP'S FIRE ALARM WAS TESTED AND SMOKE DET.		
0730	TEST OF THE WEIGEL FIRE ALARM WAS TESTED AND SMOKE DET.		
0745	WILLIAMS OILER CALL WILL CALL BACK AT 1100		
0800	MADE ROUNDS 01025		
0800	F/W MAKING ROUNDS ON GEN WEIGEL ALL SECURE "A" RT		
0900	F/W MADE RDS ON "B" RT.		
0950	WATCH TO WEIGEL TO MAKE RDS ON "B" RT.		
1001	MR. ROBINSON AND MR. CLEVELAND PORT STW. ON BOARD		
1115	F/W MAKING ROUNDS ON POPE "A" RT.		
1150	CAPT. LANDRY ASHORE		
1200	F/W MAKING ROUNDS ON WEIGEL "A" RT.		
1300	F/W MAKING RDS ON POPE "B" RT.		
1350	F/W MADE RDS ON GEN. WEIGEL		
1400	CAPT. LANDRY RETURN TO SHIP		
1428	WATCH RELIEVED by IREDALE	Joseph F. Jackson	

Continued

AT/PASSAGE FROM S.F.B.N.S. + Hunters Point	TO	
ZONE DESCRIPTION	DATE (Day, month, year) 9 Dec 69	DAY OF WEEK Tues.

TIME	REMARKS
	Mr. Wayne, RDO (1600-2400) IREDALE, G/W - ODELL, F/W
1430	Assumed the watch. All secure.
1445	Mr Wayne ABOARD.
1455	Mr Hurley ABOARD.
1500	F/W commencing security rounds - "A" Rt. - Pope -
1540	Mr Wayne, RDO, To Weigel.
1615	Detex "A" round in Weigel. Report of all secure - 1635
1650	Sunset - colors made -
1705	Detex B rd. in Pope - do. 1730
1800	Detex B round in Weigel - do. 1825
1900	Detex A rd. in Pope do. 1922
1930	Mr Wayne away TO Weigel - Weigel's gangway repositioned.
2000	Detex A round in Weigel / F/W notes all's well 2020
2100	Detex B round in Pope - do. 2130
2145	Detex B round in Weigel do.
2150	Relieved of watch by Peletti

AT Iredale

AT/PASSAGE FROM		TO	
PIER 2 BERTH #33 HUNTER'S POINT		NAVAL SHIP YARD SAN FRANCISCO CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		10 DECEMBER 1969	TUESDAY WED.
TIME	REMARKS		
	0000-0800 PELETI GANWAY WATCH PERKINS FIRE WATCH		
2200	Assumed the Watch ALL IN APPARENT GOOD ORDER		
2240	MR SHERMAN R/OO ABOARD RELIEVED MR WAYNE R/OO.		
2255	MR LARKIN A/B. WAS CALLING SICK		
2300	MR O'HARA R/OO ABOARD RELIEVED MR HURLEY R/OO.		
2305	F/W MADE ROUND "A" ON POPE ALL IN GOOD ORDER		
2355	F/W TO MADE HIS ROUNDS "A" ON WEIGEL		
0005	MR SHERMAN R/OO TO WEIGEL		
0020	MR SHERMAN ABOARD ALL IN APPARENT GOOD ORDER		
0025	F/W RETURNS FROM HIS SECURITY ROUNDS ALL SECURE		
0100	F/W MADE ROUNDS ON POPE "B" ROUTE ALL SECURE		
0200	F/W MADE ROUNDS "B" ON WEIGEL ALL SECURE		
0300	F/W MADE ROUNDS "A" ON POPE ALL SECURE		
0405	MR SHERMAN R/OO TO WEIGEL		
0415	MR SHERMAN RETURNS ABOARD ALL IN APPARENT GOOD ORDER		
0430	F/W RETURNS FROM WEIGEL ALL SECURE		
0500	F/W MADE ROUNDS "B" ON POPE ALL IN GOOD ORDER		
0605	MR PECK 1 st Eng ABOARD. MR THOMSON 2 nd Eng ABOARD 0610		
0615	F/W RETURNS FROM HIS LAST ROUNDS ON WEIGEL "B" ROUTE ALL SECURE AND CLOSED ALL WEATHER TIGHT DOORS ALL SECURE ON WEIGEL MR WAYNE Y/O (0800-1600) Delate A/B		
0630	Watch Relieved by Gray - on watch 1/0 Mr Connally Gray F/W - Jackson Ganway		
0640	Linberg (Plumber) called reported car trouble		
0700	TEST WAS MADE ON THE WEIGEL ^{POPE} FIRE ALARM		
0700	F/W MAKING ROUNDS ON GEN. POPE A RT.		
0730	TEST WAS MADE ON THE POPE ^{WEIGEL} FIRE AND SMOKE DET.		
0800	MADE MORNING COLORS		
0900	F/W MAKING ROUNDS ON POPE B RT.		
1000	MR. ROBINSON & MR. CLEVELAND ON BOARD		
1000	TEST MADE OF FIRE PUMP & EMG. GENERATOR		
1000	F/W MAKING RDS. ON WEIGEL B RT.		
1100	CAPT. LANDRY MASTER ASHORE		
1100	F/W MAKING RDS ON POPE A RT.		
1200	F/W MAKING RDS ON WEIGEL A RT.		
1300	F/W " " " POPE B RT.		
1400	F/W " " " WEIGEL B RT.		
1415	WATCH RELIEVED BY NIX A/B. Joseph H. Johnson MR WAYNE Y/O 1600-2400 = ORR-FIRE WATCH ^{NIX-GANWAY}		
1415	ASSUMED WATCH - ALL IN APPARENT GOOD ORDER.		
1445	MR WAYNE R/O ABOARD		
1455	MR. HURLEY R/O ABOARD		
1500	F/W MAKING POPE ROUNDS		
1530	MR WAYNE TO WEIGEL: 1547 MR WAYNE RETURNED		
1545	ORR MAKING DETEX ROUND ON WEIGEL.		
1600	MSTS ELCO ASHORE.		
1700	DETEX ROUND MADE ON POPE.		
1800	DETEX ROUND BEING MADE ON WEIGEL.		

AT/PASSAGE FROM

PIER 2 BERTH #33 HUNTERS POINT

TP

DATE (Day, month, year)

DAY OF WEEK

SAN FRANCISCO

CALIF

+ 7

10 DEC 1969 WED.

TIME

REMARKS

MR. HURLEY, RED

MR. WAYNE 'O

1600 - 2400 NIX GANGWAY ORR FIRE WATCH

1900 F/W MAKING POPE ROUNDS. MASTER ASHORE

2000 F/W MAKING ROUNDS ON WEIGEL. CAPTAIN ABOARD.

2100 F/W MAKING ROUNDS ON POPE

2200 F/W MAKING ROUNDS ON WEIGEL.

2210 WATCH RELIEVED BY PERKINS & PELETI.

Guy M. Vix

AT/PASSAGE FROM	TO
PIER 2 BERTH #33 HUNTER'S POINT NAVAL SHIP YARD SAN FRANCISCO CALIF	
ZONE DESCRIPTION	DATE (Day, month, year)
	11 DECEMBER 1969
	DAY OF WEEK
	WE

TIME	REMARKS
	MR ANDERSON R/D MR SHEPHERD R/D MR O'HARA R/D 0000-0800 PELETI GANGWAY WATCH PERKIN FIRE WATCH
2255	MR O'HARA R/D RELIEVED MR HURLEY R/D. ABOARD
2300	MR HURLEY R/D ASHORE. F/W ON "A" ROUTE POPE ALL SECURE
2310	MR ANDERSON R/D RELIEVED MR WAYNE ABOARD
0000	F/W MADE ROUNDS ON WEIGEL "A" ROUTE ALL SECURE
0020	MR ANDERSON TO WEIGEL FOR ROUTINE CHECK
0045	R/D ANDERSON RETURNS FROM WEIGEL ALL IN APPARENT GOOD ORDER
0100	F/W MADE ROUNDS ON POPE "B" ROUTE ALL SECURE
0200	F/W MADE ROUNDS ON WEIGEL "B" ROUTE ALL SECURE
0205	MR LARKIN A/B WAS CALLING SICK
0300	F/W MADE "A" ROUNDS ON POPE ALL SECURE
0400	F/W MADE "A" ROUNDS ON WEIGEL ALL SECURE
0500	F/W MADE "B" ROUNDS ON POPE ALL SECURE
0505	R/D MR ANDERSON TO WEIGEL FOR ROUTINE CHECK
0520	R/D MR ANDERSON RETURNS FROM WEIGEL ALL IN GOOD ORDER
0520	MR GENOVIA MACHINIST WAS CALLING SICK
0600	F/W MADE "B" ROUNDS ON WEIGEL ALL SECURE
0610	MR PECK 1 ST ENG ABOARD
0630	WATCH RELIEVED BY SINDONI
0635	JACKSON J.F. <i>Peletti A/B</i>
	MR CONLEY 1 ST (0800-1600) JACKSON J.F. GANGWAY SANDONI FIREWATCH
0635	ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER
0640	MR CONNALLY 1 ST ABOARD, MR ANDERSON R/D ASHORE
0700	MR ENG BANTZ CH. ENG. ABOARD. RT "A" ON POPE
0705	MR OHARA R/D ASHORE
0730	STEAM WILL BE SECURED FOR ONE HOUR
0730	TEST OF THE WEIGEL FIRE AND SMOKE DET TESTED
0800	MADE MORNING COLORS WATCH MAKING RDS. ON WEIGEL "A"
0830	STEAM WAS
0900	F/W MAKING RDS. ON POPE "B"
1000	F/W MAKING RDS. ON WEIGEL "B"
1006	PURSER LEFT SHIP FOR BID. 310 NAVAL SUPPLY CNTR.
1030	LT. HEATHINGTON MSTS AND LT J.G. ON BOARD
1045	CH. MATE ASHORE.
1100	RT "A" MADE ON POPE
1155	ANCHOR WINDLASS TESTED. 1200 RT "A" ON WEIGEL
1210	MR. CONLEY FIRST OFF RETURN TO SHIP
1220	MR. MINIX MSTS REP. ON BOARD
1255	CAPT. LANDRY MASTER ASHORE
1300	RT "B" MADE ON POPE
1337	PURSER RETURN TO SHIP FROM BID. 310 NAV. SUP. CNTR.
1400	F/W TO WEIGEL FOR "B" RDS.
1410	WATCH RELIEVED BY NIX A/B <i>Joseph J. Jackson</i>

AT/PASSAGE FROM
PIER 2 BERTH #33 HUNTERS POINT TO
NAVAL SHIP YARD SAN FRANCISCO
 ZONE DESCRIPTION
#7 DATE (Day, month, year) **11 DEC 1969** DAY OF WEEK **THUR.** **CALIF**

TIME	REMARKS
	MR WAYNE 1/6 MR. ROBERT R/E
	1600-2400 NIX-GANGWAY ORR-FIRE WATCH
1410	ASSUMED WATCH- ALL IN APPARENT GOOD ORDER.
1445	MR WAYNE RELIEVED MR CONNALLY 1/6.
1445	INSTU REP. ASHORE.
1500	MR. ROBERT R/E ABOARD. F/W MAKING POPE ROUNDS
1545	F/W MAKING DETEX ROUND ON WEIGEL. MR WAYNE MAKING INSPECTION OF WEIGEL.
1605	MR WAYNE RETURNED FROM WEIGEL.
1645	R/E TO WEIGEL
16	COLORS EXELUTED
1700	F/W MAKING POPE ROUNDS
1715	R/E COMPLETES INSPECTION OF WEIGEL.
1800	F/W MAKING WEIGEL ROUND.
1900	F/W MAKING POPE ROUND.
1915	MR WAYNE MAKING ROUND ON WEIGEL.
2000	F/W MAKING ROUND ON WEIGEL
2100	F/W MAKING ROUND ON POPE.
2130	R/E TO WEIGEL
2150	R/E RETURNS FROM WEIGEL.
2200	F/W MAKING ROUND WEIGEL.
2200	WATCH RELIEVED BY PELETI. ALL IN APPARENT GOOD ORDER.

Every 15 min

AT/PASSAGE FROM	TO
PER 2 BERTH #33 HUNTER'S POINT	NAVAL SHIP YARD SAN FRANCISCO CALIF
ZONE DESCRIPTION	DATE (Day, month, year)
+7	12 DECEMBER 1969
	DAY OF WEEK
	THURSDAY

TIME	REMARKS
	MR ANDERSON R/D.O MR O'HARA R/O 0000-0800 R/E 1st GANWAY WATCH PERKIN FIRE WATCH
2230	ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER
2300	MR ANDERSON R/O ABOARD RELIEVED MR WAYNE R/O ASHORE
2310	MR O'HARA R/O ABOARD RELIEVED MR ROBERT R/O ASHORE
2315	F/W MADE ROUNDS "A" ON POPE ALL IN GOOD ORDER
0000	F/W MADE ROUNDS "A" ON WEIGEL ALL SECURE
0030	MR ANDERSON R/O TO WEIGEL FOR ROUTINE CHECK
0045	MR ANDERSON R/O RETURNS FROM WEIGEL ALL IN APPARENT GOOD ORDER
0100	F/W MADE ROUNDS "B" ON POPE ALL SECURE
0200	F/W MADE ROUNDS "B" ON WEIGEL ALL SECURE. 3 RD MATE ABOARD
0300	F/W MADE ROUNDS "A" ON POPE ALL SECURE
0400	F/W MADE ROUNDS "A" ON WEIGEL ALL SECURE
0500	F/W MADE ROUNDS "B" ON POPE ALL SECURE
0600	F/W MADE ROUNDS "B" ON WEIGEL ALL SECURE
0615	MR PECK 1 ST ENG ABOARD
0620	MR ANDERSON TO WEIGEL FOR LAST ROUTINE CHECK
0630	MR ANDERSON RETURNS FROM WEIGEL ALL SECURE
0635	WATCH RELIEVED BY O'DELL
	Telet
0635	ON WATCH Iredale F/W - O'Dell A/B All in order
0655	Mr Anderson R/O Ashore 1/0 Mr Connally Aboard
0700	Iredale F/W starts "A" round Pope
0720	" " finished " " "
0800	Colours observed
0800	Iredale F/W starts "A" round Weigel
0900	" " " "B" " Pope
1000	" " " "B" " Weigel
1100	" " " "A" " Pope
1200	" " " "A" " Weigel
1300	" " " "B" " Pope
1345	" " " "B" " Weigel
1400	Watch relieved by Nix A/B
	MR. WAYNE - R/O MR ROBARDS. R/O 1600 - 2400 Nix - GANWAY OAR - FIRE WATCH
1400	WATCH ASSUMED.
1445	MR. CONNALLY 1/0 RELIEVED BY MR WAYNE - MR ROBARDS ABOARD.
1450	FIRST ASST ENG. ASHORE.
1500	DETEX ROUND ON POPE.
1600	F/W 1/0 + R/E COMPLETE TOUR OF WEIGEL
1651	SUNSET - A - COLORS EXECUTED
1700	ROUND MADE ON POPE. (F/W)
1800	DETEX ROUND ON WEIGEL MADE.
1900	DETEX ROUND ON POPE MADE.
2000	MR WAYNE 1/0 + F/W OAR MAKING ROUNDS ON WEIGEL. 2020 RETURN
2100	DETEX ROUND MADE ON POPE.
2200	DETEX ROUND MADE ON WEIGEL
2200	WATCH RELIEVED BY PELETI.
2220	MR WAYNE 1/0 TO WEIGEL A MR ROBARDS R/E
2230	MR WAYNE & ROBARDS R/E RETURNS FROM WEIGEL ALL SECURE
	Shy m nix

AT/PASSAGE FROM		TO
Pier 2 BERTH #33 HUNTER'S POINT		NAVAL SHIPYARD SAN FRANCISCO, CALI.
ZONE DESCRIPTION		DATE (Day, month, year)
		13 DECEMBER 1969
		DAY OF WEEK
		FRIDAY SAT.
TIME	REMARKS	
	MR ANDERSON R/D.O. MR O'HARA R/O	
	0000-0800 PERKIN FIRE WATCH ^{PERKIN FIRE WATCH}	
2230	ASSUMED THE WATCH ALL IN APPARENT GOOD ORDER	
2255	MR O'HARA R/O ABOARD RELIEVED MR ROBERT R/O ASHORE	
2300	MR ANDERSON R/D.O ABOARD RELIEVED MR WAYNE R/D.O ASHORE	
2305	F/W ON "A" ROUNDS POPE ALL SECURE	
0000	F/W ON "A" ROUNDS WEIGEL ALL SECURE	
0020	MR O'DELL WAS CALLING SICK	
0035	MR ANDERSON R/D.O TO WEIGEL FOR ROUTINE CHECK	
0050	MR ANDERSON R/D.O RETURN FROM WEIGEL ALL IN APPARENT IN GOOD ORDER	
0100	F/W ON "B" ROUND POPE ALL SECURE	
0200	F/W ON "B" ROUND WEIGEL ALL SECURE	
0300	F/W ON "A" ROUND POPE ALL SECURE	
0400	F/W ON "A" ROUND WEIGEL ALL SECURE	
0500	F/W ON "B" ROUND POPE ALL SECURE	
0600	F/W ON "B" ROUND WEIGEL ALL SECURE	
0620	MR ANDERSON R/D.O TO WEIGEL FOR ROUTINE CHECK	
0635	MR ANDERSON RETURNS FROM WEIGEL ALL IN APPARENT GOOD ORDER	
0635	WATCH RELIEVED BY IREDALE	
	<i>Delati</i>	
0635	Mr. Anderson, RDO (0600-1600) IREDALE F/W & G/W	
0600	Assumed the watch. Vessel quiet - Conditions normal.	
0600	Colors observed	
0630	Soundings made in Weigel - All dry	
0700	Soundings made in Pope -	
0745	Mr. Anderson To Weigel for inspection Tour.	
1045	Mr Robert, R.E. ABD.	
1055	Mr Wayne, RDO, ABOARD. Mr Anderson	
1145	B rd. made in Weigel - All secure	
1230	"A" rd made in Pope - do.	
1330	All secure throughout vessel.	
1400	Relieved of watch by Nix	
	<i>Delati</i>	
	MR WAYNE RDO 1400 - 2400 ^{NIX GANGWAY} ORR - FIRE WATCH	
1400	ASSUMED WATCH - ALL IN APPARENT GOOD ORDER.	
1415	MR WAYNE TO MAKING AN INSPECTION ON WEIGEL.	
1430	MR. WAYNE TO BACK FROM WEIGEL.	
1500	FIREWATCH MAKING ROUNDS ON WEIGEL ^{POPE} - R/O SAME.	
1600	F/W MADE ROUND ON WEIGEL	
1700	F/W MADE ROUND ON POPE	
1800	F/W MADE ROUND ON WEIGEL.	
1900	F/W MADE ROUND ON POPE	
2000	F/W MADE ROUND ON WEIGEL.	
2100	F/W MADE ROUND ON POPE.	
2115	MR WAYNE MAKING INSPECTION - 2130 RETURNS.	
2200	F/W MADE ROUND ON WEIGEL.	
2215	WATCH RELIEVED BY LARKIN	

AT/PASSAGE FROM

PIER 2, BERTH #33

TO

SFBNSY HUNTERS POINT

ZONE DESCRIPTION

DATE (Day, month, year)

14 DECEMBER

DAY OF WEEK

SUNDAY

TIME	REMARKS	REMARKS
	RDO ANDERSON HENGHORNE	(E) JACKSON G LARKIN
	0000 - 0800	
2230	2230 WATCH RELIEVED. COND NORMAL	
2255	2255 MR ROBAIR RELIEVED BY MR HORNE. RDO WAYNE REL. BY MR ANDERSON	
2300	F/W ON A'RD. DETEX RD MADE, AREA SECURE	
2400	F/W TO WEIGLE FOR A'RD. WEIGLE SECURE. (F/W REPORTS)	
0100	B'RD POPE SECURE.	
0130	RDO ANDERSON TO WEIGLE FOR ROUTINE CHECK.	
0200	F/W TO WEIGLE FOR DETEX SECURITY RD. RDO RETURNS REPORTS	
0300	F/W RETURNS WEIGLE SECURE, COMMENCES RD OF POPE	
0400	DETEX RD MADE. SECURE	
0500	SECURITY RD MADE SECURE F/W REPORTS	
0600	SECURITY RD WEIGLE MADE. WEIGLE B. SECURE	
0620	RDO TO WEIGLE FOR ROUTINE CHECK. ALL RDS MAKE CLOCK TO BRIDGE. SMOKE DETECTOR SWITCHES CHANGED WATCH REL. BE FREDACE. <i>Pat Larkin</i>	
	MR. Anderson, (0500 - 1600)	
0630	Relieved the watch. All secure.	
0635	O'DELL, A/B, called in sick.	
0640	RDO Mr Anderson returns ASD from Weigel -	
0730	R/C AWAY TO WEIGLE - Return @ 0755	
0800	Colors observed -	
0820	Soundings made in Weigel - Also inspection Tour	
0845	Soundings made in Pope -	
0945	Mr. Anderson, RDO, off to Weigel	
1000	Round made in Pope - All secure	
1045	Mr. Wayne, RDO + Mr. Robert, R/C, ABOARD -	
1100	Detex clock round made in Weigel - All secure	
1120	Kidde exhaust motor in Weigel changed - Also Pope -	
1210	Mr. Wayne off to Weigel for inspection Tour.	
1230	Detex round made in Pope. All secure	
1410	Relieved of watch by Nix	
	MR. WAYNE TO MR. ROBAIR RDO (1600 - 2400)	<i>Fredace</i> NIX - GANGWAY ORR - FIREWATCH
1410	ASSUMED WATCH - All in APPARENT GOOD ORDER.	
1500	DETEX ROUND MADE ON POPE.	
1520	MR. WAYNE ^{MAKING} INSPECTION ON WEIGLE. 1540 RETURNS.	
1600	F/W MAKING ROUND ON WEIGLE.	
1650	SUNSET: COLORS.	
1700	F/W MAKING ROUND ON POPE.	
1800	F/W MAKING ROUND ON WEIGLE.	
1900	F/W MAKING ROUND ON POPE.	
1915	MR WAYNE MAKING INSPECTION ON WEIGLE. RETURNS 1940	
1945	F/W MAKING ROUND ON WEIGLE.	
2100	F/W MAKING ROUND ON POPE.	
2200	F/W MAKING ROUND ON WEIGLE.	
2215	WATCH RELIEVED BY LARKIN.	

AT/PASSAGE FROM <i>SFBNSY HUNTERS POINT</i>	TO <i>PIER 2 BERTH 33</i>	
ZONE DESCRIPTION <i>#7</i>	DATE (Day, month, year) <i>15 DECEMBER</i>	DAY OF WEEK <i>MONDAY</i>

ZONE DESCRIPTION #7	DATE (Day, month, year) 15 DECEMBER	DAY OF WEEK MONDAY
------------------------	--	-----------------------

DATE (Day, month, year)	DAY OF WEEK
15 DECEMBER	MONDAY

DAY OF WEEK
MONDAY

70

AT/PASSAGE FROM SFBNSY	Hunters Point	TO Pier 2 Berth 33
ZONE DESCRIPTION +7	DATE (Day, month, year) 12/15/69	DAY OF WEEK Monday

TIME	REMARKS
1900	Iredale, F/W, starts "A" round Pope
2000	" " " "A" " Weigel
2100	" " " "B" " Pope
2150	" " " "B" " Weigel
2245	Watch relieved by Larkin RE O'Dell
2245	RELIEVED AND ASSUMED THE WATCH. JACKSON F/W NOT ON BD NO RELIEF. SECURITY RD'S MADE BY G/WATCH REL. BY RDO ANDERSON. R/DO ANDERSON ON BD, MR WAYNE REL.
2310	A + B RTE. USNS DORE, COMMENCED 2310 - COMPLETED 2350
2350	ALL SECURE. (2310 R/ENG O'HARA ON BD RDO ANDERSON R/ENG O'HARA 0000 - 0800 F/W LARKIN G LARKIN
2400	SECURE.
0100	G/W TO WEIGEL FOR SECURITY RD A+B, REL. BY RDO ANDERSON Larkin

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL SHIP YARD		YARD	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		16/12/69	TUESDAY
TIME	REMARKS		
	MR ANDERSON R/O MR O'HARA R/ENG F/W LARKIN		
2400	0000 - 0800		
	REL BY RDO, SECURITY RD POPE.		
2435	A+B DETEX RD. POPE SECURE. ALL STATIONS		
0100	REL FOR SECURITY RD. WEIGEL.		
0135	WEIGEL SECURE A+B. ALL STATIONS.		
0150	RDO TO WEIGEL.		
0220	RDO RETURNS SECURE.		
0300	F/W STARTS COMPLETE RD OF VESSEL 'A+B'		
0400	SECURE. R/D O MADE CHECK OF POPE		
0500	B RD DETEX CLOCKS (#TRD) SECURE		
0600	B RD. WEIGEL - 0630 COMPLETE ALL SECURE.		
0630	SECURE, WATCH RELIEVED BY (CALLS MADE.)		
0635	GARDE, ALFREDO SICK, (LEAVE) WIFE CALLED DRS CARE.		
0640	ON Watch, Iredale, F/W - O'Dell, A/B		
0700	Iredale, F/W starts round "A" ON Pope		
0800	CARRILLO, ANGEL J. (A/B) reporting abd - VICE JACKSON.		
0800	Colours observed		
0800	Iredale starts "A" ON Weigel		
0900	" " "B" " Pope		
0950	" " " " Weigel		
1100	" " A " Pope		
1200	" " " " Weigel		
1300	" " B " Pope		
1345	" " " " Weigel		
1400	Watch relieved by Perkins R.E. O'Dell		
1400	Relieved the watch - all in - APPARENT Good order		
1500	F/W - MADE "A" ON POPE		
1530	MR Wayne R/O ON Weigel - ALL IN - Good order		
	F/W - ON "A" RTE - WEIGEL		
	MR. WAYNE R/O BURDICK - R/O 1600 - 2400 - Perkins CONCERN. REL FIREWATCH		
1600	F/W - ON "A" - RTE - WEIGEL		
1657	SUNSET - colors observed		
1700	F/W - ON "B" RTE - POPE		
1800	F/W - ON "B" RTE WEIGEL		
1900	F/W - ON "A" RTE - POPE - R/O ON INSP RDS. WEIGEL		
2000	F/W - ON "A" RTE - WEIGEL		
2100	F/W - ON "B" RTE - POPE - completed - all SECURE		
2200	F/W - ON "B" RTE - WEIGEL		
2230	watch relieved by Larkin		
2300	RELIEVED AND ASSUMED THE WATCH CARRILLO F/W ON B.D.		

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL		SHIPYARD HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		17 DEC. 18/12/69	WEDNESDAY
TIME	REMARKS		
	MR ANDERSON RDO MR O'HARA R/ENG. 0000 - 0800		
	LARRIN (G) CARRILLO F/W		
2255	MR ANDERSON ON BD. REL. MR WAYNE, MR O'HARA ON BD. REL. MR BURDICK. SHIPS POWER #3 GEN. #4 BOILER (1 OILER ON WASH) REC. SHORE ELEC. (AC) + STEAM DOCKSIDE, F/W PRESSURE FROM DOCK.		
2300	F/W TO WEIGEL FOR RD. DETEX CLOCKS A' RD		
2400	F/W REPORTS A' SECURE (2430) - 0030 MASTER CAPT. LANDRY ABOARD		
0405	F/W ON B' RTE. WEIGEL. 0200 B' RTE REPORTED SECURE.		
0200	RDO ANDERSON TO WEIGEL FOR INSPECTION + CHECK. (RETURN 0220)		
0300	F/W REPORTS A' RTE SECURE. 0400		
0500	F/W TO WEIGEL FOR RD.		
0545	F/W REPORTS WEIGEL SECURE.		
0600	F/W ON RD OF POPE. RDO TO WEIGEL FOR CHECK.		
0615	WATCH RELIEVED, CALLS MADE. P. Larkin		
0625	RDO RETURNS WEIGEL SECURE.		
	MR. CONNALLY Y/O 0800 - 1600 ORR. GANGWAY NIX - FIRE WATCH		
0625	ASSUMED WATCH - ALL IN APPARENT GOOD ORDER.		
0635	PURSER + CHIEF STEWARD ABOARD.		
0640	FIRST OFFICER, MR CONNALLY, ABOARD. MR ANDERSON ASHORE.		
0700	O'HARA ASHORE. F/W MAKING POPE ROUNDS 0705 CH. ENG. ABOARD		
0715	POPE ALARM SYSTEMS TESTED O.K.		
0745	WEIGEL ALARM SYSTEMS TESTED. "A" - OK.		
0800	F/W MAKING WEIGEL ROUNDS. COLORS OBSERVED		
0900	F/W MAKING POPE ROUNDS		
0900	TESTS MADE ABOARD WEIGEL: EMERGENCY GENERATOR 1/2 HR., ANCHOR WINDLASS 15 MINS., CAPSTAN 15 MINS., AND A.C. LAUNDRY UNIT 1 HR.		
0930	TESTS ABOARD WEIGEL: EMERGENCY GENERATOR + DIESEL FIRE PUMP.		
1000	F/W MAKING WEIGEL ROUNDS		
1025	MASTER ASHORE TO CARD (ALAMEDA)		
1100	F/W MAKING POPE ROUNDS		
1145	SANITARY SYSTEM SECURED FWD OF PERM. 116		
1200	SANITARY SYSTEM BACK ON. F/W ON WEIGEL ROUNDS		
1300	DETEX ROUND ON POPE MADE.		
1330	MASTER ABOARD.		
1400	MR CLEVELAND PORT STEWARD ABOARD. = REO ABOARD.		
1400	DETEX ROUND ON WEIGEL MADE.		
1415	WATCH RELIEVED BY PELETI.		
	G. J. J. J.		
1415	RELIEVED + ASSUMED WATCH - all in apparent good order		
1445	MR. WAYNE R/O ABOARD - MR. CONNELLY R/O ASHORE MR. DAVIS SAFETY INSPECTOR ABOARD - MR. BURDICK R/O - ABOARD		
1500	F/W ON "A" RTE POPE		
1525	CH. ENGR. ASHORE		
1530	MR. WAYNE R/O - MR. DAVIS (SAFETY DIV.) R/O - F/W TO WEIGEL		
1550	all secure on WEIGEL - F/W on WEIGEL "A" RTE		
	continued		

AT/PASSAGE FROM
 SAN FRANCISCO
 ZONE DESCRIPTION

TO
 Bay Naval SHIPYARD - HUNTERS POINT - PIER #2 BERTH #33
 DATE (Day, month, year)
 17-DEC-'69
 DAY OF WEEK
 WEDNESDAY

TIME	REMARKS
	MR WAYNE - R/D MR BURDICK - R/ENG 1600-2400 PERKINS - GANGWAY PELETI FIREWATCH
1600	DUNKLE S-WIPER - LEFT JETTY FOR ASSIGNMENT
1652	SUNSET - COLORS OBSERVED - FLW - ON - "B" ROUTE - POPE {MR. DALL'S ASHORE
1800	FLW ON "B" RTE WEIGEL
1900	FLW made "A" RTE ON POPE
- do -	R/D to WEIGEL ON ADS
1945	FLW + R/ENG - to WEIGEL on "A" RTE and inspections respectively HAVE ELECTRICIANS REPLACE BURNED OUT LIT'S OVER GANGWAY
2030	CARL PEIRCE (?) ONE call → CALL - OPERATOR 31-ph. #283-5023 SAN DIEGO CALLED - CONTACT GLORIA OR yr. bro. ANY HOUR →
2100	FLW ON "B" RTE completion on POPE
2100	FLW ON "B" RTE - completion on WEIGEL
2300	Watch relieved by Carrillo AB.
2300	MR O-HART night eng. aboard

AT/PASSAGE FROM		TO	
SAN FRANCISCO BAY NAVAL SHIPYARD		HUNTERS POINT	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
#7		18 DEC 1969	THURSDAY
TIME	REMARKS		
	MR ANDERSON MR O'HARA R/ENG. LARKIN (G) CARRILLO (E)		
2300	WATCH RELIEVED BY CARRILLO.		
A2330	A'RD POPE, ALL STATIONS, REPORTED SECURE LARKIN		
A2400	A'RD. WEIGEL ALL STATIONS WEIGEL BY CARRILLO.		
B0100	B'RD POPE ALL STATION SECURE (LARKIN)		
B0200	B'RD WEIGEL.		
0220	RDO ANDERSON TO WEIGEL. FOR ROUTINE		
0240	RDO RETURNS FROM WEIGEL, ALL SECURE.		
0300	A RD. POPE. (LARKIN) SECURE		
0400	A RD WEIGEL (CARRILLO) SECURE		
0500	B RD POPE (LARKIN) SECURE ALL CALLS MADE.		
0600	B RD WEIGEL (CARRILLO) SECURE RDO TO WEIGEL.		
0630	WATCH RELIEVED BY ORR + NIX. RDO RETURNS 0640		
0645	1/0 CONNALLY ABOARD Larkin		
0700	O'HARA ASHORE. CH. ENGINEER ABOARD		
0710	POPE ALARM SYSTEMS TESTED O.K.		
0750	FIRE ALARM SYSTEMS TESTED ON WEIGEL. A. OK. MR CONNALLY 1/0 (0800-1600) ORR 4/B GANGWAY NIX 4/B FIREWATCH		
0800	COLORS OBSERVED. F/W MAKING WEIGEL CLOCK ROUNDS		
0900	POPE DETEX ROUNDS MADE.		
1000	WEIGEL ROUNDS MADE.		
1100	POPE ROUNDS MADE		
1135	PURSER ASHORE FOR \$\$\$		
1200	WEIGEL ROUND MADE.		
1200	PURSER ABOARD. BACK FROM BANK.		
1300	DETEX ROUND MADE ON POPE		
1330	ANCHOR WINDLASS & CAPSTANS ON POPE TESTED. OK.		
1400	DETEX ROUND MADE WEIGEL.		
1400	WATCH RELIEVED BY PERKINS.		
1400	watch relieved and assumed RENG MR. BURDICK		
1455	CAPT LANDRY ASHORE - MR. WAYNE 1/0 ABOARD MR. CONNALLY 1/0 ASHORE		
1500	F/W ON "A" RTE - POPE		
1535	R/O - RENG - COMPTD RDS - WEIGEL / F/W ON "A" RDS ON WEIGEL		
- do -	CAPT LANDRY ABOARD		
1652	SUNSET - COLORS OBSERVED		
1700	F/W ON "B" RTE - POPE		
1800	F/W ON "B" RTE - WEIGEL		
1900	F/W ON "A" RTE - POPE - R/O + RENG to WEIGEL ON INSP - RDS		
2000	F/W ON "A" RTE completion ON - WEIGEL		
2010	IREDALE AB CALLED IN "ALL UNABLE TO STAND OO-OR - WATCH		
2100	F/W ON "B" RTE completion - POPE		
2200	F/W ON "B" RTE completion - WEIGEL - ALL IN APPARENT GOOD ORDER		
2300	watch relieved by O'DELL AB		
	Perkins		