

AT/PASSAGE FROM		TO	
SBNSY Hunters Point		Pier #2 Berth 33	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
4 7		19 Dec. 1969	Friday
TIME	REMARKS RAINY!		
	0000-0800		
2300	ON Watch O'Dell A/B Mr Wayne R.D.O. Mr Andersen		
2300	O'Dell-F/W- starts "A" round Pope		
0000	"	"	Weigel
0100	"	"	"B" Pope
0200	"	"	Weigel
0400	"	"	"A" Weigel
0430	"	"	"A" Pope
0500	Mr. Andersen, RDO, to Weigel		
0600	O'Dell, F/W- to the Weigel		
0605	JOE MEYER ABM CALLED IN SICK		
0615	Watch relieved by Nix & Orr		
0700	R/O HARA ASHORE		
0700	F/W MAKING POPE ROUNDS		
0705	POPE ALARM SYSTEMS TESTED O.K.		
0710	CH. ENGINEER & 1/0 ABOARD		
0755	FIRE ALARM SYSTEMS TESTED ON WEIGEL. A.O.K. MR CONNALLY 1/0 (0800-1600)		
0800	F/W MAKING WEIGEL ROUNDS.		
0900	F/W MAKING POPE ROUNDS. BASE POLICE TAGGING CARS WITHOUT PASS PARKING ON PIER.		
0915	THE SANITARY SYSTEM SECURED UNTIL FURTHER NOTICE.		
1000	F/W MAKING WEIGEL ROUNDS.		
1015	CAPTAIN'S INSPECTION COMPLETED		
1045	THE SANITARY SYSTEM BACK IN OPERATION		
1100	F/W MADE POPE ROUNDS		
1200	F/W MAKING WEIGEL ROUNDS		
1300	F/W MADE POPE ROUNDS		
1400	F/W MADE WEIGEL ROUNDS		
1430	WATCH RELIEVED BY PELETI		
1435	ASSUMED WATCH ALL IN APPARENT GOOD ORDER		
1440	MR BURDICK R/O ABOARD 1455 3 RD OFFICER ABOARD		
1445	MR PECK 1 ST ASST. ENG ASHORE MR SMITH PURSER ASHORE MR WAYNE R/O ABOARD. CH. STWARD ASHORE		
1500	F/W ON "A" ROUNDS Pope		
1520	MR LANDRY MASTER ASHORE 1525 ELECTRONIC ENGINEER ASHORE		
1535	MR WAYNE TO WEIGEL AND F/W FOR ROUTINE ROUNDS "A" AND check up.		
1600	MR WAYNE R/O & F/W PERKINS RETURNS FROM WEIGEL. ALL IN GOOD ORDER		
1605	MR LYON 3 RD ASHORE, TO GEIGER. 2010 LYON ABOARD 2015 LYON ASHORE TO GEIGER		
1653	COLOR observed & MR BURDICK R/O To WEIGEL ROUTINE CHECK		
1700	F/W ON "B" ROUNDS Pope 1710 MR BURDICK R/O RETURNS ABOARD ALL SECURE		
1800	F/W ON "B" ROUNDS WEIGEL		
1900	F/W ON "A" ROUNDS Pope Mr Wayne R/O To WEIGEL		
1935	MR WAYNE R/O RETURNS FROM WEIGEL. ALL IN APPARENT GOOD ORDER		
2000	F/W ON "A" ROUNDS WEIGEL		
2040	MR BURDICK R/O To WEIGEL 2055 MR BURDICK R/O RETURNS ABOARD ALL IN GOOD ORDER		
2100	F/W ON "B" ROUNDS Pope & MR		
2200	F/W ON "B" ROUNDS WEIGEL		
2220	WATCH RELIEVED BY IREDALE A/B		

AT/PASSAGE FROM		TO	
S F B N S - Hunters Point		Pier 2 - Berth 35	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		20 DEC 69	SAT-
TIME	Mr. Anderson, RDO	REMARKS	IREDALE, G/W - O'DELL, F/W
2220	Assume the watch.	(0000-0800)	
2300	Mr. Anderson aboard.	Mr. WAYNE ashore	
2300	F/W under Taking "A" RT. in Pope.	All secure reported @	2320
0000	Water A round made in Weigel -		
0100	Water B rd. in Pope -	Air well	
0200	Water B rd. in Weigel -	do	
0300	Water A round in Pope -	do	
0320	Mr. Anderson To Weigel for Tour of inspection -	Return @	0350
0400	Water A round made in Weigel -		
0500	Water B rd. in Pope -	R/E on inspection Tour Weigel	
0600	Water B rd. in Weigel -		
0620	WATCH relieved by NIX		
0730	F/W MAKING POPE ROUNDS		
	MR ANDERSON R/O	0800-1600	ORR - GANGWAY NIX - FIREWATCH
0800	COLORS. F/W MAKING WEIGEL ROUNDS		
0900	F/W MAKING POPE ROUNDS. F/W REPORTS WATER IN COMP. 3-T.		
1000	F/W MAKING WEIGEL ROUNDS		
1015	R/O TO WEIGEL - 1030 RETURNS		
1020	MR BURDICK R/E ABOARD 1030 O'HARA ASHORE		
1045	MR WAYNE R/O ABOARD 1105 MR. ANDERSON ASHORE POPE ROUNDS MADE		
1130	CAPTAIN LANDRY ABOARD		
1150	MR. WAYNE TO WEIGEL. MR BURDICK TO WEIGEL 1215 RETURN		
1200	WEIGEL ROUNDS MADE. LIGHT OVER GANGWAY REPLACED (200W). POPE		
1300	POPE ROUNDS MADE		
1400	WEIGEL ROUNDS MADE.		
	WATCH RELIEVED BY PELETI	1600-2400	PELETI, GANGWAY WATCH PERKINS FIRE WATCH
	MR WAYNE R/O MR BURDICK R/O		
1430	ASSUMED THE WATCH LINES & RAT GUARDS GANGWAY ALL IN APPARENT GOOD ORDER		
1500	F/W ON "A" ROUNDS POPE ALL SECURE		
1505	MR WAYNE R/O TO WEIGEL 1525 MR WAYNE RETURNS ALL SECURE		
1515	MR BURDICK R/O TO WEIGEL 1535 MR BURDICK RETURNS ALL SECURE		
1600	F/W ON "A" ROUNDS WEIGEL 1653 COLORS OBSERVED.		
1700	F/W ON "B" ROUNDS POPE ALL SECURE		
1800	F/W ON "B" ROUNDS WEIGEL ALL SECURE		
1900	F/W ON "A" ROUNDS POPE ALL SECURE		
1905	MR WAYNE R/O TO WEIGEL 1930 MR WAYNE RETURNS ALL SECURE		
2000	F/W ON "A" ROUNDS WEIGEL ALL SECURE		
2040	MR BURDICK R/O TO WEIGEL 2100 MR BURDICK RETURNS ALL SECURE		
2100	F/W ON "B" ROUNDS POPE ALL SECURE		
2120	MR WAYNE R/O TO WEIGEL 2130 MR WAYNE RETURNS ALL SECURE		
2200	F/W ON "B" ROUNDS WEIGEL ALL SECURE		
2230	WATCH RELIEVED by IREDALE		

AT/PASSAGE FROM S.F.B.N.S. Hunters Point ZONE DESCRIPTION 17	TO Pier 2 - Berth 33 DATE (Day, month, year) 21 DEC 69 DAY OF WEEK Sun.
---	--

TIME	REMARKS RAIN-RAIN
	Mr. Anderson, RDO 0000-0800 IREDALE, G.W. O'DELL, F/W
2255	Mr. Lindberg, R/E, ABOARD
2300	Detex A rd. in Pope - All secure.
0000	Detex A rd. in Weigel - do
0055	RDO + R/E off to Weigel
0100	Detex B round in Pope do
0200	Detex B rd. in Weigel. "
0300	Detex A rd. in Pope. "
0400	Detex A rd. in Weigel. "
0500	Detex B rd. in Pope. "
0600	Detex B rd. in Weigel. "
0605	Relieved of watch by Nix
0650	R/E TO WEIGEL 0710 RETURNS <i>Geo Orr</i>
0700	F/W MAKING POPE ROUNDS
0730	POPE SOUNDINGS TAKEN MR. ANDERSON R/E MR. LINDBERG R/E (0800-1600) MR. NIX R/E FIRE WATCH MR. ORR R/E GANGWAY
0800	COLORS OBSERVED. F/W WALKING WEIGEL, SOUNDINGS TAKEN.
0830	R/E TO WEIGEL 0850 RETURNS
0900	F/W MAKING POPE ROUNDS
0910	R/E TO WEIGEL 0930 RETURNS
0930	F/W TO WEIGEL --- BOAT DRAINS CHECKED --- OK
1000	WEIGEL ROUNDS MADE. BUCKET IN FWD ENG. EMPTIED
1020	R/E BURDICK ABOARD 1035 LINDBERG ASHORE
1045	MR. SHERMAN R/E ABOARD
1100	F/W MADE POPE ROUNDS
1125	MR. ANDERSON ASHORE
1135	R/E TO WEIGEL
1200	F/W MADE WEIGEL ROUNDS
1205	MR. SHERMAN TO WEIGEL 1230 RETURNS
1300	F/W WALKING THE POPE ROUTE
1325	CAPT. LANDRY ASHORE
1400	F/W MADE WEIGEL ROUND. ALL IN GOOD ORDER.
1512	WATCH RELIEVED BY CARILLO 1600 - 0000 <i>Geo Orr</i>
1520	F/W ON "A" - Pope
1525	BANAGA BOARDING ON - relief for Larkin
1600	F/W - ROUND - A - POPE - twice - 1700
1653	Color secure & F/W making round Weigel
1800	F/W making round B on Weigel
1825	AB (Maint.) Mateo call that he will not work tomorrow for he will ^{take} his Dad to the hospital.
1900	F/W finished ^{finish} B on Weigel Weigel
1935	F/W making round A on Pope
2025	F/W sounding A - on Weigel
2120	Oidell call in sick, has flu
2140	F/W ON "B" Pope.
2255	F/W ON "A" Weigel completed - BANAGA

AT/PASSAGE FROM S.F.B.N.S.		TO	Pier 2 - Berth 33
ZONE DESCRIPTION +1/		DATE (Day, month, year) 22 DEC 69	DAY OF WEEK Monday
TIME	REMARKS		
	MR. Anderson RDO (0000-0800) REDALE G/L + 1/2		
2225	Assumed the watch. All's well		
2235	CAPT. LUNDY ABOARD		
2255	Mr O'hara, R/C, ABOARD		
2300	Mr Anderson, RDO, ABOARD - Mr Sherman away		
0000	Inspection Tour made in Weigel - All secure		
0100	A detox rd made in Pope - All secure		
0130	B detox rd made in Pope - All secure		
0145	Mr Anderson To Weigel		
0400	All secure -		
0500	A + B RT. made in Weigel - All secure.		
0630	Watch relieved by Meyer, A/KS.		
	at Weigel		
	MR. CONNALLY, 1/0 0800-1600 CONNALLY 1/0 SINDONI ABM. MEYER ABM.		
0655	MR. OHARA RED ASHORE. MR BANTZ CHENG ABOARD		
0700	RT "A" ON POPE		
0800	EXECUTED COLORS - ROUTE "A" ON WEIGEL -		
0900	RT "B" ON POPE		
1000	RT B ON WEIGEL		
1100	RT "A" ON POPE 1200 RTA WEIGEL		
1215	SANITARY SYSTEM SECURED ON MAIN DECK		
1300	RT "B" ON POPE		
1315	CH STEWARD, PURSER ASHORE		
1400	RT "B" ON POPE WEIGEL		
1415	CH MATE ASHORE		
1425	CH ENG. ASHORE		
	WATCH RELIEVED 1600 - 0000 REMILLARD		
1435	Assumed watch - CARRILLO-AB		
1500	Night mate aboard - Mr. Sherman		
1525	FW on "A" - "Pope" Enrillo		
1537	Remillard FW-AB aboard via Banaga		
1600	FW rounding B on Weigel - Remillard		
1653	Colors observed		
1710	FW on "B" Pope = Enrillo		
1715	Mr Sherman on the Weigel - back 1830		
1830	FW rounding A on Weigel - Remillard		
1915	FW on "A" Pope = Enrillo		
1944	" " " " " completed.		
1954	FW on "A" completed		
2000	FW rounding B on the Weigel - Remillard & Mr. Sherman too. Back 2015		
2120	FW B completed Weigel		
2230	Watch relieved by Iredale		

AT/PASSAGE FROM 5FBNS - Hunters Point ZONE DESCRIPTION +7		TO Pier 2 - Berth 33 DATE (Day, month, year) 23 Dec 69 DAY OF WEEK Tues	
TIME	REMARKS		
	Mr Anderson, 2200 (0000-0600) IREDALE SW - O'Dell, FW		
1230	Assumed the watch - All secure.		
2305	Mr Anderson AB - Mr Sherman ASHORE		
2300	FW making periodic rounds of detox stations & reporting hourly to QIR deck		
0000	Detox A round made in Weigel -		
0100	Detox B rd. in Pope - All's well -		
0110	Mr. Anderson off To Weigel. Return 0140		
0200	Detox B rd. in Weigel -		
0300	Detox A rd. in Pope - All secure.		
0400	Detox A rd. in Weigel - All's well		
0500	Detox B rd. in Pope - All secure		
0600	Detox B round in Weigel - do		
0600	Mr. Anderson off To Weigel - Return. 0620		
0630	Watch relieved by Perkins, A/B		
	Irredale		
	1112 CONNELLY % 0800-1600 PERKINS (GANGWAY) - PELETI - FIRE WATCH		
0630	watch relieved and assumed - Mr. Connelly % ASHORE		
0640	Purser and Chief Steward aboard		
0710	POPE alarm system tested - (OK) POPEFF / STOKP - CALLED IN "SICK" - "A" RTE - POPE		
0800	COPIES - EXECUTED - FRESH WATER SYSTEM -		
0830	FW - MADE "A" RTE - WEIGEL - CHF - ENGR - ASHORE		
0900	FW ON "B" RTE - POPE - CHF - STWD TO HOSP.		
0920	SAFE LANDRY		
1000	FW ON "B" RTE - WEIGEL - ALL SECURE		
1045	CHIEF ENGR. ABOARD		
1100	FW ON "A" RTE - POPE - COMPTD all secure - MR. SHADDOY - PORT - STWD - ABOARD		
1200	FW ON "A" RTE - WEIGEL - COMPTD		
1230	MR. SHADDOY - PORT - STWD ASHORE		
1300	FW ON FINAL "B" RTE - POPE - MR. LORANCE Electronics - with key to Weigel		
1430	watch properly relieved by Carrillo AB.		
	Perkins		
	1600 - 0000 Angel J. Carrillo		
	1530		
1430	Assume watch Carrillo - FW round A Pope		
1600	FW round B Weigel - + finish 1610		
1552	Finished "A" Pope		
1654	Color secured - FW - round B Pope		
1730	Night engr. rounding on Weigel - Back 1800		
1755	FW - Finish - B - on - Pope + he is on his way to round A - V		
1900	FW Finish - A - Weigel + FW rounding A - Pope Weigel		
2010	FW finish round - A - Pope		
2025	FW rounding - B - Weigel		
2115	FW finish - B - Weigel + Start - B - on Pope		
2215	Watch relieved by Nix		
2300	FW MAKING POPE ROUNDS ("A") Carrillo		
2300	MR. O'HARA % RELIEVES MR. HURLEY.		
2350	MR. AUPPERLE % RELIEVES MR. SHERMAN.		

24 DECEMBER 1969

WEDNESDAY

TIME	REMARKS RAINY!
	MR. AUPPERLE R/O MR. O'HARA R/E (0000-0800) ORR N/B GANGWAY NIX A/B FIREWATCHMAN
0000	F/W MADE DETEX ROUNDS ABOARD WEIGEL (A-1)
0100	F/W MAKING POPE ROUNDS (B-1)
0200	F/W MADE WEIGEL ROUNDS (B-1)
0300	F/W MAKING POPE ROUNDS (A-2)
0400	F/W MADE WEIGEL ROUNDS (A-2)
0500	F/W MAKING POPE ROUNDS (B-2)
0600	F/W MADE WEIGEL ROUNDS (B-2)
0600	WATCH RELIEVED BY Peletti - Geo. Orr MR CONNALLY I/O 0800-1600 PELETI AB SINDONI ABM
0620	MR PECK I/AE ABOARD.
0640	MR CONNALLY I/O ABOARD
0700	MR. OHARA REC ASHORE
0700	MR AUPPERLE R/O ASHORE - RTA POPE
0705	SMOKE TEST ON POPE
0725	SMOKE TEST ON WEIGEL
0800	COLORS EXECUTED
0800	RT "A" WEIGEL - EM. GEN. AFTER FIRE PUMP TESTED SATISFACTORY
0855	CH STEW. ABOARD
0900	RT "B" ON POPE - PURSER ASHORE
1000	RT "B" ON WEIGEL
1100	RT "A" ON POPE
1145	CH STEWARD ASHORE
1200	RT "A" ON WEIGEL - FRESH WATER SECURED.
1300	RT "B" ON POPE FRESH WATER ON.
1400	RT "B" ON WEIGEL
	- 1600-0000 Watch relieved
1400	Watch assumed - Carrillo & Remillard
1500	FW round A Pope 1500 FW finish - A - Pope
1500	RT "A" ON WEIGEL
1445	Night engineer aboard & Mr. Sherman too
1505	FW round - A - Weigel - finish - A - Weigel 1635
1654	Color secured - FW round - B - Pope
1745	FW finish - B - Pope -
1755	FW round - B - Weigel - Finished - B - Weigel
1900	FW round - A - Pope - 1945 finish - A - Pope
1955	FW round - A - Weigel - 2040 finish - A - Pope
2100	FW round - B - Pope - 2150 finish - B - Weigel
2155	FW round - B - Weigel - 2230 round - B - Weigel
2210	Watch relieved by Orr
2300	F/W MAKING POPE ROUNDS Carrillo
2300	MR AUPPERLE R/O ABOARD
2310	MR. SHERMAN ASHORE
2400	F/W MAKING WEIGEL ROUNDS

AT/PASSAGE FROM
PIER #2 BERTH #33 HUNTERS POINT
ZONE DESCRIPTION

N.S.Y. S.F. CALIF
DATE (Day, month, year) 25 DECEMBER 1969
DAY OF WEEK THURSDAY

TIME	REMARKS = MERRY CHRISTMAS
	MR. AUPPERLE R/O MR. O'HARA R/E (0000-0800) ORR 4/B GANGWAY NIX 4/B FIREWATCH
0000	F/W MAKING WEIGEL ROUNDS
0030	MR. O'HARA RELIEVES MR. HURLEY AS R/ENG.
0100	F/W MAKING POPE ROUNDS.
0200	F/W MADE WEIGEL ROUNDS.
0300	F/W MAKING POPE ROUNDS.
0400	F/W MADE WEIGEL ROUNDS.
0500	F/W MADE POPE ROUNDS.
0600	F/W MADE ON WEIGEL
0655	WATCH RELIEVED BY NIX. Geo Ch
	MR. AUPPERLE R/O MR. O'HARA R/E 0800-1600 PERTIN - GANGWAY PERTIN - FIREWATCH
0655	WATCH RELIEVED & ASSUMED
0700	MERRY Xmas - all is well
0800	COLORS - PROPERLY EXECUTED - "A" RTE - SOUNDINGS TAKEN
0900	F/W ON - "A" RTE - WEIGEL
1000	R/O TO WEIGEL - F/W ON - "B" RTE - POPE
1030	R/O ABOARD
1100	MR. SHERMAN - ABOARD - MR. AUPPERLE - R/O - ASHORE
1200	F/W TO WEIGEL - R/O - TO WEIGEL - INSPECTION
1230	MR. HURLEY R/ENG. / ABOARD MR. O'HARA R/ENG. ASHORE {MR. HURLEY ABOARD
1300	F/W ON - ROUNDS
	WATCH RELIEVED BY - REMILLARD 7/B 1600 - 0000
	R/M MR. SHERMAN G/W CARRILLO F/W REMILLARD
1340	F/W TO WEIGEL.
1355	R/E " " "
1455	F/W rounding - A - Pope - Finished - A - Pope 1510
1540	F/W rounding - A - Weigel - Finished - A - Weigel - 1640
1650	R/E to Weigel -
1655	Color secured - F/W rounding - B - Pope - 1715 - &
1745	Finished - B - Pope -
1755	F/W on - B - route - Weigel - Finish - B - Weigel - 1800
1900	F/W on - A - route - Pope - Finish - A - Pope 1925
1940	F/W on - A - route, Weigel - Finish - A - Weigel - 2030
2055	F/W on - B - route, Pope - Finish - B - Pope - 2115
2130	F/W on - B - route - Weigel - Finish - B - Weigel - 2215
2210	WATCH RELIEVED BY NIX Carrillo - AB
2250	MR. AUPPERLE R/O ABOARD --- SHERMAN ASHORE
2300	MR. O'HARA RELIEVES HURLEY AS R/E.
2300	F/W MAKING POPE ROUNDS....
2400	F/W MADE WEIGEL ROUNDS.

AT/PASSAGE FROM		DATE (Day, month, year)		DAY OF WEEK	
PIER #2 BERTH #33 HUNTERS POINT N.S.V. S.F. CALIF		DEC 26, 1969		FRIDAY	
ZONE DESCRIPTION					
TIME	REMARKS				
	MR. AUPPERLE R/O MR. O'HARA R/E (0000-0800.) MR. ORR A/B GANGWAY WATCH MR. NIX A/B FIREWATCHMAN				
0000	F/W MADE WEIGEL ROUNDS				
0100	F/W MADE POPE ROUNDS				
0200	F/W MADE WEIGEL ROUNDS				
0300	F/W MADE POPE ROUNDS				
0400	F/W MADE WEIGEL ROUNDS				
0500	F/W MADE POPE ROUNDS				
0600	F/W MADE WEIGEL ROUNDS				
0605	WATCH RELIEVED <i>Geo. Orr</i>				
	<i>MR. CONNELLEY/O 0800-1100</i> <i>PERKINS - GANGWAY</i> <i>AS/ETI - FIRE WATCH</i>				
0605	MR PECK 1 st ASS ENG ABOARD				
0645	CHIEF OFFICER - ABOARD				
0700	FW-ON-"A"-RTE-POPE				
0800	Colours observed FW-ON-"A"-RTE-WEIGEL				
0900	FW-ON-"B"-RTE-POPE				
1000	FW-ON-"B"-RTE-WEIGEL				
1100	FW-ON-"A"-RTE-POPE				
1200	FW-ON-"A"-RTE-WEIGEL				
1300	FW-ON-"B"-RTE-POPE				
1400	FW-ON-"B"-RTE-WEIGEL				
	<i>Mr Perkins</i>				
1440	Watch relieved by O'Dell A/B & Iredale F/W & Mr. Sherman R/O				
1500	Iredale F/W starts "A" round on Pope				
1600	" " " " " " " Weigel				
1656	Colours observed				
1700	Iredale, F/W, starts "B" " " " Pope				
1800	" " " " " " " Weigel				
1900	" " " " " " " Pope				
2000	" " " " " " " Weigel				
2100	" " " " " " " Pope				
2130	Shore gang secure steam on dock				
2130	Iredale F/W starts "B" round on Weigel				
2200	WATCH RELIEVED BY ORR <i>Geo. Orr</i>				
2250	MR AUPPERLE R/O RELIEVES MR. SHERMAN				
2300	MR O'HARA R/E RELIEVES MR. HURLEY				
2300	F/W MAKING POPE ROUNDS				
2305	F/W REPORTS ONLY ONE OUT OF EIGHT CARGO LIGHTS BURNING.				
2400	F/W MAKING WEIGEL ROUNDS				

AT/PASSAGE FROM		TO	
PIER #2 BERTH #33 HUNTERS POINT		N.S.Y. S.F. CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
		27 DECEMBER 1969	SATURDAY
TIME	REMARKS		
	MR AUPPERLE R/O MR O'HARA R/E (0000-0800)		ORR---GANGWAY NIX---FIREWATCH
0000	F/W MADE WEIGEL ROUNDS		
0100	F/W MADE POPE ROUNDS		
0200	F/W MADE WEIGEL ROUNDS		
0300	F/W MADE POPE ROUNDS		
0400	F/W MADE WEIGEL ROUNDS		
0500	F/W MADE POPE ROUNDS		
0600	F/W MADE WEIGEL ROUNDS		
0605	WATCH RELIEVED by PELETI <i>Ger. Orr</i>		
	0800-1600		
0700	F/W MADE ROUND "A" POPE & SOUNDING TAKEN		
0800	COLORS PROPERLY EXECUTED & F/W TO WEIGEL SOUNDING TAKEN		
0840	MR AUPPERLE R/O TO WEIGEL 0905 MR AUPPERLE RETURNS FROM WEIGEL		
0900	F/W MADE ROUNDS "B" POPE		
1000	F/W MADE ROUNDS "A" WEIGEL		
1045	MR SHERMAN R/OO ABOARD RELIEVED MR AUPPERLE R/OO ASHORE		
1055	MR HURLEY R/OO ABOARD RELIEVED MR O'HARA R/OO ASHORE		
1100	F/W MADE ROUNDS "A" POPE		
1200	F/W MADE ROUNDS "B" WEIGEL		
1205	MR SHERMAN R/OO TO WEIGEL 1220 MR SHERMAN R/OO RETURNS FROM WEIGEL		
1300	F/W MADE ROUNDS "B" POPE		
1335	MR HURLEY R/OO TO WEIGEL 1345 MR HURLEY RETURNS FROM WEIGEL		
1400	F/W MADE ROUNDS "B" WEIGEL		
1420	WATCH (RETURN) RELIEVED by IREDALE		
	<i>Telet A/B</i>		
1430	ON WATCH Iredale F/W, O'Dell A/B		
1500	Iredale ON "A" round ON Pope		
1600	" " " " " " Weigel		
1700	Colors observed		
1700	Iredale ON "B" round ON Pope		
1800	" " " " " " Weigel		
1900	" " "A" " " " Pope		
2000	" " " " " " Weigel		
2100	" " "B" " " " Pope		
2200	" " " " " " Weigel		
2205	Watch relieved by Nix & Orr		
2250	MR. O'HARA RELIEVES MR. HURLEY AS R/E		
2300	MR. SHERMAN RELIEVED BY MR AUPPERLE.		
2300	F/W MAKING POPE ROUNDS.		
2400	F/W MADE WEIGEL ROUNDS.		

AT/PASSAGE FROM

PIER #2 BERTH #33 HUNTERS

TO

POINT N.S.Y., S.F., CALIF.

ZONE DESCRIPTION

DATE (Day, month, year)

28 DECEMBER 1969

DAY OF WEEK

SUNDAY

TIME	REMARKS
	MR AUPPERLE R/O MR O'HARA R/E (0000-0800) ORR... GANGWAY NIX... FIREWATCH
0000	F/W MADE WEIGEL ROUNDS.
0100	F/W MADE POPE ROUNDS.
0200	F/W MADE WEIGEL ROUNDS.
0300	F/W MADE POPE ROUNDS. 0400 WEIGEL RDS. MADE
0440	FIRST OFFICER TO WEIGEL.
0500	PEPE ROUNDS MADE
0600	WEIGEL ROUNDS MADE.
0615	Watch received by Carrillo 0800 - 1600 Remillard - AB - ON Carrillo AB - FW
0615	Watch assumed
0650	F/W to Weigel - A - Finished "A" at 0735
0745	STARTED "B" on Pope. 0810 "B" Completed.
0800	Observed COLORS.
0835	F/W to Weigel. Completed "B" at 0930
0915	R/M to Weigel. INSPECTION & DRAFT. Returned 0945
0945	F/W to Weigel for SOUNDINGS.
1015	SOUNDINGS TAKEN ON WIEGEL.
1020	F/W MAKING "A" on Pope. 1050 Rounds Completed.
1030	R/M ABOARD {MR. SHERMAN}
1035	R/E ABOARD
1040	R/M ASHORE & R/E ASHORE.
1055	F/W to Weigel for "A" Round. Completed at 1135
1215	F/W rounded - B - Pope
1225	R/M to Weigel. 1235 R/M BACK FROM INSPECTION.
1345	Completed "A" Round on Pope.
1430	Watch Received Remillard
1430	ON Watch Tredale F/W - O'Dell AB - RDO Mr. SHERMAN
1500	Tredale starts "A" round on Pope
1600	" " " " " Weigel
1700	" " B " " Pope
1657	Colours observed
1800	Tredale starts B " " Weigel
1900	" " A " " Pope
2000	" " " " " Weigel
2100	" " B " " Pope
2130	" " " " " Weigel
2300	RDO SHERMAN ASHORE - New RDO ABOARD
0015	Watch relieved by Carrillo R E O'Dell
	0000 - 0800 Carrillo
1200	FW - A - Weigel
0115	FW - A - Pope
0200	FW - B - Weigel
0300	FW - B - Pope

AT/PASSAGE FROM		TO	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
		29-Dec, 69	
TIME	REMARKS		
	0000 - 0800		
0400	FW - A - Weigel		
0500	FW - A - Pope		
0600	FW - B - Weigel		
0620	WATCH RELIEVED BY SINBONI		
	Remilla		
0630	Assumed the Watch - on watch Mr Connally 1/0 Sinboni - Gray		
0630	Mr CONNALLY 1/0 Aboard		
0650	N/M ASHORE.		
0655	N/E ASHORE		
0700	RT "B" POPE		
0705	CH-ENG. ABOARD.		
0725	"B" Round Completed on Pope.		
0740	F/W to Weigel for Round "A", Completed 0815		
0800	Observed COLOURS.		
0810	Weigel ALARMS test O.K.		
0825	GARDE AB/M to BASE DISPENSARY.		
0900	RT "A" ON POPE		
0905	ELECTRICIAN BACK FROM WIEGEL		
0920	GARDE AB/M Returned FROM BASE DISPENSARY.		
0945	Commenced off ^{LOADING} STEWARD STORES TO TRUCK FOR MILLER		
1000	Route "B" Weigel MADE.		
1050	MASTER ABOARD.		
1100	RT "B" ON POPE		
1200	"A" Round AT ON WIEGEL.		
1215	2 nd AE, ELECTRICIAN & the PLUMBER to the WIEGEL		
1300	RT "A" ON POPE		
1310	STOREKEEPER ON MAIL RUN		
1345	" " Returned FROM MAIL RUN.		
1400	RT "B" ON WIEGEL		
1430	Watch relieved by Fredate FW, O'Dell A/B - Mr. Sherman		
1500	Fredate ON "A" round of the Pope		
1600	" " " " " " Weigel		
1700	Colours observed		
1700	Fredate ON B round of the Pope		
1800	" " " " " " Weigel		
1900	" " " A " " " Pope		
2000	" " " " " " Weigel		
2100	" " " B " " " Pope		
2130	" " " " " " Weigel		
2150	Watch relieved by Peleti		
2240	MR AUPPERLE R/OO ABOARD		
2245	MR A.H. SHERMAN R/OO ASHORE		
2255	MR O'HARA R/OO ABOARD		
2255	MR HURLEY R/OO ASHORE		

AT/PASSAGE FROM		TO	
PER 2 BERTH #33 HUNTER'S POINT		NAVAL SHIP YARD S. FRANCISCO CALI	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
		30 DECEMBER 69	TUESDAY
TIME	MR AUPPERLE RDO MR O'HARA RDO	REMARKS	PELETI GATEWAY WATCH FERKINS FIRE WATCH
		0000 - 0800	
2255		ASSUMED THE WATCH	
2300		F/W ON ROUTE "A" Pope	
0000		F/W ON "A" WIEGEL	
0100		F/W ON "B" Pope	
0200		F/W ON "B" WIEGEL	
0300		F/W ON "A" Pope	
0400		F/W ON "A" WIEGEL	
0500		F/W ON "B" Pope	
0540		MR AUPPERLE RDO & F/W TO WIEGEL FOR "B" ROUNDS	
0555		MR AUPPERLE RETURNS FROM WIEGEL	
0600		F/W ABOARD ALL IN APPARENT GOOD ORDER	
0610		WATCH RELIEVED by LEMILLARD	
		0800 - 1600	
		Plute A/B. Remillard Carrillo	
0610		Assumed watch	
0700		Fw - A - Pope	
0715		ALL sanitation system secure half hour	
0730		PERKINS off on leave.	
0735		WIEGEL ALARM tested. N/M ASHORE.	
0745		SANITATION SYSTEM BACK ON THE LINE.	
0750		Ch. ENGINEER to WIEGEL to off load MACHINERY STORES.	
0800		Observed Colors. Made "B" Round on WIEGEL.	
0900		Fw - B - Pope	
0910		CAPTAIN left the SHIP.	
1000		Round "A" on WIEGEL.	
1100		Round - A - Pope	
1200		Round "B" on WIEGEL.	
1300		Round - B - Pope	
1345		Off loaded STEWARD STORES, Bedding.	
1400		Fw - A - Wiegol	
1445		R/E ABOARD	
1450		R/M ABOARD.	
1500		F/W Relieved "A" Round on Pope.	
1550		GATEWAY Relieved	
1550		ON WATCH O'Dell/A/B - Iredale Fw - RDO - Mr Sherman	
1600		Iredale on A round of Wiegol	
1659		Colours observed	
1700		Iredale on B round of Pope	
1800		" " " " " Wiegol	
1900		" " A " " Pope	
2000		" " " " " Wiegol	
2100		" " B " " Pope	
2130		" " " " " Wiegol	
2135		Watch relieved by Peleti	

AT/PASSAGE FROM		TO	
PIER 2, BERTH #33 HUNTER'S POINT NAVAL SHIPYARD S. FRANCISCO CALI		DATE (Day, month, year)	
ZONE DESCRIPTION		DAY OF WEEK	
		31 DECEMBER 1969 WEDNESDAY	
TIME	MR AUPPERLE R/OO MR O'HARA R/OO	REMARKS	{ PELETI GANGWAY WATCH PELETI FIREWATCH }
		0000-0800	
2200		ASSUMED THE WATCH	
2250		MR AUPPERLE R/OO ABOARD RELIEVED MR SHERMAN ASHORE	
2300		MR O'HARA R/OO ABOARD RELIEVED MR HURLEY ASHORE	
2300		ROUND "A" ROUTE MADE POPE	
0000	" " " " "	WEIGEL	
0100	" " " " "	POPE	
0200	" " " " "	WEIGEL	
0300	" " " " "	POPE SKIP BY ORDER	
0400	" " " " "	WEIGEL " " "	
0500	" " " " "	POPE	
0510		MR AUPPERLE R/OO TO WEIGEL 0525 MR AUPPERLE RETURNS ABOARD.	
0600		ROUNDS "B" ROUTE MADE WEIGEL.	
0630		WATCH RELIEVED BY ^{REMILLARD} REMILLARD A/B.	
		Peliti	
		0800-1600	
		Remillard Carrillo	
0630		Assumed the watch.	
0700		MASTER ABOARD. - FV1 - round - A - Pope	
0720		WIEGEL ALARMS TESTED. R/E & R/M ASHORE.	
0740		ANCHOR WINDLASS & CAPSTON TESTED FOR 30 MIN.	
0800		OBSERVED COLORS. MADE ^{3RD} "A" ROUND ON WIEGEL	
0800		TESTED EMERGENCY GENERATOR.	
0900		Round - B - Pope	
1000		MADE ROUND "B" ON WIEGEL.	
1010		OFF LOADED BEDDING.	
1100		"A" ROUND ON POPE.	
1130		ANCHOR WINDLASS & CAPSTON TEST RUN FOR 15 MIN EACH ON THE WIEGEL.	
1140		BUNDY, R.B 31183 REPORTED ABOARD VICE CARRILLO.	
1200		BLMA "A" ON WIEGEL	
1220		MR. CONNALLY ASHORE. MASTER HAS THE WATCH.	
1300		B - round - Pope - Electrician on to Weigel	
1300		Plumber on to the Weigel ^{Plumber}	
1300		CH ENG. ASHORE	
1330		DECK YEOMAN ON MAIL RUN	
1345		" " " Returned to ship.	
1400		"B" ROUND ON WIEGEL	
1400		WATCH RELIEVED	
		Remillard.	
		LATE ENTRY: DECK ENG. & STND DEPT. SAFETY MTC. FROM 0915 - 0940 w/ 27	
		Men in attendance. Presiding - 1/o, CH. ENGR + CH STND. (Dredale)	
		CONTINUED ON NEXT PAGE	

AT/PASSAGE FROM

PIER 2, BERTH #3, HUNTERS POINT

TO

NAVAL SHIPYARD SAN FRANCISCO, CALIF.

ZONE DESCRIPTION

+7

DATE (Day, month, year)

31 DEC. 1969 WED.

DAY OF WEEK

TIME

MR. SHERMAN - RDO

MR. HURLEY - RDO

REMARKS

(1600 2400) NIX - GANGWAY ORR - FIREWATCH

1400 ASSUMED WATCH. ALL IN APPARENT GOOD ORDER.

1445 MR. HURLEY RDO ABOARD.

1450 MR. SHERMAN ABOARD.

1455 PURSER & CH. STEWARD ASHORE

1500 DETEX ROUND MADE ON POPE.

1600 DETEX ROUND MADE ON WEIGEL.

1700 COLORS: DETEX ROUND MADE ON POPE.

1800 DETEX ROUND MADE ON WEIGEL.

1900 DETEX ROUND MADE ON POPE.

2000 DETEX ROUND MADE ON WEIGEL

2100 DETEX ROUND MADE ON POPE.

2120 MR. O'HARA ABOARD TO RELIEVE MR. HURLEY.

2200 DETEX ROUND MADE ON WEIGEL.

2200 WATCH RELIEVED BY PERETTI.

Guy MSA

AT/PASSAGE FROM		TO	
PIER 2, BERTH #33 HUNTER'S POINT		NAVAL SHIPYARD S. FRANCISCO CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		1 ST JANUARY 1970	THURSDAY
TIME	MR. APPERLE R/OO MR. O'HARA R/OO MR. ALEXANDER R/OO	REMARKS	PELETI GANWAY WATCH CELEDA FIRE WATCH
		0000 - 0800	
2200		ASSUMED WATCH ALL IN APPARENT GOOD ORDER	
2300		MADE ROUND "A" ON POPE MR O'HARA R/OO ABOARD RELIEVED MR HURLEY ASHORE	
2315		MR ALEXANDER R/OO ABOARD RELIEVED MR SHERMAN	
0000		MADE ROUND "A" ON WEIGEL	
0100	" " "B" " POPE		
0200	" " "B" " WEIGEL		
0300	" " "A" " POPE		
0400	" " "A" " WEIGEL		
0500	" " "B" " POPE		
0600	" " "B" " WEIGEL		
0630		WATCH RELIEVED by REMILLARD	
		Delete.	
		0800 - 1600	
		N/M MR. ALEXANDER F/W BUNDY G/W Remillard	
0630		Assumed the watch, ALL IN APPARENT Good order	
0700		MADE ROUND "A" ON POPE. N/M ON INSPECTION to	
0800		OBSERVED COLORS. "A" Round on WEIGEL.	
0830		N/M to WEIGEL for INSPECTION. RETURNED 0910	
0900		Round "B" POPE.	
0925		N/E ABOARD. N/E ASHORE.	
0930		F/W to WEIGEL for SOUNDINGS & F/W Round "B".	
1030		F/W RETURNED FROM WEIGEL.	
1100		"A" Round on POPE.	
1130		MR. SHERMAN N/M ABOARD.	
1145		MR. ALEXANDER ASHORE.	
1150		N/E & F/W TO WEIGEL. N/E RETURNED AT 1210	
1155		N/M to WEIGEL.	
1200		Round "A" on WEIGEL.	
1300		Round "B" on POPE MADE.	
1400		Round "B" on WEIGEL MADE	
1410		WATCH RELIEVED by NIX	
		Remillard	
		MR. ALEXANDER MR. SHERMAN 1/0 (1600 - 2400) NIX - G/W MR. HURLEY - R/OO ORR. F/W	
1410		ASSUMED WATCH: ALL IN APPARENT Good ORDER.	
1500		DETEx Round MADE ON POPE.	
1600		DETEx Round MADE ON WEIGEL	
1700		COLORS --- F/W WALKING AROUND POPE	
1707		R/O TO WEIGEL - ALSO B/E THERE	
1800		F/W MADE WEIGEL	
1813		GREY 1/2 CALLED IN FROM FRESNO --- SICK --- WILL NOT BE IN FRIDAY	
1900		PELETI 1/2 CALLED IN SICK. F/W MAKING POPE ROUNDS.	
2000		F/W MAKING WEIGEL Round.	
2100		F/W MAKING POPE Round.	
2200		F/W MADE WEIGEL Round.	
2220		WATCH RELIEVED BY CELEDA	
		Grey Nix	

AT/PASSAGE FROM		TO	
Pier 2 Berth #3, Hunters Point		Naval Shipyard San Francisco, CALIF	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		2 Jan. 1970	Friday
TIME	REMARKS		
	Mr. Alexander R/O Mr. O'HARA R/E		
	0000-0800		
2300	Mr. Alexander R/O Aboard and Mr. Sherman Ashore		
2330	Made round A on Pope		
0000	Made round A on Weigel		
0100	Made round B on Pope		
0200	Made round B on Weigel		
0300	Made round A on Pope		
0400	Made round A on Weigel		
0500	Made round B on Pope		
0600	Made round B on Weigel		
0630	Watch relieved by — Iredale A/B CELADA AB.		
	Mr. Connally 1/0 (0800-1600) IREDALE, GW O'Dell, F/W		
0630	Assumed the watch. Conditions normal.		
0635	R/O returns from inspection tour in Weigel		
0715	Fire alarms (Pope) Tested satisfactorily.		
0725	F/W completes "A" route in Pope. All secure		
0800	Colors observed.		
0810	PATTERSON, Solomon A (30857) STWD. UT.I. VICE: New Position		
0820	F/W completes "A" route in Weigel - All secure.		
0845	Mr. Pike, Pool 2/0, reports abd. for duty.		
0915	F/W completes "B" rt. in Pope. All secure		
1020	F/W completes "B" route in Weigel - do -		
1115	F/W " A rt Pope - do -		
1220	F/W completes A rt in Weigel - do -		
1310	Relati's son phoned to report that A/B Relati is in the hospital - duration, illness & hospital not stated.		
1320	F/W completes B rt in Pope. All men.		
1330	Dick YEO/STCPR Popoff away on mail run.		
1400	F/W on B route in Weigel - All seen		
1400	Relieved of watch by Nix		
	1600 - 2400 Nix = GW OAR = F/W		
1400	ASSUMED WATCH: All in Apparent Good Order.		
1420	MR CONNALLY ASHORE.		
1425	CHIEF ENG. ASHORE. 1 st ASST ASHORE. HURLEY ABOARD.		
1455	MR. SHERMAN R/O ABOARD		
1500	POPE ROUNDS MADE		
1600	WEIGEL ROUND MADE. 1645 R/O TO WEIGEL 1700 RETURNS		
1700	F/W MAKING POPE ROUND. R/O TO WEIGEL. 1702 COLORS		
1800	F/W MAKING DETEX ROUND ON WEIGEL.		
1900	F/W MAKING DETEX ROUND ON POPE.		
2000	F/W MAKING ROUNDS ON WEIGEL.		
2100	F/W MADE ROUND ON POPE.		
2200	F/W MADE DETEX ROUND ON WEIGEL.		
2200	WATCH RELIEVED BY CELADA		

AT/PASSAGE FROM		TO	DATE (Day, month, year)		DAY OF WEEK
Pier 2 Berth #3, Hunter Point		Naval Shipyard	3 JAN 1970		Saturday
ZONE DESCRIPTION					
TIME	REMARKS				
	MR. Alexander R/O 0000-0800 G - Hemphill MR. O'HARA R/E Calada				
2200	Assumed Watch All in apparent Good order				
2230	F/W On A route (Pope) All Secure				
2330	F/W on A Route (Weigel)				
0030	Completed Rounds on Weigel (night mate to Weigel)				
0130	F/W Completed B Route on Weigel All Secure				
0200	F/W On B Route (Pope) All Secure				
0230	Completed B Route (All Secure)				
0300	F/W on A Route on (Weigel) Pope				
0300	Completed B Route on Weigel All Secure				
0300	F/W on B Route on Weigel				
0400	Completed B Route on Weigel				
0430	F/W on B Route on Weigel				
0500	Completed B Route on Weigel (All Secure)				
0530	F/W B Route (Pope)				
0600	Watch Relieved By Iredale				
	Mr. Alexander, RDO (0600-1600) IREDALE, F/W - O'DELL, F/W				
0710	F/W completes "A" route in Pope - All secure				
0800	Colors observed				
0805	RDO To Weigel on inspection Tour				
0810	F/W completes "A" route in Weigel - All secure				
0920	F/W completes B rt in Pope "				
1025	F/W completes B rt. in Weigel "				
1030	Mr. Sherman, RDO, aboard - Mr. Alexander ashore.				
1055	Mr. Linberg, R/E abd. - Mr. O'Hara ashore				
1130	F/W completes round A in Pope - All secure				
1200	RDO makes inspection Tour in Weigel -				
1215	"A" route made in Weigel - All secure.				
1310	F/W completes "B" route in Pope "				
1400	F/W makes B rt. in Weigel -				
1410	WATCH relieved by GEO Orr				
1445	R/E TO WEIGEL 1505 RETURNS 27 checks				
1500	F/W MAKING POPE ROUNDS				
1	MR SHERMAN R/O (1600-2400) MR. ORR - FIREWATCH MR. LINDBERG R/E MR. NIX - GANWAY				
1600	WEIGEL ROUNDS MADE				
1700	F/W MAKING POPE ROUNDS				
1715	R/O TO WEIGEL 1730 RETURNS				
1800	WEIGEL ROUNDS MADE				
1900	F/W MAKING POPE ROUNDS				
2000	F/W, R/E & R/O MAKE WEIGEL ROUNDS				
2100	F/W MAKING POPE ROUNDS				
2200	F/W MAKING WEIGEL ROUNDS				
2200	WATCH RELIEVED BY Bundy				
2230	R/O MR. ALEXANDER ABD. - MR. SHERMAN ASHORE				
2255	R/E MR. FARANI ABD.				
2300	F/W MAKING ROUND RTE. A - POPE - ALL SECURE				
	Bundy R/O				

AT/PASSAGE FROM

PIER 2 - BERTH #3. HUNTER'S POINT-NAVAL SHIPYARD - SAN FRANCISCO, CA.

ZONE DESCRIPTION

TO

DATE (Day, month, year)

DAY OF WEEK

4 JAN - 1970

SUNDAY

+ 8 8

TIME	REMARKS
	R/O MR. ALEXANDER R/E MR. FARRAN 0000-0800 F/W REMILLARD - GWY - BUNDY
0000	F/W ROUND - RTE "A" - WEIGEL - ALL SECURE
0100	F/W ROUND - RTE "B" - POPE - ALL SECURE
0200	F/W ROUND - RTE "B" - WEIGEL - R/O TO WEIGEL ROUTINE INSPCT, SECURE
0300	F/W ROUND - RTE "A" - POPE - ALL SECURE
0400	F/W ROUND - RTE "A" - WEIGEL - ALL SECURE.
0500	F/W ROUND - RTE "B" - POPE - ALL SECURE
0600	F/W ROUND - RTE "B" - WEIGEL - ALL SECURE
0630	WATCH RELIEVED BY IREDALE - Bundy A/B.
	Mr. Alexander, RDO 0800-1600 IREDALE, A/B - O'DELL, F/W
0630	Assumed the watch - All's well.
0720	RDO & R/E away to Weigel on inspection tour. Return 0745
0730	F/W completes "A" route in Pope - All's well.
0800	Colors observed
0818	F/W reports A rt. in Weigel completed. All secure
0924	F/W reports B rt. in Pope completed - do -
0950	RDO to Weigel Return 1015
1020	F/W reports B rt. in Weigel completed - do -
1040	Mr WAYNE ABOARD. Mr Linberg, R/E, ABOARD
1140	F/W reports A rt. in Pope all secure.
1140	Mr Linberg, R/E, off to Weigel on inspection tour
1210	F/W completes "A" rt. in Weigel - All secure.
1230	Mr. WAYNE on Weigel inspection tour.
1318	F/W completed B route in Pope - Notes all's well.
1345	CAPT. ASHORE
1345	F/W making B route in Weigel.
1355	WATCH RELIEVED BY GEO ORR
1500	F/W MAKING POPE ROUNDS MR WAYNE R/O (1600-2400) MR LINDBERG R/E MR. NIX - GANGWAY MR. ORR - FIREWATCHMAN
1600	F/W MAKING ROUND ON WEIGEL. MR. WAYNE TO WEIGEL.
1702	COLORS: DETEX ROUND MADE ON POPE.
1745	MASTER ABOARD.
1800	DETEX ROUND MADE ON WEIGEL.
1900	DETEX ROUND MADE ON POPE.
1935	MR WAYNE TO WEIGEL - 2005 MR WAYNE RETURNED
2000	DETEX ROUND MADE ON WEIGEL.
2100	DETEX ROUND MADE ON POPE.
2200	DETEX ROUND MADE ON WEIGEL - ALL IN APPARENT GOOD ORDER.
2200	WATCH RELIEVED BY BUNDY.
2200	ASSUMED WATCH - ALL IN APPARENT GOOD ORDER
2245	R/O MR. ALEXANDER ABOARD - MR. WAYNE ASHORE
2255	R/E MR. O'HARA ABOARD - MR. LINDBERG ASHORE
2300	F/W ROUND RTE "A", POPE - ALL SECURE
2310	R/O TO WEIGEL, ROUTINE INSPCT. - ALL'S WELL Bundy

AT/PASSAGE FROM
PIER 2-BERTH #3-HUNTERS POINT
 ZONE DESCRIPTION

TO
NAVAL SHIPYARD, SAN FRANCISCO, CA.
 DATE (Day, month, year)
5-JAN-1970

DAY OF WEEK
MONDAY

+ 8

TIME	REMARKS
	R/O MR. ALEXANDER R/O MR. O'HARA - 0000-0800 - F/W REMILLARD - bwy. BUNDY
0000	F/W ROUND-RTE "A", WEIGEL - ALL SECURE
0100	F/W ROUND-RTE "B", POPE - ALL SECURE
0200	F/W ROUND-RTE "B", WEIGEL - ALL SECURE
0300	F/W ROUND-RTE "A", POPE - ALL SECURE
0400	F/W ROUND-RTE "A", WEIGEL - ALL SECURE
0500	F/W ROUND-RTE "B", POPE - ALL SECURE
0520	R/O TO WEIGEL, INSPECTION TOUR - ALL SECURE
0600	F/W ROUND RTE "B" WEIGEL - ALL SECURE
0630	WATCH RELIEVED BY SENDONI - Bundy A/B WATCH RELIEVED 0800-1600 Sendoni Callillo
0630	Assumed watch
0700	F/W - rounding - A - Pope
0715	Electrician - on to Weigel
0800	COLORS EXECUTED. RT "A" ON WEIGEL.
0830	Sanitary system will be secured for half hour
0840	Sanitary system in on - F/W - B - Pope
0850	Capt. + 2nd Mate on the Weigel
0900	RT "B" ON POPE ALL SECURE.
0945	HEAD SECURED ON WEIGEL
1000	RT "B" ON WEIGEL
1045	2nd reefer Marinas aboard, from office
1055	F/W - rounding - A - Pope
1135	GEORGE GRIER MSTU ABOARD.
1200	Round - A - Weigel
1255	Round - B - Pope
1400	RT B ON WEIGEL
	WATCH RELIEVED
	Mr. WAYNE. 1/6 (1600 - 2400) IREDALE, F/W. ODELL, F/W
1420	Assumed the watch. Conditions normal.
1440	Mr Hurley, R/O + Mr WAYNE, R/O, ABOARD-
1500	F/W making "A" route in Pope - 1515 - noted all's well.
1540	"Cool Breeze" ashore
1550	Mr. Wayne on Weigel inspection Tour.
1605	F/W reports A route in Weigel all secure.
1703	Colours observed
1725	F/W completes B rd. in Pope - All secure
1815	F/W finishes B RT. in Weigel do
1900	R/O To Weigel
1920	F/W finishes A rd. in Pope - do -
2015	F/W completes A rd. in Weigel - do -
2118	F/W reports B route in Pope - do -
2200	F/W note B route in Weigel. All secure
2200	Relieved of watch by Bundy + Remillard.
2200	ASSUMED WATCH - ALL IN GOOD ORDER 27 Iredale
2240	R/O MR. ALEXANDER ABD - MR. WAYNE ASHORE
2255	R/O MR. O'HARA ABD. - MR. HURLEY ASHORE Bundy A/B