

USNS GEN. JOHN POPE (T-AP 110)
C/O FLEET POST OFFICE
SAN FRANCISCO, CALIFORNIA

22 December 1969

From: Master, USNS GEN. JOHN POPE (T-AP 110)
To: Department Heads, USNS GEN. JOHN POPE (T-AP 110)

Subj: Captain's Inspection; report of

The following is a report of the Captain's Inspection held 19 December 1969, with general remarks following at the end of the report:

1. 1-86-1-L Excellent
- * 2. SR #147 Field day with head
- * 3. SR #145 Clean
- * 4. SR #143 (1-68-1-L) Replace lights. Remove stains and prepare area for use.
- * 5. 1-59-3-Q (1-63-1-L) Field day. Need toilet-paper-holder. Towels, etc.
- * 6. 1-59-4-Q (CS HldDept) Remove stains and replace curtains. Convert for ladies. Need towels, soap. Remove stains. Install new curtains. Clean
- * (Items 2-6 to be used during upcoming Safety Ceremony)
7. 1-74-2-L Good.
8. 1-66-2-L Excellent.
9. Dining Salon Continues to improve. Remove cardboard crates of fruit.
10. 1-127-4-A (Strm) Square away. Remove leaky cans and rusty cans.
11. Cleaning Gear Lkr Better/
12. 1-132-2-Q Clean drains, scuppers on deck. Suggest protective case for thermostat to insure its use.
13. 1-138-2-Q Reinstall safety guard. Place knives in locked drawer. Fabricate grooves in wooden block for knives. Otherwise good.
14. 1-127-41-Q Thermostat at sink at aft end of galley still not functioning. Steam kettles much improved. Suggest lids be greased/oiled. Clean overhead. Clean all grilles in area.
15. 1-127-3-Q Clean under and back of grille. Remove debris. Remove all rusty cans from fruit juice box.
16. 1-127-1-A Clean around ice cream storage area. Lights out.
17. 2-138-4-L Clean underside of sinks (this area is potential source of dermatitis). Deck much better in head. Head improved. Continue to improve.
18. 2-135-2-L Square away personal gear.
19. 2-138-4-L Improved.
20. 2-141-2-L Square away personal gear.
21. 2-144-2-L Remove poisons and square away shelves.
22. 2-149-2-L Improving. Clean under sink.
23. 2-147-4-L Good. Straighten up back shelves.
24. 2-152-2-L


"Think Safety—Talk Safety—and Sell Safety"

Captain's Inspection of 19 December 1969, continued:

25.	2-153-2-L	Soap dish missing. Otherwise good.
26.	2-155-2-L	Progressing on stains. Keep it up. Smells better. Remove verdigris on underside of toilet.
27.	2-158-4-L	Excellent.
28.	2-162-2-L	Assist room steward by stowing personal gear and squaring away room.
29.	2-164-4-L	Very Good.
30.	2-167-4-L	Continues to improve.
31.	2-167-6-L	Good.
32.	2-175-6-L	Good.
33.	2-173-2-L	Clean and activate washer/dryer. Exhaust vent needs dusting. Decks dirty.
34.	2-173-6-L	Excellent.
35.	2-176-2-L	Good.
36.	2-179-2-L	Good.
37.	2-183-2-L	Very good.
38.	Linen Lkr.	Improved. Continue to maintain.
39.	2-188-4-L	Very good.
40.	2-189-2-L	Very good.
41.	2-193-2-L	Very good.
42.		

In conclusion, the slight improvements found in some areas were noted with pleasure. Maximum effort must be expended by all hands to assist the room stewards. In order to give the best appearance to our ship and its living areas, in particular, cooperate with those personnel assigned for a few hours daily to maintain the crew living spaces. They can use all the help they can get.

Also, ensure that plenty of disinfectant is added to water used for cleaning purposes. Pay attention in areas not immediately noticeable, such as the areas under sinks and toilets. As mentioned before, these are particularly bad areas for contamination and disease, due to their continual neglect.


ROBERT E. LANDRY