

USNS GEN. JOHN ROPE (T-AP 116) & USNS GEN. WILSON (T-AP 119)

3 October 1969

W A T C H L I S T S

INSTRUCTIONS FOR WATCHES: USNS METHOD

1. "Day/Work" men report on board USNS ROPE to watch of 1st cert.
2. Make Detex rounds - "1" each even hour - "2" each odd hour. Check areas for security, fire/leaks, etc., and report by phone each hour to gangway, USNS ROPE - phone no. 2041.
3. Make log entries, neat & accurate.
4. Observe NO SMOKING & NO VISITORS - (no exceptions).
5. Check smoke detector on bridge during rounds, also lights.
6. Check draft, take soundings each 08-16 watch - 103 S.W.
7. Keep outside doors & PDS closed.
8. EACH MAN initials alongside his name to indicate his understanding of these remarks, and his time to report for watches.

FOR

	Tues	Wed	Thur	Fri	Sat	Sun
TIPTON	08-08	08-08	08-08	08-08	OFF	OFF
LARKIN	08-16	08-16	08-16	OFF	OFF	16-24
MAHO	16-24	OFF	OFF	16-24	16-24	08-16
WILKEL	OFF	16-24	16-24	Day/Work	08-16	OFF
MURKINS	OFF	OFF	Day/Work	Day/Work	Day/Work	08-16
OSADA	08-08	08-08	08-08	OFF	OFF	08-08
DAVOCOL	08-08	08-08	08-08	OFF	OFF	08-08
TERMINAL	08-16	08-16	OFF	OFF	08-08	08-16
GRAYSON	16-24	08-16	OFF	OFF	08-08	08-16
GER	16-24	OFF	OFF	08-16	08-16	16-24
WIK	OFF	OFF	08-16	08-16	08-16	16-24
PONKINS	OFF	16-24	16-24	16-24	16-24	OFF
JACKSON, JR.	OFF	16-24	16-24	16-24	16-24	OFF

First Officer, USNS GEN JOHN ROPE (T-AP 116)

pg 10/3/69