

11-4

11 AUGUST 1967

QPT

110115S POPE

JO 80-710

PNEUMATIC BILGE VALVE (VR 5)

SHOP 38 KNOWN DEFICIENCY TO THE PNEUMATIC BILGE VALVE
LOCATED IN THE MACHINE SHOP.

AIR LEAKS AT STEM SEAL THREADS IN SEAL RETAINER STRIPPED.
REPAIR OR RENEW BY INSTALLING A NEW THREADED RUSHING AT STEM TO
RETAIN SEALS QUANTITY FOUR.

SHOP ASSIST 31

SIGNED

KOPP CASSIDY CATRON

Completed