

# PRODUCT SERVICE REPORT

21384-K

## SPERRY GYROSCOPE COMPANY DIVISION OF SPERRY RAND CORPORATION

DISTRICT ROUTING

SERVICE

STOCK

ACCTG

DISTRICT **PACIFIC CENTRAL**

DATE **NOV. 5, 1965** JOB NO. **963- 0520215**

VESSEL <b>U.S.N.S. GEN. J. POPE</b>		INVOICE NO.		INVOICE DATE	
LOCATION <b>TODD SHIP YARD</b>		CUSTOMER			
PORT <b>ALAMEDA, CALIFORNIA</b>		ADDRESS			
ORIGIN OF SERVICE CALL	DISPATCHER	CAPTAIN		CITY	
	AGENT		DATE		STATE
CUSTOMER'S ORDER NO.		CUSTOMER'S REQ. NO.			

PROD. NO.	PRODUCT NAME	SERIAL NO.	MANUFACTURER	TOTAL OPER. TIME	CHARGES	
171	GYRO-COMPASS		S	?	I G	C X X

### REASON FOR CALL

**REMOVE GYRO-COMPASS AND ASSOCIATED EQUIPMENT FROM SHIP TO SHOP FOR OVERHAUL AND REFURBISHMENT.**

### TROUBLE FOUND & WORK PERFORMED

- 1- REMOVED THE FOLLOWING UNITS TO SPERRY SHOP FOR OVERHAUL: MASTER COMPASS, BINNACLE, MOTOR GENERATOR, CARBON PILE REGULATOR, COURSE RECORDER, SEVEN (7) REPEATERS AND TOPSIDE PELORUS HEAD.
- 2- ALL UNITS WERE COVERED WITH PRESERVATIVE AND EVIDENCE OF CORROSION ON PARTS NOT SO PRESERVED. ALL UNITS WERE DISASSEMBLED COMPLETELY AND PARTS TO BE REFURBISHED, CLEANED AND RE-PAINTED.
- 3- MASTER COMPASS: COMPLETE DISASSEMBLY AND ALL CRITICAL PARTS RENEWED. COMPASS REASSEMBLED AND GIVEN SWING TEST.
- 4- MOTOR-GENERATOR COMPLETELY OVERHAULED AND BENCH CHECKED.
- 5- ALL REPEATERS REFURBISHED ALL NEW PARTS INSTALLED FOR DEFECTIVE COMPONENTS. BENCH TESTED.
- 6- COURSE RECORDER COMPLETELY OVERHAULED ALL DEFECTIVE COMPONENTS AND PARTS R RENEWED. CHART DRIVE AND CLOCK UNIT TESTED AND ADJUSTED. COMPLETE ASS'Y. BENCH CHECKED.
- 7- REINSTALLED ALL EQUIPMENT ABOARD SHIP.

