

PRODUCT SERVICE REPORT

81334-E

SPERRY GYROSCOPE COMPANY DIVISION OF SPERRY RAND CORPORATION

DISTRICT ROUTING

SERVICE

STOCK

ACCT'G

DISTRICT

DATE

JOB NO.

VESSEL

INVOICE NO.

INVOICE DATE

LOCATION

CUSTOMER

PORT

ADDRESS

ORIGIN OF
SERVICE
CALL

DISPATCHER

CAPTAIN

AGENT

DATE

CITY

CUSTOMER'S ORDER NO.

CUSTOMER'S REQ. NO.

STATE

PROD. NO.

PRODUCT NAME

SERIAL NO.

MANUFACTURER

TOTAL OPER. TIME

CHARGES

171

Gyro Compass

#415293

SPERRY

I
G

C
X

REASON FOR CALL

Service Gyro Compass, Check over Gyro Pilot

TROUBLE FOUND & WORK PERFORMED

Disassembled Compass to, and including upper guide bearing. Renewed guide and Horizontal base bearings. Opened rotor. Checked wicks and North Thrust - renewed oil. Reconditioned Azimuth Motor and Transmitter. Cleaned ballistie pots and tubes and removed mercury. Made balances and settled Compass to North heading. Checked ballages and follow up.

Gyro Pilot:-

Cleaned slip rings and carriages and increased spring tension on repeating locking device. Checked equipment aft - OK. Checked operation - Satisfactory.

