

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-8

[illegible]

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

NAVSHPHS 539 (Rev. 8-48)

U. S. GOVERNMENT PRINTING OFFICE 16-58394-3

NAVSHPHS 539 (Rev. 8-48)

[illegible]

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53894-2

HULL HISTORY CARD

STOCKED IN CDS

NAVJAG 539 (Rev. 8-48)

1-170(192)

OVER-HANG (GHT OF ENCLOSED ROOM)

COMP. OR FILE NO.

COMMON NAME OF COMPARTMENT, SYSTEM OR EQUIPMENT

LAST INSP.

LAST TEST

CARD NO.

REFERENCE

INSTRUCTIONS—ENTER BELOW SIGNIFICANT HISTORY ONLY, OMITTING MINOR REPAIRS AND WEEKLY ROUTINE INSPECTIONS

TEST REQ'D

ALL DROP

DIV. RESP.

DATE

REFERENCE

HISTORY

WORK BY

4/22/66 BOW W/B Scaled and Painted Underside of "Over-hang" Port & Starboard.

S/R

WORK DONE, MATERIAL USED, COST, ETC.

Main deck: Frame 172 to 213 P&S renewed caulking on wooden deck approx 8600 lin ft.

4/58 = WOOD RAILS PORT & STBD. FR. 172 TO 213
 (SCRAPE TO BARE WOOD), 2 COATS VARNISH APPLIED → CHIEF
 ENCLOSED PROM.
 5/58 = DOUBLE DOORS FR. 160, FR. 166 TO MAIN DINING ROOM, FR. 172, BOTH / CHIEF
 PORT & STBD. SCRAPE TO BARE WOOD, 2 COATS VARNISH APPLIED.
 5/58 = DOUBLE DOORS TO CHAPEL (PORT & STBD) SCRAPE TO BARE WOOD, 2 COATS VARNISH APPLIED / CHIEF

11/62 Renewed vent frame 172 between main deck and O1 level.

Todds

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 10-53394-3

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

U. S. GOVERNMENT PRINTING OFFICE 16-53304-3

HULL HISTORY CARD

STOCKED IN CDS

NAVSHIPS 539 (Rev. 8-48)

COMP. OR FILE NO.		COMMON NAME OF COMPARTMENT, SYSTEM OR EQUIPMENT		LAST INSP.	LAST TEST	CARD NO.
REFERENCE		INSTRUCTIONS—ENTER BELOW SIGNIFICANT HISTORY ONLY, OMITTING MINOR REPAIRS AND WEEKLY ROUTINE INSPECTIONS			TEST REQ'D	DIV. RESP.
DATE	REFERENCE	HISTORY				WORK BY
2/55		<i>POL - 12</i>				<i>S/F</i>
7-58		<i>- 122 DECK LIFTED & SCREWED AND PLANKED</i>				<i>CHEN</i>
3-64		<i>Repair lebrary lock:</i>				
4/67		<i>Painted Deck</i>				<i>MW</i>
		<i>Stained and waxed decks. Painted ladders.</i>				<i>SF</i>

U. S. GOVERNMENT PRINTING OFFICE 16-53894-3

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16--53394-8

NAVSHPHS 539 (Rev. 8-48)

NAVSHIPS 539 (Rev. 8-48)

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

U. S. GOVERNMENT PRINTING OFFICE 16-53394-8

STOCKED IN CDSU. S. GOVERNMENT PRINTING OFFICE 16-53394-2

NAVSHIPS 539 (Rev. 8-48)

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

STOCKED IN CDS

[illegible]

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-3

U. S. GOVERNMENT PRINTING OFFICE 16-53394-2

STOCKED IN CDS

10-53394-3

HULL HISTORY CARD

STOCKED IN CDS

NAVSHIPS 539 (Rev. 8-48)

[illegible]

STOCKED IN CDS

U. S. GOVERNMENT PRINTING OFFICE 16-53394-8