

CHAPTER I

MISSION AND ORGANIZATION

UNIT: Detachment 5, 38 Aerospace Rescue and Recovery Squadron, Military Airlift Command.

PERIOD: Detachment 5, 38 Aerospace Rescue and Recovery Squadron is located at Udorn Royal Thai Air Base, Thailand. The base is located three and one half miles southeast of Udorn Thani, Thailand. The town has a population of approximately 70,000. The base population is presently more than 6,500.

ASSIGNMENT: Detachment 5, is assigned to the 38 Aerospace Rescue and Recovery Squadron at Tan Son Nhut Air Base, Republic of Vietnam. The 38th ARRSq is assigned to the 3rd Aerospace Rescue and Recovery Group, also located at Tan Son Nhut. Operational control of the 38 ARRSq aircraft is exercised by the 7th Air Force. Thirteenth Air Force is responsible for logistics and administrative support. The 432nd Combat Support Group, located at Udorn RTAFB, is responsible for control of base facilities and support of tenant units.

DET 5, 38ARRS, HISTORY, JUL-SEP 1970

5-2

ORGANIZATIONAL CHART:

	38 ARRSq	
	Det 5	
	Commander	
Administration	Operations	Maintenance

COMMANDER: The Commander of Det 5 is Major Harry E. Raisor

DET 5, 38ARRS HISTORY, JUL-SEP 1970

5-3

CHAPTER II

RESOURCES

PERSONNEL:

UDL AS OF 30 APR 1970

AUTHORIZED VERSUS ASSIGNED

<u>Grade</u>	<u>Duty Title</u>	<u>AFSC</u>	<u>No Authorized</u>	<u>No Assigned</u>
Major	Pilot, Helicopter	A1025C	1	1
Major	Pilot, Helicopter	1025C	1	0
Capt	Pilot, Helicopter	1025C	2	3
Capt	Pilot, Helicopter	1021C	0	2
Lt	Pilot, Helicopter	1025C	2	0
SMSGT	Acft Maint Supt	43191	1	1
MSGT	Helicopter Tech	A43170B	0	1
TSGT	Helicopter Tech	A43170B	1	0
SSGT	Helicopter Mech	A43170B	0	1
SSGT	Helicopter Mech	A43150B	1	2
SSGT	Helicopter Mech	43150B	1	1
SSGT	Jet Engine Mech	43250	1	2
SGT	Helicopter Mech	A43150B	2	2
SGT	Helicopter Mech	43150B	4	1
SGT	Administrative Spec	70250	1	1

DET 5, 38ARRS, HISTORY, JUL-SEP 1970

5-4

ASSIGNED PERSONNEL: Detachment 5 had a heavy turnover of personnel this quarter gaining one officer and four NCO's. The officer is Captain Robert C. Ricketson a co-pilot. The NCO's are SSgt Leonel Carrillo, a jet engine mechanic; SSgt Richard S. Flynt, a jet engine mechanic; Sgt Jerome Bridges, a helicopter mechanic; and Sgt Richard J. Krajewski, an administrative specialist. One officer, two NCO's and one airman left the detachment this quarter. The officer was Major Alfred W. Lamkin, an aircraft commander. The NCO's were Sgt Edgar A Dangel Jr., a helicopter mechanic; and Sgt Gerald W. Buell, a jet engine mechanic. The airman was ALC Joe Chatman, an administrative specialist.

ATTACHED PERSONNEL: Six Fire Fighters of the 432nd Civil Engineering Squadron and four Medical Technicians from the 432nd USAF Hospital(PACAF) are attached to Detachment 5 for flying. They fly training missions and rescue missions with the Detachment.

DET 5, 38ARRS, HISTORY, JUL-SEP 1970

5-5

ROSTER OF ASSIGNED PERSONNEL:

<u>NAME</u>	<u>GRADE</u>	<u>SSAN</u>
-------------	--------------	-------------

Harry E. Raisor	Major	
-----------------	-------	--

Robert O. Martin	Capt	
------------------	------	--

William T. Lyon	Capt	
-----------------	------	--

ADDITIONAL DUTY

Aircrew Standardization  
Pilot, FCF Pilot, Top  
Secret Control Officer,  
Chairman Aircrew Review  
and Certification Board,  
Primary Censor, Chairman  
Accident Prevention  
Council  
Operations Officer  
Aircrew Standardization  
Officer, FCF Pilot,  
Mobility Officer,  
Medication Control  
Officer, MAC Pride  
Monitor, Manuals Control  
Officer, Member APC.  
Administrative Officer,  
Information Officer,  
Accountable Forms  
Officer, FCF Co-Pilot,  
JOC Representative,



DET 5, 38ARRS, HISTORY, JUL-SEP 1970

5-6

ROSTER OF ASSIGNED PERSONNEL (CONT):

<u>NAME</u>	<u>GRADE</u>	<u>SSAN</u>	<u>ADDITIONAL DUTY</u>
William T. Lyon	Capt		(CONT): Records Control Officer, Voting Officer, Reports Monitor, Member APC, Ration Card Control Officer, Security Officer.
Glynn A. McGregor	Capt		Training Officer, Explosive Safety Officer, Unit Fire Marshal, FCF Co-Pilot, Life Support Officer, Aerobics Physical Fitness Officer, Safety Officer, Accident Prevention Committee Recorder, COMSEC Officer, Intelligence Officer, Asst Operations Officer, Facility Improvement Officer.

DET 5, 38AERS, HISTORY, JUL-SEP 1970

5-7

ROSTER OF ASSIGNED PERSONNEL (CONT):

<u>NAME</u>	<u>GRADE</u>	<u>SSAN</u>
-------------	--------------	-------------

Donald C. Koenig	Capt	
------------------	------	--

Robert C. Ricketsen Capt

Joseph W. Kennedy SMSGT

ADDITIONAL DUTY

Supply Officer, FOD Officer, Disaster Preparedness Officer, L.P. Representative, Cost Reduction Project Officer, Weapons Control Officer, Budget Officer, FCF CO-Pilot.

Awards and Decorations Officer, Unit Historian, Postal Officer, Vehicle Control Officer.

First Sergeant, Maintenance NCOIC, Time Change Monitor, Dormitory Improvement Monitor, Official Pay Representative, TCTO Monitor, Supply Representative, WRM Monitor, Member APC, NCO Advisory Council, Top Three Representative, PDO Representative, Rentention NCO.

DFT 5, 38ARRS, HISTORY, JUL-SEP 1970

5-8

ROSTER OF ASSIGNED PERSONNEL (CONT):

<u>NAME</u>	<u>GRADE</u>	<u>SSAN</u>	<u>ADDITIONAL DUTY</u>
Willie Bostic Jr.	MSgt		Safety NCO, Alternate APC Member, FOD Control NCOIC, Alt Fire Marshal, Hangar Queen Monitor, Corrosion Control Man- ager, FCF Flight Mechanic. Quality Control Inspec- tor, Life Support NCO, Spectrometric Oil Analysis Monitor. PMEL Monitor, Supply NCO. Disaster Preparedness NCO, Barracks Chief, Aerobics Physical Fit- ness NCO. Unit Fire Warden, Barracks Chief, Tech Order Monitor. Specialist Support, Asst FOD Monitor, Asst Bar- racks Chief, ALT Unit Fire Warden.
Russell E. Planck	SSgt		
James S. Hargrove	SSgt		
James B. Kennedy	SSgt		



DET 5, 38ARRS, HISTORY, JUL-SEP 1970

5-9

ROSTER OF ASSIGNED PERSONNEL (CONT):

<u>NAME</u>	<u>GRADE</u>	<u>SSAN</u>
-------------	--------------	-------------

Clarence Brown Jr.	SSgt	
--------------------	------	--

Leonel Carrillo	SSgt	
-----------------	------	--

Richard S. Flynt	SSgt	
------------------	------	--

Frederick R. Marshall	Sgt	
-----------------------	-----	--

Alphonso Lizarraga	Sgt	
--------------------	-----	--

Jerome Bridges	Sgt	
----------------	-----	--

Richard J Krajewski	Sgt	
---------------------	-----	--

ADDITIONAL DUTY

780 Monitor, Hanger Chief,  
Asst Tech Order Monitor,  
Mail Clerk.

Asst Supply NCO, Asst  
Spectrometric Oil  
Analysis Monitor.

OJT Supervisor, Train-  
ing NCO.

Unit Mail Clerk, Hootch  
Chief, Asst Supply NCO,  
Asst Hanger Chief, Airman  
Advisory Council Rep-  
resentative

Administrative Clerk,  
Unit Mail Clerk, LP Store  
Representative, PDO Acct  
Representative, Ration  
Card Monitor, Meal Card  
Monitor, Airman Advisory  
Council.

AIRCRAFT: The Detachment is equipped with two Kaman HH-43B helicopters. The serial numbers of these helicopters are 59-1572 and 60-0259. One aircraft is continually of immediate response alert. The other stands backup alert. Both aircraft are used for training missions.

FACILITIES: Detachment 5 is located on the flight line near the control tower and civilian air terminal. The alert facility provides office space and alert quarters for crew members overnight. Nearby tool sheds contain all the necessary equipment for aircraft maintenance. A hangar is located approximately 100 yards from the alert facility. This hangar is capable of sheltering two aircraft in inclement weather and provides a sheltered maintenance work area.

CHAPTER III

OPERATIONS AND TRAINING

RESCUE MISSIONS: During this quarter Detachment 5 flew intercepts on a total of 111 aircraft, amassing 37.9 hours of operational mission time. A total of 124 training missions and 128.2 hours were flown from 1 July to 30 September 1970.

OFF BASE MISSIONS: On 29 August 1970, Pedro Operations was notified that a man had been seriously injured in a motor vehicle accident at a remote site 45 miles from Udorn. The man required immediate evacuation from an Army radar site near Khon Kaen, Thailand where he had been taken. Pedro 09 launched at 2000L and flew to the site, where, upon landing it was evident the injured man's condition had greatly deteriorated and his life was in jeopardy. The man had suffered a chest wound and had a collapsed lung. The helicopter mechanic and a medical technician loaded the injured man on the aircraft. After a normal flight back to Udorn RTAFB, the man was off loaded to an ambulance. It was later learned that the man probably would not have lived without the prompt air evacuation provided by the Pedro crew. The crew on this flight was: Captain Glynn A. McGregor, Aircraft Commander; Major Alfred W. Lamkin, Co-pilot; and Sgt Frederick R. Marshall, Helicopter Mechanic.